1141 - Work Orders In Progress (Fiscal Year)

Selected Da	te Range for Request Building	Dates:7/1/2015 - 6 Area	5/30/2016 Order By Loc Deferred By		equest Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•	Create	d Date/Time	Actual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requester	· Name								
Location:	Alta Vista	Early College H	IS						
135852					7/14/2015		323		\$0.00
Medium	Work In Progress			7/14/2015	12:01:35 PM	1			
Vallejo, All	pert	Improve sidew	alks at front entrance).					
Albert Valle	ejo								
146127					1/13/2016		140		\$0.00
Medium	Work In Progress			1/13/201	6 7:58:43 AN	1			
Vallejo, All	pert	Upgrade electr	rical service for portal	oles.					
Albert Valle	ejo								
153596					5/20/2016		12		\$0.00
Medium	Work In Progress			5/20/2016	10:51:44 AN	1			
Carrasco,	Danny		10 gallons of paint 26 rder# 0003561 exteri)				
Alfredo Am	nbriz								
153598					5/20/2016		12		\$0.00
Medium	Work In Progress			5/20/2016	11:05:42 AN	1			
Carrasco,	•		40 gallons of paint #6 ble school thank you.	623 for mysite to)				
Alfredo Am					7/20/2045		247		ФО 00
136112	Curriculum and	ANINIEN/		7/00/004	7/20/2015		317		\$0.00
Medium Marquez, (Work In Progress Gerardo	GLASS DOOR BE REPLACED IDENTIFICATION	D DOORS WITH WO S AT ANNEX BUILDI D HAVE BEEN LABE DN. ANY QUESTION ETTE OR GEMA AT A	OD FRAME AND NG. DOORS TO LED FOR IS, PLEASE	O	1			
Yvette Cor	tez								
147971					2/18/2016		104		\$0.00
Medium	Work In Progress			2/18/201	6 8:56:12 AN	1			
Vallejo, All	pert	Move (3) Doub	le Portables from D	Γ to AVEC.					
Alfredo Ho	lguin								
150522					4/3/2016		59		\$0.00
Medium	Work In Progress			4/3/2016	12:43:32 AN	1			
Ronquillo,		Monthly - Alta \ to PMschedule	/ista ECHS - (Qtrly) F e details.	Fitness Equip - I	Refer				
Margret Vi	llalobos								

6/1/2016 11:47:05 AM Page 1 of 174

WOID	te Range for Request Building	Area I	Deferred By	Until Request Date	Target Comp Date	Days	Labor Hours	
Priority	Status _	Area Number	Reason	Created Date/Time	•	Aged	Hours	
Assigned		Description			Action Taken			
Requester								
Location:	Alta Vista	a Early College HS	•					
154056				5/31/2016		1		\$0.00
Medium	Work In Progress			5/31/2016 12:54:48 AM	1			
Martinez, S	Salvador	Monthly - Desert to PMschedule o		Meter Readings - Refer				
Margret Vi	lalobos							
150625				4/3/2016	4/9/2016	59		\$0.00
Medium	Work In Progress			4/3/2016 12:44:46 AM	1			
Soriano, D	avid	Monthly - Alta Vis Refer to PMsche		y FE Inspection -				
Margret Vi	lalobos							
154042				5/31/2016	7/1/2016	1		\$0.00
Medium	Work In Progress			5/31/2016 12:54:39 AM	1			
Aguilar, Pa	atricio	Yearly - Desert F to PMschedule o		Unit)(Yearly) - Refer				
Margret Vi	lalobos							
150060		Parking Lot		3/23/2016		70		\$0.00
Medium	Work In Progress	Front Parking		3/23/2016 3:11:22 PM	1			
Lara, Ralp	h			DES NOT LOCK AND OS A PAD LOCK FOR				
Yvette Cor	tez							
153516		Classroom		5/19/2016		13		\$0.00
Medium	Work In Progress			5/19/2016 2:38:11 PM	1			
Lara, Ralp	h	need to service lo	ocks and worked	on door cylinders,				
Ralph Lar	a							
143208				11/6/2015		208		\$0.00
Medium	Work In Progress			11/6/2015 11:55:58 AM	1			
Vallejo, All	pert		puters are. Also	nt on top of the first roof leak in portable s desk.				
David Sori	ano							
146209				1/14/2016		139		\$0.00
Medium	Work In Progress			1/14/2016 9:51:31 AM	1			
Soriano, D	avid	PVC cement and	d primer to fix rup	otured water pipe				
,-	ano			1 1 -				

6/1/2016 11:47:05 AM Page 2 of 174

1141 - Work Orders In Progress (Fiscal Year)

David Soriano

Selected Da	ate Range for Request Building	Dates:7/1/2015 - 6/30/2016 Order By Location, Status Area Deferred By Until Request Date Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number Reason Created Date/Time Actual Comp Date	Aged	Hours	
Assigned '	То	Description Action Taken			
Requester	r Name				
Location:	Alta Vista	Early College HS			
142013		10/20/2015	225		\$0.00
Medium	Work In Progress	10/20/2015 2:25:50 PM			
Soriano, D	Pavid	4- White Heavy Duty Shelf and Rod Support3- Concrete Mix Sacks			
David Sori	iano				
140462		9/23/2015	252		\$0.00
Medium	Work In Progress	9/23/2015 8:58:29 AM			
Soriano, D	David	10-2x4x8 Studs to hang up window blinds			
David Sori	iano				
142305		10/26/2015	219		\$0.00
Medium	Work In Progress	10/26/2015 11:40:36			
Soriano, D	David	2- Melnor Y Shut-Off 2-Way Metal Hose Connector			
David Sori	iano				
142306		10/26/2015	219		\$0.00
Medium	Work In Progress	10/26/2015 11:51:47			
Soriano, D	Pavid	2 Boxes-#6 x2 in. Phillips Bugle-Head Coarse Thread Sharp Point Gold Screw (1 lbPack)			
		2 Boxes-#8 3 in. Philips Bugle-Head Coarse Thread Wood Screws (1 lbPack)			
		2 Boxes - #6 x 1-5/8 in. Philips Bugle-Head Coarse Thread Gold Screw			
David Sori	iano				
142369		10/27/2015	218		\$0.00
Medium	Work In Progress	10/27/2015 8:43:13 AM			
Soriano, D	Pavid	3-42x29 window blinds 2-48x48 window blinds			
David Sori	iano				
139907		9/14/2015	261		\$0.00
Medium	Work In Progress	9/14/2015 2:04:54 PM			
Soriano, D	David	10 - Ballaster 4 lamp 110 v			

6/1/2016 11:47:05 AM Page 3 of 174

WOID Priority Assigned Requester	Building Status To	Area Number Description	/30/2016 Order By Lo Deferred By Reason		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:		a Early College H	IS					
139734				9/10/2015		265		\$0.00
Medium	Work In Progress			9/10/2015 2:27:06 PM	1			
Soriano, D	avid	4 - 9 in. Roller 4-2 in. Roller C 1-2 in. Roller 1- 10 oz Caulki 1- 4-in Metal T	overs	den Hose)				
David Sori	ano							
139349				9/4/2015		271		\$0.00
Medium	Work In Progress			9/4/2015 10:38:51 AM				
Soriano, D	avid	25ft - 3/8 Plasti 25ft - 1/2 Plasti						
		5- (3/8 - 7/8) Ho	se Repair Clamp					
David Sori	ano			0/4/0045		074		ФО 00
139356				9/4/2015		271		\$0.00
Medium	Work In Progress			9/4/2015 11:07:10 AM				
Soriano, D	avid	1/2 in. length)		s (size - 1/4 in width x				
		washers and n	ts 3/8 in width x 2 1, uts	z lengui) wiui				
David Sori	ano							
139910		Library		9/14/2015		261		\$0.00
Medium	Work In Progress			9/14/2015 2:11:00 PM	1			
Soriano, D	avid		ed wire connectors e the green ones for					
David Sori	ano							
143206		Parking Lot		11/6/2015		208		\$0.00
Medium	Work In Progress			11/6/2015 11:43:48 AM				
Soriano, D	avid	4 - Flat Bar 17 8 - Carriage Bo	x 1 x 1/8 olts with nuts (1 1/2	in x 3/8)				
David Sori	ano							
144961				12/14/2015		170		\$0.00
Medium	Work In Progress			12/14/2015 12:39:25				
Soriano, D	avid		Ballast for 4 ft. 4-La Ballast for 4 ft. 2-La					
David Sori	ano							

6/1/2016 11:47:05 AM Page 4 of 174

WOID Priority Assigned		Area Number Description	Deferred By		•	Days Aged	Labor Hours	Costs
Requester								
Location:	Alta Vista	Early College H	S					
152835		Parking Lot		5/9/2016		23		\$0.00
Medium	Work In Progress			5/9/2016 2:27:39 PM				
Gonzalez,	Salvador		come and fix the d	front entrance gate its				
Alfredo Am	briz							
153999		Office		5/27/2016		5		\$0.00
Medium	Work In Progress			5/27/2016 11:35:03 AM				
Gonzalez,	Salvador			a security bar on the office as soon as you				
Alfredo Am	briz							
151657		Library		4/19/2016		43		\$0.00
Medium	Work In Progress	Library		4/19/2016 4:49:40 PM				
Lara, Ralp	h		OT SWING FREE GAINS CEMENT.	LY. BOTTOM OF				
Yvette Cor	tez							
150312				3/31/2016		62		\$0.00
Medium	Work In Progress			3/31/2016 11:31:32 AM				
Miranda, D	Danny		mize sound penet	orinciples office and ration. See Ms.				
Albert Valle	ejo							
152882		Library		5/10/2016		22		\$0.00
Medium	Work In Progress	Library		5/10/2016 10:02:46 AM				
Lara, Ralp	h	DOOR CANNO		TO BE REPLACED. OR FIXED DUE TO TH WINDOW.				
Yvette Cor	tez							
146141				1/13/2016		140		\$0.00
Medium	Work In Progress			1/13/2016 11:02:07 AM				
Soriano, D	avid			Wrap Insulation				
David Sori	ano							
146067		Parking Lot		1/12/2016		141		\$0.00
Medium	Work In Progress			1/12/2016 2:26:28 PM				
Soriano, D	avid	18ft uni-strut to	hang up sings in p	parking lot.				
David Sori			5 i - 5- ··· i	5				

6/1/2016 11:47:05 AM Page 5 of 174

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Area Number Reason Created Date/Time Actual Comp Date **Status Priority Assigned To Description Action Taken** Requester Name Location: Alta Vista Early College HS 153897 Office 5/25/2016 7 \$0.00 Work In Progress Main Office 5/25/2016 9:34:35 AM Medium REPLACE FRONT OFFICE DOOR (MAIN ENTRANCE) Lara, Ralph WITH NEW DOOR DUE TO SECURITY PURPOSES. Yvette Cortez **Count: 34 Work Orders** Total for Alta Vista Early College HS 0 \$0.00

Avg. Age of WO's 139

6/1/2016 11:47:05 AM Page 6 of 174

WOID Priority Assigned 7	Building Status To	Dates:7/1/2015 - 6/30/2016 Ord Area Deferred Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:		On Track Pre-K (Village)					
137103			8/3/2015		303		\$0.00
Medium	Work In Progress		8/3/2015 2:08:08 PM				
Ontiveros,	Guadalupe	Please trim trees that are thank you.	in the front office				
Laura Vazo	quez						
144025			11/30/2015		184		\$0.00
Medium	Work In Progress		11/30/2015 2:00:33 PM				
Chavez, Sa	antos	Install wall packs around b	ouilding.				
Albert Valle	ejo						
143784			11/18/2015		196		\$0.00
Medium	Work In Progress	882-1904	11/18/2015 2:32:43 PM				
Marquez, C	Serardo	Install chains furnished ar	nd weld on to gates please				
Laura Vazo	quez						
142145			10/22/2015		223		\$0.00
Medium	Work In Progress		10/22/2015 10:34:31				
Ontiveros,	Joe	Admin Portable - water fou	ntain (exterior) does not work.				
Albert Valle	eio						
150744	•		4/5/2016		57		\$0.00
Medium	Work In Progress		4/5/2016 9:30:04 AM				
Ronquillo,	Ruben		nss replaced in room #110 at 141/4 x191/2. single pane.				
Arturo Nun	ez						
153610			5/20/2016		12		\$0.00
Medium	Work In Progress		5/20/2016 2:28:21 PM				
Nunez, Artı		please assemble four new room 101 and 102 thank	v cafeteria tables they are in you.				
Laura Vazo	quez		F (00 (0040				Φο οο
153954			5/26/2016		6		\$0.00
Medium	Work In Progress		5/26/2016 12:16:54 PM				
Nunez, Artı		remove all coat hangers from install two new ones in each	om all pre-k class rooms and ch cafeteria thank you :)				
Laura Vazo	quez	0.4.4.	7/00/0045		044		40.00
136332		Cafeteria	7/23/2015		314		\$0.00
Medium	Work In Progress	882-1904	7/23/2015 12:06:53 PM				
Nunez, Artı Laura Vazo		doors from room 101 and	102 need a weather strip				

6/1/2016 11:47:05 AM Page 7 of 174

In Progress In Progress	requesting an additional entrance of the restrooms that are out side questions ask Ms. Sandy Classroom 882-1904 requesting cabinets install in four any questions please ask Sandy	2/26/2016 2/26/2016 11:29:36 AM teacher classrooms. Silvas	56 20 96	\$0.00 \$0.00 \$0.00
In Progress In Progress	requesting an additional entrance of the restrooms that are out side questions ask Ms. Sandy Classroom 882-1904 requesting cabinets install in four	4/6/2016 2:53:00 PM 5/12/2016 5/12/2016 10:52:09 AM e on the opposite side the pre-k any 2/26/2016 2/26/2016 11:29:36 AM teacher classrooms. Silvas	96	\$0.00
In Progress In Progress	requesting an additional entrance of the restrooms that are out side questions ask Ms. Sandy Classroom 882-1904 requesting cabinets install in four	5/12/2016 5/12/2016 10:52:09 AM e on the opposite side the pre-k any 2/26/2016 2/26/2016 11:29:36 AM teacher classrooms. Silvas	96	\$0.00
In Progress	requesting an additional entrance of the restrooms that are out side questions ask Ms. Sandy Classroom 882-1904 requesting cabinets install in four	5/12/2016 10:52:09 AM e on the opposite side e the pre-k any 2/26/2016 2/26/2016 11:29:36 AM teacher classrooms. Silvas	96	\$0.00
In Progress	of the restrooms that are out side questions ask Ms. Sandy Classroom 882-1904 requesting cabinets install in four	5/12/2016 10:52:09 AM e on the opposite side e the pre-k any 2/26/2016 2/26/2016 11:29:36 AM teacher classrooms. Silvas	96	\$0.00
In Progress	of the restrooms that are out side questions ask Ms. Sandy Classroom 882-1904 requesting cabinets install in four	5/12/2016 10:52:09 AM e on the opposite side e the pre-k any 2/26/2016 2/26/2016 11:29:36 AM teacher classrooms. Silvas	96	\$0.00
In Progress	of the restrooms that are out side questions ask Ms. Sandy Classroom 882-1904 requesting cabinets install in four	2/26/2016 2/26/2016 11:29:36 AM teacher classrooms. Silvas		
In Progress	of the restrooms that are out side questions ask Ms. Sandy Classroom 882-1904 requesting cabinets install in four	2/26/2016 2/26/2016 11:29:36 AM teacher classrooms. Silvas		
)	882-1904 requesting cabinets install in four	2/26/2016 11:29:36 AM teacher classrooms. Silvas 5/23/2016		
)	882-1904 requesting cabinets install in four	2/26/2016 11:29:36 AM teacher classrooms. Silvas 5/23/2016		
)	requesting cabinets install in four	teacher classrooms. Silvas 5/23/2016	9	\$0.00
		5/23/2016	9	\$0.00
In Drograss			9	\$0.00
In Drograss			9	\$0.00
In Drograss		E/22/2016 2:16:25 DM		
In Progress		5/23/2016 2:46:25 PM		
	please wash all black chairs that a room thank you.	are in the office lunch		
		4/5/2016	57	\$0.00
In Progress	882-1904	4/5/2016 1:10:36 PM		
	removed carpet from room 111 ar	nd install tile		
	Classroom	5/19/2016	13	\$0.00
In Progress		5/19/2016 1:12:28 PM		
	please paint al classroom form O cafeterias	n Track Pre-k including		
		8/24/2015	282	\$0.00
In Progress	ANTHONY	8/24/2015 3:12:32 PM		
	DRY ERASE BOARD WAS REMO ANTHONY FAMILY LITERACY CE	OVED AT THE ENTER. CONTACT		
1	n Progress	Classroom n Progress ANTHONY PLEASE PAINT AN INSIDE ONE DRY ERASE BOARD WAS REMO ANTHONY FAMILY LITERACY CE JUANA ESPINOZA @ EXT.4420 (Classroom 8/24/2015 n Progress ANTHONY 8/24/2015 3:12:32 PM PLEASE PAINT AN INSIDE ONE WALL WHERE THE DRY ERASE BOARD WAS REMOVED AT THE ANTHONY FAMILY LITERACY CENTER. CONTACT JUANA ESPINOZA @ EXT.4420 OR RAY LARA @	Classroom 8/24/2015 282 n Progress ANTHONY 8/24/2015 3:12:32 PM PLEASE PAINT AN INSIDE ONE WALL WHERE THE DRY ERASE BOARD WAS REMOVED AT THE ANTHONY FAMILY LITERACY CENTER. CONTACT JUANA ESPINOZA @ EXT.4420 OR RAY LARA @

6/1/2016 11:47:05 AM Page 8 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da	ate Range for Request Building	Dates:7/1/2015 - 6/30/2016 Order By Location Area Deferred By U		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number Reason	Created Date/Time	-	Aged	Hours	
Assigned		Description	Groated Bate, Time	Action Taken			
Requeste				7.0			
Location:	Anthony	- On Track Pre-K (Village)					
150651			4/4/2016		58		\$0.00
Medium	Work In Progress		4/4/2016 8:31:29 AM				
Nunez, Ar	turo	please repaint the yellow arrows that are side the one that the children's use to ric					
Laura Vaz	zquez						
150652			4/4/2016		58		\$0.00
Medium	Work In Progress		4/4/2016 8:32:35 AM				
Nunez, Ar	turo	please paint a caterpillar on the side wa details ask Sandy	lk more info or				
		Thank you					
Laura Vaz	zquez						
147803			2/11/2016		111		\$0.00
Medium	Work In Progress		2/11/2016 1:46:27 PM				
Nunez, Ar	turo	as per Ray L. For the POA center in the Anthony Pre-K. To re-paint stairs/racenter entrance. Thank you.					
Esteban F	Rosas						
152834			5/9/2016		23		\$0.00
Medium	Work In Progress		5/9/2016 2:26:39 PM				
Solis, Lore	en <i>z</i> o	Need assistance in troubleshooting mi possible shorted due to power outage.	ni split system				
Arturo Nui	nez						
Count: 19	Work Orders	Avg. Age of WO's 109	Total for Anthony - 0	On Track Pre-K (Vill	age)	0	\$0.00

6/1/2016 11:47:05 AM Page 9 of 174

WOID Priority Assigned 1 Requester		Area Deferred By Until Request Date Area Number Reason Created Date/Time Description	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Anthony	ES				
	Antilony	4/11/2016		51		\$0.00
151091 Madium	Work In Brogross		•	31		φυ.υυ
Medium	Work In Progress	4/11/2016 9:28:06 AV	l			
Villalobos,		supersuction colt wet and dry does not pick up water squeegee is shot				
David Vega	a	4/40/0040		40		<u>ФО 00</u>
151610		4/19/2016	_	43		\$0.00
Medium	Work In Progress	4/19/2016 1:07:04 PN	1			
Villalobos,	Jose	vacuum cleaner serial #5372 sometimes wont tum on				
David Vega	a					
151895		4/25/2016		37		\$0.00
Medium	Work In Progress	4/25/2016 8:51:59 AV	I			
Villalobos,	Jose	WEEDEATER STIHL SERIAL #9512 needs repair sometimes wont start				
David Vega	a					
152558		5/3/2016		29		\$0.00
Medium	Work In Progress	5/3/2016 3:52:49 PM	1			
Villalobos,	Jose	Can I have blower serviced and pull sting replaced.				
Arturo Nun	ez					
152885		5/10/2016		22		\$0.00
Medium	Work In Progress	5/10/2016 11:16:55 AV	I			
Villalobos,	Jose	shower scrubber serial #00012 fix handle also needs bottom plate(call david)				
David Vega	a	, , ,				
147779		2/11/2016		111		\$0.00
Medium	Work In Progress	2/11/2016 7:38:06 AV	I			
Solis, Lore	nzo	Need some assistance on trouble shooting mini split unit in room # 108 at pre k.				
Arturo Nun	ez					
151238		4/12/2016		50		\$0.00
Medium	Work In Progress	4/12/2016 3:48:48 PM	1			
Vallejo, Alb	ert	Need to replace or repair Hi. Delta water heater, making loud popping sound.				
Arturo Nun	ez					
152721		5/5/2016		27		\$0.00
Medium	Work In Progress	5/5/2016 4:00:15 PM	1			
Gonzalez, I	Maritza	MILK COOLER IS OVER 48 DEGREES.SNP MANAGER LORENA B. 882.3507				
	nzalez					

WOID Priority Assigned	Building Status	Area Number Description	i/30/2016 Order By Loc Deferred By Reason	Until Reque		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester		Description				Action Taken			
Location:	Anthony	ES							
154049				5/	31/2016		1		\$0.00
Medium	Work In Progress			5/31/2016 12:5		1	'		Ψ0.00
	_		50 M (II M (4.43 AW	I			
Apodaca, I	Wario	to PMschedule	ony ES - Monthly Mete e details .	er Readings - Refer					
Margret Vil	lalobos								
151065				4/	10/2016	4/26/2016	52		\$0.00
Medium	Work In Progress			4/10/2016 12:3	2:26 AM	1			
Nunez, Art	uro	Monthly - Antho to PMschedule	ony ES Monthly Playg e details.	round Insp Refer					
Margret Vil	lalobos								
152801				5	/8/2016	5/24/2016	24		\$0.00
Medium	Work In Progress			5/8/2016 12:3	1:47 AM	1			
Nunez, Art	uro	Monthly - Antho to PMschedule	ony ES Monthly Playg e details.	round Insp Refer					
Margret Vil	lalobos								
152795				5	/7/2016		25		\$0.00
Medium	Work In Progress			5/7/2016 12:2	7:42 AM	1			
Nunez, Art	uro	Daily - Anthony schedule detai	ES - Fire Pump (Biv ls.	veekly) - Refer to PM					
Margret Vil	lalobos				/				
153653					22/2016		10		\$0.00
Medium	Work In Progress			5/22/2016 12:3	0:31 AM	1			
Nunez, Art		Daily - Anthony schedule detai	ES - Fire Pump (Biv ls.	reekly) - Refer to PM					
Margret Vil	lalobos					7/2/2010			
152333					/1/2016		31		\$0.00
Medium	Work In Progress			5/1/2016 1:0	4:47 AM	1			
Nunez, Art	uro	Monthly - Antho to PMschedule	ony ES Emer. Light T e details.	est: Monthly - Refer					
Margret Vil	lalobos								
150548				4	/3/2016	4/11/2016	59		\$0.00
Medium	Work In Progress			4/3/2016 12:4	3:51 AM	1			
Nunez, Art	uro	Monthly - Antho to PMschedule	ony ES Emer. Light T e details.	est: Monthly - Refer					
Margret Vil	lalobos								

6/1/2016 11:47:06 AM Page 11 of 174

WOID Priority	Building Status	Area Area Number	/30/2016 Order By Loc Deferred By Reason	Until	=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Assigned Requester		Description				Action Taken			
Location:	Anthony	FS							
	Anthony				4/3/2016	4/11/2016	59		\$0.00
150549	\\/			4/0/00			39		φυ.υυ
Medium	Work In Progress				16 12:43:52 AN	1			
Nunez, Art	uro	Monthly - Antho PMschedule d	ony ES Exit Sign Insp etails.	p: Monthly - Re	efer to				
Margret Vil	lalobos								
152287					5/1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress			5/1/2	016 1:03:25 AN	1			
Vallejo, Alb	pert	Monthly - Antho PMschedule d	ony ES Fire Suppres etails.	sion Insp R	efer to				
Margret Vil	lalobos								
152266					5/1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress			5/1/2	016 1:03:09 AN	1			
Orozco, Da	nniel	Monthly - Antho PMschedule d	ony ES Range Hood etails.	Cleaning - R	efer to				
Margret Vil	lalobos								
154028					5/31/2016	7/1/2016	1		\$0.00
Medium	Work In Progress			5/31/20	16 12:54:28 AN	1			
Nunez, Art	uro	Yearly - Anthon PMschedule d	y ES A2 (Split Syste etails.	m)(Yearly) - R	defer to				
Margret Vil	lalobos								
148986					3/6/2016		87		\$0.00
Medium	Work In Progress			3/6/20	16 12:40:41 AN	1			
Nunez, Art	uro	Yearly - Anthon to PMschedule	y ES A10(Heat Pum edetails.	nps)(Yearly) -	Refer				
Margret Vil	lalobos								
148987					3/6/2016	4/6/2016	87		\$0.00
Medium	Work In Progress			3/6/20	16 12:40:42 AN	1			
Nunez, Art	uro	Yearly - Anthon PMschedule d	y ES R3 (Ref. Unit)(etails.	(Yearly) - Refe	r to				
Margret Vil	lalobos								
150238					3/31/2016	5/1/2016	62		\$0.00
Medium	Work In Progress			3/31/20	16 12:45:57 AN	1			
Nunez, Art	uro	Yearly - Anthon PMschedule d	y ES A8(Rooftop Un etails.	nit)(Yearly) - R	efer to				
Margret Vil	lalobos								

6/1/2016 11:47:06 AM Page 12 of 174

WOID Priority Assigned ⁻ Requester		Area Area Number Description	Deferred By Reason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Anthony	ES						
150239				3/31/2016		62		\$0.00
Medium	Work In Progress			3/31/2016 12:45:58 AM				
Nunez, Art	uro	Yearly - Anthon PMschedule d		nit)(Yearly) - Refer to				
Margret Vil	lalobos							
150461				4/3/2016	5/4/2016	59		\$0.00
Medium	Work In Progress			4/3/2016 12:42:46 AM				
Nunez, Arti	uro	Yearly - Anthon Refer to PMsch	y ES A13 (AC Wall I nedule details.	Mount)(Yearly) -				
Margret Vil	lalobos							
150316				3/31/2016		62		\$0.00
Medium	Work In Progress			3/31/2016 11:40:53 AM				
Chavez, Sa	antos	are secure. Su	at electrical pole and oplypower to Morga permanent manner.					
Albert Valle	ejo							
153957				5/26/2016		6		\$0.00
Medium	Work In Progress			5/26/2016 2:24:23 PM				
Hernande	z, Guillemo	Old Main Bldg (conference roo	Cafeteria - Install AC m	controls in large				
Alfredo Ho	lguin							
153904				5/25/2016		7		\$0.00
Medium	Work In Progress	Room 102		5/25/2016 1:33:33 PM				
Nunez, Artı	uro	room. Since w	oom 102 as a trainin e have several traini omeone remove sor	ngs in that room we				
Susie Ran	nos Lara							
153905				5/25/2016		7		\$0.00
Medium	Work In Progress	Room 111		5/25/2016 1:35:28 PM	l			
Nunez, Art	uro	department. W needed for the paint this area	se 3 staff members. and remove the chal e send someone to	ging the work space We also need to kboards that are on help us				

6/1/2016 11:47:06 AM Page 13 of 174

1141 - Work Orders In Progress (Fiscal Year)

	Building Status o	Area Number	Deferred By	•	Target Comp Date	Days	Labor	
			Reason	Created Date/Time	Actual Comp Date	Aged	Hours	
		Description	Reason	Or Gatou Bato, Time	Action Taken			
Requester I	Name	•						
Location:	Anthony I	ES						
144956				12/14/2015	5	170		\$0.00
Medium	Work In Progress	261		12/14/2015 11:39:1	5			
Chavez, Sar	ntos	Please replace	light bulb in room #2	61 V. Ramos				
Jessica Lop	oez							
148198				2/23/2016	3	99		\$0.00
Medium	Work In Progress			2/23/2016 8:05:39 Al	М			
Chavez, Sar	ntos	Need to have el Alamo restroon	ectricity connected to	wall heaters on				
Arturo Nune	Z.							
153629				5/20/2016	3	12		\$0.00
Medium	Work In Progress			5/20/2016 3:45:18 P	M			
Ontiveros, J	oe		culating pump for boi I # 185-101, 115 V.					
Arturo Nune	Z							
143685				11/16/2015	5	198		\$0.00
Medium	Work In Progress			11/16/2015 4:19:44 PI	М			
Marquez, Ge	erardo	Please cut extr	a keys for Alamo Ca	feteria.				
Albert Vallej	0							
153562				5/20/2016	3	12		\$0.00
Medium	Work In Progress			5/20/2016 7:49:46 Al	M			
Marquez, G	erardo	CHECK ALL D	RS. FOR PROPER C	PERATION.				
Gerardo Ma	rquez							
148883				3/3/2016	3	90		\$0.00
Medium	Work In Progress			3/3/2016 3:47:23 P	M			
Ontiveros, G	Guadalupe	Need to borrow areas.	boom sprayer for ga	tor, to spraylarge				
Arturo Nune	Z							
149442				3/10/2016	3	83		\$0.00
Medium	Work In Progress			3/10/2016 3:54:05 P	М			
Flores, Pete	•	Vehicle 55 nee	ds to be serviced. T	hank you.				
Susie Ram	os Lara							
136796				7/30/2015	5	71		\$0.00
Medium	Work In Progress			7/30/2015 3:53:27 P	M 10/9/2015			
Holguin, Alfr	redo		fire sprinkler connec Iking prettybad.	tion repaired in	will fax to dimar for	quote as	per alfred	0
Arturo Nune	Z		J. ,					

6/1/2016 11:47:06 AM Page 14 of 174

WOID Priority Assigned Requester		Area Area Number Description	Deferred By		arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Anthony	ES						
136827				7/31/2015		306		\$0.00
Medium	Work In Progress	107		7/31/2015 9:04:38 AM				
Nunez, Art	uro		nite board to a differ GibsonRoom #107	entlocation				
Jessica Lo	opez							
153486				5/19/2016		13		\$0.00
Medium	Work In Progress			5/19/2016 10:35:36 AM				
Gonzalez,	Salvador	repair gate doo	at alamo parking lo	t				
David Veg	a							
146128				1/13/2016		140		\$0.00
Medium	Work In Progress			1/13/2016 8:14:42 AM				
Nunez, Art	· ·		ane Zone sensors † 90842-01 Rev. A (\$					
Arturo Nur	nez							
151255				4/12/2016		50		\$0.00
Medium	Work In Progress	Room 120 Spe	t	4/12/2016 4:13:19 PM				
Nunez, Art	uro		echnician to secure Sped Department b	4 files on the wall in uilding.				
Susie Ran	nos Lara							
150006				3/22/2016		71		\$0.00
Medium	Work In Progress			3/22/2016 3:34:01 PM				
Nunez, Art	uro		ght fixtures in class s a lot of bulbs out, s					
Arturo Nur	nez							
148158	Cafeteria	Kitchen		2/22/2016		100		\$0.00
Medium	Work In Progress			2/22/2016 3:23:45 PM				
Nunez, Art	uro		ss steel work table Manager Lorena B		eroute to Art			
Dino Facio)							
139297		Office		9/3/2015		272		\$0.00
Medium	Work In Progress			9/3/2015 1:41:36 PM				
Nunez, Art	uro		meone come in an s in the SPED ADM					
Susie Ran	nos Lara							
Count: 43	Work Orders	A	/g. Age of WO's 6	6	Total for Anthor	y ES	0	\$0.00

6/1/2016 11:47:06 AM Page 15 of 174

WOID Priority Assigned 1 Requester		Area Area Number Description	Deferred By	Until Request Date	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Berino ES	3						
153250				5/16/2016	3	16		\$0.00
Medium	Work In Progress			5/16/2016 10:15:20 AM	M			
Diaz, Seba	stian	WALKIN NEED STATING THE	ARD-FLOOR TO BAG TO BE CHECKED. HAVE TO LIFT CAF MANGER SUSANA	SNP MANAGER RTS TO TAKE IN				
Maritza Go	nzalez							
141139				10/6/2015	5	239		\$0.00
Medium	Work In Progress			10/6/2015 3:19:29 PM	M			
Gonzalez,	Salvador	Need to install	metal ramp on porta	ble 18 thank you				
Sebastian	Diaz							
152577		Kitchen		5/4/2016	3	28		\$0.00
High	Work In Progress			5/4/2016 7:39:45 AM	М			
Solis, Lore	en <i>z</i> o		ot working (gas sme a (575) 882-2417	II) SNP Manager				
Dino Facio)							
152447		Kitchen		5/2/2016	3	30		\$0.00
High	Work In Progress			5/2/2016 1:08:03 PM	M			
Ontiveros,	Joe		t Sink not holding wa a (575) 882-2417	ater. SNP Manager				
Dino Facio)							
148528		Kitchen		2/26/2016	3	96		\$0.00
High	Work In Progress			2/26/2016 3:24:38 PM	M			
Orozco, Da	niel		NOT ABLE TO USE R SUSANA HERREF					
Dino Facio)							
150750				4/5/2016	3	57		\$0.00
Medium	Work In Progress			4/5/2016 10:19:05 AM	М			
Orozco, Da	niel		OUBLED DOOR RE OR 5 EA (21' X 26') 2.2417	_				
Maritza Go	nzalez							
147583				2/8/2016	3	114		\$0.00
Medium	Work In Progress			2/8/2016 3:31:12 PM	М			
Gonzalez,	Salvador	need to secure	new heater on por	table 18 DP thank you				
Sebastian			·	•				

6/1/2016 11:47:06 AM Page 16 of 174

WOID Priority Assigned T Requester	Building Status o	Area Number Reason Description	Until Request Date Target Comp Date Created Date/Time Actual Comp Date Action Taken	e Aged	Labor Hours	Costs
Location:	Berino ES					
148076			2/19/2016	103		\$0.00
Medium	Work In Progress		2/19/2016 3:42:43 PM			
Gonzalez, S	Salvador	Need frame A/C on portable 18 DF	thank you			
Sebastian	Diaz					
153229			5/16/2016	16		\$0.00
Medium	Work In Progress		5/16/2016 8:48:16 AM			
Flores, Pet	e	John Deere Need service MODEL 3TNV82A- KJMZ SERIAL CH3013D222619 DM997SC021632 997 Z TRAK BERINO TAG 0401	10WER			
Sebastian	Diaz					
153233			5/16/2016	16		\$0.00
Medium	Work In Progress		5/16/2016 8:53:03 AM			
Flores, Pet	Э	Need Service On Kubota model RTV-X900G-A SERIAL 32095 TAG 0529				
Sebastian	Diaz					
153565			5/20/2016	12		\$0.00
Medium	Work In Progress		5/20/2016 7:53:48 AM			
Marquez, G	erardo	CHECK DRS. FOR PROPER OPE	RATION.			
Gerardo Ma	arquez					
144663			12/8/2015	176		\$0.00
Medium	Work In Progress		12/8/2015 3:04:59 PM			
Ontiveros,	Joe	Need to check boiler domestic water you	er not turn on thank			
Sebastian	Diaz					
143637			11/16/2015	198		\$0.00
Medium	Work In Progress		11/16/2015 1:41:51 PM			
Ontiveros,	Joe	Need check leak water on boiler pip	es thank you			
Sebastian	Diaz					
149302			3/9/2016	84		\$0.00
Medium	Work In Progress		3/9/2016 9:05:30 AM			
Ontiveros,	loe	Need to check washer on room 113	thankyou			
Sebastian	Diaz					

6/1/2016 11:47:06 AM Page 17 of 174

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Locat Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Berino ES						
147395			2/4/2016		118		\$0.00
Medium	Work In Progress		2/4/2016 9:07:08 AM				
Ontiveros,	Joe	Need to check water heater on portabl not hot water thank you	e 156				
Sebastian	Diaz						
147588			2/8/2016		114		\$0.00
Medium	Work In Progress		2/8/2016 3:33:36 PM	l			
Ontiveros,	Joe	SINK FAUCETS LEAKING. SNP MAN. MERCEDES F. 882.2417	AGER	reroute to Joe			
Maritza Go	nzalez						
151502			4/18/2016		44		\$0.00
Safety	Work In Progress		4/18/2016 8:15:22 AM				
Ontiveros,	Joe	Need to ck on gas odor.					
Albert Valle	ejo						
148073			2/19/2016		103		\$0.00
Medium	Work In Progress		2/19/2016 3:40:47 PM				
Chavez, Sa	antos	Need to connect A/C on portable 18 [OP thank you				
Sebastian	Diaz						
148529			2/26/2016		96		\$0.00
Medium	Work In Progress		2/26/2016 3:29:14 PM	l			
Chavez, Sa	antos	Need to fix outlet on room 107 thank	you				
Sebastian	Diaz						
146611			1/22/2016		131		\$0.00
Medium	Work In Progress		1/22/2016 3:41:30 PM	I			
Chavez, Sa	antos	Need to fix emergency lights on hall t	hank you				
Sebastian	Diaz						
140256			9/18/2015		257		\$0.00
Medium	Work In Progress		9/18/2015 3:36:56 PM	I			
Chavez, Sa	antos	need to fix light on room 10 thank you	J				
Sebastian							
139814			9/11/2015		264		\$0.00
Medium	Work In Progress		9/11/2015 2:31:31 PM	l			
Chavez, Sa	_	Need to install power for smart board you	on room 101 thank				
Sebastian	Diaz	7					

6/1/2016 11:47:06 AM Page 18 of 174

e Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location Building Area Deferred By Un Status Area Number Reason Description Name	ntil Request Date Ta Created Date/Time Ac		Days Aged	Labor Hours	Costs
Berino ES					
	5/16/2016		16		\$0.00
Work In Progress	5/16/2016 9:30:19 AM				
ntos On the room 108 Need power for smarth	ooard thank you				
Diaz					
	5/11/2016		21		\$0.00
Work In Progress	5/11/2016 9:42:12 AM				
stian Need to paint crossing lines on parking l	ot				
Diaz					
	5/11/2016		21		\$0.00
Work In Progress	5/11/2016 9:47:25 AM				
stian Need to paint some class room					
Diaz					
	5/31/2016	7/1/2016	1		\$0.00
Work In Progress	5/31/2016 12:54:26 AM				
Yearly - Berino ES A2 (Split System)(Ye PMschedule details.	arly) - Refer to				
alobos					
	5/1/2016	5/22/2016	31		\$0.00
Work In Progress	5/1/2016 1:03:10 AM				
niel Monthly - Berino ES Range Hood Clean PMschedule details.	ning - Refer to				
alobos	5/4/2040	5/00/0040	04		Ф0.00
	5/1/2016	5/22/2016	31		\$0.00
Work In Progress	5/1/2016 1:03:26 AM				
ert Monthly - Berino ES Fire Suppression Ir PMschedule details.	nsp Refer to				
alobos	5/31/2016		1		\$0.00
World by Day and a			ı		φυ.υυ
Work In Progress	5/31/2016 12:54:44 AM				
fario Monthly - Berino ES - Monthly Meter Rea PMschedule details.	adings - Refer to				
alobos					
Kitchen	5/2/2016		30		\$0.00
Work In Progress	5/2/2016 7:41:50 AM				
•	ess Walk In Freezer at 65° and Freezer at 30		Walk In Freezer at 65° and Freezer at 30° SNP	Walk In Freezer at 65° and Freezer at 30° SNP	Walk In Freezer at 65° and Freezer at 30° SNP

6/1/2016 11:47:06 AM Page 19 of 174

Selected Da WOID	ate Range for Request Building	Dates:7/1/2015 - 6/30/2016 Order By Area Deferred By	Location, Status Until Request Date Ta			Costs
Priority	Status	Area Number Reason	Created Date/Time Ac	tual Comp Date Aged	Hours	
Assigned	То	Description		Action Taken		
Requeste	r Name					
Location:	Berino E	3				
139809			9/11/2015	264		\$0.00
Medium	Work In Progress		9/11/2015 12:58:12 PM			
Solis, Lore	enzo	Need to fix water fountain on roo	om 121 thank you			
Sebastian	n Diaz					
145973	Main Building	Custodial	1/11/2016	142		\$0.00
Medium	Work In Progress		1/11/2016 9:12:09 AM			
Carbajal,	Jimmy	vaccum cleanersmoking#do5a	00005374			
Francisco	Marin	-				
149394	Main Building	Custodial	3/10/2016	83		\$0.00
Medium	Work In Progress		3/10/2016 11:52:48 AM			
Ronquillo	, Ruben	need to order new letters for mark principal	kie requested by			
Francisco	Marin					
152972		Custodial	5/11/2016	21		\$0.00
Medium	Work In Progress		5/11/2016 9:47:52 AM			
Villalobos	, Jose	if you can send me a couple of cli to keep them on	ps for the vacuum tires			
Francisco						
151306	Main Building	Pump House	4/13/2016	49		\$0.00
Medium	Work In Progress		4/13/2016 2:37:28 PM			
Chavez, S	antos	the new water solenoid valve for t need to be wired up .	the irrigation system			
Mario Apo	daca					
152436			5/2/2016	30		\$0.00
Medium	Work In Progress	UV-BE-0529	5/2/2016 9:47:25 AM			
Villalobos	, Jose	Need to service Kubota UV-BE-0	0529. Thank You			
Sebastiar	n Diaz					
Count: 36	Work Orders	Avg. Age of WO's	85	Total for Berino ES	0	\$0.00

6/1/2016 11:47:06 AM Page 20 of 174

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs Building WOID Area Until **Request Date Target Comp Date Davs** Labor **Deferred By** Aged Hours Area Number Reason Status Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description Requester Name Chaparral ES Location: 153725 5/23/2016 9 \$0.00 Medium Work In Progress 5/23/2016 3:51:22 PM Caliper Construction Chavez, Santos Company. Main Contact Phone: (575) 635-8919 Address: PO Box 1719 City, St, Zip: Las Cruces, NM88004 Main Contact Email: blanca@caliperconst.com CompanyPhone: (575) 524-3924 Main Contact: Fernie Reyes Spotting Instructions Locate Per the work Plan Dominique Esparza 4/11/2016 51 \$0.00 151161 Medium Work In Progress 4/11/2016 4:11:26 PM Quinones, Paul 4-11-16 .5,chk e-mail/get materials 2.0,chk server no cooling locate problem send w/0.@chm 2.0,150559-c 1.0,150529-c 1.0,150456-c 1.0,150475-c .5, meeting with contractors total hrs.3.0 Paul Quinones 149393 3/10/2016 83 \$0.00 3/10/2016 11:45:20 AM Medium Work In Progress Quinones, Paul replace media pads mastercool evap.coolers, requesting new pads **Paul Quinones** 152813 5/8/2016 5/24/2016 24 \$0.00 5/8/2016 12:31:55 AM Medium Work In Progress Quinones, Paul Monthly - Chaparral ES Playground Insp - Refer to PM schedule details. Margret Villalobos 154086 Concession Classroom 5/31/2016 \$0.00 Medium Work In Progress bins 5/31/2016 2:05:47 PM Marquez, Gerardo need 3 locks for bins located outside. Need these containers to stavclosed as they hold teacher books. smartboards, etc... see Danny custodian Jennifer Corral

6/1/2016 11:47:06 AM Page 21 of 174

WOID Priority Assigned		Area Number Description	Deferred By	Until	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester		LEC							
Location:	Chaparra	1 E3			-///	-//			
152289					5/1/2016		31		\$0.00
Medium	Work In Progress			5/1/2	2016 1:03:27 AN	1			
Vallejo, All	pert	Monthly-Chap to PMschedule	arral ES Fire Suppre details.	ession Insp	Refer				
Margret Vil	llalobos								
152268					5/1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress			5/1/2	2016 1:03:11 AN	1			
Orozco, Da	aniel	Monthly-Chap to PMschedule	paral ES Range Ho details.	od Cleaning -	Refer				
Margret Vil	llalobos								
145308					1/3/2016	2/3/2016	150		\$0.00
Medium	Work In Progress			1/3/20	016 12:43:18 AM	1			
Quinones	, Paul	Yearly - Chapa schedule detail	rral ES Backflow In: s.	spection - Re	fer to PM				
Margret Vil	llalobos								
151923					4/25/2016		37		\$0.00
Medium	Work In Progress			4/25/2	2016 3:30:32 PN	Л			
Quinones	, Paul	white paint chm	restrms.need pair	nting					
Paul Quine	ones								
151035					4/8/2016		54		\$0.00
Medium	Work In Progress			4/8/2	2016 4:15:37 PN	Л			
Solis, Lore	enzo		taylor drinking fount						
Paul Quine	ones	,,	•						
151111					4/11/2016		51		\$0.00
Medium	Work In Progress			4/11/2	2016 1:39:29 PN	Л			
Ontiveros,	Guadalupe	open areas and	concha he needs th d fence lines @ che eds s chool dude co	and dte for w	eed				
Paul Quine	ones								
154004					5/27/2016		5		\$0.00
Medium	Work In Progress			5/27/2	2016 2:15:46 PN	Л			
Chavez, Sa	antos		ice to comply with N puter lab at old PE b						
Albert Valle	ejo			3 (,				

6/1/2016 11:47:06 AM Page 22 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da	ate Range for Request Building	Dates:7/1/2015 - 6	6/30/2016 Order By Loca Deferred By	ition, Status Until	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•		=	Actual Comp Date	Aged	Hours	
Assigned		Description				Action Taken			
Requeste		-							
Location:	Chaparra	al ES							
148444					2/25/2016		97		\$0.00
Medium	Work In Progress			2/25/20	016 3:38:05 PN	Л			
Chavez, S	antos	powersource	for wall heater rm.501						
Paul Quin	ones								
153691	Main Building	Hallway/Corric	dor		5/23/2016		9		\$0.00
Medium	Work In Progress	202/hallway		5/23/20	016 1:25:10 PN	Л			
Chavez, S	antos		outlets for the copiers nnot plug in. need one illway.						
Jennifer C	Corral								
153573					5/20/2016		12		\$0.00
Medium	Work In Progress			5/20/20	016 8:07:22 AN	1			
Marquez,	Gerardo	CHECK DRS.	FOR PROPER OPER	ATION.					
Gerardo N	<i>l</i> arquez								
145069	Main Building	Hallway/Corrid	dor		12/15/2015		169		\$0.00
Medium	Work In Progress	school hallway	s	12/15/20	015 3:11:54 PM	1			
Quinones	, Paul		ut up pennants throug on as possible. See N		or Ms.				
Jennifer C	Corral								
152594	Main Building	Office			5/4/2016		28		\$0.00
Medium	Work In Progress	office, nurse		5/4/20	16 10:36:21 AN	1			
Quinones	, Paul	will go to Favel Principal, and	moved to following cla a Room 202, Principal Counselor will go to Ho conquillo room 201.	, Assistant					
Jennifer C	Corral								
153503	Main Building	Office			5/19/2016		13		\$0.00
Medium	Work In Progress	office		5/19/20	016 1:02:36 PN	Л			
Quinones			noved from data clerk ssible. See Jennifer	room to nev	v office.				
Jennifer C		1.05			E /4.0 /0.04.0		4.4		# 0.00
153408	Main Building	Library		E 14.0 10.	5/18/2016		14		\$0.00
Medium	Work In Progress	101		5/18/20	016 9:29:52 AN	/ I			
Quinones	, Paul	take t.v.'s off ca	stration Paul needs to l arts, Racks out library, removed asap becau	and wall mo	ount for				
Jennifer C	Corral								

6/1/2016 11:47:06 AM Page 23 of 174

Assigned 1 Requester		Area Number	Reason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date	Days Aged	Labor Hours	
Requester		Description			Action Taken			
	Name							
Location:	Chaparra	IES						
154072				5/31/2016		1		\$0.00
Medium	Work In Progress			5/31/2016 12:14:47 PM				
Quinones,	Paul	Need to move t the new front of	he signage at CHE t fice location?	o direct parents to				
Albert Valle	ejo							
144018				11/30/2015		184		\$0.00
Medium	Work In Progress			11/30/2015 12:47:38				
Marquez, G	Gerardo		ndicap door closer do ple requesting door					
Paul Quind	ones							
153662				5/23/2016		9		\$0.00
Medium	Work In Progress			5/23/2016 8:17:35 AM	I			
Marquez, G	Serardo	_	OVE DOOR HARD TO USE AT OTHER	WARE THAT CAN R SCHOOOL SITES.				
Gerardo M	arquez							
153773				5/24/2016		8		\$0.00
Medium	Work In Progress	room 212		5/24/2016 8:46:33 AM	I			
Gonzales,	Camilo	moved from Ch and brought to Please note all COMPLEX CAR	al items of furniture naparral Elementary the SPED COMPLE items needing to be ETERIA ARE LABE	School room #212 EX CAFETERIA. Borought to the SPED LED. ATTACHED				
Susie Ram	nos Lara							
154132	Main Building	Office		6/1/2016		0		\$0.00
Medium	Work In Progress	201		6/1/2016 8:28:25 AM	I			
Marquez, G	Gerardo		to fix restroom door and does not close.	in the office area. The see administration				
Jennifer C	orral							
146526				1/21/2016		132		\$0.00
Medium	Work In Progress			1/21/2016 3:32:39 PM	1			
Quinones,	Paul		e metal bath rm. met or hinges reorder ha					

6/1/2016 11:47:06 AM Page 24 of 174

Paul Quinones

			5/30/2016 Order By Loc Deferred By	•	Target Comp Date	Days	Labor	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Aged	Hours	
Assigned '	То	Description			Action Taken			
Requester	· Name							
Location:	Chaparra	I ES						
146831				1/27/2016		126		\$0.00
Medium	Work In Progress			1/27/2016 10:28:26 AM				
Quinones	, Paul	Need 3 surveill	ance signs.					
Paul Quin	ones							
153016				5/11/2016		21		\$0.00
Medium	Work In Progress			5/11/2016 3:41:48 PM				
Quinones	, Paul	windowscreer screening	n and spline needed	o replace old				
Paul Quin	ones							
152982				5/11/2016		21		\$0.00
Medium	Work In Progress			5/11/2016 10:50:51 AM				
Quinones	, Paul	blinds for porta	bles 1and 2 @ chm					
Paul Quin	ones							
Count: 28	Work Orders	Δ	vg. Age of WO's 4)	Total for Chaparra	al ES	0	\$0.00

6/1/2016 11:47:06 AM Page 25 of 174

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Area Number Reason Created Date/Time Actual Comp Date **Priority Status Assigned To Description Action Taken** Requester Name Location: Chaparral High - Pre-K 151006 Classroom 4/8/2016 54 \$0.00 Medium Work In Progress 4/8/2016 3:27:54 PM Ortiz, Alfredo Need to assemble four Community Lofts at Pre-K. Also some furniture. Alfredo Ortiz Count: 1 Work Orders Avg. Age of WO's 54 Total for Chaparral High - Pre-K 0 \$0.00

6/1/2016 11:47:06 AM Page 26 of 174

1141 - Work Orders In Progress (Fiscal Year)

WOID Priority Assigned 1 Requester Location:		Area Number Description	Deferred By Reason		Target Comp Date Actual Comp Date	Days Aged	Labor Hours	
Assigned 1 Requester	o Name		Reason	Grouted Bate, Time	-			
Requester	Name				Action Taken			
Location:	Chaparra							
		I HS						
153052		Classroom		5/12/2016	<u> </u>	20		\$0.00
Medium	Work In Progress			5/12/2016 8:27:51 AN	Л			
Ortiz, Alfred	lo		everal Classrooms r Summer Break Pro					
Alfredo Ort	z							
154138	G-Wing	Classroom		6/1/2016		0		\$0.00
Medium	Work In Progress	G7		6/1/2016 8:59:34 AN	Л			
Ortiz, Alfred	lo	Wall need fres	h coat of paint, very	dull. (Ms. Davis, G7)				
Mireya Mez	a							
152995		Parking Lot		5/11/2016		21		\$0.00
Medium	Work In Progress			5/11/2016 2:05:44 PM	И			
Ortiz, Alfred	lo	Need to paint li	nes on parking lot fo	or summer Project.				
Alfredo Orti	Z							
151593	Q-Wing			4/19/2016		43		\$0.00
Medium	Work In Progress	Q2		4/19/2016 9:32:00 AN	Л			
Chavez, Sa	antos	Move and conn (Ms. Cordova,		opneumaticsystem.				
Mireya Mez	a							
145122				12/16/2015		168		\$0.00
Medium	Work In Progress			12/16/2015 8:40:49 AN	Л			
Chavez, Sa	antos	storage and an	roundskeeper, nee inside light at least enance.equipment edo Olguin or to who	thank you				
Pedro Vald	ez							
146844		Athletic Field		1/27/2016	i	126		\$0.00
Medium	Work In Progress			1/27/2016 2:15:45 PM	M			
Holguin, Al	fredo	Football field A cleaning service		n SportChamp deep				
Alfredo Ho	guin							
151662		Athletic Field		4/20/2016	i	42		\$0.00
Medium	Work In Progress			4/20/2016 7:49:31 AN	Л			
Vallejo, Alb	ert		idewalks have crac	come and do a Safety ks and holes that				
Alfredo Ort	Z	•						

6/1/2016 11:47:06 AM Page 27 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da	te Range for Request Building	Dates:7/1/2015 - 6 Area	5/30/2016 Order By Loc	cation, Status Until	Poguest Date	Target Comp Date	Dave	Labor	Tota Costs
Priority	Status	Area Number	Deferred By		=	Actual Comp Date	Days Aged	Hours	
Assigned [·]		Description	reason	0.00	2010/11110	Action Taken			
Requester		•							
Location:	Chaparra	al HS							
139387					9/4/2015		271		\$0.00
Medium	Work In Progress			9/4/2	.015 3:16:11 PN	Л			
Ontiveros,	Guadalupe	parking lot by th maintenance l	e shrubberyin plante ne amphitheater and andscaping. (Primar genous flora) See Ms estion)	replace with by screening, by	low ooulders				
Albert Valle	ejo								
149795	A-Wing	Foyer			3/17/2016		76		\$0.00
Medium	Work In Progress	Amphitheater		3/17/2	.016 8:48:27 AN	1			
Valdez, Pe		amphetheater The ones there	e all landscaping on t near nurse's office, e are all dried up (dea r foliage. (Sofia Paye	with new bus ld) and are no	hes.	Reroute to Grounds	3/21/16		
Mireya Me	za					2 (2 (2 2 2 2			•
145329					1/3/2016	2/3/2016	150		\$0.00
Medium	Work In Progress			1/3/20	16 12:43:35 AN	Л			
Ortiz, Alfre	do	Yearly - Chapa PMschedule d	rral HS Backflow Ins etails.	spection - Ref	fer to				
Margret Vil	lalobos								
154027					5/31/2016	7/1/2016	1		\$0.00
Medium	Work In Progress			5/31/20	16 12:54:27 AN	Л			
Ortiz, Alfre	do	Yearly - Chapa PMschedule d	rral HS A2 (H/C Unit etails.	(Yearly) - Re	fer to				
Margret Vil	lalobos								
152264					5/1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress			5/1/2	:016 1:03:08 AN	1			
Orozco, Da	aniel	Monthly-Chap PMscheduled	arral HS Range Hoo etails.	d Cleaning - F	Referto				
Margret Vil	lalobos								
152307					5/1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress			5/1/2	:016 1:03:48 AN	Л			
Orozco, Da	aniel	Monthly-Chap to PMschedule	arral HS Fire Suppre e details.	ssion Insp	Refer				
Margret Vil	lalobos								
153655					5/22/2016		10		\$0.00
Medium	Work In Progress			5/22/20	16 12:30:32 AN	1			
Ortiz, Alfre	do	Daily - Chapar PMschedule d	ral HS - Fire Pump (l etails.	Biweekly) - R	efer to				
Margret Vil	lalobos								
6/1/2016 1	11·47·06 AM								00 of 174

6/1/2016 11:47:06 AM Page 28 of 174

Requester	Chaparra				Actual Comp Date Action Taken	Aged	Hours	
Location:	Gliabarra	I HS						
154136	I-Wing	Classroom		6/1/2016		0		\$0.00
Medium	Work In Progress	Band room		6/1/2016 8:56:14 AM		ŭ		Ψ0.00
Urquidi, Je	· ·		arpetin band room (m)					
Mireya Mez	za		,					
150916				4/7/2016		55		\$0.00
Medium	Work In Progress			4/7/2016 10:55:52 AM				
Villalobos,	, Jose	Auto scrubber i	s not keeping the ch	arge.				
Jesus Urq	ļuidi							
154149	A-Wing	Library		6/1/2016		0		\$0.00
Medium	Work In Progress	Library		6/1/2016 9:15:00 AM				
Urquidi, Je	esus	Carpet in librar DeVine, library		nd vacuumed. (Ms.				
Mireya Mez	za							
153490	I-Wing	Classroom		5/19/2016		13		\$0.00
Medium	Work In Progress	Band Room		5/19/2016 10:52:54 AM				
Urquidi, Je	esus	Please clean c (Mr. Rios, Band	arpet over the summ d)	ner in band room.				
Mireya Mez								
145840	Field House	Athletic Field		1/7/2016		146		\$0.00
Medium	Work In Progress	Softball		1/7/2016 4:06:58 PM				
Appelzolle	r, Fred		a water fountain/fauc ater. (coach Heddle					
Mireya Mez								
140161	Field House	Athletic Field		9/17/2015		258		\$0.00
Medium	Work In Progress	Football &		9/17/2015 2:20:24 PM				
·	Guadalupe		wind screens placed ccerfield areas. (Ms					
Mireya Mez		Add 4: F : 11		4 7 10040		1.40		Φο οο
145838	Field House	Athletic Field		1/7/2016		146		\$0.00
Medium	Work In Progress	softball field		1/7/2016 4:02:57 PM				
Ontiveros,	Guadalupe		n protect the girls fr	ts with winds creens or om the elements.				
Mireya Mez	za							

6/1/2016 11:47:06 AM Page 29 of 174

WOID Priority Assigned [:] Requester		Area Area Number Description	Deferred By Reason	Until Request Date 1 Created Date/Time	Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Chaparra	II HS						
152537	A-Wing			5/3/2016		29		\$0.00
Medium	Work In Progress			5/3/2016 3:33:19 PM				
Solis, Lore	nzo	We have a GEO fixed in pump ro		eak that needs to be				
Alfredo Ort	iz							
150308	Field House			3/31/2016		62		\$0.00
Medium	Work In Progress			3/31/2016 11:19:35 AM				
Solis, Lore	nzo	machine and th because of the i	e filling cabinet pa	Field house, the copy pers are getting ruined idity also she gets rigerated unit.				
Alfredo Ort	·-							
152584	A-Wing	Gym		5/4/2016		28		\$0.00
Medium	Work In Progress			5/4/2016 9:30:42 AM				
Solis, Lore	nzo	Ice machine at 0	Sym snack bar bro	ken needs repair.				
Alfredo Ort	iz							
153289		Hallway/Corrido	or	5/16/2016		16		\$0.00
Medium	Work In Progress			5/16/2016 3:49:46 PM				
Solis, Lore	nzo		mp Units leaking nes, can't close v					
Alfredo Ort	iz							
152833		Kitchen		5/9/2016		23		\$0.00
High	Work In Progress			5/9/2016 2:16:27 PM				
,		Refrigerator (sta Juanita M. (575)	and up) not cooling 824-4461	g. SNP Manager				
Dino Facio)			7/2/22/2				
152818		Kitchen		5/9/2016		23		\$0.00
High	Work In Progress			5/9/2016 7:38:20 AM				
,			SNP Manager Jua tion called out 5/0	nita M. (575) 824-4461 9/16 7:40am)				
Dino Facio)			4/40/00:0		40		Φο ο σ
151266		Gym		4/13/2016		49		\$0.00
Medium	Work In Progress			4/13/2016 7:49:19 AM				
Carbajal, J	immy	need gym floors	re varnished, Da	tes 5-23-16 to 6-3-16.				

6/1/2016 11:47:06 AM Page 30 of 174

1141 - Work Orders In Progress (Fiscal Year)

WOID Priority	Building Status		Deferred By				Labor	
		Area Number	Reason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date	Days Aged	Hours	
Assigned ⁻	Го	Description			Action Taken			
Requester	Name							
Location:	Chaparra	I HS						
152125	Field House	Roof		4/28/2016		34		\$0.00
Medium	Work In Progress			4/28/2016 8:07:11 AM	1			
Ortiz, Alfred	do	Need to replace	e bearing on several A	/C units				
Alfredo Ort	iz							
153215		Roof		5/16/2016		16		\$0.00
Medium	Work In Progress			5/16/2016 8:17:24 AM	1			
Ortiz, Alfred	do	Need to remove class rooms.	e sand from roof. San	d going in units and				
Alfredo Ort	iz							
147467		Athletic Field		2/5/2016		117		\$0.00
Medium	Work In Progress			2/5/2016 8:50:18 AM	1			
Ontiveros,	Guadalupe		a new gate on softball damaging batting cag					
Alfredo Ort	iz							
154145	Q-Wing	Classroom		6/1/2016		0		\$0.00
Medium	Work In Progress	Q7		6/1/2016 9:09:44 AM	1			
Carbajal, J	limmy	Tile floor is bro Rodriguez, Q7)	ken in classroom, ple)	ase repair. (Mr.				
Mireya Mez	za							
146864	H-Wing			1/27/2016		126		\$0.00
Medium	Work In Progress			1/27/2016 3:44:13 PM	1			
Carbajal, J	limmy		myCustodial Supervi o on the Hallwaytile ba		p.o. #151605703 -to	be compl	leted by C	ES
Alfredo Ort	iz							
144860	Q-Wing	Hallway/Corrid	lor	12/11/2015		173		\$0.00
Medium	Work In Progress			12/11/2015 9:41:19 AM	1			
Chavez, Sa	antos	Need to replace side light.	e burned out timer and	l contactor for out				
Alfredo Ort								
139947	Field House	Mechanical		9/14/2015		261		\$0.00
Medium	Work In Progress			9/14/2015 3:58:21 PM	1			
Chavez, Sa	antos	Buster pump for needs to check electrical power		reset every day,				
Alfredo Ort	iz							

6/1/2016 11:47:06 AM Page 31 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da	ite Range for Request Building	Dates:7/1/2015 - 6	3/30/2016 Order By Loc Deferred By	cation, Status Until	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•		=	Actual Comp Date	Aged	Hours	
Assigned		Description	reason	0.04	104 2410, 11110	Action Taken			
Requester									
Location:	Chaparra	al HS							
154141	A-Wing	Classroom			6/1/2016		0		\$0.00
Medium	Work In Progress	A-104		6/1/2	016 9:03:20 AN	1			
Chavez, S	antos		the wall on the left hat needs to be capp 4)						
Mireya Me									
154137	Q-Wing	Classroom			6/1/2016		0		\$0.00
Medium	Work In Progress	Q4		6/1/2	016 8:58:21 AN	1			
Chavez, S	antos	Need outlets for machine. (Mr.	r plasma cutter and l Lawler, Q4)	new TIG weld	ing				
Mireya Me									
137857	Field House	Athletic Field			8/12/2015		294		\$0.00
Medium	Work In Progress	Softball field		8/12/2	015 3:36:25 PN	1			
Chavez, S	antos	Need electricit (Mireya Meza)	yfor new softball/bas	eball batting	cage.				
Mireya Me	za								
146650	Q-Wing	Classroom			1/25/2016		128		\$0.00
Medium	Work In Progress			1/25/2	016 8:32:32 AN	1			
Chavez, S	antos	The hoist in the	welding shop won't ontact.	move up or do	own.				
Alfredo Or	tiz								
144639	H-Wing	Gym			12/8/2015		176		\$0.00
Medium	Work In Progress	Gym Training		12/8/20	15 10:00:34 AN	1			
Chavez, S	antos		ght bulbs are burned (Mrs. Walsh, gym tra		า				
Mireya Me	za								
148500	H-Wing	Gym			2/26/2016		96		\$0.00
Medium	Work In Progress			2/26/2	016 8:54:24 AN	1			
Chavez, S	antos		e switches for the ba m up and down sev						
Alfredo Or	tiz								
147256	Q-Wing	Classroom			2/2/2016		120		\$0.00
Medium	Work In Progress	Q4		2/2/20	16 11:00:06 AN	1			
Chavez, S	antos	I need two 220 Lawler, Q4)	female wall plugs ho	ooked up. (Mr.					
Mireya Me	za	, ,							

6/1/2016 11:47:06 AM Page 32 of 174

1141 - Work Orders In Progress (Fiscal Year)

WOID	Building	Area	:/30/2016 Order By Loc Deferred By	Until Request Date	Target Comp Date	Days Aged	Labor Hours	Costs
Priority Assigned	Status	Area Number	Reason	Created Date/Time	Actual Comp Date Action Taken	Agcu	Hours	
Requester		Description			Action Taken			
Location:	Chaparra	II HS						
137624	C-Wing	Classroom		8/10/2015	5	296		\$0.00
Medium	Work In Progress	Glassissin		8/10/2015 9:37:57 A		200		φυ.σσ
Chavez, Sa	•		ouse need to rewire of A/C. Thank you.		vi			
Alfredo Ort	iz							
154147	Q-Wing	Classroom		6/1/2016	3	0		\$0.00
Medium	Work In Progress	Q6		6/1/2016 9:12:50 Al	M			
Marquez, C	Gerardo		e key#1 to tool room break soon. (Mr. Roo					
Mireya Mez	za							
149741	A-Wing	Classroom		3/16/2016	3	77		\$0.00
Medium	Work In Progress	office		3/16/2016 3:20:02 P	M			
Marquez, C	Gerardo		keycopies of baseb T13 & #BT14. (Mirey					
Mireya Mez	za							
153576				5/20/2016	3	12		\$0.00
Medium	Work In Progress			5/20/2016 8:10:10 A	М			
Marquez, C	Serardo	CHECK DRS.	FOR PROPER OPER	RATION.				
Gerardo M	arquez							
142462	Field House	Athletic Field		10/28/2015	5	217		\$0.00
Medium	Work In Progress	Baseball Field		10/28/2015 9:32:29 Al	М			
Ontiveros,	Guadalupe	Install dug out odug outs.	made of cinder block. ich Rojas)	In visitor and home				
Mireya Mez	za							
153214		Mechanical		5/16/2016	6	16		\$0.00
Medium	Work In Progress			5/16/2016 8:13:03 Al	М			
Ortiz, Alfred	do		every Mechanical, El e light bulbs in those t					
Alfredo Ort	iz							
151665		Exterior		4/20/2016	3	42		\$0.00
Medium	Work In Progress			4/20/2016 8:00:41 Al	М			
Ortiz, Alfred	do	Need to replace	e several GFCI outle	t and covers.				
Alfredo Ort								

6/1/2016 11:47:06 AM Page 33 of 174

1141 - Work Orders In Progress (Fiscal Year)

WOID	Building	Area	5/30/2016 Order By Loca Deferred By	Until Request Date	Target Comp Date	Days	Labor Hours	Costs
Priority	Status -	Area Number	Reason	Created Date/Time	=	Aged	nours	
Assigned		Description			Action Taken			
Requeste								
Location:	Chaparra	al HS						
154139	A-Wing	Classroom		6/1/2016		0		\$0.00
Medium	Work In Progress	A-104		6/1/2016 9:00:59 AM	1			
Ortiz, Alfre	edo		vaya shortthree shelf It was left in room by A-104)					
Mireya Me	eza							
154140	A-Wing	Classroom		6/1/2016		0		\$0.00
Medium	Work In Progress	A-104		6/1/2016 9:02:11 AM	1			
Ortiz, Alfre	edo		vaya student desk tha . (Ms. S. Sanchez, A-					
Mireya Me	eza							
154142	F-Wing	Classroom		6/1/2016		0		\$0.00
Medium	Work In Progress	F5		6/1/2016 9:04:52 AM	1			
Ortiz, Alfre	edo	Please change	e air conditioner filter.	(Ms. Ortiz, F5)				
Mireya Me	eza							
154143	F-Wing	Classroom		6/1/2016		0		\$0.00
Medium	Work In Progress	F5		6/1/2016 9:06:15 AM	1			
Ortiz, Alfre	edo	Please fix wall Ortiz, F5)	by student computers	s, it has a hole. (Ms.				
Mireya Me	eza							
154146	Q-Wing	Classroom		6/1/2016		0		\$0.00
Medium	Work In Progress	Q6		6/1/2016 9:11:25 AM	1			
Ortiz, Alfre	edo		nole on wall between h and install door stoppe odriguez, Q6)					
Mireya Me								
143521	R-Wing	Classroom		11/12/2015		202		\$0.00
Medium	Work In Progress			11/12/2015 4:00:54 PM	1			
Orozco, D	aniel	replace gas va	ve ovens not working i lve. omics classroom.	need to fix or				
Alfredo Or	rtiz							
142460	Field House	Athletic Field		10/28/2015		217		\$0.00
Medium	Work In Progress	Baseball Field		10/28/2015 9:28:03 AM	1			
Gonzalez,	, Salvador	Please install (Coach Rojas)	4 mini batting cages fo	rbaseball field.				
Mireya Me	eza							

6/1/2016 11:47:06 AM Page 34 of 174

WOID	Building	Area Deferred By	y Until Request Date		Days Labor	
Priority	Status	Area Number Reason	Created Date/Time	Actual Comp Date	Aged Hours	
Assigned	То	Description		Action Taken		
Requeste	r Name					
Location:	Chaparra	il HS				
154144	Q-Wing	Classroom	6/1/2016		0	\$0.00
Medium	Work In Progress	Q7	6/1/2016 9:08:22 AV	I		
Marquez, (Gerardo	Replace broken inside door h (Mr. Rodriguez, Q7)	nandle on storage room.			
Mireya Me	za					
154150	F-Wing	Classroom	6/1/2016		0	\$0.00
Medium	Work In Progress	F6	6/1/2016 9:16:10 AM	I		
Marquez, (Gerardo	The door slams shut. The do (Mr. Ruiz, F6)	or arm needs adjusting.			
Mireya Me	za					
154148	F-Wing	Classroom	6/1/2016		0	\$0.00
Medium	Work In Progress	F1	6/1/2016 9:13:50 AM	I		
Quinones	, Paul	I have 1 broken student chai replaced. (Ms. M. Sanchez, F				
Mireya Me						
149793	Field House	Athletic Field	3/17/2016		76	\$0.00
Medium	Work In Progress	Soccerfield	3/17/2016 8:25:45 AV	I		
Ontiveros,	Guadalupe	Please replace the green scr Looking very torn up in differe				
Mireya Me						
153843	A-Wing	Office	5/24/2016		8	\$0.00
Medium	Work In Progress	Ms. Lopez	5/24/2016 11:37:37 AN	I		
Gonzales,	Camilo	Please pick up one box of caloffice. (Ms. Lopez)	culators from Ms. Lopez's			
	za					

6/1/2016 11:47:07 AM Page 35 of 174

WOID	Building	Area Number Beasen	-	Farget Comp Date	Days Aged	Labor Hours	
Priority	Status	Area Number Reason	Created Date/Time	Actual Comp Date Action Taken	Ageu	i loui 3	
Assigned ⁻ Requester		Description		Action Taken			
<u> </u>		LIMO					
Location:	Chaparra	II M2					
153163			5/13/2016		19		\$0.00
Medium	Work In Progress		5/13/2016 2:06:24 PM				
Quinones,	, Paul	Please remove partitions from nurafter flooring has been installed.	rses office and replace				
Albert Valle	<u>•</u>						
152535	Main Building	Classroom	5/3/2016		29		\$0.00
Medium	Work In Progress	205	5/3/2016 3:29:33 PM				
Quinones,	, Paul	difficulty closing door					
Gidget Mo	ra						
151762	Main Building	Classroom	4/21/2016		41		\$0.00
Medium	Work In Progress	409	4/21/2016 9:51:12 AM				
Quinones	, Paul	Teacher needs assistance for end Needs equipment cables, project sound. Teacher requesting Arnold	ors, screens and				
Gidget Mo	ra						
151764	Main Building	Classroom	4/21/2016		41		\$0.00
Medium	Work In Progress	303	4/21/2016 10:39:04 AM				
Quinones,	, Paul	Blue cabinet next to the sink has a	broken drawer.				
Gidget Mo	ra						
153791	Main Building	Classroom	5/24/2016		8		\$0.00
Medium	Work In Progress	303	5/24/2016 9:13:27 AM				
Quinones,	, Paul	Back of 3 chairs are either loose o	rdisjointed				
Gidget Mo			,				
152209	. •		4/29/2016		33		\$0.00
Medium	Work In Progress		4/29/2016 1:48:50 PM				
Quinones,	-	Nurse - Need to remove partition new flooring. Any ?'s please call A					
Albert Valle	ejo	, .					
138787	-		8/26/2015		280		\$0.00
Medium	Work In Progress		8/26/2015 3:04:42 PM				
Gonzalez,	Salvador	Need to make and install 4 sets of sections of Chaparral Middle Scho					
Johnny Ac	una						
149378			3/10/2016		83		\$0.00
Medium	Work In Progress		3/10/2016 8:22:36 AM				
Orozco, Da	aniel	ONE OF THE TOP OVENS IS NO PROPERLY. SNP MANAGER SAM	_				
Maritza Go	n70107						

	Го Name	Area Number Description	Reason	Created Date/Time	Actual Comp Date Action Taken	Aged	Hours	
Location:	Chaparra	IMS						
151447		Classroom		4/15/2016		47		\$0.00
Medium	Work In Progress	309		4/15/2016 11:25:17 AN	1			Ψ0.00
Quinones,	-	Tighten metal o	clamps that hold the s ck packs . Paul Quinor t	helves up in the				
Gidget Mor	a							
139031		Classroom		8/31/2015		275		\$0.00
Medium	Work In Progress	305		8/31/2015 10:34:06 AV	1			
Acuna, Joh	nny	Please anchor	smartboard to wall					
Gidget Mor	a							
136119	Main Building	Classroom		7/20/2015		317		\$0.00
Medium	Work In Progress	p-14		7/20/2015 1:24:35 PM	1			
Acuna, Joh	inny	please fill hole	s in wall					
Gidget Mor	a							
136120	Main Building	Classroom		7/20/2015		317		\$0.00
Medium	Work In Progress	101		7/20/2015 1:25:55 PM	1			
Acuna, Joh	nny	Please mount	SMART Board on the	wall				
Gidget Mor	-							
148933	Main Building	Athletic Field		3/4/2016		89		\$0.00
Medium	Work In Progress	OUTSIDE		3/4/2016 2:25:55 PM	1			
Ontiveros,	Guadalupe	COURTS FOR	LEASE LINE OUTSID BASKETBALL AND C CASTILLO FOR SPEC	ΓENNIS, PLEASE				
		THANKS, TER	RY					
Terry Alvara	ado	-,						
152975				5/11/2016		21		\$0.00
Medium	Work In Progress			5/11/2016 10:00:35 AV	1			
Acuna, Joh	inny	Need to renova	ate outside of portabl	e #1 and #2 at CMS				
Johnny Acı	-		•					
149225	Main Building	Classroom		3/8/2016		85		\$0.00
Medium	Work In Progress			3/8/2016 9:37:58 AM	1			
Quinones,	_	Please mount Poitevints room	white boards in Ms. A า	den and Ms.				

6/1/2016 11:47:07 AM Page 37 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da WOID	te Range for Request Building	Dates:7/1/2015 - 6 Area	6/30/2016 Order By L Deferred By	ocation, Status Until	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•		=	Actual Comp Date	Aged	Hours	
Assigned [•]	Го	Description				Action Taken			
Requester	Name								
Location:	Chaparra	al MS							
150132	Main Building	Classroom			3/29/2016		64		\$0.00
Medium	Work In Progress	300		3/29/2	016 3:44:16 PM	1			
Quinones,	Paul	one of the wind	lows needs a scree	en					
Gidget Mo	a								
153243		Classroom			5/16/2016		16		\$0.00
Medium	Work In Progress			5/16/2	016 9:24:14 AM	1			
Quinones,	Paul		e checar aireacond 01 delpacillo#100 G						
M. Carmer	n Perez								
136489		Portables			7/27/2015		0		\$0.00
Medium	Work In Progress			7/27/2	015 9:26:41 AM	7/27/2015			
Quinones,	Paul	senesecita rep GRACIAS	olace broken tiles a	nd portables #5	5	7-27-15			
M. Carmer	n Perez								
139807		Hallway/Corrid	dor		9/11/2015		264		\$0.00
Medium	Work In Progress			9/11/20	15 12:42:35 PM	1			
Quinones,	Paul	senesecita ren GRACIAS	mplasar focos que	no prenden en	ellobby				
M. Carmer	Perez								
139808		Hallway/Corrid	dor		9/11/2015		264		\$0.00
Medium	Work In Progress			9/11/20	15 12:47:37 PM	1			
Quinones,	Paul		ner lampara que no way del lobby GRA		ar				
M. Carmer	Perez								
153481		Gym			5/19/2016		13		\$0.00
Medium	Work In Progress			5/19/2	016 9:20:33 AM	1			
Marquez, (Gerardo		nbiar candados de m que comiensa al S						
M. Carmer	n Perez								
153572					5/20/2016		12		\$0.00
Medium	Work In Progress			5/20/2	016 8:05:24 AM	1			
Marquez, 0	Gerardo	CHECK DRS.	FOR PROPER OP	ERATION.					
Gerardo M	arquez								

6/1/2016 11:47:07 AM Page 38 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da	te Range for Request Building	Dates:7/1/2015 - 6 Area	/30/2016 Order By Lo Deferred By	cation, Status Until	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•			Actual Comp Date	Aged	Hours	
Assigned ⁻	Го	Description				Action Taken			
Requester	Name								
Location:	Chaparra	I MS							
148498					2/26/2016		96		\$0.00
Medium	Work In Progress			2/26/2	016 8:41:38 AN	1			
Acuna, Joh	nnny	fan motors W/a 125 (Medium) i	enHeck SP-108 D1 ssemblyhousing, motors W/assembly emblyhousing (Big)	(6) ĠreenĤeck /housing, (6) \	SP-				
Johnny Ac	una								
144644		Office			12/8/2015		176		\$0.00
Medium	Work In Progress			12/8/20	15 11:19:35 AN	1			
Chavez, Sa	antos	senesecita ren administration	nplasar lus de laent GRACIAS	rada de la offio	e de				
M. Carmer	n Perez								
147260					2/2/2016		120		\$0.00
Medium	Work In Progress			2/2/20	16 11:48:01 AN	1			
Ontiveros,	Joe		otor pump hooked u Mechanical Room is						
Johnny Ac	una								
153789	Main Building	Classroom			5/24/2016		8		\$0.00
Medium	Work In Progress	305		5/24/2	016 9:11:30 AN	1			
Marquez, C	Gerardo	Cabinet key bro	oke off in lock. Teac t	her cannot un	lock				
Gidget Mo	ra								
148220					2/23/2016		99		\$0.00
Medium	Work In Progress			2/23/2	016 2:22:42 PN	1			
Chavez, Sa	antos	lamp upgrade	n restrms.wing 300),200,and 400.					
Paul Quind	ones								
146990					1/29/2016		124		\$0.00
Medium	Work In Progress			1/29/20	16 12:31:45 PM	I			
Chavez, Sa	antos	Need to install CMS	new hand dryer to G	irls locker roor	n at				
Johnny Ac	una								
146109					1/12/2016		141		\$0.00
Medium	Work In Progress			1/12/2	016 3:54:22 PN	1			
Chavez, Sa	antos	Need to relocate	te electrical outlet to CMS.	restroom in SI	PED				
Johnny Ac	una								

6/1/2016 11:47:07 AM Page 39 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Dat	e Range for Request Building	Dates:7/1/2015 - 6 Area	5/30/2016 Order By Loca Deferred By		Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•		=	Actual Comp Date	Aged	Hours	
Assigned 1	Го	Description				Action Taken			
Requester	Name								
Location:	Chaparra	I MS							
151289	Main Building	Classroom			4/13/2016		49		\$0.00
Medium	Work In Progress	303		4/13/20	16 9:15:28 AM	1			
Appelzolle	r, Fred	Please repair s	sink in art room						
Gidget Mor	a								
153418		Kitchen			5/18/2016		14		\$0.00
High	Work In Progress			5/18/20	16 1:35:25 PN	1			
Appelzolle	r, Fred	Hand sink leak Sandra D. (575	ing from the bottom. S 5) 824-4376	SNP Manager					
Dino Facio	1								
152931					5/10/2016		22		\$0.00
Medium	Work In Progress			5/10/20	16 3:57:42 PN	1			
Chavez, Sa	antos	Need 4 outdoo #2 at CMS	r wall mount lighting fo	or Portable #1	and				
Johnny Acı	ına								
145311					1/3/2016	2/3/2016	150		\$0.00
Medium	Work In Progress			1/3/2010	6 12:43:21 AM	1			
Acuna, Joh	nny	Yearly - Chapa PMschedule d	rral MS Backflow Insp etails.	pection - Refe	· to				
Margret Vil	lalobos								
152308					5/1/2016	5/9/2016	31		\$0.00
Medium	Work In Progress			5/1/20	16 1:03:51 AM	1			
Acuna, Joh	inny	Monthly - Chap schedule detai	pparral MS Roof Inspe ls.	ection - Refer t	o PM				
Margret Vil	lalobos								
152269					5/1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress			5/1/20	16 1:03:11 AM	1			
Orozco, Da	niel	Monthly-Chap to PMschedule	paral MS Range Hood details.	d Cleaning - Ro	efer				
Margret Vil	lalobos								
154026					5/31/2016	7/1/2016	1		\$0.00
Medium	Work In Progress			5/31/2010	6 12:54:27 AM	1			
Quinones,	Paul	Yearly - Chapa PMschedule d	rral MS A2 (H/C Unit) etails.	(Yearly) - Refe	r to				
Margret Vil	lalobos								

6/1/2016 11:47:07 AM Page 40 of 174

Selected Date WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By Area Number Reason Description	ocation, Status Until Request Date Ta Created Date/Time Ac	-	Days Aged	Labor Hours	Costs
Location:	Chaparra	I MS					
152290		········	5/1/2016	5/22/2016	31		\$0.00
	Mark In Draman			3/22/2010	31		ψ0.00
Medium	Work In Progress		5/1/2016 1:03:28 AM				
Vallejo, Alb		Monthly - Chaparral MS Fire Suppl to PMschedule details.	ression Insp Refer				
Margret Vil	lalobos		5/4/0040	0/4/0040	- 04		# 0.00
152348			5/1/2016	6/1/2016	31		\$0.00
Medium	Work In Progress		5/1/2016 1:05:16 AM				
Acuna, Joh	nnny	Monthly - Chaparral MS Bleacher I PMschedule details.	Inspection - Refer to				
Margret Vil	lalobos						
153775		Football Field	5/24/2016		8		\$0.00
Medium	Work In Progress		5/24/2016 8:51:47 AM				
Ontiveros,	Guadalupe	RE-SEED FOOTBALL FIELD NEA AREA.	R EACH GOAL				
T Al	- 4-	Thank you					
Terry Alvara	ado	Exterior	5/24/2016		8		\$0.00
	W 11 B	Exterior			O		φυ.υυ
Medium	Work In Progress		5/24/2016 8:54:51 AM				
Ontiveros,	Guadalupe	PAINT OUTDOOR BASKETBALL OBOTH BASKETBALL INES, INCLUWELLAS TENNIS COURT LINES.					
		THANK YOU					
Terry Alvara	ado						
151303			4/13/2016		49		\$0.00
Medium	Work In Progress		4/13/2016 1:46:57 PM				
Vallejo, Alb	-	Make repairs to roof at CMS and D building mechanic.	TE as marked by				
Albert Valle	eio	Januari g Januari d					
145621	Main Building	Classroom	1/5/2016		148		\$0.00
Medium	Work In Progress	P-5	1/5/2016 12:02:58 PM				
Carbajal, J	-	Tiles in Nurse's office breaking and Please repair					
Gidget Mor	ra						
151265		Gym	4/13/2016		49		\$0.00
Medium	Work In Progress		4/13/2016 7:41:05 AM				
Carbajal, J	•	para aser el piso del GYM/6/de jun june/2016 GRACIAS					
M. Carmer	n Perez	Janot 2010 Old Old O					
	1:47:07 AM						11 of 174

6/1/2016 11:47:07 AM Page 41 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da WOID	ate Range for Request Building	Dates:7/1/2015 - 6. Area	/30/2016 Order By Lo Deferred By		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Aged	Hours	
Assigned	То	Description			Action Taken			
Requeste	r Name							
Location:	Chaparra	I MS						
139646	Main Building	Kitchen		9/9/2015		266		\$0.00
Medium	Work In Progress			9/9/2015 11:47:14 AM				
Estrada, J	esus		oming up under the after the kitchen floo					
Jesus Est	trada							
154092				5/31/2016		1		\$0.00
Medium	Work In Progress			5/31/2016 3:05:23 PM				
Vallejo, Al	bert	Resurface Park	king Lot					
Albert Vall	ejo							
152211				4/29/2016		33		\$0.00
Medium	Work In Progress			4/29/2016 1:59:54 PM				
Vallejo, Al	bert	Repair, seal an	d re-stripe parking l	otatCMS.				
Albert Vall	ejo							
154001		Office		5/27/2016		5		\$0.00
Medium	Work In Progress			5/27/2016 1:30:32 PM				
Gonzales	, Camilo	Pick up obsole disposal. Thar	te items and delive ik you.	r to IM/PPD for				
Theresa F	Ramirez							
Count: 47	Work Orders	А	vg. Age of WO's 8	35	Total for Chaparra	I MS	0	\$0.00

6/1/2016 11:47:07 AM Page 42 of 174

Selected Dai WOID Priority Assigned I Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Loca Area Deferred By Area Number Reason Description	Until Request Date	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert P	ride HS					
152973			5/11/2016	<u> </u>	21		\$0.00
Medium	Work In Progress		5/11/2016 9:50:24 AM	Л			
Diaz, Seba	stian	Need to replace wood on ramps that	nk you				
Sebastian		·	,				
139620		Portables	9/9/2015		266		\$0.00
Medium	Work In Progress	room #18	9/9/2015 5:20:08 AM	Л			
Chavez, Sa	antos	Two light fixtures that need to be ch the other does not turn on.	eck. one flicking and				
David Acos	sta						
153567			5/20/2016	i	12		\$0.00
Medium	Work In Progress		5/20/2016 7:55:10 AM	Л			
Marquez, C	Serardo	CHECK DRS. FOR PROPER OPER	RATION.				
Gerardo M	arquez						
150517			4/3/2016		59		\$0.00
Medium	Work In Progress		4/3/2016 12:43:28 AM	Л			
Ronquillo,	Ruben	Monthly - Desert Pride - (Qtrly) Fitne Refer to PMschedule details.	ss Equipment -				
Margret Vil	lalobos		2//2/22/2				•
149873		Portables	3/18/2016		75		\$0.00
Medium	Work In Progress	room#1&2,13.	3/18/2016 11:21:59 AM	Л			
Gallegos, l		Crack floor tiles in restrooms (rooms entrance to room 1&2	s 1&2 & 13) and				
David Acos	sta	Dortobles	0/42/2045	,	202		<u> </u>
137898		Portables	8/13/2015		293		\$0.00
Medium	Work In Progress	room #19	8/13/2015 5:24:27 AN	Л			
Ambriz, Jos	se	a/c unit not cooling (asap).					
David Acos	sta						
151898		Custodial	4/25/2016		37		\$0.00
Medium	Work In Progress		4/25/2016 9:39:58 AM	Л			
Villalobos,		Need to replace broken handle and #CO8C00000157.	core to vacuum				
David Acos	sta	0	F /0/0040				Фо оо
152742		Custodial	5/6/2016		26		\$0.00
Medium	Work In Progress		5/6/2016 11:14:30 AM	Л			
Villalobos,		need one roto brush for carpet					
David Acos							
Count: 8 W	ork Orders	Avg. Age of WO's 99		Total for Desert Prid	le HS	0	\$0.00

1141 - Work Orders In Progress (Fiscal Year)

Selected Da WOID	te Range for Request Building	Dates:7/1/2015 - 6. Area	5/30/2016 Order By Lo Deferred By	ocation, Status Until	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Crea	ted Date/Time	Actual Comp Date	Aged	Hours	
Assigned		Description				Action Taken			
Requeste	Name								
Location:	Desert Ti	ail ES							
139805					9/11/2015		264		\$0.00
Medium	Work In Progress			9/11/20	15 12:01:57 PM	1			
Carrasco,	Danny	Need unleaded	d fuel for worktruck #	[‡] 192					
Johnny Ac	una								
146911					1/28/2016		125		\$0.00
Medium	Work In Progress			1/28/20	16 11:53:34 AN	1			
Gonzalez,	Salvador		te stand for new refr #304 (computer ro		roof				
Johnny Ac	una								
153070					5/12/2016		20		\$0.00
Medium	Work In Progress			5/12/20	16 12:44:12 PM	1			
Acuna, Jo	hnny		ch and patch up blu picnic table area	ie canopy tent	cover				
Johnny Ac	una								
146061					1/12/2016		141		\$0.00
Medium	Work In Progress			1/12/20	016 1:57:52 PN	1			
Acuna, Jo	hnny		vers for light fixtures er samples to PPD)						
Johnny Ac	una				- / / /-				
153995					5/27/2016		5		\$0.00
Medium	Work In Progress			5/27/20	016 9:29:33 AN	1			
Acuna, Jo	hnny	Please check w	valk-in temperature.						
Albert Vall	<u> </u>								
150318	Main Building	Office			3/31/2016		62		\$0.00
Medium	Work In Progress	front office		3/31/20	16 11:47:15 AN	1			
Marquez, (Gerardo	Mr. Nunez need cabinet. ASAP	ds key extra keys m	ade for his de	sk and				
Elizabeth	Hernandez								
152074					4/27/2016		35		\$0.00
Medium	Work In Progress			4/27/20	016 2:16:37 PN	1			
Marquez, (Gerardo		alike padlocks to be s to Desert Trail Por		door				
Johnny Ac	una								
153575					5/20/2016		12		\$0.00
Medium	Work In Progress			5/20/20	016 8:08:59 AN	1			
Marquez, (Gerardo	CHECK DRS. I	FOR PROPER OPE	RATION.					
Gerardo N	1arquez								
	11.47.07 ΔΜ								

6/1/2016 11:47:07 AM Page 44 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da	te Range for Request Building	Dates:7/1/2015 - 6 Area	3/30/2016 Order By Local Deferred By	ition, Status Until	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	_		=	Actual Comp Date	Aged	Hours	
Assigned ⁻	Го	Description				Action Taken			
Requester	Name								
Location:	Desert Ti	rail ES							
147957					2/16/2016		106		\$0.00
Medium	Work In Progress			2/16/2	016 3:52:18 PN	1			
Appelzolle	r, Fred	Need to replac	e faucets in the north 1	00 hallway.					
Johnny Ac	una								
152680					5/5/2016		27		\$0.00
Medium	Work In Progress			5/5/20	16 12:34:03 PN	1			
Appelzolle	r, Fred	Need to replac SW 100 wing	e 7 single entryfaucet	s to classroo	oms in				
Johnny Ac	una								
144870					12/11/2015		173		\$0.00
Medium	Work In Progress			12/1	1/2015 11:39:29)			
Chavez, Sa	antos	-	E- ELECTRICAL OUTI CED SNP MANAGER	_	_				
Maritza Go	nzalez								
154036					5/31/2016	7/1/2016	1		\$0.00
Medium	Work In Progress			5/31/20	16 12:54:34 AM	1			
Acuna, Joh	nnny	Yearly - Desert PMschedule d	: Trail ES A2 (H&C Un etails.	it)(Yearly) - I	Refer to				
Margret Vil	lalobos								
152270					5/1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress			5/1/2	016 1:03:12 AM	1			
Orozco, Da	niel	Monthly - Dese Refer to PMsch	ert Trail ES - Range He nedule details.	ood Cleanin	ıg -				
Margret Vil	lalobos								
152291					5/1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress			5/1/2	016 1:03:28 AM	1			
Vallejo, Alb	pert	Monthly - Dese Refer to PMsch	ert Trail ES - Fire Supp nedule details.	ression Ins	p				
Margret Vil	lalobos								
145312					1/3/2016	2/3/2016	150		\$0.00
Medium	Work In Progress			1/3/20	16 12:43:22 AM	1			
Acuna, Joh	nnny	Yearly - Desert PMschedule d	: Trail ES - Backflow Ir etails.	nspection - F	Refer to				
Margret Vil	lalobos								

6/1/2016 11:47:07 AM Page 45 of 174

WOID Priority Assigned ⁻	Building Status To	Area Area Number Description	/30/2016 Order By Loc Deferred By Reason	Until Request Date	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester								
Location:	Desert Ti	rail ES						
150247				3/31/2016	3	62		\$0.00
Medium	Work In Progress			3/31/2016 12:46:04 AM	М			
Acuna, Joh	nnny	Monthly - Dese Refer to PMsch	rt Trail ES A16(Exhs nedule details.	t Fan)(S.Annual) -				
Margret Vil	lalobos							
152808				5/8/2016	5/24/2016	24		\$0.00
Medium	Work In Progress			5/8/2016 12:31:52 AM	M			
Acuna, Joh	nnny	Monthly - Dese PMschedule d	rt Trail ES - Playgro etails.	und Insp - Refer to				
Margret Vil	lalobos							
145755				1/6/2016	6	147		\$0.00
Medium	Work In Progress			1/6/2016 4:01:51 PI	M			
Chavez, Sa	antos	playground equand remove se	ease: (Security light uipment) Need to dis curity light pole. Pole the pole. (Safety Ha	connectelectrical has massive rust				
Johnny Ac	una							
152605				5/4/2016	5	28		\$0.00
Medium	Work In Progress			5/4/2016 12:24:58 PI	M			
Ontiveros,	Guadalupe	Please aerate	and fertilize playgrou	nd grass area at DT				
Johnny Ac	una							
135165				7/1/2015	5	336		\$0.00
Medium	Work In Progress			7/1/2015 7:43:14 AM	М			
Solis, Lore	en <i>z</i> o	Need Refrigera RM. 304	ation unit for new con	nputer class room.				
Johnny Ac	una							
153174				5/13/2016	3	19		\$0.00
Medium	Work In Progress			5/13/2016 3:10:28 PI	M			
Solis, Lore	enzo	Room #104: N	eed to replace A/c 65	00 downdraft				
Johnny Ac	una							
153743				5/23/2016	6	9		\$0.00
Medium	Work In Progress			5/23/2016 4:03:24 PI	М			
Solis, Lore	enzo	Need to conne	ct ductwork to compu	ıterlab				
,								

6/1/2016 11:47:07 AM Page 46 of 174

Selected Da WOID	ate Range for Request Building	Dates:7/1/2015 - 6/30/2016 Order By Loca Area Deferred By		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number Reason	Created Date/Time	•	Aged	Hours	
Assigned	То	Description		Action Taken			
Requeste	r Name						
Location:	Desert Ti	rail ES					
153614			5/20/2016		12		\$0.00
Medium	Work In Progress	nurse	5/20/2016 3:21:38 PN	1			
Villalobos	s, Jose	Our custodians need a dolly to more cabinets.	the two fireproof				
Elizabeth	Hernandez						
151686		Custodial	4/20/2016		42		\$0.00
Medium	Work In Progress		4/20/2016 12:43:19 PM	1			
Villalobos	s, Jose	necesito 3 bolsas para las aspirado	as,porfavorgracias				
Laura Sa	ndoval						
135927			7/15/2015		322		\$0.00
Medium	Work In Progress		7/15/2015 11:48:40 AM	1			
Estrada, c	Jesus	Need to replace VCT tile in the bus I in front of main doors. Also, need to holes on this section where the tile w Size of Area: 7' L X 11' W	fill in and level out				
Laura Sa	ndoval						
136190		Custodial	7/21/2015		316		\$0.00
Medium	Work In Progress		7/21/2015 11:06:40 AM	1			
Estrada, c	Jesus	Buenos dias Chuy, el piso de los Bar necesita remplasar. Num de clases 205, 206, 207, 208, y el bano de la necesita remplasar gradas	201, 202, 203, 204,				
Laura Sa	ndoval						
148046		Custodial	2/19/2016		103		\$0.00
Medium	Work In Progress		2/19/2016 12:15:54 PM	1			
Carbajal,	Jimmy	Buenas tardes . Jimmyla alfombra d necesita reparar por favor gracias	el portable 407 se				
Laura Sa	ndoval						
Count: 27	Work Orders	Avg. Age of WO's 96		Total for Desert Tra	ail ES	0	\$0.00

6/1/2016 11:47:07 AM Page 47 of 174

WOID Priority Assigned ⁻ Requester		Area Defe Area Number Reas Description	,	Jntil Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Desert V	iew ES						
151674	Main Building	Restroom		4/20/2016		42		\$0.00
Medium	Work In Progress			4/20/2016 9:30:45 AM				
Gallegos,	Rafael	On both boyand girls causing the lost of re and they need to be r	eflection. They are					
Israel Orte	ga							
152586		Custodial		5/4/2016		28		\$0.00
Medium	Work In Progress			5/4/2016 9:41:32 AM				
Villalobos,	Jose	Advance Aqua Clean form bottom and also hose come off causin	cap that goes on	the waste water				
Israel Orte	ga							
153326				5/17/2016		15		\$0.00
Medium	Work In Progress			5/17/2016 9:37:23 AM				
Castillo, C		Done with the scisso Ruben	or lift. It can be pic	k up. Thank you				
Ruben Ort	Z			5/04/0040				MO 00
154096				5/31/2016		1		\$0.00
Medium	Work In Progress			5/31/2016 3:31:51 PM				
Castillo, C	arlos	The occupant has ren site. The electrical wi are exposed. Need it electrocuted.	ires were cut to gro	ound level and				
Ruben Ort	z							
150455				4/3/2016		59		\$0.00
Medium	Work In Progress			4/3/2016 12:42:41 AM				
Vallejo, Alb	pert	Monthly - DesertView Refer to PMschedule		er Drain Inlets -				
Margret Vil	lalobos							
151600				4/19/2016		43		\$0.00
Medium	Work In Progress			4/19/2016 11:23:37 AM				
Ortiz, Rube		Need to replace sprin Thank you, Ruben	nklers in the socce	er field I40				
Ruben Ort	Z			= 1.15 - · ·				00.00
152292				5/1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress			5/1/2016 1:03:29 AM				
Vallejo, Alb	ert	Monthly - Desert View	w ES Fire Suppres	ssion Insp Refer				

6/1/2016 11:47:07 AM Page 48 of 174

WOID Priority Assigned ¹ Requester		Area Deferred By Area Number Reason Description	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Desert V	iew ES					
154095			5/31/2016		1		\$0.00
Medium	Work In Progress		5/31/2016 3:30:35 PM	1			
Villalobos,	David	The occupant has removed the tra site. The water line, gas line and s They need to be covered and sea	ewage are exposed.				
Ruben Ort	iz						
143709			11/17/2015		197		\$0.00
Medium	Work In Progress		11/17/2015 2:36:41 PM				
	Guadalupe	Principal Araujo, is requesting for paint the basketball lines on the basketball					
Ruben Orti	iz	Classica	F/40/004C		40		<u>Фо оо</u>
153509		Classroom	5/19/2016	_	13		\$0.00
Medium	Work In Progress		5/19/2016 2:23:48 PM	1			
Lara, Ralpl		need to service locks on gates and cylinders on	l work on doors				
Ralph Lara	<u> </u>		5/17/2016		15		\$0.00
Medium	Work In Progress	Teacher's	5/17/2016 1:20:43 PM	1	10		ψ0.00
	-		3/11/2010 1.20.431 W	ı			
Lara, Ralpl		Need a mailbox key. (Gonzalez)					
<u> </u>	e Gonzalez	Classroom	5/24/2016		8		\$0.00
153847	Madala Dassassas			4	O		φυ.υυ
Medium	Work In Progress	Teacher's	5/24/2016 1:11:52 PM	1			
Ortiz, Rube		Move bulletin boards as per our co	nversation. (Segura)				
	e Gonzalez		2/27/22/2				
148466			2/25/2016		97		\$0.00
Medium	Work In Progress	Outside	2/25/2016 3:49:41 PM	1			
Ortiz, Rube	en	Paintswing set in upper playgrour	nd.				
Guadalupe	e Gonzalez						
151601			4/19/2016		43		\$0.00
Medium	Work In Progress		4/19/2016 11:24:20 AM	1			
Ortiz, Rube	en	Need sprayer for the Polaris Thank you, Ruben					
Ruben Ort	iz						
151602			4/19/2016		43		\$0.00
Medium	Work In Progress		4/19/2016 11:25:02 AN	1			
Ortiz, Rube		Need gas tiller Thank you, Ruben					
Ruben Ort	iz						

				,				Tota
Selected Da WOID	ate Range for Request Building	Dates:7/1/2015 - 6 Area	3/30/2016 Order By Loca Deferred By	Until Request Date	Target Comp Date	Days	Labor	Cost
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Aged	Hours	
Assigned	То	Description			Action Taken			
Requester	r Name							
Location:	Desert V	iew ES						
151982				4/26/2016		36		\$0.00
Medium	Work In Progress			4/26/2016 11:05:19 AN	Л			
Ortiz, Rub	en	Need to install	sings in the parking lo	t.				
Ruben Ort	tiz							
145861				1/8/2016		145		\$0.00
Medium	Work In Progress			1/8/2016 9:19:46 AN	Л			
Gonzalez,	Salvador		for the swing gates o top them from swing	n the southwest of				
Ruben Ort	tiz							
153062		Library		5/12/2016		20		\$0.00
Medium	Work In Progress	Library		5/12/2016 10:13:41 AN	Л			
Lara, Ralp	oh .	The door to the properly. (Segu	e office in the library d ura)	oesn't close				
Guadalup	e Gonzalez							
Count: 18	Work Orders	Δ	vg. Age of WO's 47		Total for Desert Vie	w ES	0	\$0.00

6/1/2016 11:47:07 AM Page 50 of 174

WOID Priority Assigned ⁻ Requester		Area Deferred By Un Area Number Reason Description	Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	GAC						
153952			5/26/2016		6		\$0.00
Medium	Work In Progress		5/26/2016 9:37:59 AM	1			
Lara, Ralpl	n	The handicap button that is located in the here in the GAC isn't working correctly. No checked on. Thank you.					
Elisa Sant	illano						
149932			3/21/2016		72		\$0.00
Medium	Work In Progress		3/21/2016 1:49:41 PM	1			
Lara, Ralpl	า	conversation between Alfredo and Calixto door inside the server room being some door as long as it has lock.					
		please talk to Alfredo or Calixto					
Cora Ram	irez						
147473			2/5/2016		117		\$0.00
Medium	Work In Progress		2/5/2016 11:31:15 AM	1			
Lara, Ralpl	n	Wanting to place an Auto-Door closer or Reception area[B-wing](HR section).	n the door in the				
Esteban R	osas						
145250			12/18/2015		166		\$0.00
Medium	Work In Progress		12/18/2015 8:19:00 AM	1			
Orozco, Da	niel	STEAM LINE IS LEAKING. SNP MANAGE 882.6784	ER IRMAS.				
Maritza Go	nzalez						
151698		Cafeteria	4/20/2016		42		\$0.00
Medium	Work In Progress		4/20/2016 3:09:30 PM	1			
Moncayo, I	- Fernando	Dishwasher Pressure Gauge broken and Accelerator leaking. Irma Valencia Manag 6784					
Dino Facio)						
153069		Kitchen	5/12/2016		20		\$0.00
High	Work In Progress		5/12/2016 12:35:40 PM				
Moncayo, I	- ernando	Walk in Refrigerator at 45° SNP Manage 882-6784	er Irma V. (575)				
		-					

6/1/2016 11:47:07 AM Page 51 of 174

WOID Priority Assigned Requester		Area Deferred B Area Number Reason Description	y Until Request Date Created Date/Time	Target Comp Date Days Actual Comp Date Aged Action Taken	Labor Hours
Location:	GAC				
153507			5/19/2016	13	\$0.00
Medium	Work In Progress		5/19/2016 2:01:58 PM		
Ronquillo	, Ruben	There is a skylight located in the Finance Department. Sor cracked it.			
Elisa Sant	tillano				
153842			5/24/2016	8	\$0.00
Medium	Work In Progress		5/24/2016 11:31:52 AM		
Moncayo, Elisa San		The bookshelf in Mrs. Luz ar apart and needs to be fixed. Department			
153850	ullano		5/24/2016	8	\$0.00
Medium	Work In Progress		5/24/2016 2:15:32 PM	_	ψ0.00
Moncayo,	ŭ	We need to have a cabinet n room to Melissa's office. Loc Department. Thank you.	noved from the payroll file		
Elisa Sant	tillano	,			
149749		Office	3/16/2016	77	\$0.00
Medium	Work In Progress	C-WING GLASS	3/16/2016 3:42:31 PM		
Moncayo,	Fernando	AS PER MRS. YTURRALDE, LIGHT IN THE CUBICLE GL CLEANED FROM THE INSID BETTER LIGHT AND VISIBIL QUESTIONS PLEASE CONT @ EXT. 6743	ASS OFFICE IN C-WING DE AND OUTSIDE FOR LITY. THANK YOU. ANY	3/31/16 - as per Jimmy, route Moncayo	to Fernando
Karla Que	sada				
135227			7/2/2015	335	\$0.00
Medium	Work In Progress		7/2/2015 2:31:29 PM		
Moncayo,	Fernando	SNP Vehicle # 177 needs to borganized.	oe cleaned out and		
Maritza Go					
153511	Pre-K	Classroom	5/19/2016	13	\$0.00
Medium	Work In Progress		5/19/2016 2:31:26 PM		
Lara, Ralp	oh .	need to service locks and wo	rked on door cylinders,		

6/1/2016 11:47:07 AM Page 52 of 174

WOID	Building	Area Deferred By Un	til Request Date	Target Comp Date	Days	Labor	
Priority	Status	Area Number Reason	Created Date/Time	Actual Comp Date	Aged	Hours	
Assigned '		Description		Action Taken			
Requester	Name						
Location:	GAC						
139283			9/3/2015		272		\$0.00
Medium	Work In Progress		9/3/2015 10:21:09 AM	1			
Ambriz, Jo	se	Server room at GAC is warm					
		please check ASAP					
Cora Ram	irez						
154094			5/31/2016		1		\$0.00
Medium	Work In Progress		5/31/2016 3:13:24 PM	1			
Ambriz, Jo	se	The air conditioner in Mrs. Josie Padilla's working correctly. She is located in the Conformation Systems Department.					
Elisa Sant	tillano						
152293			5/1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress		5/1/2016 1:03:30 AM	1			
Vallejo, All	bert	Monthly - GAC Fire Suppression Insp I schedule details.	Refer to PM				
Margret Vi	llalobos						
142724			11/1/2015	11/22/2015	213		\$0.00
Medium	Work In Progress		11/1/2015 12:54:21 AM	1			
Vallejo, All	pert	Monthly - GAC Fire Suppression Insp I schedule details.	Refer to PM				
Margret Vi	llalobos						
154034			5/31/2016	7/1/2016	1		\$0.00
Medium	Work In Progress		5/31/2016 12:54:33 AM	1			
Moncayo,	Fernando	Yearly - GAC A-2 Package Unit Gas Year PMschedule details.	rly - Refer to				
Margret Vi	llalobos						
152807			5/8/2016	5/24/2016	24		\$0.00
Medium	Work In Progress		5/8/2016 12:31:51 AM	1			
Moncayo,	Fernando	Monthly - GAC Playground Insp - Refer to details.	o PM schedule				
Margret Vi	llalobos						
146680			1/25/2016		128		\$0.00
Medium	Work In Progress		1/25/2016 3:20:50 PM	1			
Castillo, C	arlos	Can we get a work order for lights in the Superintendents file room(C-wing). More Elisa Saenz.					

6/1/2016 11:47:07 AM Page 53 of 174

1141 - Work Orders In Progress (Fiscal Year)

	te Range for Request Building	Dates:7/1/2015 - 6 Area			Poguest Date	Target Comp Date	Dove	Labor	Costs
WOID Priority	Status	Area Number	Deferred By Reason	Until Crea	-	Actual Comp Date Action Taken	Days Aged	Hours	
Assigned 1 Requester		Description				Action Taken			
Location:	GAC								
145521					1/4/2016		149		\$0.00
Medium	Work In Progress			1/4/2	016 9:47:52 AN	1			
Castillo, Ca	arlos		oier from Calixto Offi lectrical outlet in ne		tertech				
Cora Ram	irez								
153895					5/25/2016		7		\$0.00
Medium	Work In Progress			5/25/2	016 9:20:22 AN	1			
Castillo, C	arlos		sting use of the bud to work on the flash						
Cora Ram	irez								
153499					5/19/2016		13		\$0.00
Medium	Work In Progress			5/19/20	16 11:44:56 AN	1			
Moncayo, F	Fernando	noises the first in the HR wing.	ne is in Ms. Ludym	larcon's office	located				
Elisa Sant	illano								
150380		Hallway/Corric	lor		3/31/2016		62		\$0.00
Medium	Work In Progress			3/31/2	016 4:25:10 PN	1			
Carbajal, J	limmy		PLACE OR REPAIR ECOMEING A TRIP		WAYS				
Jimmy Cai	rbajal								
143696					11/17/2015		197		\$0.00
Medium	Work In Progress	FEDERAL		11/17/2	015 9:31:30 AN	1			
Moncayo, F	- ernando	HANG PICTUR	RE FRAME IN OFFIC	CE.					
Noemi Du	ron								
150726					4/5/2016		57		\$0.00
Medium	Work In Progress			4/5/2	016 7:29:25 AN	1			
Ambriz, Jos	se	Need to replace at GAC.	e the back up unit	#2 for the serv	er room				
Guillermo	Hernandez								
150754					4/5/2016		57		\$0.00
Medium	Work In Progress			4/5/20	16 11:59:24 AN	1			
Ambriz, Jos	se	technologyma a/c unit #2	in server room need	d to replace ba	ckup				
Fernando	Moncayo								

6/1/2016 11:47:07 AM Page 54 of 174

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building Until **Request Date Target Comp Date** Days Labor Area **Deferred By** Hours Aged Area Number Reason Created Date/Time Actual Comp Date **Priority Status Assigned To Description Action Taken** Requester Name Location: **GAC** 152203 4/29/2016 33 \$0.00 Medium Work In Progress 4/29/2016 11:44:46 AM Board Room - Please check a/c, it was not working last Ambriz, Jose nite at the board meeting. Alfredo Holguin Count: 27 Work Orders Total for GAC 0 \$0.00 Avg. Age of WO's 79

6/1/2016 11:47:07 AM Page 55 of 174

Location: GAC - Pre-K 153820 Cafeteria 5/24/2016 8 Medium Work In Progress 5/24/2016 10:09:50 AM Castillo, Carlos moving computers to back of cafeterial (right side corner) behind panel- there are no outlets, need electrical Leticia Tangonan 5/31/2016 1 154060 Work In Progress 5/31/2016 8:33:05 AM Castillo, Carlos no electrical power in Pre K Fernando Moncayo Fernando Moncayo Medium Work In Progress 4/29/2016 1:50:29 PM Rodriguez, Arturo Need to wax floors. Albert Vallejo 15/23/2016 10:01:58 AM Moncayo, Fernando Office 5/23/2016 10:01:58 AM Moncayo, Fernando Continuation: After moving computer shelves please move Amanda's desk into office work room. 'If Letty or Amanda are not available, please see Rosy Villalobos. 9 Medium Work in Progress 5/23/2016 9:59:44 AM Moncayo, Fernando Please transfer computer shelves from computer room by office to cafeteria work room.' 'If Letty or Amanda are not available, please see Rosy Villalobos. 9 Medium Work in Progress 5/23/2016 9:59:44 AM 9 <th></th> <th>Days Labor ged Hours</th> <th></th> <th>Until Request Date Created Date/Time</th> <th>Deferred By Reason</th> <th>Area Number Description</th> <th></th> <th>WOID Priority Assigned Requester</th>		Days Labor ged Hours		Until Request Date Created Date/Time	Deferred By Reason	Area Number Description		WOID Priority Assigned Requester
Medium Work In Progress 5/24/2016 10:09:50 AM Castillo, Carlos moving computers to back of cafeteria (right side corner) behind panel-there are no outlets, need electrical Leticia Tangonan 5/31/2016 1 1540600 5/31/2016 8:33:05 AM 1 Medium Work In Progress 5/31/2016 8:33:05 AM						-K	GAC - Pre	Location:
Castillo, Carlos mowing computers to back of cafeteria (right side corner) behind panel - there are no outlets, need electrical	\$0.00	8		5/24/2016		Cafeteria		153820
Dehind panel - there are no outlets, need electrical				5/24/2016 10:09:50 AM			Work In Progress	Medium
154060							arlos	Castillo, C
Medium Work In Progress 5/31/2016 8:33:05 AM Castillo, Carlos no electrical power in Pre K Fernando Moncayo 4/29/2016 33 Medium Work In Progress 4/29/2016 1:50:29 PM Rodriguez, Arturo Need to wax floors. Albert Vallejo 5/23/2016 1:50:29 PM Medium Work In Progress 5/23/2016 0:523/2016 9 Medium Work In Progress 5/23/2016 10:01:58 AM 9 Moncayo, Fernando Continuation: After moving computer shelves please move Amanda's desk into office work room. *If Letty or Amanda are not available, please see Rosy Villalobos. 9 Amanda Flores 153668 Computer Lab 5/23/2016 9 Medium Work In Progress 5/23/2016 9:59:44 AM 9 Moncayo, Fernando Please transfer computer shelves from computer room by office to cafeteria work room. *If Letty or Amanda are not available, please see Rosy Villalobos. 2 Armanda Flores 139652 9/9/2015 266 Medium Work In Progress 9/9/2015 12:40:15 PM Moncayo, Fernando NO ELECTRICITY IN PRE-K. <th< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td>ngonan</td><td>Leticia Tar</td></th<>							ngonan	Leticia Tar
Castillo, Carlos no electrical power in Pre K	\$0.00	1		5/31/2016				154060
Fernando Moncayo				5/31/2016 8:33:05 AM			Work In Progress	Medium
152210					wer in Pre K	no electrical po	arlos	Castillo, C
Medium Work In Progress 4/29/2016 1:50:29 PM Rodriguez, Arturo Need to wax floors. Albert Vallejo 153669 Office 5/23/2016 9 Medium Work In Progress 5/23/2016 10:01:58 AM Moncayo, Fernando Continuation: After moving computer shelves please move Amanda's desk into office work room. "If Letty or Amanda are not available, please see Rosy Villalobos. Amanda Flores 5/23/2016 9 Medium Work In Progress 5/23/2016 9:59:44 AM Moncayo, Fernando Please transfer computer shelves from computer room by office to cafeteria work room. "If Letty or Amanda are not available, please see Rosy Villalobos. 266 Amanda Flores 9/9/2015 12:40:15 PM Moncayo, Fernando NO ELECTRICITY IN PRE-K. Maritza Gonzalez 5/18/2016 14							Moncayo	Fernando
Rodriguez, Arturo Albert Vallejo 153669 Office 5/23/2016 9 Medium Work In Progress S/23/2016 10:01:58 AM Moncayo, Fernando Continuation: After moving computer shelves please move Amanda's desk into office work room. *If Letty or Amanda are not available, please see Rosy Villalobos. Amanda Flores 153668 Computer Lab S/23/2016 9 Medium Work In Progress F/23/2016 9:59:44 AM Moncayo, Fernando Please transfer computer shelves from computer room by office to cafeteria work room. *If Letty or Amanda are not available, please see Rosy Villalobos. Amanda Flores 139652 9/9/2015 266 Medium Work In Progress 9/9/2015 12:40:15 PM Moncayo, Fernando NO ELECTRICITY IN PRE-K. Maritza Gonzalez Exterior 5/18/2016 14	\$0.00	33		4/29/2016			<u> </u>	152210
Albert Vallejo Office 5/23/2016 9 Medium Work In Progress 5/23/2016 10:01:58 AM Moncayo, Fernando Continuation: After moving computer shelves please move Amanda's desk into office work room. *If Letty or Amanda are not available, please see Rosy Villalobos. Amanda Flores 153668 Computer Lab 5/23/2016 9 Medium Work In Progress 5/23/2016 9:59:44 AM 9 Moncayo, Fernando Please transfer computer shelves from computer room by office to cafeteria work room. *If Letty or Amanda are not available, please see Rosy Villalobos. 266 Amanda Flores 9/9/2015 266 139652 9/9/2015 12:40:15 PM Moncayo, Fernando NO ELECTRICITY IN PRE-K. Maritza Gonzalez 5/18/2016 14				4/29/2016 1:50:29 PM			Work In Progress	Medium
Medium Work In Progress 5/23/2016 10:01:58 AM Moncayo, Fernando Continuation: After moving computer shelves please move Amanda's desk into office work room. *If Letty or Amanda are not available, please see Rosy Villalobos. Amanda Flores 153668 Computer Lab 5/23/2016 9:59:44 AM Moncayo, Fernando Please transfer computer shelves from computer room by office to cafeteria work room. *If Letty or Amanda are not available, please see Rosy Villalobos. Amanda Flores 139652 9/9/2015 266 Medium Work In Progress 9/9/2015 12:40:15 PM Moncayo, Fernando NO ELECTRICITY IN PRE-K. Maritza Gonzalez Exterior 5/18/2016 14					oors.	Need to wax flo	, Arturo	Rodriguez
153669 Office 5/23/2016 9 Medium Work In Progress 5/23/2016 10:01:58 AM Moncayo, Fernando Continuation: After moving computer shelves please move Amanda's desk into office work room. "If Letty or Amanda are not available, please see Rosy Villalobos. Amanda Flores 153668 Computer Lab 5/23/2016 9 Medium Work In Progress 5/23/2016 9:59:44 AM Moncayo, Fernando Please transfer computer shelves from computer room by office to cafeteria work room. "If Letty or Amanda are not available, please see Rosy Villalobos. Amanda Flores 139652 9/9/2015 266 Medium Work In Progress 9/9/2015 12:40:15 PM Moncayo, Fernando NO ELECTRICITY IN PRE-K. Maritza Gonzalez 153415 Exterior 5/18/2016 14							eio	Albert Valle
Moncayo, Fernando Continuation: After moving computer shelves please move Amanda's desk into office work room. *If Letty or Amanda are not available, please see Rosy Villalobos. Amanda Flores 153668 Computer Lab 5/23/2016 9 Medium Work In Progress 5/23/2016 9:59:44 AM Moncayo, Fernando Please transfer computer shelves from computer room by office to cafeteria work room. *If Letty or Amanda are not available, please see Rosy Villalobos. Amanda Flores 139652 9/9/2015 266 Medium Work In Progress 9/9/2015 12:40:15 PM Moncayo, Fernando NO ELECTRICITY IN PRE-K. Maritza Gonzalez Exterior 5/18/2016 14	\$0.00	9		5/23/2016		Office	<i>,</i>	
move Amanda's desk into office work room. *If Letty or Amanda are not available, please see Rosy Villalobos. Amanda Flores 153668				5/23/2016 10:01:58 AM			Work In Progress	Medium
153668 Computer Lab 5/23/2016 9 Medium Work In Progress 5/23/2016 9:59:44 AM Moncayo, Fernando Please transfer computer shelves from computer room by office to cafeteria work room. *If Letty or Amanda are not available, please see Rosy Villalobos. Amanda Flores 139652 9/9/2015 266 Medium Work In Progress 9/9/2015 12:40:15 PM Moncayo, Fernando NO ELECTRICITY IN PRE-K. Maritza Gonzalez 153415 Exterior 5/18/2016 14				ork room. *If Letty or	's desk into office wo	move Amanda	Fernando	Moncayo,
Medium Work In Progress Moncayo, Fernando Please transfer computer shelves from computer room by office to cafeteria work room. *If Letty or Amanda are not available, please see Rosy Villalobos. Amanda Flores 139652 Medium Work In Progress Moncayo, Fernando NO ELECTRICITY IN PRE-K. Maritza Gonzalez Exterior 5/18/2016 14							lores	Amanda F
Moncayo, Fernando Please transfer computer shelves from computer room by office to cafeteria work room. *If Letty or Amanda are not available, please see Rosy Villalobos. Amanda Flores 139652 9/9/2015 266 Medium Work In Progress 9/9/2015 12:40:15 PM Moncayo, Fernando NO ELECTRICITY IN PRE-K. Maritza Gonzalez 153415 Exterior 5/18/2016 14	\$0.00	9		5/23/2016		Computer Lab		153668
by office to cafeteria work room. *If Letty or Amanda are not available, please see Rosy Villalobos. Amanda Flores 139652 9/9/2015 266 Medium Work In Progress 9/9/2015 12:40:15 PM Moncayo, Fernando NO ELECTRICITY IN PRE-K. Maritza Gonzalez 153415 Exterior 5/18/2016 14				5/23/2016 9:59:44 AM			Work In Progress	Medium
139652 9/9/2015 266 Medium Work In Progress 9/9/2015 12:40:15 PM Moncayo, Fernando NO ELECTRICITY IN PRE-K. Maritza Gonzalez 153415 Exterior 5/18/2016 14				Letty or Amanda are	eteria work room. *If	by office to cafe	- ernando	Moncayo,
Medium Work In Progress 9/9/2015 12:40:15 PM Moncayo, Fernando NO ELECTRICITY IN PRE-K. Maritza Gonzalez 5/18/2016 14				0/0/0045			lores	
Moncayo, Fernando NO ELECTRICITY IN PRE-K. Maritza Gonzalez 153415 Exterior 5/18/2016 14	\$0.00	66	2					
Maritza Gonzalez 153415 Exterior 5/18/2016 14				9/9/2015 12:40:15 PM			Work In Progress	Medium
153415 Exterior 5/18/2016 14					ITY IN PRE-K.	NO ELECTRIC	-ernando	Moncayo,
							nzalez	Maritza Go
Medium Work In Progress playground 5/18/2016 12:13:35 PM	\$0.00	14		5/18/2016		Exterior		153415
				5/18/2016 12:13:35 PM		playground	Work In Progress	Medium
Moncayo, Fernando Please assemble outdoor musical instruments located in boxes in cafeteria.				instruments located in			ernando	Moncayo,
Amanda Flores							lores	Amanda F

6/1/2016 11:47:07 AM Page 56 of 174

Calcatad Da	to Dongo for Dogwoot	Detect 7/1/2015 6/20/2016 Order By	Logation Status			Tota Costs
WOID	Building	Dates:7/1/2015 - 6/30/2016 Order By Area Deferred By		arget Comp Date Days	Labor	Cost
Priority	Status	Area Number Reason	Created Date/Time A	ctual Comp Date Aged	Hours	
Assigned	То	Description		Action Taken		
Requeste	Name					
Location:	GAC - Pre	e-K				
150659		Classroom	4/4/2016	58		\$0.00
Medium	Work In Progress	202	4/4/2016 10:37:51 AM			
Moncayo,	Fernando	Please assemble new loft in roo	m 202.			
Amanda F	Tores					
146577		Classroom	1/22/2016	131		\$0.00
Medium	Work In Progress	203	1/22/2016 8:36:05 AM			
Moncayo,	Fernando	cabinet door in room 203 is hang	ging off hinge			
Leticia Ta	ngonan					
153896		Classroom	5/25/2016	7		\$0.00
Medium	Work In Progress	203	5/25/2016 9:22:23 AM			
Moncayo,	Fernando	Upper cabinet on right side miss replace.	sing shelves-please			
Leticia Ta	ngonan					
153512		Classroom	5/19/2016	13		\$0.00
Medium	Work In Progress		5/19/2016 2:33:18 PM			
Lara, Ralp	h	need to service locks and worke	d on door cylinders,			
Ralph Lar	a					
Count: 11	Work Orders	Avg. Age of WO's	50	Total for GAC - Pre-K	0	\$0.00

6/1/2016 11:47:07 AM Page 57 of 174

Selected Da WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Loc Area Deferred By Area Number Reason Description	cation, Status Until Request Date Targ Created Date/Time Act		Labor Hours	Costs
Location:	Gadsden	ES				
153564			5/20/2016	12		\$0.00
Medium	Work In Progress		5/20/2016 7:52:26 AM			
Marquez, C	Gerardo	CHECK DRS. FOR PROPER OPE	RATION.			
Gerardo M	larquez					
146983	·	Classroom	1/29/2016	124		\$0.00
Medium	Work In Progress	302	1/29/2016 10:29:58 AM			
Chavez, Sa	antos	need immediate assistance for ele room 302just converted to compu appreciate your assistance in this r	iter labsgreatly			
Loraine Ga	andara					
152199		Parking Lot	4/29/2016	33		\$0.00
Medium	Work In Progress		4/29/2016 9:43:14 AM			
Chavez, Sa	antos	need assistance with lighting outsi lotfour light bulbs are outgreatly assistance in this matter				
Loraine Ga	andara					
146658		Classroom	1/25/2016	128		\$0.00
Medium	Work In Progress		1/25/2016 9:31:12 AM			
Chavez, Sa	antos	need assistance with electrical worldb in room 302 greatly appreciate y				
Loraine Ga	andara	- OI	1/40/0040			**
151503		Classroom	4/18/2016	44		\$0.00
Medium	Work In Progress	304	4/18/2016 8:16:59 AM			
Chavez, Sa	antos	Would you please submit a work or that needs to be replaced in my roomearest to the door.	•			
		Thank you, Melissa				
Loraine Ga 153812	andara	Restroom	5/24/2016	8		\$0.00
	Model la Drogrado			0		φυ.υυ
Medium	Work In Progress	104	5/24/2016 9:50:27 AM			
Chavez, Sa		need assistance with lightdoes n be done before K-3 program starts				
Loraine Ga	andara	Cofotovia	F/F/2040	07		<u>ФО 00</u>
152676	\\\\\\\-\\\\-\\\\\\-\\\\\\\\\\\\\\\\	Cafeteria	5/5/2016	27		\$0.00
Medium	Work In Progress		5/5/2016 9:59:17 AM			
Chavez, Sa		need to fix emergency lights in kitc appreciate your assistance in this r				
Loraine Ga	andara					

6/1/2016 11:47:07 AM Page 58 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da	ite Range for Request Building	Dates:7/1/2015 - 6 Area	5/30/2016 Order By Lo Deferred By	ocation, Status Until	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	-			Actual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requester	Name								
Location:	Gadsden	ES							
146931					1/28/2016		125		\$0.00
Medium	Work In Progress			1/28/2	016 3:30:00 PN	Л			
Ontiveros,	Joe		vater supplyfor was installing a water filt						
Albert Vall	ejo								
150333					3/31/2016		62		\$0.00
Medium	Work In Progress			3/31/2	016 1:59:00 PN	Л			
Ontiveros,	Joe	Garden Corord was done prop what needs to assistance in t	os and Ms. Marque linator what was dis erlycan someone be donegreatly ap his matterour Gar thank you once ag	cussed in the please come spreciate your den Cor. come	m eeting see				
Loraine G	andara								
153810		Exterior			5/24/2016		8		\$0.00
Medium	Work In Progress			5/24/2	016 9:49:19 AN	1			
Ontiveros,	Joe	to kinder wing.	ce with outside plun it is leaking and th K order for Mr.Holgu	e wall is starin					
Loraine G	andara								
154089					5/31/2016		1		\$0.00
Medium	Work In Progress	GES SCHOOL		5/31/2	016 2:32:48 PN	Л			
Ontiveros,	Joe	STINGE COMI HALLWAYSN LOOKED AT	ANCE THERE IS AI NG OUT OF VENTS IEED FOR THIS TO TO AWEFUL TO BE THANK YOU GRE.	S INTO DBE PLEASE I					
Loraine G	andara								
153962					5/26/2016		6		\$0.00
Medium	Work In Progress	OUTSIDE MAII	N	5/26/2	016 3:20:22 PN	Л			
Ontiveros,	Joe	ROLLING TIRE	ANCE WITH MAIN (ES NEED TO BE RE Æ LOOSEGREAT ANCE	EPLACED THE					
Loraine G	andara								
149985					3/22/2016		71		\$0.00
Medium	Work In Progress			3/22/2	016 8:43:10 AN	1			
Ontiveros,	Joe		ject personal are re o be replaced, leaki						
0	o Ontivoros								

6/1/2016 11:47:07 AM Page 59 of 174

Guadalupe Ontiveros

153145 Medium Work In Progress MaSHING MACHINE IS NOT WASHING THE TOWELS/RAGS RIGHT. NOT ENDUGH WATER. SNP WANSHER LAURA H. 882.3410 Medium Work In Progress Washing Machine Is NOT Washing THE TOWELS/RAGS RIGHT. NOT ENDUGH WATER. SNP WANSHER LAURA H. 882.3410 Work In Progress Medium Work In Progress Medium Work In Progress Mechanical room near to room 308thank you Work In Progress Mechanical 2/26/2016 9.27.38 AM Work In Progress Mechanical Medium Work In Progress Mechanical 2/26/2016 9.27.38 AM Work In Progress Mechanical Medium Work In Progress Mechanical Mechanical room next to the mechanical room next to the Nurses Stationgreatly appreciate your assistance in this matter 11/3/2015 211 3 Medium Work In Progress Conference 11/3/2015 9.26.50 AM Medium Work In Progress Conference 11/3/2015 9.26.50 AM Medium Work In Progress Medium Mork In Progress Monthly- Gadsden ES-Range Hood Cleaning - Refer to PMschedule details. Medium Work In Progress Monthly- Gadsden ES-Range Hood Cleaning - Refer to PMschedule details. Medium Work In Progress Medium Work In Progress Monthly- Gadsden ES-Fire Suppression Insp-Refer to PMschedule details. Medium Work In Progress Monthly- Gadsden ES-Fire Suppression Insp-Refer Monthly- Gadsden ES-Fire Suppression Insp-Refer Monthly- Gadsden ES-Fire Suppression Insp-Refer Membra Membra Monthly- Gadsden ES-Fire Suppression Insp-Refer Membra Mem	WOID Priority Assigned Requester			eferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Medium Work In Progress 5/13/2016 10:14:39 AM Ontiveros, Joe WASHING MACHINE IS NOT WASHING THE TOWELS/RAGS RIGHT. NOT ENDUGH WATER. SNP MANAGER LAURAH. 882:3410 Maritza donzalez 148775 Hallway/Corridor 3/2/2016 10:34:44 AM Medium Work In Progress Bottom hinge broken on mechanical room near to room 308thank you Loraine Gandara Hallway/Corridor 2/26/2016 9:27:38 AM Medium Work In Progress Mechanical Medium Work In Progress Mechanical Coraine Gandara 11/3/2015 9:26:50 AM Hagliegos, Rafael need immediate assistance for leak in roofwater coming in greatly appreciate assistance. Loraine Gandara 11/3/2015 9:26:50 AM Gallegos, Rafael need immediate assistance for leak in roofwater coming in greatly appreciate assistance. Loraine Gandara 15/2285 Medium Work In Progress 5/1/2016 1:03:24 AM Orozoo, Daniel Monthly-Gadsden ES- Range Hood Cleaning - Refer to PM schedule details. Medium Work In Progress 5/1/2016 1:03:24 AM Vallejo, Abert Monthly- Gadsden ES - Fire Suppression	Location:	Gadsden	ES						
Ontiveros, Joe WASHING MACHINE IS NOT WASHING THE TOWELS/RAGS RIGHT. NOT ENDUGH WATER. SNP MANAGER LAURA H. 882.3410 Maritza Gonzalez 148775 Hallway/Corridor 3/2/2016 10:34:44 AM Marquez, Gerardo Bottom hinge broken on mechanical room near to room 308thank you Loraine Gandara Hallway/Corridor 2/26/2016 9:27:38 AM Medium Work in Progress Mechanical 2/26/2016 9:27:38 AM Ontiveros, Joe There is a loud rattling noise next to the mechanical room next to the Nurses Stationgreatly appreciate your assistance in this mattler Loraine Gandara 142949 11/3/2015 9:26:50 AM Gallegos, Rafael need immediate assistance in this mattler 2 5/1/2016 5/22/2016 31 \$ Loraine Gandara Loraine Gandara Loraine Gandara Loraine Gandara Medium Work in Progress 5/1/2016 5/22/2016 31 5 Medium Work	153145				5/13/2016		19		\$0.00
Maritza Gonzalez	Medium	Work In Progress			5/13/2016 10:14:39 AM				
148775 Hallway/Corridor 3/2/2016 91 \$ Medium Work in Progress 3/2/2016 10:34:44 AM 91 \$ Marquez, Gerardo Bottom hinge broken on mechanical room near to room 308thank you Bottom hinge broken on mechanical room near to room 308thank you 96 \$ Loraine Gandara Hallway/Corridor 2/26/2016 96 \$ Medium Work in Progress Mechanical 2/26/2016 9:27:38 AM 96 \$ Ontiveros, Joe There is a loud rattiing noise next to the mechanical room next to the Nurses Stationgreatly appreciate your assistance in this matter 2/26/2016 9:27:38 AM 211 \$ Loraine Gandara 11/3/2015 211 \$ \$ Medium Work in Progress Conference 11/3/2015 9:26:50 AM 211 \$ Gallegos, Rafael need immediate assistance for leak in roofwater coming in greatly appreciate assistance \$ 5/1/2016 5/22/2016 31 \$ Medium Work in Progress 5/1/2016 5/22/2016 31 \$ Medium Work in Progress 5/1/2016	Ontiveros,	Joe	TOWELS/RAGS F	RIGHT. NOT ENOL	GH WATER.				
Medium Work In Progress 3/2/2016 10:34:44 AM Marquez, Gerardo Bottom hinge broken on mechanical room near to room 308thank you Loraine Gandara Hallway/Corridor 2/26/2016 96 \$ Medium Work In Progress Mechanical 2/26/2016 9:27:38 AM 96 \$ Ontiveros, Joe There is a loud rattling noise next to the mechanical room next to the Nurses Stationgreatly appreciate your assistance in this matter 11/3/2015 211 \$ Loraine Gandara Conference 11/3/2015 9:26:50 AM 211 \$ Medium Work in Progress Conference 11/3/2015 9:26:50 AM 211 \$ Loraine Gandara Loraine Gandara Beard in mediate assistance for leak in roof water coming in greatly appreciate assistance 5/1/2016 5/22/2016 31 \$ Medium Work in Progress Monthly- Gadsden ES - Range Hood Cleaning - Refer to PMschedule details. \$ \$ Medium Work in Progress 5/1/2016 1:03:24 AM \$ \$ \$ Medium Work in Progress 5/1/2016 1:03:24 AM \$ \$ \$ <td>Maritza Go</td> <td>onzalez</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	Maritza Go	onzalez							
Marquez, Gerardo Bottom hinge broken on mechanical room near to room 308thank you	148775		Hallway/Corridor		3/2/2016		91		\$0.00
Solution Solution	Medium	Work In Progress			3/2/2016 10:34:44 AM				
148503 Hallway/Corridor 2/26/2016 96 \$ Medium Work In Progress Mechanical 2/26/2016 9:27:38 AM 96 \$ Ontiveros, Joe There is a loud rattling noise next to the mechanical room next to the Nurses Stationgreatly appreciate your assistance in this matter 211 \$ Loraine Gandara 11/3/2015 211 \$ Medium Work In Progress Conference 11/3/2015 9:26:50 AM Gallegos, Rafael need immediate assistance for leak in roofwater coming in greatly appreciate assistance 20 Loraine Gandara 5/1/2016 5/22/2016 31 \$ Medium Work In Progress 5/1/2016 1:03:24 AM \$ \$ Morozco, Daniel Monthly-Gadsden ES - Range Hood Cleaning - Refer to PM schedule details. \$	Marquez, 0	Gerardo	•		room near to room				
Medium Work In Progress Mechanical 2/26/2016 9:27:38 AM Ontiveros, Joe There is a loud rattling noise next to the mechanical room next to the Nurses Stationgreatly appreciate your assistance in this matter Loraine Gandara 11/3/2015 211 \$ Medium Work In Progress Conference 11/3/2015 9:26:50 AM 211 \$ Gallegos, Rafael need immediate assistance for leak in roofwater coming in greatly appreciate assistance 5/1/2016 5/22/2016 31 \$ Loraine Gandara 5/1/2016 5/22/2016 31 \$ Medium Work In Progress 5/1/2016 5/22/2016 31 \$ Margret Villalobos 5/1/2016 5/22/2016 31 \$ Medium Work In Progress 5/1/2016 1.03:24 AM \$ Vallejo, Albert Monthly- Gadsden ES - Fire Suppression Insp - Refer to PMschedule details. \$ 5/31/2016 1 \$ Medium Work In Progress 5/31/2016 1 \$ \$ Margret Villalobos 5/31/2016 1 \$ \$ </td <td></td> <td>andara</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>		andara							
Ontiveros, Joe There is a loud rattling noise next to the mechanical room next to the Nurses Stationgreatly appreciate your assistance in this matter Loraine Gandara 142949 11/3/2015 211 \$ Medium Work In Progress Conference 11/3/2015 9:26:50 AM Gallegos, Rafael need immediate assistance for leak in roofwater coming in greatly appreciate assistance Loraine Gandara 152285 5/1/2016 5/22/2016 31 \$ Medium Work In Progress 5/1/2016 1:03:24 AM Orozco, Daniel Monthly- Gadsden ES - Range Hood Cleaning - Refer to PMschedule details. Margret Villalobos 152286 5/1/2016 1:03:24 AM Work In Progress 5/1/2016 1:03:24 AM Work In Progress 5/1/2016 1:03:24 AM Monthly- Gadsden ES - Fire Suppression Insp - Refer to PMschedule details. Margret Villalobos 154047 5/31/2016 1:54:42 AM Apodaca, Mario Monthly - Gadsden ES - Monthly Meter Readings -	148503		Hallway/Corridor				96		\$0.00
Loraine Gandara	Medium	Work In Progress	Mechanical		2/26/2016 9:27:38 AM				
142949 11/3/2015 211 \$ Medium Work In Progress Conference 11/3/2015 9:26:50 AM 211 \$ Gallegos, Rafael need immediate assistance for leak in roofwater coming in greatly appreciate assistance	Ontiveros,	Joe	room next to the N	Nurses Stationgr					
Medium Work In Progress Conference 11/3/2015 9:26:50 AM Gallegos, Rafael need immediate assistance for leak in roofwater coming in greatly appreciate assistance Loraine Gandara 5/1/2016 5/22/2016 31 \$ Medium Work In Progress 5/1/2016 1:03:24 AM \$ Orozco, Daniel Monthly- Gadsden ES - Range Hood Cleaning - Refer to PMschedule details. \$ \$ Margret Villalobos 5/1/2016 5/22/2016 31 \$ Medium Work In Progress 5/1/2016 1:03:24 AM \$ Vallejo, Albert Monthly- Gadsden ES - Fire Suppression Insp - Refer to PMschedule details. \$ \$ Margret Villalobos 15/4047 5/31/2016 1 \$ Medium Work In Progress 5/31/2016 12:54:42 AM A Apodaca, Mario Monthly - Gadsden ES - Monthly Meter Readings -	Loraine G	andara							
Gallegos, Rafael need immediate assistance for leak in roofwater coming in greatly appreciate assistance Loraine Gandara 152285 5/1/2016 5/22/2016 31 \$ Medium Work In Progress 5/1/2016 1:03:24 AM Orozco, Daniel Monthly- Gadsden ES - Range Hood Cleaning - Refer to PMschedule details. Margret Villalobos 152286 5/1/2016 5/22/2016 31 \$ Medium Work In Progress 5/1/2016 1:03:24 AM Vallejo, Albert Monthly- Gadsden ES - Fire Suppression Insp - Refer to PMschedule details. Margret Villalobos 154047 5/31/2016 1:53:44.24 AM Apodaca, Mario Monthly - Gadsden ES - Monthly Meter Readings -	142949				11/3/2015		211		\$0.00
Coming in greatly appreciate assistance Loraine Gandara	Medium	Work In Progress	Conference		11/3/2015 9:26:50 AM				
152285 5/1/2016 5/22/2016 31 3 4	Gallegos,	Rafael							
Medium Work In Progress 5/1/2016 1:03:24 AM Orozco, Daniel Monthly- Gadsden ES - Range Hood Cleaning - Refer to PMschedule details. Margret Villalobos 152286 5/1/2016 5/22/2016 31 \$ Medium Work In Progress 5/1/2016 1:03:24 AM Vallejo, Albert Monthly- Gadsden ES - Fire Suppression Insp - Refer to PMschedule details. Margret Villalobos 154047 5/31/2016 1:54:42 AM Apodaca, Mario Monthly - Gadsden ES - Monthly Meter Readings -		andara							
Orozco, Daniel Monthly- Gadsden ES - Range Hood Cleaning - Refer to PMschedule details. Margret Villalobos 152286 5/1/2016 5/22/2016 31 \$ Medium Work In Progress 5/1/2016 1:03:24 AM Vallejo, Albert Monthly- Gadsden ES - Fire Suppression Insp - Refer to PMschedule details. Margret Villalobos 154047 5/31/2016 1:54:42 AM Apodaca, Mario Monthly - Gadsden ES - Monthly Meter Readings -	152285				5/1/2016	5/22/2016	31		\$0.00
Margret Villalobos 152286 5/1/2016 5/22/2016 31 \$ Medium Work In Progress 5/1/2016 1:03:24 AM Vallejo, Albert Monthly- Gadsden ES - Fire Suppression Insp - Refer to PMschedule details. Margret Villalobos 154047 5/31/2016 1:54:42 AM Medium Work In Progress 5/31/2016 12:54:42 AM Apodaca, Mario Monthly - Gadsden ES - Monthly Meter Readings -	Medium	Work In Progress			5/1/2016 1:03:24 AM				
152286 5/1/2016 5/22/2016 31 \$ Medium Work In Progress 5/1/2016 1:03:24 AM Vallejo, Albert Monthly- Gadsden ES - Fire Suppression Insp - Refer to PM schedule details. Margret Villalobos 5/31/2016 1 \$ Medium Work In Progress 5/31/2016 12:54:42 AM Apodaca, Mario Monthly - Gadsden ES - Monthly Meter Readings -					Cleaning - Refer				
Medium Work In Progress 5/1/2016 1:03:24 AM Vallejo, Albert Monthly- Gadsden ES - Fire Suppression Insp - Refer to PM schedule details. Margret Villalobos 154047 5/31/2016 1 2:54:42 AM Medium Work In Progress 5/31/2016 12:54:42 AM Apodaca, Mario Monthly - Gadsden ES - Monthly Meter Readings -		llalobos			5/4/0040	F /00 /00 40			
Vallejo, Albert Monthly- Gadsden ES - Fire Suppression Insp - Refer to PM schedule details. Margret Villalobos 154047 5/31/2016 1 \$ Medium Work In Progress 5/31/2016 12:54:42 AM Apodaca, Mario Monthly - Gadsden ES - Monthly Meter Readings -							31		\$0.00
to PMschedule details. Margret Villalobos 154047 5/31/2016 1 \$ Medium Work In Progress 5/31/2016 12:54:42 AM Apodaca, Mario Monthly - Gadsden ES - Monthly Meter Readings -		· ·							
154047 5/31/2016 1 \$ Medium Work In Progress 5/31/2016 12:54:42 AM Apodaca, Mario Monthly - Gadsden ES - Monthly Meter Readings -	-				sion Insp - Refer				
Medium Work In Progress 5/31/2016 12:54:42 AM Apodaca, Mario Monthly - Gadsden ES - Monthly Meter Readings -		llalobos			5 /0.4 /0.04.0				
Apodaca, Mario Monthly - Gadsden ES - Monthly Meter Readings -							1		\$0.00
	Medium	Work In Progress			5/31/2016 12:54:42 AM				
	Apodaca,	Mario			er Readings -				

6/1/2016 11:47:07 AM Page 60 of 174

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Created Date/Time Actual Comp Date Status Area Number Reason **Priority Description Action Taken Assigned To** Requester Name Location: Gadsden ES 139709 9/10/2015 265 \$0.00 Work In Progress 9/10/2015 7:25:13 AM Medium Ontiveros, Guadalupe Please remove trees that have died and replace with Texas Ash. Please remove the dead ones ASAP, and replant once the trees have gone dormant this fall. Albert Vallejo Parking Lot 5/13/2016 19 \$0.00 153147 Medium Work In Progress 5/13/2016 11:07:03 AM Ontiveros. Joe need assistance with painting signs on the parking route to Joe asp albert blocks ex: PRINCIPAL, SECRETARY, and such.....would like to request orange and black paint.... Loraine Gandara Count: 22 Work Orders **Total for Gadsden ES** 0 Avg. Age of WO's 64 \$0.00

6/1/2016 11:47:07 AM Page 61 of 174

WOID Priority Assigned	ate Range for Request Building Status To	Area Area Number Description	Deferred By	Until F	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester		•							
Location:	Gadsden	HS							
153582					5/20/2016		12		\$0.00
Medium	Work In Progress			5/20/20	16 8:42:53 AM	1			
Medina, E	ric	repair wall dam tape, texture, a	aged bybreak in in nd paint	admin office					
Eric Medin	na								
153587					5/20/2016		12		\$0.00
Medium	Work In Progress			5/20/20	16 8:49:23 AM	1			
Medina, E	ric	repair partition'	s in boys gang restr	room in north bu	ilding				
Eric Medin	na								
154058					5/31/2016		1		\$0.00
Medium	Work In Progress			5/31/20	16 8:24:07 AM	1			
Medina, E	ric	please need to cafeteria thank	remove coolers ar you	nd sink in the kito	hen				
Luis Sauc	edo								
153918					5/25/2016		7		\$0.00
Medium	Work In Progress			5/25/20	16 3:40:45 PN	1			
Medina, E	ric	remove equipm	nent from kitchen						
Eric Medin	na								
152996					5/11/2016		21		\$0.00
Medium	Work In Progress			5/11/20	16 2:09:47 PN	1			
Medina, E	ric	Requested by re-assemble ca	Ms. Hartmann for Po abinet	ortable#7-Repa	irand				
Velia Alaro	con								
153171					5/13/2016		19		\$0.00
Medium	Work In Progress			5/13/20	16 2:42:24 PN	1			
Medina, E	ric		Mr. Mora Rm. 227 No cork board installed						
Velia Alaro	con								
153478					5/19/2016		13		\$0.00
Medium	Work In Progress			5/19/20	16 8:35:14 AM	1			
Ronquillo,	, Ruben		stalum.letters pain ners Gym. Installed		read				
Ruben Ro	nquillo								

6/1/2016 11:47:08 AM Page 62 of 174

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order Area Deferred By Area Number Reason Description	Days Aged	Labor Hours			
Location:	Gadsden	HS					
154099			5/31/2016		0		\$0.00
Medium	Work In Progress		5/31/2016 3:35:35 PM	5/31/2016			
Escobar, [David	05/31/2016. A/C unit in pool locker rooms service.	is down and needs				
David Esc	obar						
153399			5/18/2016		14		\$0.00
Medium	Work In Progress		5/18/2016 8:26:15 AM				
Escobar, [David	05/18/2016. repair of stall door and partition bathroom.	on at weight room girls				
David Esc	obar		5/40/0040		4.4		Φο οο
153449			5/18/2016		14		\$0.00
Medium	Work In Progress		5/18/2016 3:48:17 PM				
Escobar, [05/18/2016. fire alarm and construction a	tboys gym.				
David Esc	obar		5/20/2016		12		\$0.00
153581	Modela December				12		φυ.υυ
Medium Escobar, [Work In Progress David	05/20/2016. repair and paint wall at science restroom.	5/20/2016 8:41:39 AM ce bldg. upstairs boys				
David Esc	obar						
153583			5/20/2016		12		\$0.00
Medium	Work In Progress		5/20/2016 8:43:07 AM				
Escobar, D	David	05/20/2016. repair and rewire exit signs a	tgirls gym.				
David Esc	obar						
151468			4/15/2016		0		\$0.00
Medium	Work In Progress		4/15/2016 3:33:14 PM	4/15/2016			
Escobar, D		04/15/2016. unclog mop sink at janitor clo	os et at cafeteria .				
David Esc	obar		0/44/0040		00		ФО ОО
149467			3/11/2016		82		\$0.00
Medium	Work In Progress		3/11/2016 10:51:45 AM				
Escobar, D		Requested by Ms. Leahy Rm Light bulbs in Faculty Restroo					
Velia Alarc	on						

6/1/2016 11:47:08 AM Page 63 of 174

WOID Priority Assigned	Building Status To	Area Area Number Description	/30/2016 Order By Loc Deferred By Reason		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester		ue						
Location:	Gadsden	нъ						
149495				3/11/2016		82		\$0.00
Medium	Work In Progress			3/11/2016 3:38:33 PM				
Escobar, D	David	trouble shoot e locker room.	lectrical circuit to ligh	ts in boys baseball				
David Esc								
151394	Grounds Shop			4/14/2016		48		\$0.00
Medium	Work In Progress			4/14/2016 3:36:58 PM				
Herrera, Ja	aime	tools, chains, b	de bed mount tool be ooms and straps. Al tool boxes to tie down	so easier access to				
Jaime Her	rera							
149349				3/9/2016		84		\$0.00
Medium	Work In Progress			3/9/2016 3:47:32 PM				
Apodaca, I	Mario	Need to have g	rease traps pumped	out at panther hut				
Eric Medin	a							
149351				3/9/2016		84		\$0.00
Medium	Work In Progress			3/9/2016 3:48:30 PM				
Apodaca, I	Mario	Mario need che	mical for floor drains	thank you				
Eric Medin	a							
151613				4/19/2016		43		\$0.00
Medium	Work In Progress			4/19/2016 2:27:58 PM				
Apodaca, I	Mario	GHS POOL CH MAINTAIN THE	IEMICALS AND WAT WATER	ER FILTER TO				
Mario Apo	daca							
150384	Grounds Shop	Mechanical		4/1/2016		61		\$0.00
Medium	Work In Progress			4/1/2016 7:38:08 AM				
Apodaca, I	Mario	need spare blo plant	wer motor for waste	watertreatment				
Salvador N	Martinez							
150752	Cafeteria (1998)	Kitchen		4/5/2016		57		\$0.00
High	Work In Progress			4/5/2016 10:26:32 AM				
Orozco, Da	aniel		the Southbend Stov n need replacing. SN 5522					
Dino Facio)							

6/1/2016 11:47:08 AM Page 64 of 174

WOID Priority Assigned Requester	Building Status To	Area Area Number Description	/30/2016 Order By Loc Deferred By Reason	Until Request Date ¹ Created Date/Time		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Gadsden	HS							
152599					5/4/2016		28		\$0.00
Medium	Work In Progress			5/4/20	16 11:00:45 AM	1			
Lara, Ralpl	1	NEED TO BE S	VING LINE (ITALIAN) SECURED BY THE T 0.SNP MANAGER FI	TIME MANAGE					
Maritza Go	nzalez								
140674	Main Building	Pump House			9/25/2015		250		\$0.00
Medium	Work In Progress			9/25/20	015 4:01:26 PM	1			
Sanchez, F	Raul	chlorination eq well in case of	vork order for the inst uiptment for the supp emergencyuse		nestic				
Raul Sanc	hez	Thanks, Raul							
143192	1102				11/6/2015		208		\$0.00
Medium	Work In Progress			11/6/20	15 10:49:59 AM	1			
Gonzalez,	· ·		Coach Vasquezfor Fonts Coach Vasquezfor Fonts Coach Vasquezier						
Velia Alarc	on								
148065					2/19/2016		103		\$0.00
Medium	Work In Progress			2/19/20	016 3:24:59 PM	1			
Gonzalez,	Salvador	Need to replace gate (automatic	e gate wheels and hi c gate).	nges to the so	uth				
Guillermo	Hernandez								
147595					2/8/2016		114		\$0.00
Medium	Work In Progress			2/8/20	016 3:40:49 PN	1			
Gonzalez,	Salvador	Need to install the Weight room	window guard to new n.	v doors install	ed at				
	Hernandez								
151603					4/19/2016		43		\$0.00
Medium	Work In Progress			4/19/20	16 11:25:41 AM	1			
Lara, Ralpl	n	Rafa need to re	pair panic bar on doo	or in girls gym	thank				
Eric Medin	a								

6/1/2016 11:47:08 AM Page 65 of 174

WOID Building Priority Status Assigned To Requester Name		•	=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Gadsden	HS					
153063			5/12/2016		20		\$0.00
Medium	Work In Progress	5/12/2016	6 10:22:45 AM				
Lara, Ralpl	h	please i need assistance can you please help me with the curtain in the varsity gym it stock and we conot opened just one side as we needed for tomorromorning.	an				
Luis Sauce	edo						
153845			5/24/2016		8		\$0.00
Medium	Work In Progress	5/24/2016	6 12:05:39 PM				
Ronquillo,	Ruben	Ruben need grinder and grinding wheels					
Eric Medin	а						
153336			5/17/2016		15		\$0.00
Medium	Work In Progress	5/17/201	16 1:30:50 PM				
Flores, Pet	te	Pete truck 154 heated up and threw out water from pump hose	า				
Eric Medin	a						
144164			12/2/2015		182		\$0.00
Medium	Work In Progress	12/2/201	15 6:47:00 AM				
Flores, Pet	te	please the john deere gator uv-ghs-0905 is making of noise when driving can yuo plese see it thank y					
Luis Sauce	edo						
146628			1/22/2016		131		\$0.00
Medium	Work In Progress	1/22/201	16 3:52:32 PM				
Flores, Pet	te	please the john deere gator uv-ghs-0905 is making of noise when driving can yuo plese see as we nee to move furniture it thank you					
Luis Sauce	edo						
142871			11/2/2015		212		\$0.00
Medium	Work In Progress	11/2/2015	5 10:56:01 AM				
Flores, Pet	te	please the john deere gator uv-ghs-0905 flat tire fro the back of passenger side not good thank you	om				
Luis Sauce	edo						
153665			5/23/2016		9		\$0.00
Medium	Work In Progress	5/23/201	16 9:02:16 AM				
Lara, Ralpl	h	need to re-keybus turnaround for construction plea	ise				

6/1/2016 11:47:08 AM Page 66 of 174

WOID	Building	Area Number Bases	Until Request Date	-	Days Aged	Labor Hours	
Priority	Status	Area Number Reason	Created Date/Time	-	Ageu	Hours	
Assigned ⁻ Requester		Description		Action Taken			
<u> </u>		IIIC					
Location:	Gadsden	H5					
153679	North Building		5/23/2016		9		\$0.00
Medium	Work In Progress		5/23/2016 12:11:44 PM				
Lara, Ralp		can you please open one class roo building no key I need to clean it u thank you					
Luis Sauc							
152831	New Admin Bldg		5/9/2016		23		\$0.00
Medium	Work In Progress		5/9/2016 2:10:52 PM				
Lara, Ralp	h	Requested by Velia for Mail Box# not open with teacher's key or extra					
Velia Alarc	on		- // -				
153410			5/18/2016		14		\$0.00
Medium	Work In Progress		5/18/2016 10:42:08 AM				
Lara, Ralp	h	please needs to changes the locks boys gyms, old English gym as the floors needs to change the locks be thank you	ygoing to varnish the				
Luis Sauc	edo						
153517		Classroom	5/19/2016		13		\$0.00
Medium	Work In Progress		5/19/2016 2:40:09 PM				
Lara, Ralp	h	need to service locks and worked o	on door cylinders,				
Ralph Lara	a						
146493			1/21/2016		132		\$0.00
Medium	Work In Progress		1/21/2016 7:49:11 AM				
Ontiveros.	Guadalupe	Need to fill the rain run-outs around	dcampus.				
	Hernandez		,				
148287	110111011002		2/24/2016		98		\$0.00
Medium	Work In Progress		2/24/2016 8:43:23 AM				
Ontiveros, Guadalupe		Requested by Coach Yanezfor Bas maroon windscreen slats on the bas similar to S.T.H.S. fence. SEE COA MORE INFORMATION.	seball Field-Install aseball outfield fence,				
Velia Alarc	on						
146829		Athletic Field	1/27/2016		126		\$0.00
Medium	Work In Progress	Track	1/27/2016 10:12:18 AM				
Ontiveros,	Guadalupe	Requested by Coach Walker for Tra GHS Track 4-6 spots on track are worn or have holes on track surface track needs to be resurfaced.	extremely cracked,				
Velia Alaro	nn						

6/1/2016 11:47:08 AM Page 67 of 174

WOID Priority Assigned T	Building Status o	Dates:7/1/2015 - 6/30/2016 Order By Loc Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS					
141301		Athletic Field	10/8/2015		237		\$0.00
Medium	Work In Progress	Track Field	10/8/2015 3:36:12 PM				
Ontiveros, 0	-	Requested by Coach Walker for Tractrack, track has bubbled at the 14 your worn patches (x3-5). Needs to be reremarked.	d marker and has				
Velia Alarco	on						
152445			5/2/2016		30		\$0.00
Medium	Work In Progress		5/2/2016 10:53:50 AM				
Lara, Ralph	n	Requested by Coach Joseph Vasqu Coach's Office in Boy's Gym- Teach storage cabinet that's needs to be re are needed. This needs to be compl of the school year. Teacher will need store classroom items during the su	er has received a e-keyed and sixkeys eted before the end I to secure and				
Velia Alarco	on						
138952			8/28/2015		278		\$0.00
Medium	Work In Progress		8/28/2015 2:15:09 PM				
Lara, Ralph	1	Need to replace the panic bars to ba library, the alarm stopped working a books.					
Guillermo I	Hernandez						
152444		Classroom	5/2/2016		30		\$0.00
Medium	Work In Progress		5/2/2016 10:48:12 AM				
Lara, Ralph	n	Requested by Marie Acosta Rm. 326 -The built in cabinets need to be re-k keys are needed. This needs to be c end of the school year. Teacher will r store classroom items during the su	eyed and three ompleted before the need to secure and				
Velia Alarco	on						
150730			4/5/2016		57		\$0.00
Medium	Work In Progress		4/5/2016 8:00:28 AM				
Villalobos,	David	04/05/2016. piping in wall of girls restroom in we clear out.	eight room will not				
David Esco	bar						
143088			11/5/2015		209		\$0.00
Medium	Work In Progress		11/5/2015 7:01:35 AM				
Villalobos,	David	please on the weigth room girls res clogged and over flows i tried to uncl thank you					
Luis Sauce	ado	-					

6/1/2016 11:47:08 AM Page 68 of 174

Selected Da WOID Priority Assigned Requeste	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Location, Status Area Deferred By Until Request Date Ta Area Number Reason Created Date/Time A Description		Costs abor ours
Location:	Gadsden	HS		
136037	Boys Gym	7/16/2015	321	\$0.00
Medium	Work In Progress	7/16/2015 4:00:37 PM		
Villalobos	s, David	As per Mr. Giron he would like to have all the showers working. Location is locker rooms in the Boys Gym.		
Guillermo	Hernandez			
154130	New Vocational	6/1/2016	0	\$0.00
Medium	Work In Progress	6/1/2016 7:39:13 AM		
Appelzolle	er, Fred	Troubles hoot and repair Vocational air compressor.		
Albert Vall	lejo			
148634	Pool Pump	Pump House 2/29/2016	93	\$0.00
Medium	Work In Progress	2/29/2016 2:57:20 PM		
Villalobos	s, David	2 inch copper water line need to install a water strainer at the ghs pool pump room		
Mario Apo	odaca			
140227		9/18/2015	257	\$0.00
Medium	Work In Progress	9/18/2015 1:53:22 PM		
Chavez, Santos		Santos need to rewire outside light near panther paw light dropped and pulled out wires		
Eric Medir	na			
153344		5/17/2016	15	\$0.00
Medium	Work In Progress	5/17/2016 3:01:20 PM		
Castillo, C		Check all football field area lighting and electrical systems.		
Carlos Ca	astillo	- W-19949		
153345		5/17/2016	15	\$0.00
Medium	Work In Progress	5/17/2016 3:02:52 PM		
Castillo, C	Carlos	Check football field electrical and lighting systems.		
Carlos Ca	astillo			
153584		5/20/2016	12	\$0.00
Medium	Work In Progress	5/20/2016 8:44:18 AM		
Escobar,	David	05/20/2016. paint football coaches offices.		
David Esc	cobar			*
153586		5/20/2016	12	\$0.00
Medium	Work In Progress	5/20/2016 8:45:35 AM		
Escobar,		05/20/2016. paint hand rails at science bldg.		
David Esc	cobar			
6/1/2016	11:47:08 AM			Page 69 of 174

6/1/2016 11:47:08 AM Page 69 of 174

WOID Priority Assigned		Area Area Number Description	Deferred By Reason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Requester								
Location:	Gadsden	HS						
153585				5/20/2016		12		\$0.00
Medium	Work In Progress			5/20/2016 8:44:25 AM				
Medina, Eı	ric	scrape off old p portables 11,1		ors and iron bars on				
Eric Medin								
153579	Boys Gym			5/20/2016		12		\$0.00
Medium	Work In Progress			5/20/2016 8:40:15 AM				
Medina, Eı	ric	paint boys gym	building					
Eric Medin	а							
153580				5/20/2016		12		\$0.00
Medium	Work In Progress			5/20/2016 8:41:14 AM				
Medina, Eı	ric	primer and pair	nt walls in north buil	ding				
Eric Medin	а							
153212				5/16/2016		16		\$0.00
Medium	Work In Progress			5/16/2016 7:55:47 AM				
Ronquillo,	Ruben	need window re and 1/2 double		fice 79 and 3/4 by 36				
Eric Medin	a							
146847		Athletic Field		1/27/2016		126		\$0.00
Medium	Work In Progress			1/27/2016 2:27:04 PM				
Holguin, A	Ifredo		tificial Turf - Perforn e, Seam Repairs a	n SportChamp deep nd add infill Rubber				
Alfredo Ho	lguin							
150740		Athletic Field		4/5/2016		57		\$0.00
Medium	Work In Progress			4/5/2016 8:44:03 AM				
Ronquillo,	Ruben	need 15 gallon	sprayer					
Guadalupe	e Ontiveros							
152066				4/27/2016		35		\$0.00
Medium	Work In Progress			4/27/2016 11:04:45 AM				
Ontiveros,	Guadalupe	barriers to prevand 5 foot outsi	ent parking - Space de of outside white posts so we have s	/ 228 - install flexible e them 5 foot apart line. will need a ome spare when they				

6/1/2016 11:47:08 AM Page 70 of 174

Selected Day WOID Priority Assigned Requester		Dates:7/1/2015 - 6/ Area Area Number Description	Deferred By	Until Request Date	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS						
141599				10/13/2015	5	232		\$0.00
Medium	Work In Progress			10/13/2015 11:37:3	1			
Ontiveros,	Guadalupe	regular trash du across from Te	mpster from the blo ch/Ag building to the nurse/girls gym. C	ess road- Move one ock enclosed area e block enclosed area all Alfredo as soon as				
Alfredo Ho	lguin							
154035				5/31/2016	7/1/2016	1		\$0.00
Medium	Work In Progress			5/31/2016 12:54:33 AM	M			
Escobar, D	Pavid	Yearly - Gadsde PMschedule de	en HS A2 (H/C Unit etails.)(Yearly) - Refer to				
Margret Vil	lalobos							
152272				5/1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress			5/1/2016 1:03:13 AM	M			
Orozco, Da	nniel	Monthly-Gadso PMschedulede		d Cleaning - Refer to				
Margret Vil	lalobos							
152294				5/1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress			5/1/2016 1:03:30 AM	M			
Vallejo, Alb	pert	Monthly-Gadso PMschedulede		ssion Insp Refer to				
Margret Vil	lalobos							
153656				5/22/2016	3	10		\$0.00
Medium	Work In Progress			5/22/2016 12:30:33 AM	M			
Medina, Er	ic	Daily - Gadsdei PMschedule de		Biweekly) - Refer to				
Margret Vil	lalobos							
154055				5/31/2016	5	1		\$0.00
Medium	Work In Progress			5/31/2016 12:54:47 AM	M			
Martinez, S	Salvador	Monthly - Gads Refer to PMsch	den HS - Monthly M edule details.	eter Readings -				
Margret Vil	lalobos							
143602				11/15/2015	5	145	6	\$348.59
Medium	Work In Progress			11/15/2015 12:27:5	3 4/8/2016			
Villalobos, Margret Vil		Yearly-Gadsde Refer to PMsch		419/0428) Grounds -	Pending 04190408 3/31/2016 replaced blades, reverse ped work on 4/18 replace bus hings	air, oiİ, fu Ial0428-	uel filters & completed	ķ

6/1/2016 11:47:08 AM Page 71 of 174

Selected Da WOID	te Range for Request Building	Dates: 7/1/2015 - 6 Area	6/30/2016 Order By Loca Deferred By		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•	<u>-</u>	Actual Comp Date	Aged	Hours	
Assigned	То	Description			Action Taken			
Requeste	r Name							
Location:	Gadsden	HS						
153169				5/13/201		19		\$0.00
Medium	Work In Progress			5/13/2016 2:35:49 P	M			
Vallejo, Al	bert	Constructnew	softball back stop sys	stem.				
Albert Vall	eio							
151283	•			4/13/201	6	49		\$0.00
Medium	Work In Progress			4/13/2016 8:43:54 A	M			
Vallejo, Al	bert	Repair door fra	ame in gym.					
Albert Vall	eio							
152152	•			4/28/201	6	34		\$0.00
Medium	Work In Progress			4/28/2016 2:41:07 P	M			
Vallejo, Al	bert	Constructnew	backstop at baseball	field				
Albert Vall	ejo							
151275				4/13/201	6	49		\$0.00
Medium	Work In Progress			4/13/2016 8:16:49 A	M			
Carbajal,	Jimmy	varsity gym, bo	ng for the varnishing o bys,and the girls gym. hey are completed. th	, to begin on june				
Luis Sauc	edo							
146908		Athletic Field		1/28/201	6	125		\$0.00
Medium	Work In Progress			1/28/2016 11:02:35 A	M			
Ontiveros	Guadalupe		Coach Walker for Disond install net for track r field.					
Velia Alar	con							
153400		Athletic Field		5/18/201	6	14		\$0.00
High	Work In Progress			5/18/2016 8:27:45 A	M			
Gonzalez,	Salvador	Soccer goal or sides.	n upper field needs to l	be weld on the				
Guadalup	e Ontiveros							
151916				4/25/201	6	37		\$0.00
Medium	Work In Progress			4/25/2016 1:41:28 P	M			
Ambriz, Jo	se		A/C is leaking from wa					

6/1/2016 11:47:08 AM Page 72 of 174

Guadalupe Ontiveros

Priority Assigned ⁻			Deferred By	Until	ricquest bate	Target Comp Date	Days	Labor	
Assigned	Status	Area Number	•	Crea	ted Date/Time	Actual Comp Date	Aged	Hours	
	Го	Description				Action Taken			
Requester	Name								
Location:	Gadsden	HS							
153748					5/24/2016		8		\$0.00
Medium	Work In Progress			5/24/2	016 8:01:34 AM	1			
Villalobos,	Jose		& dry vacuum # 022 oneed a loaner thank y		k up the				
Luis Sauc	edo								
153749		Custodial			5/24/2016		8		\$0.00
Medium	Work In Progress			5/24/2	016 8:03:04 AM	1			
Villalobos,	Jose		& dry vacuum # 2272 I need a loaner thank		e				
Luis Sauc	edo								
153136					5/12/2016		20		\$0.00
Medium	Work In Progress			5/12/2	016 8:53:56 PM	1			
Villalobos,	Jose	please I need a	vacuum bag.						
		thank you							
Luis Sauc	edo								
153489					5/19/2016		13		\$0.00
Medium	Work In Progress			5/19/20	16 10:48:29 AM	1			
Villalobos,	Jose	model #GWD3 WORKING	60 THE ADVANCE W	VET AND DR	YNOT				
Luis Sauc	edo								
151369					4/14/2016		48		\$0.00
Medium	Work In Progress	UV GHS 0905		4/14/20	16 10:46:29 AM	1			
Flores, Pe	te	when turning to	out of the alignment of left rubs against the d to Mr. Carbajal toda	fender as pe					
Luis Sauc	edo								
153840					5/24/2016		8		\$0.00
Medium	Work In Progress			5/24/20	16 11:21:40 AM	1			
Villalobos,	Jose	Loan new vipe	r wet dry to Custodia	I					

6/1/2016 11:47:08 AM Page 73 of 174

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Area Number Reason Created Date/Time Actual Comp Date Status **Priority Assigned To Description Action Taken** Requester Name Location: Gadsden HS 153332 Pool Dressing Pool 5/17/2016 15 \$0.00 Medium Work In Progress 5/17/2016 12:38:15 PM Carbajal, Jimmy Need the following supplies for the pool: Hand Soap for dispensers Toilet Bowl Cleaner Toilet Bowl Brush Regular Broom (2) Disinfectant for Diaper Changing Table Thank you Terry Alvarado 5/18/2016 14 \$0.00 153452 Medium Work In Progress 5/18/2016 3:51:41 PM Flores, Pete 05/18/2016. UTV 05-15 will not start. possible fuel system problem. David Escobar Grounds Shop 4/20/2016 42 \$0.00 151664 Medium Work In Progress 4/20/2016 7:53:18 AM Need special Hand ratchet in order to use bits. Also a Herrera, Jaime 3/8 breaker bar and a 1/2 breaker bar to break bolts when to tight. Jaime Herrera Count: 85 Work Orders **Total for Gadsden HS** Avg. Age of WO's 61 6 \$348.59

6/1/2016 11:47:08 AM Page 74 of 174

WOID Priority Assigned Requester	Building Status To	Area Area Number Description	/30/2016 Order By Loc Deferred By Reason	Until Request Date	e Target Comp Date e Actual Comp Date Action Taken	Days Lab Aged Hou	
Location:	Gadsden	MS					
150901	Cafeteria	Office		4/7/2016	3	55	\$0.00
Medium	Work In Progress			4/7/2016 8:43:55 Al	М		
Solis, Lore	enzo	need to replac	e duct work SNP offic	ce			
Mario Herr	era						
152985	Gym	Athletic Field		5/11/2016	6	21	\$0.00
Medium	Work In Progress	TENNIS		5/11/2016 11:12:05 A	М		
Ontiveros,	Guadalupe	LUPE - GROU	NDS,				
		OF OUTDOOR	PLEASE BE ABLE TO BASKETBALL SYST RTS, INCLUDES THE	EM IN THE OLD			
		PO# 15160710	00 - 7 PIECES (AT W	AREHOUSE) - GMS			
		THANK YOU!					
Terry Alvar	ado						
146986	C-Wing			1/29/2016	6	124	\$0.00
Medium	Work In Progress	AVECHS-		1/29/2016 10:52:15 A	M		
Chavez, Sa	antos	need to install	an outlet in the studer	nt union.			
Rosa Que	zada						
153321	Cafeteria	Kitchen		5/17/2016	6	15	\$0.00
Medium	Work In Progress			5/17/2016 9:28:19 Al	М		
Carbajal,	limmy		air in kitchen and offic sa P. (575) 882-2824	e area. SNP			
Dino Facio)						
151892				4/25/2016	6	37	\$0.00
Medium	Work In Progress			4/25/2016 8:11:35 Al	M		
Facio, Dine	0	MILK COOLER P.882.2824	DOWN. SNP MANA	GER TERRY	A&M WAS CALLED	OUT 10:50 AM	
Maritza Go	nzalez						
151580	Gym	Gym		4/19/2016	6	43	\$0.00
Medium	Work In Progress			4/19/2016 7:44:45 Al	М		
Carbajal, c	limmy		em come varnish the can come anytime in				
Martin Sor	ia						

6/1/2016 11:47:08 AM Page 75 of 174

WOID	Building	Area Deferred By	Until Request Date Target Co	A	Labor Hours
Priority	Status	Area Number Reason	Created Date/Time Actual Co	•	nours
Assigned Requeste		Description	Actio	on Taken	
Location:		MS			
	Gausuen		F/0.4/0.04C		Фо оо
153846		Custodial	5/24/2016	8	\$0.00
Medium	Work In Progress		5/24/2016 12:26:39 PM		
Herrera, N		Out of propane for the propane bu Requesting more propane.	rnisher.		
Martin So			-12.15		
153825	Band Room		5/24/2016	8	\$0.00
Medium	Work In Progress	Band room	5/24/2016 10:43:29 AM		
Soria, Ma	rtin	Front entrance, buff and seal tile			
Hilda Adle	er				
151463			4/15/2016	47	\$0.00
Medium	Work In Progress		4/15/2016 3:11:49 PM		
Castillo, C	Carlos	A-Wing - No power			
Mario Her	rera				
153822	Band Room		5/24/2016	8	\$0.00
Medium	Work In Progress	Band room	5/24/2016 10:39:02 AM		
Herrera, N	<i>M</i> ario	Finish instrument bins Paint in pe	rcussion room		
Hilda Adle	er				
153828	Band Room		5/24/2016	8	\$0.00
Medium	Work In Progress	Entrance to	5/24/2016 10:53:38 AM		
Herrera, N	Mario	Paint outside entrance doors, fror	ntand back		
Hilda Adle					
153594	-		5/20/2016	12	\$0.00
Medium	Work In Progress		5/20/2016 10:08:43 AM		
Herrera, N	_	need paint to paint class rooms in school	different part of the		
Mario Her	rera				
153671	Main Building	Office	5/23/2016	9	\$0.00
Medium	Work In Progress	Mrs. Mejia's	5/23/2016 10:41:53 AM		
Herrera, N	Mario	Please paint Office and paint doo	or. Thank you		
Hilda Adle	er				
152901		Classroom	5/10/2016	22	\$0.00
Medium	Work In Progress	A-Wing Rm#169	5/10/2016 3:26:53 PM		
Herrera, N	<i>l</i> lario	Classroom needs a paint job. Re- Please mount flag holders next to any. Thank you			
Hilda Adle	er				
6/1/2016	11:47:08 AM				Page 76 of 174
0, 1, =0.0	1 11 11 100 7 1111				rage room r

6/1/2016 11:47:08 AM Page 76 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da	ate Range for Request Building	Dates:7/1/2015 - 6 Area	6/30/2016 Order By Loc Deferred By		equest Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	-		=	Actual Comp Date	Aged	Hours	
Assigned		Description				Action Taken			
Requeste	r Name								
Location:	Gadsden	MS							
153672	Vocational	Classroom			5/23/2016		9		\$0.00
Medium	Work In Progress	Voc #308		5/23/2016	10:44:13 AM	1			
Herrera, N	<i>l</i> lario	Please paint the white-board.	ne pink square on wa	all that is next to th	е				
Hilda Adle	er								
153688		Classroom			5/23/2016		9		\$0.00
Medium	Work In Progress	B-Wing Rm#1	22	5/23/2016	12:54:25 PM	1			
Herrera, M	Mario	Please paint th	ie class room						
Hilda Adle	er								
153690		Classroom			5/23/2016		9		\$0.00
Medium	Work In Progress	A-Wing Rm#1	61	5/23/201	6 1:00:43 PN	И			
Herrera, N	<i>l</i> ario	Paint the wall needs white pa	next to the door, ther aint	re's a pink squar	e that				
Hilda Adle	er								
153680		Classroom			5/23/2016		9		\$0.00
Medium	Work In Progress	B-Wing Rm#1	40	5/23/2016	12:30:15 PM	1			
Herrera, M		Please paint roceiling. Thank	oom including the po cyou	oles that support					
Hilda Adle	er	Classroom			5/17/2016		15		\$0.00
153337	We date Decrees		00	E /4.7/0.04			15		φυ.υυ
Medium	Work In Progress	A-Wing Rm#1		5/17/201	6 2:32:55 PN	/1			
Herrera, N		-Please paint or -Paint brown s	door trip where the call bu	utton is at					
Hilda Adle 153338	er	Classroom			5/17/2016		15		\$0.00
Medium	Work In Progress			E/17/201	3/17/2010 6 2:35:22 PN		13		ψ0.00
	Work In Progress	A_Wing		5/17/201	0 2.30.22 PN	/1			
Herrera, M		Please paint ro	om						
Hilda Adle	er	Classroom			5/17/2016		15		\$0.00
153339 Medium	Work In Progress		5 0	E/17/201			15		φυ.υυ
	· ·	A-Wing Rm#1		5/17/201	6 2:36:17 PN	/1			
Herrera, M		Please paint ro	OOM						
Hilda Adle	Annex				5/18/2016		14		\$0.00
153393				E/40/004			14		φυ.υυ
Medium	Work In Progress				6 7:42:17 AN	1			
	, Guadalupe	Please fill gard Thank you	den beds up with top	soil ASAP					
Mario Her	rera								
2/4/2040	11.47.08 ΔΜ								77 of 174

6/1/2016 11:47:08 AM Page 77 of 174

WOID Priority Assigned Requester			ferred By	Until Request Da	te Target Comp Date ne Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	MS						
153823	Band Room			5/24/20	16	8		\$0.00
Medium	Work In Progress	Band room		5/24/2016 10:40:53	AM			
Hernande	z, Guillermo	Flush AC System in	n back large units					
Hilda Adle	r							
153320	Cafeteria	Kitchen		5/17/20	16	15		\$0.00
Medium	Work In Progress			5/17/2016 9:25:56	AM			
Ontiveros,	Joe	3 compartment sir (rusting) SNP Man						
Dino Facio)							
152250				4/30/20	16	32		\$0.00
Medium	Work In Progress			4/30/2016 12:41:27	AM			
Apodaca,	Mario	Monthly - Gadsder (Monthly) - Refer to						
Margret Vi	llalobos							
154048				5/31/20	16	1		\$0.00
Medium	Work In Progress			5/31/2016 12:54:43	AM			
Apodaca,	Mario	Monthly - Gadsder Refer to PMsched		eter Readings -				
Margret Vi	llalobos							
152295				5/1/20	16 5/22/2016	31		\$0.00
Medium	Work In Progress			5/1/2016 1:03:31	AM			
Vallejo, Al	bert	Monthly - Gadsder PMschedule detai		ssion Insp Refer to				
Margret Vi								
145061	C-Wing	Office		12/15/20	15	169		\$0.00
Medium	Work In Progress	AVECHS-		12/15/2015 1:02:11	PM			
Chavez, S	antos	THE LIGHT SWITC BE MOVED TO TH ENTRANCE INSTI (QUEZADA)	E FRONT OF TH					
Rosa Que								
148847	C-Wing	Office		3/3/20	16	90		\$0.00
Medium	Work In Progress	AVECHS-		3/3/2016 10:44:24	AM			
Chavez, S	antos	Need an electrical projector in the cor		•				
	zada							

6/1/2016 11:47:08 AM Page 78 of 174

WOID	Building	Area Deferred By		Target Comp Date	Days	Labor	
Priority	Status	Area Number Reason	Created Date/Time		Aged	Hours	
Assigned		Description		Action Taken			
Requester	Name						
Location:	Gadsden	MS					
153675	C-Wing	Exterior	5/23/2016		9		\$0.00
Medium	Work In Progress	C-Wing area	5/23/2016 10:48:37 AN	1			
Herrera, M	ario	Mario, when you have some time, over to cut the grass in C-Wing a					
		Thank you!					
Terry Alvar			F /0 4 /0 04 C				#0.00
153829	Band Room		5/24/2016		8		\$0.00
Medium	Work In Progress	frontentrance	5/24/2016 10:59:49 AM	1			
Herrera, M	ario	Front entrance lands cape, clear w	veeds				
Hilda Adle	r						
152273			5/1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress		5/1/2016 1:03:14 AM	1			
Orozco, Da		Monthly - Gadsden MS Range Ho PMschedule details.	ood Cleaning - Refer to				
Margret Vi	lalobos		2/2//22/2				
150254			3/31/2016		62		\$0.00
Medium	Work In Progress		3/31/2016 12:46:09 AM	1			
Herrera, M		Monthly - Gadsden MS A-16 Fan Refer to PMschedule details.	Exhaust Semiannual -				
Margret Vi	lalobos		0/00/0040	0/04/0040	00		#0.00
148574			2/29/2016		93		\$0.00
Medium	Work In Progress		2/29/2016 12:58:22 AM	1			
Herrera, N		Yearly - Gadsden MS C-11 Evap to PMschedule details.	Coolers Yearly - Refer				
Margret Vi	lalobos		F /0.4 /0.04C	7/4/2040			ФО 00
154043			5/31/2016		1		\$0.00
Medium	Work In Progress		5/31/2016 12:54:39 AM	1			
Herrera, M		Yearly - Gadsden MS A-2 Split Sy to PMschedule details.	stems Yearly - Refer				
Margret Vi	lalobos		E 10.1 10.010	7/4/0040			* • • • • • • • • • • • • • • • • • • •
154044			5/31/2016		1		\$0.00
Medium	Work In Progress		5/31/2016 12:54:40 AM	1			
Herrera, M	ario	Yearly - Gadsden MS A-9 Air Coo Refer to PMschedule details.	led Cond Yearly -				
Margret Vi	lalobos						

6/1/2016 11:47:08 AM Page 79 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da	ate Range for Request Building	Dates:7/1/2015 - 6	6/30/2016 Order By Lo Deferred By		Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	_		=	Actual Comp Date	Aged	Hours	
Assigned		Description				Action Taken			
Requeste		•							
Location:	Gadsden	MS							
145979					1/11/2016		142		\$0.00
Medium	Work In Progress	See Mr.Mora		1/11/20	016 9:54:29 AM	1			
Marquez,		storage with (1	n expanded metal sto I) expanded door & r. Mora for details. T	(1) loft key.					
Hilda Adle									
137816	C-Wing				8/12/2015		294		\$0.00
Medium	Work In Progress	AVECHS -		8/12/20	015 9:06:55 AM	1			
Marquez,	Gerardo	Need keys is so Counselor Eve	ued for Custodian Je elyn Chisari.	eremy Apodaca	and				
Margret V	illalobos								
145125		Cafeteria			12/16/2015		168		\$0.00
Medium	Work In Progress			12/16/20	015 8:52:29 AM	1			
Marquez,	Gerardo		A PRICE QUOTE TO FETERIA ROLL UP						
Gerardo M	Marquez								
143488					11/12/2015		202		\$0.00
Medium	Work In Progress			11/12/20	015 3:31:25 PM	1			
Marquez,	Gerardo		ychain and padlock t EPEC can double lo		eter				
Albert Val	lejo								
153643		Gym			5/20/2016		12		\$0.00
Medium	Work In Progress			5/20/20	016 3:51:53 PN	1			
Marquez,	Gerardo	changed Stout	n we need the locks floors will be sched y July 1, Thank you						
Jimmy Ca	arbajal								
153561					5/20/2016		12		\$0.00
Medium	Work In Progress			5/20/20	016 7:47:43 AM	1			
Marquez,	Gerardo	CHECK DRS I	FOR PROPER OPE	RATION.					
Gerardo M	<i>M</i> arquez								
151836	Cafeteria	Cafeteria			4/22/2016		40		\$0.00
Medium	Work In Progress			4/22/20	16 10:37:42 AM	1			
Ontiveros	, Guadalupe		us her fine for front of here the mora tree is lastic.						
Martin So	ria								

6/1/2016 11:47:08 AM Page 80 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da	te Range for Request Building	Dates:7/1/2015 - 6 Area	/30/2016 Order By Loca Deferred By		e Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•		e Actual Comp Date	Aged	Hours	
Assigned ¹	То	Description			Action Taken			
Requester	Name							
Location:	Gadsden	MS						
145631	C-Wing	Portables		1/5/201	6	148		\$0.00
Medium	Work In Progress			1/5/2016 2:44:05 F	PM			
Vallejo, Alt	pert	Roof in Nursing	g Dept portable leakin	g.				
Lisa Alarco	on							
153824	Band Room	Office		5/24/201	6	8		\$0.00
Medium	Work In Progress	Band room		5/24/2016 10:42:18	AM			
Herrera, M	ario	Check and rep	ace light bulbs in offic	е				
Hilda Adle	r							
153139				5/13/201	6	19		\$0.00
Medium	Work In Progress			5/13/2016 8:03:24	AM			
Solis, Lore	enzo	Requesting big	gger pulley For auto sh	op A/C	route to Lorenzo asp	albert		
Mario Herr	era							
153158	Cafeteria	Kitchen		5/13/201	6	19		\$0.00
Medium	Work In Progress	Cafeteria		5/13/2016 1:31:53 F	PM			
Soria, Mar	tin	Please replace kitchen.	all our soap dispens	ers in the cafeteria				
Hilda Adle	r							
151594		Classroom		4/19/201	6	43		\$0.00
Medium	Work In Progress	A-Wing Rm#16	54	4/19/2016 10:48:31 A	AM			
Herrera, M	ario	Please caulk w	indow seals & cover v	ents.				
Hilda Adle	r							
153676		Classroom		5/23/201	6	9		\$0.00
Medium	Work In Progress	Rm#159 Sims		5/23/2016 10:49:53 A	AM			
Herrera, M	ario		s over teachers desk loes not work, please	fix.				
Hilda Adle	r							
153419		Classroom		5/18/201	6	14		\$0.00
Medium	Work In Progress	A-Wing Rm#18	57	5/18/2016 1:47:20 F	PM			
Herrera, M	ario	- Paint room - move flags to the TV.	the right side of boar	d so they don't block				
Hilda Adle	r							
153268		Classroom		5/16/201	6	16		\$0.00
Medium	Work In Progress	A-Wing Rm#1	56	5/16/2016 2:43:14 F	PM			
		Diagon Doint d						
Herrera, M	ario	Please Paint d	oor					

6/1/2016 11:47:08 AM Page 81 of 174

1141 - Work Orders In Progress (Fiscal Year)

Sequester Name Seq	\$0.00
Medium Work In Progress 5/10/2016 9:45:28 AM Herrera, Mario Would like to have all of Nurses storage moved to bathroom' portable. Please contact Mrs. Creegan or Runyan for any questions. Lisa Alarcon 153141 Main Building Library 5/13/2016 8:06:42 AM Medium Work In Progress 5/13/2016 8:06:42 AM Herrera, Mario Paint Library summer project Mario Herrera Vork In Progress 9 Medium Work In Progress a-awing 5/23/2016 12:36:57 PM Herrera, Mario -Remove pull down screen on top of green chalk boards - Replace missing board on wall next to door Hilda Adler 153682 Classroom 5/23/2016 12:39:52 PM Herrera, Mario Install BB on wall. Hilda Adler Install BB on wall. Hilda Adler Electrical wires are exposed. Please cover properly for safety. Hilda Adler Electrical wires are exposed. Please cover properly for safety.	\$0.00
Medium Work In Progress 5/10/2016 9:45:28 AM Herrera, Mario Would like to have all of Nurses storage moved to bathroom' portable. Please contact Mrs. Creegan or Runyan for any questions. Lisa Alarcor 153141 Main Building Library 5/13/2016 8:06:42 AM Medium Work In Progress 5/13/2016 8:06:42 AM Herrera, Mario Paint Library summer project Mario Herrera Vork In Progress 9 Medium Work In Progress a-awing 5/23/2016 12:36:57 PM Herrera, Mario - Remove pull down screen on top of green chalk boards - Replace missing board on wall next to door Hilda Adler Classroom 5/23/2016 9 Medium Work In Progress B-Wing RM#112 5/23/2016 12:39:52 PM Herrera, Mario Install BB on wall. Hilda Adler Install BB on wall. Herrera, Mario Classroom 5/16/2016 10:28:50 AM Herrera, Mario Electrical wires are exposed. Please cover properly for safety. Hilda Adler Electrical wires are exposed. Please cover properly for safety.	
Sathroom' portable. Please contact Mrs. Creegan or Runyan for any questions. Saturyan for any questions.	
183141 Main Building	
Medium Work In Progress 5/13/2016 8:06:42 AM Herrera, Mario Paint Library summer project Mario Herrera 153681 Classroom 5/23/2016 9 Medium Work In Progress a-awing 5/23/2016 12:36:57 PM Herrera, Mario - Remove pull down screen on top of green chalk boards - Replace missing board on wall next to door Hilda Adler 5/23/2016 9 Medium Work In Progress B-Wing RM#112 5/23/2016 12:39:52 PM Herrera, Mario Install BB on wall. Hilda Adler 153252 Classroom 5/16/2016 10:28:50 AM Herrera, Mario Electrical wires are exposed. Please cover properly for safety. Hilda Adler Classroom 5/16/2016 16	
Herrera, Mario Paint Library summer project	\$0.00
Mario Herrera Classroom 5/23/2016 9 Medium Work In Progress a-awing 5/23/2016 12:36:57 PM Herrera, Mario - Remove pull down screen on top of green chalk boards - Replace missing board on wall next to door Hilda Adler 153682 Classroom 5/23/2016 9 Medium Work In Progress B-Wing RM#112 5/23/2016 12:39:52 PM 9 Herrera, Mario Install BB on wall. Hilda Adler 16 Medium Work In Progress Voc Rm#303 5/16/2016 10:28:50 AM 16 Herrera, Mario Electrical wires are exposed. Please cover properly for safety. Hilda Adler 16 Hilda Adler Classroom 5/16/2016 16	
153681 Classroom 5/23/2016 9	
Medium Work In Progress a-awing 5/23/2016 12:36:57 PM Herrera, Mario - Remove pull down screen on top of green chalk boards - Replace missing board on wall next to door Hilda Adler 5/23/2016 9 Medium Work In Progress B-Wing RM#112 5/23/2016 12:39:52 PM Herrera, Mario Install BB on wall. Hilda Adler 153252 Classroom 5/16/2016 16 Medium Work In Progress Voc Rm#303 5/16/2016 10:28:50 AM Herrera, Mario Electrical wires are exposed. Please cover properly for safety. Hilda Adler Classroom 5/16/2016 16	
Herrera, Mario - Remove pull down screen on top of green chalk boards - Replace missing board on wall next to door Hilda Adler 153682 Classroom 5/23/2016 9 Medium Work In Progress B-Wing RM#112 5/23/2016 12:39:52 PM Herrera, Mario Install BB on wall. Hilda Adler 153252 Classroom 5/16/2016 16 Medium Work In Progress Voc Rm#303 5/16/2016 10:28:50 AM Herrera, Mario Electrical wires are exposed. Please cover properly for safety. Hilda Adler 153253 Classroom 5/16/2016 16	\$0.00
- Replace missing board on wall next to door Hilda Adler 153682 Classroom 5/23/2016 9 Medium Work In Progress B-Wing RM#112 5/23/2016 12:39:52 PM Herrera, Mario Install BB on wall. Hilda Adler 153252 Classroom 5/16/2016 10:28:50 AM Herrera, Mario Electrical wires are exposed. Please cover properly for safety. Hilda Adler 153253 Classroom 5/16/2016 10:28:50 AM	
153682 Classroom 5/23/2016 9	
Medium Work In Progress B-Wing RM#112 5/23/2016 12:39:52 PM Herrera, Mario Install BB on wall. Hilda Adler 153252 Classroom 5/16/2016 16 Medium Work In Progress Voc Rm#303 5/16/2016 10:28:50 AM Herrera, Mario Electrical wires are exposed. Please cover properly for safety. Hilda Adler 153253 Classroom 5/16/2016 16	
Herrera, Mario Install BB on wall. Hilda Adler 153252 Classroom 5/16/2016 16 Medium Work In Progress Voc Rm#303 5/16/2016 10:28:50 AM Herrera, Mario Electrical wires are exposed. Please cover properly for safety. Hilda Adler 153253 Classroom 5/16/2016 10:28:50 AM	\$0.00
Hilda Adler 153252 Classroom 5/16/2016 16 Medium Work In Progress Voc Rm#303 5/16/2016 10:28:50 AM Herrera, Mario Electrical wires are exposed. Please cover properly for safety. Hilda Adler 153253 Classroom 5/16/2016 16	
153252 Classroom 5/16/2016 16 Medium Work In Progress Voc Rm#303 5/16/2016 10:28:50 AM Herrera, Mario Electrical wires are exposed. Please cover properly for safety. Hilda Adler 153253 Classroom 5/16/2016 16	
Medium Work In Progress Voc Rm#303 5/16/2016 10:28:50 AM Herrera, Mario Electrical wires are exposed. Please cover properly for safety. Hilda Adler 153253 Classroom 5/16/2016 10:28:50 AM	
Herrera, Mario Electrical wires are exposed. Please cover properly for safety. Hilda Adler 153253 Classroom 5/16/2016 16	\$0.00
safety. Hilda Adler 153253 Classroom 5/16/2016 16	
153253 Classroom 5/16/2016 16	
	\$0.00
Medium Work In Progress Voc Rm#303 5/16/2016 10:34:13 AM	
Herrera, Mario -Fire extinguisher is on the floor, needs to be mounted on the wallPlease install flag holders Paint the door, it needs a paint job.	
Hilda Adler	
153254 Classroom 5/16/2016 16	\$0.00
Medium Work In Progress Voc Rm#302 5/16/2016 10:39:27 AM	
Herrera, Mario -holes on wall need to be covered/repairedinstall flag holders and flags -Paint doors	
Hilda Adler	

6/1/2016 11:47:08 AM Page 82 of 174

153689 Annex Classroom 5/23/201 Medium Work In Progress Annex Rm#401 5/23/2016 12:56:30 P Herrera, Mario Base board is falling, please fix (by computer on floor) Hilda Adler 146289 1/15/201 Medium Work In Progress Front Office-Gulf 1/15/2016 12:05:14 P Flores, Pete Need 6 keys for New Gulf Cart. Approved per Mrs. Quinonez. Should you need additional information please contact Connie Avalos. Thank you Hilda Adler	M 3	9	\$0.00
Location: Gadsden MS 153689 Annex Classroom 5/23/201 Medium Work In Progress Annex Rm#401 5/23/2016 12:56:30 P Herrera, Mario Base board is falling, please fix (by computer on floor) Hilda Adler 146289 1/15/201 Medium Work In Progress Front Office-Gulf 1/15/2016 12:05:14 P Flores, Pete Need 6 keys for New Gulf Cart. Approved per Mrs. Quinonez. Should you need additional information please contact Connie Avalos. Thank you Hilda Adler	M 3		\$0.00
153689 Annex Classroom 5/23/201 Medium Work In Progress Annex Rm#401 5/23/2016 12:56:30 P Herrera, Mario Base board is falling, please fix (by computer on floor) Hilda Adler 146289 1/15/201 Medium Work In Progress Front Office-Gulf 1/15/2016 12:05:14 P Flores, Pete Need 6 keys for New Gulf Cart. Approved per Mrs. Quinonez. Should you need additional information please contact Connie Avalos. Thank you Hilda Adler	M 3		\$0.00
Medium Work In Progress Annex Rm#401 5/23/2016 12:56:30 P Herrera, Mario Base board is falling, please fix (by computer on floor) Hilda Adler 146289 1/15/201 Medium Work In Progress Front Office-Gulf 1/15/2016 12:05:14 P Flores, Pete Need 6 keys for New Gulf Cart. Approved per Mrs. Quinonez. Should you need additional information please contact Connie Avalos. Thank you Hilda Adler	M 3		ψ0.00
Herrera, Mario Base board is falling, please fix (by computer on floor) Hilda Adler 146289 1/15/201 Medium Work In Progress Front Office-Gulf 1/15/2016 12:05:14 P Flores, Pete Need 6 keys for New Gulf Cart. Approved per Mrs. Quinonez. Should you need additional information please contact Connie Avalos. Thank you Hilda Adler	3	138	
Hilda Adler 146289 1/15/201 Medium Work In Progress Front Office-Gulf 1/15/2016 12:05:14 P Flores, Pete Need 6 keys for New Gulf Cart. Approved per Mrs. Quinonez. Should you need additional information please contact Connie Avalos. Thank you Hilda Adler		138	
1/15/201 Medium Work In Progress Front Office-Gulf 1/15/2016 12:05:14 P Flores, Pete Need 6 keys for New Gulf Cart. Approved per Mrs. Quinonez. Should you need additional information please contact Connie Avalos. Thank you Hilda Adler		138	
Medium Work In Progress Front Office-Gulf 1/15/2016 12:05:14 P Flores, Pete Need 6 keys for New Gulf Cart. Approved per Mrs. Quinonez. Should you need additional information please contact Connie Avalos. Thank you Hilda Adler			\$0.00
Flores, Pete Need 6 keys for New Gulf Cart. Approved per Mrs. Quinonez. Should you need additional information please contact Connie Avalos. Thank you Hilda Adler			·
147790 2/11/201	5	111	\$0.00
Medium Work In Progress 2/11/2016 10:24:51 A	М		
Ontiveros, Joe Need new Faucets and Faucet plates and 3/8x1/2x12 w/supplylines			
Mario Herrera			
146039 Gym Mechanical 1/12/201		141	\$0.00
Medium Work In Progress 1/12/2016 8:00:16 A	М		
Ontiveros, Joe Domestic water heater in Mechanical room pressure relief valve is leaking			
Mario Herrera			
140230 Annex Restroom 9/18/201	5	257	\$0.00
Medium Work In Progress 9/18/2015 2:27:59 P	M		
Ontiveros, Joe please replace new sink faucets with new ones kids are leaving them on.			
Martin Soria			
153674 Classroom 5/23/201		9	\$0.00
Medium Work In Progress Rm#152 Tellez 5/23/2016 10:47:05 A	М		
Ontiveros, Joe Faucet is loose. Can not use as is, Please tighten/fix. Thank you.			
Hilda Adler	_		
138659 8/25/201		281	\$0.00
Safety Work In Progress 8/25/2015 9:23:01 A	M		
Ontiveros, Joe Eye Wash - All 3 missing string for shower and 002-valve is broken asp PM136938			

6/1/2016 11:47:08 AM Page 83 of 174

Mario Herrera

WOID Priority Assigned 1 Requester		Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	MS						
143775				11/18/2015		196		\$0.00
Medium	Work In Progress			11/18/2015 12:13:09				
Marquez, G	Serardo	SNP OFFICES	NEED 4 CD1 KEY	S FOR STORAGE.				
Maritza Go	nzalez							
140237	C-Wing			9/18/2015		257		\$0.00
Medium	Work In Progress	Main Annex		9/18/2015 3:00:33 PM	I			
Chavez, Sa	antos		POWER OURTAGI JATE SITUATION A	E IN THE BUILDING. SAP.				
Yvette Cort								
153827	Band Room			5/24/2016		8		\$0.00
Medium	Work In Progress	Band room		5/24/2016 10:51:45 AM				
Chavez, Sa	antos	Install wall elec	trical outlet under s	ink				
Hilda Adle	r							
151102				4/11/2016		51		\$0.00
Medium	Work In Progress	Choir Room		4/11/2016 10:44:47 AM				
Chavez, Sa	antos	Room 306 - pre	wire for outlets on r	new stage.				
Danny Mira	anda							
143779				11/18/2015		196		\$0.00
Medium	Work In Progress			11/18/2015 1:03:44 PM				
Chavez, Sa	antos		ng on the scoreboa es. He thinks it is e	ard in the gym. They lectrical.				
Cora Ram	irez							
139909				9/14/2015		261		\$0.00
Medium	Work In Progress			9/14/2015 2:07:22 PM				
Chavez, Sa		Please see Ma Signs	rio, Building Mecha	nic regarding Exit				
Mario Herr				9/14/2015		261		<u>ФО ОО</u>
139952	Annex	A F I				201		\$0.00
Medium	Work In Progress	Annex Electrica		9/14/2015 4:04:27 PM				
Chavez, Sa		Annexelectrica	l boxis not working	or jumping as well.				
Hilda Adle	r			4/00/0040		101		Φο οο
146587				1/22/2016		131		\$0.00
Medium	Work In Progress			1/22/2016 10:50:50 AM				
Chavez, Sa		Replace perim parking lot.	eter lights to improv	e lighting conditions in				

6/1/2016 11:47:08 AM Page 84 of 174

1141 - Work Orders In Progress (Fiscal Year)

WOID	Building	Area	3/30/2016 Order By Loc Deferred By	Until Request Date	Target Comp Date	Days Aged	Labor Hours	Costs
Priority Assigned	Status To	Area Number Description	Reason	Created Date/Time	Actual Comp Date Action Taken	Ageu	Hours	
Requeste		2000 iption			Action randin			
Location:	Gadsden	MS						
148765		Kitchen		3/2/2016		91		\$0.00
High	Work In Progress			3/2/2016 8:44:03 AN	Л			
Chavez, S	antos		rical plugs installed o P Manager Teresa Po					
Dino Faci	0							
139948		Football Field		9/14/2015		261		\$0.00
Medium	Work In Progress	Electrical/Field	-	9/14/2015 3:58:31 PM	Л			
Chavez, S	antos	Electrical grou football clock is	nd box by the footbal s not working.	l field to connect the				
Hilda Adle	er							
149740		Athletic Field		3/16/2016		77		\$0.00
Medium	Work In Progress	Baseball battin	g	3/16/2016 3:17:38 PM	Л			
Chavez, S	antos		g an electrical outlet c Should you have any a. Thank you					
Hilda Adle	er							
141522	Band Room	Classroom		10/12/2015		233		\$0.00
Medium	Work In Progress	Rm#100 Band	/	10/12/2015 3:10:56 PM	1			
Chavez, S	antos	Install wall elec	ctrical outlet under sir	nk.				
Hilda Adle	er							
138519	C-Wing	Office		8/21/2015		285		\$0.00
Medium	Work In Progress	AVECHS -		8/21/2015 2:40:17 PM	Л			
Marquez,	Gerardo	PLEASE CON	SHELVING FOR KITO FACT MRS. HOOD O R DETAILS AT 882-6	R MRS QUEZADA				
Yvette Co	rtez							
149729				3/16/2016		77		\$0.00
Medium	Work In Progress			3/16/2016 11:57:21 AN	1			
Orozco, D	aniel	REACH IN FRI TERRY P. 882	EEZER IS DOWN . S .2824	NP MANAGER				
Maritza Go	onzalez							
153318	Cafeteria	Kitchen		5/17/2016		15		\$0.00
Medium	Work In Progress			5/17/2016 9:15:08 AN	1			
Apodaca,	Mario	Low water pres Teresa P. (575	ssure in kitchen area.) 882-2824	SNP Manager				
Dino Faci	0							

6/1/2016 11:47:08 AM Page 85 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da WOID	te Range for Request Building	Dates:7/1/2015 - 6 Area	30/2016 Order By Locat Deferred By		ate Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Created Date/Ti	me Actual Comp Date	Aged	Hours	
Assigned		Description			Action Taken			
Requester	Name							
Location:	Gadsden	MS						
150092		Parking Lot		3/29/2	016	64		\$0.00
Medium	Work In Progress			3/29/2016 8:09:34	AM			
Gonzalez,	Salvador	Need adapters	for pole lights for new	LED lighting				
Santos Ch	navez							
153826	Band Room			5/24/2	016	8		\$0.00
Medium	Work In Progress	Band room		5/24/2016 10:44:59	AM			
Marquez, 0	Gerardo	Lubricate all do	oor locks and knobs					
Hilda Adle	r							
144336	East Mechanical			12/4/2	015	180		\$0.00
Medium	Work In Progress			12/4/2015 8:27:19) AM			
Marquez, 0	Gerardo	Requesting ne	w doors to boiler room					
Mario Her	rera							
144337				12/4/2	015	180		\$0.00
Medium	Work In Progress			12/4/2015 8:28:05	5 AM			
Marquez, (Gerardo	Requesting ne cafeteria	w doors to mechanica	I room behind				
Mario Her	rera							
152593	Main Building	Exterior		5/4/20	016	28		\$0.00
Medium	Work In Progress			5/4/2016 10:27:10) AM			
Marquez, (Gerardo	Please have th May need new	em check all four doors doors.	s on the portable.				
Martin Sor								
150885	Cafeteria	Cafeteria		4/6/20	016	56		\$0.00
Medium	Work In Progress	Cafeteria door		4/6/2016 4:34:40) PM			
Marquez, (The hinge on t repair. thank y	op of the Cafeteria dod ou.	or broke off. Please				
Hilda Adle	r							
153142				5/13/2	016	19		\$0.00
Medium	Work In Progress			5/13/2016 8:07:24	AM			
Herrera, M	lario	Paint Exterior d	oors of school summe	erproject				
Mario Her	rera							
153051				5/12/2	016	20		\$0.00
Medium	Work In Progress			5/12/2016 8:26:12	? AM			
Herrera, M	lario	Requesting Bli	nds for room 164 and l	ibraryalso 188				
Mario Her	rera							

6/1/2016 11:47:08 AM Page 86 of 174

			/30/2016 Order By Loc		,	-	_		Total Costs
WOID	Building	Area	Deferred By		=	Target Comp Date	Days Aged	Labor Hours	
Priority	Status	Area Number	Reason	Create	ed Date/Time	Actual Comp Date	Ageu	i loui s	
Assigned		Description				Action Taken			
Requeste Location:		MS							
	Odusuen	WIO			4/40/0040		4.4		
151511					4/18/2016		44		\$0.00
Medium	Work In Progress			4/18/20	16 8:58:06 AN	1			
Herrera, N	<i>M</i> ario	requesting 25	emergencylights and	d 25 exitsigns					
Mario Her	rera								
146767					1/26/2016		127		\$0.00
Medium	Work In Progress			1/26/20	16 3:11:59 PN	Л			
Herrera, M	<i>f</i> ario	Need supplies units (Master C	and replacement coi	mponents for A	VC				
Mario Her	rera								
153601					5/20/2016		12		\$0.00
Medium	Work In Progress			5/20/201	6 11:25:17 AN	1			
Herrera, N	Mario	Need ceiling til	es and T8 lamps						
Mario Her	rera								
153602	Gymnasium				5/20/2016		12		\$0.00
Medium	Work In Progress			5/20/201	6 11:26:41 AN	1			
Herrera, N	<i>M</i> ario	Need sit downs	s ceiling tiles for the g	ıym lobby					
Mario Her	rera								
153603	Gymnasium				5/20/2016		12		\$0.00
Medium	Work In Progress			5/20/201	6 11:28:03 AN	1			
Herrera, N	<i>M</i> ario	Need U-lamps	FB32T8/TL741/6						
Mario Her	rera								
Count: 93	Work Orders	•	vg. Age of WO's 69	9		Total for Gadsde	n MS	0	\$0.00

6/1/2016 11:47:08 AM Page 87 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da	ate Range for Request Building	Dates:7/1/2015 - 6 Area	6/30/2016 Order By Lo Deferred By		Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•		=	Actual Comp Date	Aged	Hours	
Assigned		Description	Rousen	0.00.	2010, 11110	Action Taken			
Requester	r Name	-							
Location:	La Union	ES							
149723					3/16/2016		77		\$0.00
Medium	Work In Progress			3/16/20)16 9:42:03 AM	1			
Vallejo, All	bert	Order new mar	rquee for La Union E	Elementary					
Vicente Sa	anchez								
154065					5/31/2016		1		\$0.00
Medium	Work In Progress			5/31/201	6 10:40:55 AM	1			
Villalobos	, David		cate between Wate ?'s please see Alb		sting				
Albert Vall	ejo								
150201					3/30/2016		63		\$0.00
Medium	Work In Progress			3/30/20)16 3:25:46 PN	1			
Villalobos	, Jose		hn deer mower la 1 blades need sharp		rive				
Patricio Ag	guilar								
154064					5/31/2016		1		\$0.00
Medium	Work In Progress			5/31/201	6 10:36:45 AM	1			
Castillo, C	arlos		cate between Wate ?'s please see Alb		sting				
Albert Vall	ejo								
153330					5/17/2016		15		\$0.00
Medium	Work In Progress			5/17/201	6 10:57:05 AM	1			
Aguilar, Pa	atricio	wo to myself - s rooms	summer projects pa	aint office - class	•				
Patricio Ag	guilar								
143854					11/19/2015		195		\$0.00
Medium	Work In Progress			11/19/20)15 2:49:02 PM	1			
Castillo, C	arlos	emergencyligh	ht fixer needing ball	astr310					
Patricio Ag	guilar								
149396					3/10/2016		83		\$0.00
Medium	Work In Progress			3/10/201	6 12:23:09 PM	1			
Castillo, C	arlos		ent emergency light ent light fixture? ne						
Patricio Ag	guilar								

6/1/2016 11:47:08 AM Page 88 of 174

WOID Priority Assigned	te Range for Request Building Status To	Area Number Description	Deferred By	Until	=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester									
Location:	La Union	ES							
154054					5/31/2016		1		\$0.00
Medium	Work In Progress			5/31/20)16 12:54:47 AM	1			
Martinez, S	Salvador	Monthly - La Ur to PMschedule	nion ES - Monthly Me details.	eter Reading	s - Refer				
Margret Vi	llalobos								
152296					5/1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress			5/1/2	2016 1:03:32 AM	1			
Vallejo, All	bert	Monthly - La Ur PMschedule de	nion ES Fire Suppre etails.	ession Insp	Refer to				
Margret Vi	llalobos								
145319					1/3/2016	2/3/2016	150		\$0.00
Medium	Work In Progress			1/3/20)16 12:43:27 AM	1			
Aguilar, Pa	atricio	Yearly - La Unio schedule detail	on ES Backflow Ins s.	pection - Ref	er to PM				
Margret Vi	llalobos								
154041					5/31/2016		1		\$0.00
Medium	Work In Progress			5/31/20)16 12:54:38 AM	1			
Aguilar, Pa	atricio	Yearly - La Unio Refer to PMsch	on ES A-2 Package nedule details.	Unit Elec Yea	arly -				
Margret Vi	llalobos								
152274					5/1/2016		31		\$0.00
Medium	Work In Progress			5/1/2	2016 1:03:15 AM	1			
Orozco, Da	aniel	Monthly - La Ur PMschedule de	nion ES Range Hoo etails.	d Cleaning -	Refer to				
Margret Vi	llalobos								
153515		Classroom			5/19/2016		13		\$0.00
Medium	Work In Progress			5/19/2	2016 2:37:38 PN	Л			
Lara, Ralp	h	need to service	locks and worked o	n door cylind	ers,				
Ralph Lar	a								
153484					5/19/2016		13		\$0.00
Medium	Work In Progress			5/19/20)16 10:15:21 AM	1			
Lara, Ralp	h	a old old door c old wing front door will n	loser - broken frame ot close.	e, will be hart t	o find,				
Patricio Ag	guilar								

6/1/2016 11:47:08 AM Page 89 of 174

WOID	Building	·	Target Comp Date		Costs bor urs
Priority	Status		Actual Comp Date	Ageu 110	uis
Assigned ⁻ Requester		Description	Action Taken		
		F0			
Location:	La Union				
146153		1/13/2016	5	140	\$0.00
Medium	Work In Progress	1/13/2016 2:56:39 P	М		
Aguilar, Pa	tricio	wo to myself - need to replace toilet wax gasket - floor tiles rest room kitchen			
Patricio Ag	juilar				
153341		5/17/2016	5	15	\$0.00
Medium	Work In Progress	5/17/2016 2:48:38 P	М		
Villalobos,	David	toilet in r 309 - 307 are backing up drain is clog will need to use snak. thanks for the help			
Patricio Ag	juilar				
153949		5/26/2010	3	6	\$0.00
Medium	Work In Progress	5/26/2016 9:10:47 A	M		
Ronquillo,	Ruben	could you get sun city glass to replace the glass on door? It is a wire mesh glass 21 1/4" by 67 1/2" at the old wing hall way exit.			
Patricio Ag	juilar				
148357		2/24/2016	3	98	\$0.00
Medium	Work In Progress	2/24/2016 3:17:13 P	М		
Aguilar, Pa	ıtricio	wo to myself - replace light bulbs new wing hall way.			
Patricio Ag	ıuilar				
153342	<u> </u>	5/17/2016	3	15	\$0.00
Medium	Work In Progress	5/17/2016 2:50:29 P	М		
Aguilar, Pa	ıtricio	wo to myself - need to add cherry mat to all the drains			
Patricio Ag	ıuilar				
152752	<u> </u>	Kitchen 5/6/2016	3	26	\$0.00
Medium	Work In Progress	5/6/2016 1:27:10 P	М		
Villalobos,	David	Garbage Disposal making noise. Manager Linda Yanaga (575) 589-2040			
Dino Facio)				
Count: 20 \	Work Orders	Avg. Age of WO's 49	Total for La Unior	n ES	0 \$0.00

6/1/2016 11:47:08 AM Page 90 of 174

WOID Priority Assigned	Building Status	Area Number Description	/30/2016 Order By Loc Deferred By Reason	Until Request Date	e Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester		Description			Action Taken			
Location:	Loma Lin	da ES						
152963				5/11/2010	6	21		\$0.00
Medium	Work In Progress			5/11/2016 9:19:30 A	M			
Marquez, (Serardo	ROOM PARTIT	A PRICE QUOTE TO IANS IN 1ST, 5TH, A 'S AND GIRL'S RES	ND 6TH GRADE				
Gerardo M	arquez							
152189	Main Building	Athletic Field		4/28/2010	6	34		\$0.00
Medium	Work In Progress			4/28/2016 4:04:28 P	M			
Gonzalez,	Salvador		elding done on some to Coach Ontiveros nith.					
Hector Pa	checo							
153242		Cafeteria		5/16/2010	6	16		\$0.00
Medium	Work In Progress			5/16/2016 9:22:58 A	M			
Pacheco, I	Hector	Need to replace	e exit sign in cafeteria	a.				
Hector Pa	checo							
151832		Exterior		4/22/2010	6	40		\$0.00
Medium	Work In Progress			4/22/2016 8:34:11 A	M			
Pacheco, I	Hector	In need of a stro	ong wheelbarrow					
Hector Pa	checo							
151831		Library		4/22/2010	6	40		\$0.00
Medium	Work In Progress			4/22/2016 8:31:55 A	M			
Pacheco, I	Hector	In need of a 8 fo	oot ladder to change	amps in library				
Hector Pa	checo							
144165	Main Building	Restroom		12/2/201	5	182		\$0.00
Medium	Work In Progress			12/2/2015 7:42:04 A	M			
Ontiveros,	Joe	Need to replace room across te	e gaskets on flush va achers lounge.	llve teachers rest				
Hector Pa								
147412	Main Building	Restroom		2/4/2010	6	118		\$0.00
Medium	Work In Progress			2/4/2016 12:46:51 P	M			
Ontiveros,	Joe		ce to repair toilet flus aks on all joints . Mar de wing.					
Hector Pa	checo							

6/1/2016 11:47:08 AM Page 91 of 174

Assigned [•] Requester		Area Number Reason Description	•	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Loma Lin	da ES					
148767	Main Building	Athletic Field	3/2/2016		91		\$0.00
Medium	Work In Progress		3/2/2016 8:50:43 AV	1			
Ontiveros,	Joe	Need assistance to reprequest by assistant pri	air out side water fountains per ncipal Mr Smith.				
Hector Pa	checo						
141376			10/9/2015		236		\$0.00
Medium	Work In Progress	Kitchen	10/9/2015 2:43:55 PM	1			
Ontiveros,	Joe		nt of tilt skillet. Per ergonomic should be replaced with an e call Cynthia with any	reroute to Joe			
Cynthia Ma	aes						
140150	Main Building	Restroom (Girls)	9/17/2015		258		\$0.00
Medium	Work In Progress		9/17/2015 11:52:44 AM	1			
Ontiveros,	Joe		nd fixthe drainer from the girl of the teachers lunch room its				
Alfredo Am	briz						
147822		Restroom (Girls)	2/11/2016		111		\$0.00
Medium	Work In Progress		2/11/2016 3:44:32 PM	1			
Ontiveros,	Joe	toilet needs to be anche working other leaking.tr	ored to floor. 1 flush valve not ed trouble shooting.				
Hector Pa	checo						
147624	Main Building	Restroom (Girls)	2/9/2016		113		\$0.00
Medium	Work In Progress		2/9/2016 7:58:33 AM	1			
Ontiveros,	Joe	Toilet not fastened to flo Tried Teflon tape no suc	or, leaking flush valve at joints. cess.				
Hector Pa	checo						
147839		Restroom	2/11/2016		111		\$0.00
Medium	Work In Progress		2/11/2016 3:49:00 PM	1			
Ontiveros,	Joe	5th 6th grade wing boyr	estroom 2 leaking flush valves.				
Hector Pa	checo						
147874	Main Building	Restroom	2/12/2016		110		\$0.00
Medium	Work In Progress		2/12/2016 3:34:35 PM	1			
Ontiveros,	Joe	3rd and 4th grade wing not anchored to floor flu	2 urinal flush valve leaking, toilet sh valve leaking.				

6/1/2016 11:47:08 AM Page 92 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da	te Range for Request		30/2016 Order By Loca Deferred By		Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•		=	Actual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requester	Name								
Location:	Loma Lir	nda ES							
143944	Main Building	Restroom			11/20/2015		194		\$0.00
Medium	Work In Progress			11/20/20	15 3:37:51 PM	1			
Ontiveros,	Joe	Need assistand across teachers	e replacing flush val s lounge.	ve in boys res	troom				
Hector Pa	checo								
148002		Cafeteria			2/18/2016		104		\$0.00
Medium	Work In Progress			2/18/20	16 3:44:35 PN	1			
Ontiveros,	Joe		le wing girls bathroor 4 toilets not anchore		king				
Hector Pa									
152433	Main Building	Restroom			5/2/2016		30		\$0.00
Medium	Work In Progress			5/2/20	16 8:17:59 AM	1			
Ontiveros,	Joe	Need assistand restroom at mai	e to unclog floor drair n entrance.	ns boys and g	irls				
Hector Pa	checo								
148922		Cafeteria			3/4/2016		89		\$0.00
Medium	Work In Progress			3/4/201	6 10:46:12 AN	1			
Chavez, S	antos	door bell ringer	not loud enough to he	ear		3/4/16 - route to ele	ctrician a	asp Alfredo)
		please see mar	nager						
Cora Ram	irez								
150271	Main Building	Exterior			3/31/2016		62		\$0.00
Medium	Work In Progress			3/31/20	16 7:56:24 AM	1			
Chavez, S	antos	Need assistand entrance.	e to replace ballast u	ınder porch at	main				
Hector Pa	checo								
150445		Classroom			4/1/2016		61		\$0.00
Medium	Work In Progress			4/1/20	16 3:56:19 PN	1			
Chavez, S	antos	Need assistand	e to change out balla	ıst.					
Hector Pa	checo								
150448		Classroom			4/1/2016		61		\$0.00
Medium	Work In Progress			4/1/20	16 3:58:46 PN	1			
Chavez, Sa	_	Need assistand	e to change out balla	stroom #210					
Hector Pa									
TICULOI FA	011600								

6/1/2016 11:47:08 AM Page 93 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da	te Range for Request Building	Dates:7/1/2015 - 6 Area	5/30/2016 Order By L Deferred By	ocation, Status Until	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Crea	ted Date/Time	Actual Comp Date	Aged	Hours	
Assigned '	То	Description				Action Taken			
Requester	Name								
Location:	Loma Lir	nda ES							
151291	Main Building	Library			4/13/2016		49		\$0.00
Medium	Work In Progress			4/13/20	16 10:19:00 AN	1			
Chavez, Sa	antos	Need assistar to poor lighting	ice to change out ba	allastin Library	area do				
Hector Pa	checo								
148153	Main Building	Roof			2/22/2016		100		\$0.00
Medium	Work In Progress			2/22/2	016 2:55:29 PN	Л			
Chavez, Sa	antos	need to check cafeteria	the contactor for th	ne a/c on east s	side of				
Hector Pa	checo								
148155		Roof			2/22/2016		100		\$0.00
Medium	Work In Progress			2/22/2	016 2:57:32 PN	Л			
Chavez, Sa	antos	need to check	the contactor on th	e west of cafet	eria				
Hector Pa	checo								
148506	Main Building	Exterior			2/26/2016		96		\$0.00
Medium	Work In Progress			2/26/2	016 9:45:26 AN	1			
Marquez, (Gerardo	In need to repla side entrance.	ace door lock on ext	erior door mair	west				
Hector Pa	checo								
153563					5/20/2016		12		\$0.00
Medium	Work In Progress			5/20/2	016 7:51:18 AN	1			
Marquez, 0	Gerardo	CHECK ALL D	RS. FOR PROPER	OPERATION.					
Gerardo M	larquez								
152111					4/27/2016		35		\$0.00
Medium	Work In Progress			4/27/2	016 4:14:42 PN	Л			
Marquez, 0	Gerardo	MR LAWLER'S	KEY GOT STUCK CK OUT.	AT WEST SIDE	EDR.				
Gerardo M	1arquez								
153900	Main Building				5/25/2016		7		\$0.00
Medium	Work In Progress			5/25/20	16 10:38:48 AN	1			
Marquez, (Gerardo	remove G59 ke building from the need to be able	key the LSC Portab ey from being able to ne 6th grade hall. The to also open the 6 le. This needs to be tion	o Access the m he new LSC Ke th grade hall do	ain ys or				
Angie Flor	es								

6/1/2016 11:47:09 AM Page 94 of 174

Orozco, Dani Margret Villal 154033	Work In Progress iel lobos Work In Progress	Monthly-Loma L to PMschedule o		5/1/2016 5/1/2016 1:03:15 AM ood Cleaning - Refer 5/31/2016 5/31/2016 12:54:32 AM	5/22/2016 I 7/1/2016	31	\$0.00
152275 Medium V Orozco, Dani Margret Villal 154033 Medium V Pacheco, He Margret Villal	Work In Progress iel lobos Work In Progress ector	Monthly-Loma L to PMs chedule of Yearly - Loma Li		5/1/2016 1:03:15 AM nod Cleaning - Refer 5/31/2016	I		\$0.00
Medium V Orozco, Dani Margret Villal 154033 Medium V Pacheco, He Margret Villal	iel lobos Work In Progress	to PMschedule of		5/1/2016 1:03:15 AM nod Cleaning - Refer 5/31/2016	I		\$0.00
Orozco, Dani Margret Villal 154033 Medium V Pacheco, He Margret Villal	iel lobos Work In Progress	to PMschedule of		ood Cleaning - Refer 5/31/2016		1	
Margret Villal 154033 Medium V Pacheco, He Margret Villal	lobos Work In Progress ector	to PMschedule of		5/31/2016	7/1/2016	1	
154033 Medium V Pacheco, He Margret Villal	Work In Progress				7/1/2016	1	
Medium V Pacheco, He Margret Villal	ector				7/1/2016	- 1	
Pacheco, He Margret Villal	ector			5/31/2016 12:54:32 AM		'	\$0.00
Margret Villal					I		
	lobos		nda ES A2 (Split S dule details.	ystem)(Yearly) -			
152297							
				5/1/2016	5/22/2016	31	\$0.00
Medium V	Work In Progress			5/1/2016 1:03:33 AM			
Vallejo, Alber		Monthly-Loma L to PMschedule o		ression Insp Refer			
Margret Villal	lobos	LC: 1		= /4.0 /0.040			
153075		Kitchen		5/12/2016		20	\$0.00
Medium V	Work In Progress			5/12/2016 1:01:13 PM	1		
Pacheco, He	ector	Need to paint floo	or in kitchen area.				
Hector Pache	eco						
151828		Kitchen		4/22/2016		40	\$0.00
Medium V	Work In Progress			4/22/2016 7:50:36 AM	I		
Pacheco, He	ector	Floor in kitchen a	rea needs to be pa	inted.			
Hector Pache	eco						
153071		Classroom		5/12/2016		20	\$0.00
Medium V	Work In Progress			5/12/2016 12:45:20 PM			
Pacheco, He	ector	Need to paint roo Readyfor summ	oms (108,111,103, er class.	110,107,102,104)			
Hector Pache	eco						
153073		Classroom		5/12/2016		20	 \$0.00
Medium V	Work In Progress			5/12/2016 12:52:52 PM			
Pacheco, He	ector	Need to paint roo (207,209,210,21 of 5th 6th grade	1,212,213,214,21	5,217,218,220,222) all			

6/1/2016 11:47:09 AM Page 95 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da	te Range for Request Building	Dates:7/1/2015 - 6 Area	6/30/2016 Order By Loc Deferred By	cation, Status Until	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•	Crea	ted Date/Time	Actual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requester	· Name								
Location:	Loma Lin	ida ES							
153074		Classroom			5/12/2016		20		\$0.00
Medium	Work In Progress			5/12/20	16 12:58:44 PM	1			
Pacheco,	Hector	Need to paint r (101,102,104, included.	ooms 105,108,109,112,20 ⁻	1,208,205,)res	et rooms				
Hector Pa	checo								
153077		Restroom			5/12/2016		20		\$0.00
Medium	Work In Progress			5/12/2	016 1:35:22 PN	1			
Pacheco,	Hector	Paintboys and	girls restrooms 6 in	total.					
Hector Pa	checo								
153079		Restroom			5/12/2016		20		\$0.00
Medium	Work In Progress			5/12/2	016 1:39:05 PN	1			
Pacheco,	Hector	Need to paint 7 IN total.	eachers Men"s and I	ady"s restroo	ms 6				
Hector Pa	checo								
153054	Main Building	Hallway/Corric	dor		5/12/2016		20		\$0.00
Medium	Work In Progress			5/12/2	016 8:48:00 AN	1			
Hernande	z, Guillermo		stance to remove and ountains 3rd and 6th		ouble				
Hector Pa									
152139	Main Building	Classroom			4/28/2016		34		\$0.00
Medium	Work In Progress			4/28/20	16 10:49:00 AN	1			
Pacheco,	Hector	Need to paint 3	37 rooms.						
Hector Pa	checo								
153852					5/24/2016		8		\$0.00
Medium	Work In Progress			5/24/2	016 3:17:42 PN	1			
Villalobos	, Jose	water from one	or not working prope e side. Serial # 13780 s not properlypicking 8A32M72851	21	hooting				
David Sori	ano								
152425		Custodial			5/2/2016		30		\$0.00
Medium	Work In Progress			5/2/2	016 7:26:59 AN	1			
Villalobos	, Jose	Vacuum clean Serial # E08C0							
David Sori	ano								

6/1/2016 11:47:09 AM Page 96 of 174

Salactad Da	ite Pange for Peguest	Dates:7/1/2015 - 6	5/30/2016 Order By Loc	ation Status	,				Tota Costs
WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	COSI
Priority	Status	Area Number	Reason	Crea	ated Date/Time	Actual Comp Date	Aged	Hours	
Assigned '	То	Description				Action Taken			
Requester	Name								
Location:	Loma Lin	ida ES							
154063					5/31/2016		1		\$0.00
Medium	Work In Progress			5/31/20)16 10:21:32 AV	1			
Villalobos	, Jose	Shampooer is water on one s Serial # 12122		. Itis onlysqu	uirting				
David Sori	ano								
143932		Classroom			11/20/2015		194		\$0.00
Medium	Work In Progress	Music Portable		11/20/2	2015 2:26:44 PM				
Estrada, J	esus	CARPET IS TO CHILDREN	ORN CREATING A HA	AZARD FOR					
Angie Flor	es								
145978	Main Building	Classroom			1/11/2016		142		\$0.00
Medium	Work In Progress	107		1/11/2	2016 9:46:41 AM	1			
Pacheco, I	Hector	Student Corral	lease go to San Migu and place it in room ? er IEP we need Stude	107 with Ms.					
Angie Flor	es								
Count: 45	Work Orders	Α	vg. Age of WO's 7	0		Total for Loma Lind	la ES	0	\$0.00

6/1/2016 11:47:09 AM Page 97 of 174

WOID	Building	Area	/30/2016 Order By Loc Deferred By	Until Request Date	Target Comp Date	Days Aged	Labor Hours	Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date Action Taken	Ageu	riours	
Assigned 1 Requester		Description			Action Taken			
		F0						
Location:	Mesquite	E3						
153805				5/24/2016		8		\$0.00
Medium	Work In Progress			5/24/2016 9:39:40 AM	l			
Villalobos,	Jose	water vaccum	SN18WD-06095					
		Electrical cord i	s damaged, wire is o	ut near the plug				
Mario Valle	es							
154091				5/31/2016		1		\$0.00
Medium	Work In Progress			5/31/2016 3:03:28 PM	1			
Villalobos,	Jose		er serial number: 100 keeps leaking and co	0326 water tank on it ord wires are				
Mario Valle	es							
153422				5/18/2016		14		\$0.00
Medium	Work In Progress			5/18/2016 2:06:19 PM	1			
Ramirez, J	oe	need to repaint	asst. principals offic	e				
Joe Ramir	ez							
153423				5/18/2016		14		\$0.00
Medium	Work In Progress			5/18/2016 2:07:07 PM	1			
Ramirez, J	oe	need to paint rn	n.101					
Joe Ramir	ez							
151974				4/26/2016		36		\$0.00
Medium	Work In Progress			4/26/2016 9:00:13 AM	l			
Ramirez, J	oe	need to repaint	reception area.					
Joe Ramir	ez							
151975				4/26/2016		36		\$0.00
Medium	Work In Progress			4/26/2016 9:01:19 AM	l			
Ramirez, J	oe	need to repaint	fire lanes.					
Joe Ramir	ez	•						
152873				5/10/2016		22		\$0.00
Medium	Work In Progress			5/10/2016 6:05:48 AM	l			
	Guadalupe	neeed all grass fertilized	s areas on campus to					
Joe Ramir	e <i>7</i>							

6/1/2016 11:47:09 AM Page 98 of 174

WOID Priority Assigned Requester	Building Status To	Area Area Number Description	/30/2016 Order By Loc Deferred By Reason		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Mesquite	ES						
152298				5/1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress			5/1/2016 1:03:33 AM				******
Vallejo, All	•	Monthly - Mesq PMschedule de		ssion Insp Refer to				
Margret Vi	llalobos	i Wischedule d	otano.					
154052				5/31/2016		1		\$0.00
Medium	Work In Progress			5/31/2016 12:54:45 AM				
Apodaca,	Mario	Monthly - Mesq Refer to PMsch	uite ES - Monthly Me redule details.	ter Readings -				
Margret Vi								
136170	2003 Classroom	Hallway/Corrid	or	7/20/2015		317		\$0.00
Medium	Work In Progress	E Wing		7/20/2015 3:59:34 PM				
Marquez, (Gerardo	Munoz, L. Balda	e plaque's for the fol auf, C. Zuloaga, G. N ank you, Sandy					
Sandra Mo	ora			E /0.4 /0.4.0	7/4/0040			
154039				5/31/2016	7/1/2016	1		\$0.00
Medium	Work In Progress			5/31/2016 12:54:36 AM				
Ramirez, J		Yearly - Mesqu PMschedule d	ite ES A-2 Electric H etails.	eat Yearly - Refer to				
Margret Vi	llalobos			F /A /0040	F/00/0040	04		ФО 00
152276				5/1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress			5/1/2016 1:03:16 AM				
Orozco, Da		Monthly - Mesq PMschedule d		d Cleaning - Refer to				
Margret Vi	llalobos			1/3/2016	2/2/2016	150		\$0.00
145320	W 11 B				2/3/2016	150		\$0.00
Medium	Work In Progress			1/3/2016 12:43:28 AM				
Ramirez, J		Yearly - Mesqu schedule detail		ection - Refer to PM				
Margret Vi		000		-11		- 1-		
153271	Main Building	Office		5/16/2016		16		\$0.00
Medium	Work In Progress	Room # 107		5/16/2016 3:26:29 PM				
Marquez, (Gerardo		nstructional Coach, I hard to open with ke					
Sandra Mo	ora							

6/1/2016 11:47:09 AM Page 99 of 174

WOID Priority Assigned Requester	Building Status To	Area Number Description	i/30/2016 Order By Loc Deferred By Reason		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Mesquite	FS						
153571	- Incoquite			5/20/2016		12		\$0.00
Medium	Work In Progress			5/20/2016 8:04:05 AM	•	12		ψ0.00
	•	CHECK DD6	FOR PROPER OPER					
Marquez, (CHECK DRS.	FOR PROPER OPER	ATION.				
Gerardo M 148434	arquez			2/25/2016		97		\$0.00
Medium	Work In Progress			2/25/2016 2:37:18 PN	1	31		ψ0.00
	•				I			
Ramirez, J		need to replace	e several hunter sprin	kiers.				
Joe Ramir 151615	ez			4/19/2016		43		\$0.00
Medium	Work In Brogross			4/19/2016 2:42:22 PN	1	40		ψ0.00
Vallejo, Alt	Work In Progress pert	Mesquite Elem	Main Bldg. (1964) re		ı			
Alfredo Ho	lguin							
145770	Main Building	Storage		1/7/2016		146		\$0.00
Medium	Work In Progress	Main Office		1/7/2016 8:49:28 AM	I			
Chavez, Sa		power to powe	nirez/Bldg. Mech. we a r a new refrigerator m talled. Thank you					
Sandra Mo		Cafeteria		0/40/0045		200		ФО 00
138289	Main Building			8/18/2015		288		\$0.00
Medium	Work In Progress	Cafeteria		8/18/2015 4:08:23 PM				
Chavez, Sa	antos	Requesting, su	uggest power surge p	orotector ASAP.				
Sandra Mo		D 11		0/40/0045		0.57		Φο οο
140233	Pump House	Pump House		9/18/2015		257		\$0.00
Medium	Work In Progress			9/18/2015 2:52:32 PM	1			
Chavez, Sa	antos		ol boxneed to identify ntrol system to well ar					
Mario Apo	daca							
153420		Kitchen		5/18/2016		14		\$0.00
High	Work In Progress			5/18/2016 1:52:46 PM	1			
Chavez, Sa	antos		l outlet installed for ca Emilia C. (575) 233-2					
Dino Facio)							

6/1/2016 11:47:09 AM Page 100 of 174

Selected Da WOID	ate Range for Request Building	Dates:7/1/2015 - 6 Area	/30/2016 Order By Lo		est Date Target Comp D	ate Days	Labor	Costs
Priority	Status	Area Number	Reason	Created Da	te/Time Actual Comp D	ate Aged	Hours	
Assigned	То	Description			Action Tak	ken		
Requeste	r Name							
Location:	Mesquite	ES						
149719	Main Building			3/	16/2016	77		\$0.00
Medium	Work In Progress	Main hallway		3/16/2016 8:5	51:17 AM			
Chavez, S	antos	that our copy m	achine be moved sone for each copy	ipal, she is requesting to hallway, we need 2 machine, asap.				
Sandra M	ora							
139560				ξ	9/8/2015	267		\$0.00
Medium	Work In Progress			9/8/2015 10:1	4:50 AM			
Chavez, S	antos	we have 4 park	ing/securitylights t	hat are not working				
Joe Rami	rez							
138478	Main Building			8/	21/2015	285		\$0.00
Medium	Work In Progress	Cafeteria		8/21/2015 7:5	53:48 AM			
Chavez, S	antos	outlet is loose i	n cafeteria.					
Sandra M	ora							
146579				1/	22/2016	131		\$0.00
Medium	Work In Progress			1/22/2016 9:1	6:51 AM			
Chavez, S	antos	elect. wall heat not working.	er in the teachers b	athroom (north end) is				
Joe Rami	rez							
Count: 25	Work Orders	Δ	vg. Age of WO's	92	Total for Me	squite ES	0	\$0.00

6/1/2016 11:47:09 AM Page 101 of 174

WOID Priority Assigned	Building Status To	Area Area Number Description	/30/2016 Order By Loc Deferred By Reason	Until Reques		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester									
Location:	North Va	lley ES							
153654				5/2	2/2016		10		\$0.00
Medium	Work In Progress			5/22/2016 12:30	0:32 AM				
Vega, Dan	iny	Daily - North Va PMschedule d		(Biweekly) - Refer to					
Margret Vi	llalobos								
152300				5/	1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress			5/1/2016 1:03	3:35 AM				
Vallejo, All	pert	Monthly - North to PMschedule	•	oression Insp Refer	•				
Margret Vi	llalobos								
143845		Hallway/Corrid	or	11/1	9/2015		195		\$0.00
Medium	Work In Progress			11/19/2015 1:28	3:39 PM				
Chavez, S	antos	copiers by our make sure the	e electrical outlets in office area. Per the s e is enough ampera Min. of 25 amps.	service tech need to					
Gloria Rey	/es								
152265				5/	1/2016		31		\$0.00
Medium	Work In Progress			5/1/2016 1:03	3:09 AM				
Orozco, Da	aniel	Monthly - North Refer to PMsch	Valley ES - Range I nedule details.	Hood Cleaning -					
Margret Vi	llalobos								
154046				5/3	1/2016		1		\$0.00
Medium	Work In Progress			5/31/2016 12:54	4:41 AM				
Vega, Dan	iny	Monthly - North Refer to PMsch	Valley ES A16 (Fan nedule details.	Exhst)(S.Ann.) -					
Margret Vi	llalobos								
154032				5/3	1/2016	7/1/2016	1		\$0.00
Medium	Work In Progress			5/31/2016 12:54	4:31 AM				
Vega, Dan	iny	Yearly - North \ PMschedule d		nit)(Yearly) - Refer to					
Margret Vi	llalobos								
148927				3/	4/2016		89		\$0.00
Medium	Work In Progress			3/4/2016 11:24	4:39 AM				
Chavez, S	antos	emergencybal	lastoutrm 307-212-	302					
Danny Veg	ga								

6/1/2016 11:47:09 AM Page 102 of 174

WOID	ate Range for Request Building		Deferred By		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Aged	Hours	
Assigned [*]	То	Description			Action Taken			
Requester	r Name							
Location:	North Va	lley ES						
152130		Custodial		4/28/2016		34		\$0.00
Medium	Work In Progress			4/28/2016 9:34:26 AM	1			
Villalobos	, Jose	low oil engine le refill Thank yo		ffer machine, please				
Ivan Rodri	guez							
153086		Classroom		5/12/2016		20		\$0.00
Medium	Work In Progress	309		5/12/2016 3:10:10 PM	1			
Chavez, Sa	antos			mputers turn off often tes to turn them back				
Gloria Rey	yes							
153892				5/25/2016		7		\$0.00
Medium	Work In Progress			5/25/2016 8:34:42 AN	1			
Villalobos	, Jose	PPD Loaner Au	to Scubber to site					
Jimmy Ca	rbajal							
150047				3/23/2016		70		\$0.00
Medium	Work In Progress			3/23/2016 12:13:08 PM	1			
Gonzalez,	Salvador	soccer goal top	rail needs to be w	elded				
Danny Veg	ga							
153848		Classroom		5/24/2016		3		\$0.00
Medium	Work In Progress			5/24/2016 1:44:18 PM	<i>f</i> 5/27/2016			
Vega, Dan	nny	Starboard wher Whiteboard ove possible.						
Gloria Rey	yes							
153108				5/12/2016		20		\$0.00
Medium	Work In Progress			5/12/2016 3:48:07 PM	1			
Vega, Dan	nny	summerprojec	ts paint rms at nve					
Danny Veg	ga							
153114				5/12/2016		20		\$0.00
Medium	Work In Progress			5/12/2016 3:52:07 PM	1			
Vega, Dan	nny	replace fluores	cent lamp thru-out	bldg				
Danny Veg	na							

6/1/2016 11:47:09 AM Page 103 of 174

MOID	Building	Dates:7/1/2015 - 6/30/2016 Order E Area Deferred By		Target Comp Date	Days La	Costs abor
Priority	Status	Area Number Reason	Created Date/Time	-	•	ours
Assigned ⁻	То	Description		Action Taken		
Requester	Name					
Location:	North Va	ley ES				
146284			1/15/2016		138	\$0.00
Medium	Work In Progress		1/15/2016 9:56:42 AM			
Chavez, Sa	antos	need to replace exit signs in 20 206,207,208, and 209	00- wing hallway204,			
Danny Mira	anda					
150048			3/23/2016		70	\$0.00
Medium	Work In Progress		3/23/2016 12:14:54 PM			
Chavez, Sa	antos	emergency lamp ballast are o	utin rm 306-310-302			
Danny Veg	ja					
150103			3/29/2016		64	\$0.00
Medium	Work In Progress		3/29/2016 10:37:20 AM			
Chavez, Sa	antos	BAD BALLAST IN MECHANNI CLASSRMS-101-203-206-20	-			
Danny Veg	ja					
141341			10/9/2015		236	\$0.00
Medium	Work In Progress		10/9/2015 7:25:07 AM			
Chavez, Sa	antos	emergency ballast out in hallw 201-205-211-rio grand wing b				
Danny Veg	ja					
141189			10/7/2015		238	\$0.00
Medium	Work In Progress		10/7/2015 8:35:13 AM			
Chavez, Sa	antos	exterior bldg. lighting have 14 (out thru out bdlg please ck to				
Danny Veg	ja					
153569			5/20/2016		12	\$0.00
Medium	Work In Progress		5/20/2016 8:00:57 AM			
Marquez, C	Gerardo	CHECK DRS. FOR PROPER	OPERATION.			
Gerardo M	larquez					

6/1/2016 11:47:09 AM Page 104 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da	ate Range for Request Building	Dates:7/1/2015 - 6 Area	3/30/2016 Order By Lo Deferred By	cation, Status Until	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•	Crea	=	Actual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requeste	r Name								
Location:	Northern	On-Track Pre-l	(LM)						
153110					5/12/2016		20		\$0.00
Medium	Work In Progress			5/12/2	016 3:49:27 PN	1			
Vega, Dar	nny	summer proje	cts piant rms at lm p	re-kas needed	l				
Danny Ve	ga								
153570					5/20/2016		12		\$0.00
Medium	Work In Progress			5/20/2	016 8:02:49 AM	1			
Marquez,	Gerardo	CHECK DRS.	FOR PROPER OPE	RATION.					
Gerardo N	Marquez								
154031	·				5/31/2016	7/1/2016	1		\$0.00
Medium	Work In Progress			5/31/20	16 12:54:31 AM	1			
Vega, Dar	nny	Yearly - Northe PMschedule d	rn Pre-K A2 (H/C U etails.	nit)(Yearly) - R	efer to				
Margret Vi	llalobos								
154045					5/31/2016		1		\$0.00
Medium	Work In Progress			5/31/20	16 12:54:41 AM	1			
Vega, Dar	nny	Monthly - North Refer to PMscl	ern Pre-K A16(Fan nedule details.	Exhst)(S. Ann	ual) -				
Margret Vi	llalobos								
154051					5/31/2016		1		\$0.00
Medium	Work In Progress			5/31/20	16 12:54:45 AM	1			
Apodaca,	Mario	Monthly - North Refer to PMscl	iern Pre-K - Monthly nedule details.	Meter Readin	gs -				
Margret Vi	llalobos								
150657					4/4/2016		58		\$0.00
Medium	Work In Progress			4/4/20	16 10:10:39 AM	1			
Ontiveros	,Guadalupe	down some br	body to operate a c anches from a tree, a safety hazard as pe s's request	he branches a	are				
Brian Pac	heco								
140486	Main Building	Athletic Field			9/23/2015		252		\$0.00
Medium	Work In Progress	outside		9/23/2	015 1:57:54 PN	1			
Ontiveros	,Guadalupe	set up where o not have appro	canopy in our cafe ur sandboxis for the priate shade to be w eyare digging holes	students. The here the sand	eydo is	9/29/15 - Asp Albert	, route to	Grounds	
Concepci	on Montalvo				-				

6/1/2016 11:47:09 AM Page 105 of 174

0

\$0.00

1141 - Work Orders In Progress (Fiscal Year)

Joe Ontiveros

Count: 8 Work Orders

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Area Number Reason **Created Date/Time Actual Comp Date Priority Status Assigned To Description Action Taken** Requester Name Location: Northern On-Track Pre-K (LM) 150878 4/6/2016 56 \$0.00 Medium Work In Progress 4/6/2016 3:58:37 PM 4-6-16 18350.8 18367.2 Ontiveros, Joe .5 ck E-Mail-Material LLES 2-147624-p GES 2-150245-p GES 2-Water grass 'Trees BES 1-147262-p .5- Enter Log 1 Total HR

Total for Northern On-Track Pre-K (LM)

Avg. Age of WO's 50

6/1/2016 11:47:09 AM Page 106 of 174

WOID Priority	Building Status	Area Deferred By Area Number Reason	Until Request Date Created Date/Time	-	Days Aged	Labor Hours	
Assigned		Description		Action Taken			
Requeste							
Location:	Physical	Plant Complex					
146584			1/22/2016		131		\$0.00
Medium	Work In Progress		1/22/2016 10:44:56 AM				
Chavez, S	Santos	Install exterior shop lighting.					
Albert Val	lejo						
153913			5/25/2016		7		\$0.00
High	Work In Progress		5/25/2016 3:33:58 PM	1			
Chavez, S	Santos	Control that opens and closes ove dock door#4 at SNP Warehouse no SNP Warehouse Mgr. Jose Rodrig	ot working properly.				
Dino Faci	io						
152733	Motor Vehicle		5/6/2016		26		\$0.00
Medium	Work In Progress	Welding/Smalll	5/6/2016 9:41:34 AM				
Ontiveros	,Joe	Need to run water lines to a/c's in n	ewshop.				
Jose Villa	alobos						
152734	Motor Vehicle		5/6/2016		26		\$0.00
Medium	Work In Progress	Welding/Smalll	5/6/2016 9:43:54 AV	I			
Ontiveros	, Joe	Need to run air line to new shop.					
Jose Villa	alobos						
151284			4/13/2016		49		\$0.00
Medium	Work In Progress		4/13/2016 8:53:16 AM	I			
Lara, Ralp	ph	NEED ORDER PEN LUBE AEROS FOR DIS WIDE	SOL SPRAY CANS				
Ralph La	ra						
151288			4/13/2016		49		\$0.00
Medium	Work In Progress		4/13/2016 8:59:55 AN				
Lara, Ralp	ph	NEED TO ORDER EXIT DEVICES	S, FOR R.S.E.				
Ralph La	ra						
151282			4/13/2016		49		\$0.00
Medium	Work In Progress		4/13/2016 8:41:31 AN				
Lara, Ralp	ph	NEED TO ORDER CLASS RM LO WIDE	CKSETS FOR DIST				
Ralph La			2.22.2				*
148508	Main Warehouse		2/26/2016		96		\$0.00
Medium	Work In Progress		2/26/2016 10:29:43 AN				
Marquez,		please switch lock to a clssroom lissues with lock.	ock. Still having				
Lisa Sand	cnez						
6/1/2016	11·47·09 AM					Do 10	77 of 174

6/1/2016 11:47:09 AM Page 107 of 174

WOID Priority Assigned Requester		Area Deferred By Area Number Reason Description	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Physical	Plant Complex					
146121			1/12/2016		141		\$0.00
Medium	Work In Progress		1/12/2016 11:18:09 PM				
Marquez, (Gerardo	1/12/16 3167-3217 .5-CHECK E-MAIL/PREP MATRL 2-CH. H.S. 145697 C. 1-CH. H. S. 145969 WP. .5-LOG OUT.	.4-GMS. 145085 C.				
Gerardo M	Marquez		40/40/0045				
141935			10/19/2015		226		\$0.00
Medium	Work In Progress		10/19/2015 2:49:46 PM				
Marquez, 0		AS PER MR. CHAVEZ, ALL NOR NEED TO BE REKEYED.	THERN KITCHENS				
Maritza Go	onzalez		-/				
153148			5/13/2016		19		\$0.00
Medium	Work In Progress		5/13/2016 11:10:59 AM	l			
Flores, Pe	te	Vehicle #10 has a cracked windsl replacement	nield needs				
		Thank You					
Marin Her	rera						
148835			3/3/2016		90		\$0.00
Medium	Work In Progress		3/3/2016 8:12:27 AN				
Marquez, (Gerardo	NEED TO HAVE FRONT DRIVER (FLAT)	S SIDE TIRE FIXED.				
Gerardo M	Marquez						
153096			5/12/2016		20		\$0.00
Medium	Work In Progress		5/12/2016 3:40:36 PM	1			
Flores, Pe	te	vehicle #135 - needs oil change a	nd shocks				
Cora Ram	nirez						
153257	Purchasing		5/16/2016		16		\$0.00
Medium	Work In Progress		5/16/2016 11:05:42 AM	I			
Flores, Pe	te	Tommy lift not working on truck#1 see if working properly.	10 please check to				
Danny Ca	rrasco						
153340	Main Warehouse	Office	5/17/2016		15		\$0.00
	Work In Progress	Support	5/17/2016 2:42:41 PM	1			
Medium							

6/1/2016 11:47:09 AM Page 108 of 174

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6 Area Area Number Description	/30/2016 Order By Loc Deferred By Reason		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:		Plant Complex						
153424	Motor Vehicle			5/18/2016		14		\$0.00
Medium	Work In Progress	equip#0530		5/18/2016 2:18:00 PM		• •		Ψ0.00
Flores, Pe	-			ake master cylinder.				
Pete Flore	S							
153769	Motor Vehicle			5/24/2016		8		\$0.00
Medium	Work In Progress	equip#0404		5/24/2016 8:37:40 AM				
Flores, Pe	te	mowerleaking	hydraulic fluid. pleas	se check and advise.				
Pete Flore	S							
153605				5/20/2016		12		\$0.00
Medium	Work In Progress			5/20/2016 12:04:48 PM				
Flores, Pe	te	Veh.152 driver	s seatneeds reupho	olster.				
Carlos Ca	stillo							
153001				5/11/2016		21		\$0.00
Medium	Work In Progress			5/11/2016 3:19:24 PM				
Flores, Pe	te	Vehicle #86 A/0	C does not work need	ds attention.				
		Thank You						
Marin Herr	era							
153945				5/25/2016		7		\$0.00
Medium	Work In Progress			5/25/2016 4:05:56 PM				
Flores, Pe	te	PLEASE HAVE VAN 181.	POWER INVERTER	R INSTALLED IN				
Gerardo M	<u> </u>							
153886	Motor Vehicle			5/25/2016		7		\$0.00
Medium	Work In Progress	vehicle#120		5/25/2016 7:56:12 AM				
Flores, Pe	te	vehicle losing e	engine coolant. pleas	se check and advise				
Pete Flore	s							
153888	Motor Vehicle			5/25/2016		7		\$0.00
Medium	Work In Progress	vehicle#02		5/25/2016 7:59:39 AM				
Flores, Pe	te		eration of power door esigned. please che	rlocks. not locking or ck and advise				
Pete Flore								
153901	Motor Vehicle			5/25/2016		7		\$0.00
Medium	Work In Progress	vehicle#173		5/25/2016 11:04:21 AM				
Flores, Pe	te	please check fo	or any required main	tenance				
Pete Flore	s							
	1:47:09 AM							09 of 174

6/1/2016 11:47:09 AM Page 109 of 174

WOID Priority Assigned 7 Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Lo Area Deferred By Area Number Reason Description	Until Request Date Target Comp Dat Created Date/Time Actual Comp Dat Action Taker	e Aged	Labor Hours	Costs
Location:	Physical	Plant Complex				
153613			5/20/2016	12		\$0.00
Medium	Work In Progress		5/20/2016 3:15:20 PM			
Marquez, C	Gerardo	NEED TO ORDER PADLOCKS FO WIDE.	OR USE DISTRICT			
Gerardo M	larquez					
153221			5/16/2016	16		\$0.00
Medium	Work In Progress		5/16/2016 8:38:30 AM			
Marquez, C	Gerardo	NEED TO ORDER TOOLS FOR L	OCKSMITH SHOP.			
Gerardo M	larquez					
148635	·		2/29/2016	93		\$0.00
Medium	Work In Progress		2/29/2016 3:00:10 PM			
Apodaca, I	Mario	need too order air compressor for system pressure tanks	the irrigation water			
Mario Apod	daca					
150328			3/31/2016	62		\$0.00
Medium	Work In Progress		3/31/2016 1:35:50 PM			
Apodaca, I	Mario	need to order spare parts for the	UVUNIT			
Mario Apod	daca					
138657			8/25/2015	281		\$0.00
Medium	Work In Progress		8/25/2015 8:53:15 AM			
Apodaca, I	Mario	stainless steel fittings for the new wastewater plant at ppd also to be				
Mario Apod	daca					
153396			5/18/2016	14		\$0.00
Medium	Work In Progress		5/18/2016 8:03:43 AM			
Ronquillo,	Ruben	FIRST AID KIT REFILL				
Ruben Ro	nquillo					
152760			5/6/2016	26		\$0.00
Medium	Work In Progress		5/6/2016 3:03:02 PM			
Miranda, D	anny	Remove double entrance doors to window. Thank you	whs.and install new			
Ruben Ro	nquillo					
152129	Motor Vehicle		4/28/2016	34		\$0.00
Medium	Work In Progress		4/28/2016 9:09:44 AM			
Ronquillo,	Ruben	4 signs for auto shop (authorized p	personnel only)			
Maria Ruiz	•					

6/1/2016 11:47:09 AM Page 110 of 174

Selected Da WOID	te Range for Request Building	Dates:7/1/2015 - 6 Area	3/30/2016 Order By Loca Deferred By	ation, Status Until	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	-	Crea	-	Actual Comp Date	Aged	Hours	
Assigned ⁻	Го	Description				Action Taken			
Requester	Name								
Location:	Physical	Plant Complex							
149721					3/16/2016		77		\$0.00
Medium	Work In Progress			3/16/20	016 9:04:45 AM	1			
Miranda, D	danny	TEXTURED AN CURRENTLY WALLS AND A	E DRYWALL REPAIR ID PAINTED. LOCKS HAS MANY GAPS ANI IREAS AROUND THE WALL ENTIRELY.	MITH OFFICI D HOLES IN					
Gerardo M	arquez								
141695					10/14/2015		231		\$0.00
Medium	Work In Progress			10/14/20	015 2:47:58 PM	I			
Marquez, (Gerardo		ole at each North Dist se start with LLE per e		tchen				
Cynthia Ma	aes								
140460					9/23/2015		252		\$0.00
Medium	Work In Progress			9/23/20	015 8:36:42 AM	1			
Marquez, (Gerardo		S RUSTED. PLEASE AND LOCKSMITH EN						
Ruben Ro	nquillo								
141694					10/14/2015		231		\$0.00
Medium	Work In Progress			10/14/20	015 2:45:35 PM	I			
Lara, Ralp	h		ole at each South Dis se start with STMS po						
Cynthia Ma	aes				-//				
153615					5/20/2016		12		\$0.00
Medium	Work In Progress			5/20/20	016 3:24:38 PN	1			
Villalobos,	Jose	Move Custodia	I Repair Shop to New	Shop.					
Jose Villal	obos								
135167	Motor Vehicle				7/1/2015		336		\$0.00
Medium	Work In Progress			7/1/20	015 9:19:42 AM	1			
Marquez, (Gerardo	WESTSIDE OF	TALL DOOR AT META AUTOSHOP. THIS V EXT TO ROLL UP DR	VILL BE THE					

6/1/2016 11:47:09 AM Page 111 of 174

Gerardo Marquez

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Location Area Deferred By U Area Number Reason Description	ntil Request Date Target Created Date/Time Actual	A	Labor Hours	Costs
Location:		Plant Complex				
152670			5/5/2016	27		\$0.00
Medium	Work In Progress		5/5/2016 8:28:36 AM			
Marquez, G	-	Install double doors in old plbg. area. thank you!				
Ruben Ro	nquillo					
137531		Lift Station	8/7/2015	299		\$0.00
Medium	Work In Progress		8/7/2015 3:13:14 PM			
Gonzalez,	Salvador	the uv system shaded area need too pu metal to cover the uv system	t more sheet			
Mario Apod	laca					
153989			5/26/2016	6		\$0.00
Medium	Work In Progress		5/26/2016 3:55:03 PM			
Gonzalez,	Salvador	5-26-16 Need to move all stuff from old shop to r	new one			
Salvador G	Sonzalez					
143609			11/16/2015	198		\$0.00
Medium	Work In Progress		11/16/2015 7:43:51 AM			
Gonzalez,	Salvador	Sal can you please construct a pipe ract the Morgan building at the GAC. Thank				
David Villa	lobos					
149802			3/17/2016	76		\$0.00
Medium	Work In Progress		3/17/2016 10:33:07 AM			
Gonzalez,	Salvador	3-17-16 Need to cover shop wall with sheet met	al			
Salvador G	Sonzalez					
147550			2/8/2016	114		\$0.00
Medium	Work In Progress		2/8/2016 7:39:23 AM			
Gonzalez,	Salvador	2-8-16 I Need fabricate racks for shop				
Salvador G	Sonzalez					
153474			5/19/2016	13		\$0.00
Medium	Work In Progress		5/19/2016 7:45:13 AM			
Gonzalez,	Salvador	5-19-16 Need to fabricate metal work table for s	SERS and WS			
Salvador G	Sonzalez					
153009			5/11/2016	21		\$0.00
Medium	Work In Progress		5/11/2016 3:33:29 PM			
Hernandez	z, Guillermo	Need to verify kitchen inventory district	wide.			
Albert Valle						
	1:47:09 AM				Dage 44	12 of 174

Assigned 1 Requester		Area Number Reason Description	Until Request Date 7 Created Date/Time 7	Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Physical	Plant Complex					
152755	Motor Vehicle		5/6/2016		26		\$0.00
Medium	Work In Progress		5/6/2016 1:53:29 PM				
Marquez, G	Serardo	small name plates for wall filesplea	asesee Maria				
Maria Ruiz							
151112			4/11/2016		51		\$0.00
Medium	Work In Progress	FEDERAL	4/11/2016 1:39:44 PM				
Flores, Pet	e	LIGHT FOR MOTOR TURNED ON					
Noemi Dui							
140148	Motor Vehicle		9/17/2015		258		\$0.00
Medium	Work In Progress		9/17/2015 11:31:24 AM				
Flores, Pet	e	Tune and repair District Warehouse	van #11				
Enrique Br		·					
154053			5/31/2016		1		\$0.00
Medium	Work In Progress		5/31/2016 12:54:46 AM				
Apodaca, N	Mario	Monthly - PPD/GHS - WW Monthly Sa PMschedule details.	ampling - Refer to				
Margret Vil	lalobos						
152000			4/26/2016		3		\$0.00
Medium	Work In Progress		4/26/2016 1:46:12 PM	4/29/2016			
Ontiveros,	Guadalupe	Please water dirt road here at PPD.	(done			
Margret Vil	lalobos						
153747			5/24/2016		8		\$0.00
Medium	Work In Progress		5/24/2016 7:35:58 AM				
	z, Guillemo	NEED FOR DUCTWORK TO AC. TO CORRECTLY TO THE LOCKSMITH					
Gerardo M	arquez		F/20/2040		40		<u>ФО 00</u>
153604			5/20/2016		12		\$0.00
Medium	Work In Progress		5/20/2016 12:02:42 PM				
Castillo, Ca		submit request for general maintena equipment for summer.	ance material and				
Carlos Cas			#11.15a				^ ^ ^ - -
152969	Motor Vehicle		5/11/2016		21		\$0.00
Medium	Work In Progress		5/11/2016 9:41:04 AM				
Chavez, Sa	antos	Check air compressor in auto shop,	trips breaker daily.				

6/1/2016 11:47:09 AM Page 113 of 174

Priority Assigned 1	Status To	Area Number Description	Deferred By Until Request Date Target Comp Date Days Labor Number Reason Created Date/Time Actual Comp Date Aged Hours cription Action Taken						
Requester									
Location:	Physical	Plant Complex							
153956					5/26/2016		6		\$0.00
Medium	Work In Progress			5/26/201	6 1:37:41 PM	1			
Villalobos,	Margaret	as well as dollie floor crew will be	start assembling a es that are going to y e using these mach vaxing at this schoo	yucca heights the nines in june to					
Jimmy Car	rbajal								
150766					4/5/2016		57		\$0.00
Medium	Work In Progress			4/5/201	6 3:18:13 PM	1			
Villalobos,	Jose	the custodial ga	tor here at the ppd r	needs lights					
Jimmy Car	rbajal								
150907	Motor Vehicle				4/7/2016		55		\$0.00
Medium	Work In Progress	auto shop		4/7/201	6 9:40:53 AM	1			
Tobias, Vic	ctor	please supplyh technician.	and tools for Victor	Tobias -auto sho	р				
Pete Flores	s								
150167	Motor Vehicle				3/30/2016		63		\$0.00
Medium	Work In Progress			3/30/201	6 8:56:16 AM	1			
Villalobos,	Jose	requesting sup	plies for small engi	ne repair shop					
Jose Villale	obos								
150169	Motor Vehicle				3/30/2016		63		\$0.00
Medium	Work In Progress			3/30/201	6 9:04:55 AM	1			
Villalobos,	Jose	requesting tool	ooxand tools for sm	nall engine repair					
Jose Villale									
150170	Motor Vehicle				3/30/2016		63		\$0.00
Medium	Work In Progress			3/30/201	6 9:06:56 AM	1			
Villalobos,	Jose	requesting equ equipment	pment lift for repair	ing grounds					
Jose Villal	obos								
152212					4/29/2016		33		\$0.00
Medium	Work In Progress			4/29/201	6 2:48:09 PM	1			
Miranda, D	anny	Need to frame for	or new window at M	aint Warehouse.					

6/1/2016 11:47:09 AM Page 114 of 174

WOID Priority Assigned Requester	Building Status To	Area Area Number Description	Deferred By	cation, Status Until Request Date 7 Created Date/Time	Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:		Plant Complex						
153000				5/11/2016		21		\$0.00
Medium	Work In Progress			5/11/2016 3:16:24 PM				
Flores, Pet	te	Vehicle #195 th	e A/C does not worl	cneeds attention.				
		Thank You						
Marin Herr	era							
153497	Motor Vehicle			5/19/2016		13		\$0.00
Medium	Work In Progress	vehicle#119		5/19/2016 11:17:51 AM				
Flores, Pet	te	fan belt excess	ivelynoisyplease c	heck and advise				
Pete Flore	S							
153767				5/24/2016		8		\$0.00
Medium	Work In Progress			5/24/2016 8:31:24 AM				
Flores, Pet			72 needs service m acio (575) 882-628					
Dino Facio	Motor Vehicle			5/18/2016		14		\$0.00
Medium	Work In Progress	vehicle 102		5/18/2016 10:18:30 AM		14		ψ0.00
	-		i a a a la a a alla a	5/16/2016 10.16.30 AW				
Flores, Pet		needs new rec	inernandies					
Pete Flore: 153172	Motor Vehicle			5/13/2016		19		\$0.00
Medium	Work In Progress	VEHICLE#23		5/13/2016 2:59:55 PM		10		ψ0.00
Flores, Pet	-		CK CAUSE OF VEH					
Pete Flore	S							
153247	Motor Vehicle			5/16/2016		16		\$0.00
Medium	Work In Progress	vehicle 23		5/16/2016 9:41:58 AM				
Flores, Pet	te	vehicle 23 need	ls a new fuel pump					
Pete Flore								
154087	Motor Vehicle			5/31/2016		1		\$0.00
Medium	Work In Progress	vehicle 178		5/31/2016 2:17:56 PM				
Ruiz, Maria	a	needs an align	ment & new tires					
Maria Ruiz				100000				00.00
151979	Motor Vehicle	:		4/26/2016		36		\$0.00
Medium	Work In Progress	veh 48, 178 &		4/26/2016 9:55:26 AM				
Ruiz, Maria		vehicles 48,17 cracked	8 & 179 needs dasł	n mats, dash is				
Maria Ruiz								

6/1/2016 11:47:09 AM Page 115 of 174

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 C Area Deferre Area Number Reason Description	ed By Until Request Date 1		Days Labor aged Hours	Costs
Location:		Plant Complex				
152697	Motor Vehicle		5/5/2016		27	\$0.00
Medium	Work In Progress		5/5/2016 3:45:44 PM			Ψ0.00
Ruiz, Maria	_	vehicles need repair pai	int & body 49, 149, 178, 47 &			
Maria Ruiz						
153407	Motor Vehicle		5/18/2016		14	\$0.00
Medium	Work In Progress	vehicle 29	5/18/2016 9:13:38 AM			
Ruiz, Maria	a	need rack made (Delgae	do's Iron Works)			
Pete Flore	S					
147973	Motor Vehicle		2/18/2016	1	04	\$0.00
Medium	Work In Progress	vehicle#134	2/18/2016 9:03:08 AM			
Flores, Pet	te	please prepare vehicle fo	or us e by grounds dept.			
Pete Flore	S					
148837	Motor Vehicle		3/3/2016		90	\$0.00
Medium	Work In Progress		3/3/2016 8:33:04 AM			
Flores, Pet	te	vehicle 64 has a recall or to dealer for service.	n seat belts, needs to be taken			
Maria Ruiz						
152596	Motor Vehicle		5/4/2016		28	\$0.00
Medium	Work In Progress	vehicle#44	5/4/2016 10:46:30 AM			
Flores, Pet	te	please check overall cor service as required	ndition of vehicle, and repair or			
Pete Flore	S		1/0/0010			
150837			4/6/2016		56	\$0.00
Medium	Work In Progress		4/6/2016 1:13:07 PM			
Flores, Pet		SNP VEHICLE 172- DRI NOT GO UP.	IVER SIDE WINDOW WILL			
Maritza Go			F/04/0040		4	ФО 00
154088	Motor Vehicle		5/31/2016		1	\$0.00
Medium	Work In Progress	vehicle 110	5/31/2016 2:26:44 PM			
Flores, Pet	te	needs new lift switch for	gate			
Pete Flore	S					
153907			5/25/2016		7	\$0.00
Medium	Work In Progress	Vehicle #171	5/25/2016 3:20:53 PM			
Flores, Pet	te	"CHANGE OIL" LIGHT C	N			
Lorenzo So	olis					

6/1/2016 11:47:09 AM Page 116 of 174

WOID	Building	Dates:7/1/2015 - 6/30/2016 Order By L Area Deferred By		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number Reason	Created Date/Time	Actual Comp Date	Aged	Hours	
Assigned [*]	То	Description		Action Taken			
Requester	r Name						
Location:	Physical	Plant Complex					
152225			4/29/2016		33		\$0.00
Medium	Work In Progress		4/29/2016 3:46:55 PM	1			
Marquez, 0	Gerardo	Need to order new window, once I Albert for size.	Dannyframe area, see				
Albert Valle	ejo						
152949			5/11/2016		21		\$0.00
Medium	Work In Progress		5/11/2016 7:50:59 AM	1			
Chavez, Sa	antos	Materials for electrical departmen out of.	trunning very low or				
Santos Ch	navez						
153395			5/18/2016		14		\$0.00
Medium	Work In Progress		5/18/2016 7:47:59 AM	1			
Miranda, D	Danny	Maint Warehouse - Please installe	ed drop ceiling.				
Ruben Ro	onquillo						
153064	Motor Vehicle		5/12/2016		20		\$0.00
Medium	Work In Progress	auto shop	5/12/2016 10:23:46 AM	1			
Hernande	z, Guillemo	please install mini split system in	new shop lounge				
Pete Flore	es						
150968			4/7/2016		55		\$0.00
Medium	Work In Progress		4/7/2016 4:17:32 PN	1			
Carrasco,	Danny	scissor lift needed for Plan B to rui warehouse. please let me know v them to use					
Cora Ram	nirez						
152859			5/9/2016		23		\$0.00
Medium	Work In Progress		5/9/2016 3:54:09 PM	1			
Lara, Ralp	oh .	5-9-16-SHOP-69581-69621-MILE .5 2.S.T.H.SWO-148367-P					
		5.G.H.SWO-152444-P-WO-1524 .5	145-P-WO-152831-P				
Ralph Lar	a						
151448			4/15/2016		47		\$0.00
Medium	Work In Progress		4/15/2016 11:31:11 AM	1			
Briones, E	Enrique	move/organize equipment/salvagarea to prepare for auction - conta					
Alfredo Ho	olguin						

6/1/2016 11:47:09 AM Page 117 of 174

Selected Da			/30/2016 Order By Loc	•	•				Tota Costs
WOID	Building	Area	Deferred By	Until	Request Date Ta	•	Days	Labor	
Priority	Status	Area Number	Reason	Crea	ted Date/Time A		Aged	Hours	
Assigned '		Description				Action Taken			
Requester	· Name								
Location:	Physical	Plant Complex							
151695	Main Warehouse				4/20/2016		42		\$0.00
Medium	Work In Progress			4/20/2	016 2:38:04 PM				
Vallejo, All	pert	Install fence in	Barracks area						
Alfredo Ho	lguin								
153590					5/20/2016		12		\$0.00
Medium	Work In Progress			5/20/2	016 9:08:19 AM				
Vallejo, Alb	pert	Install Desks ir	Autoshop office						
Albert Valle	ejo								
152151					4/28/2016		34		\$0.00
Medium	Work In Progress			4/28/2	016 2:24:46 PM				
Vallejo, Alb	pert	•	ck flow preventers thoual inspection.	at were foun	d to be				
Albert Valle	ejo								
138019					8/14/2015		292		\$0.00
Medium	Work In Progress			8/14/2	015 8:57:46 AM				
Marquez, 0	Gerardo	PLEASE MEET QUOTE.	WITH DR. VENDOR	FOR PRICE	:				
Gerardo M	larquez								
Count: 87	Work Orders	Α	vg. Age of WO's 60)	Total for P	hysical Plant Com	plex	0	\$0.00

6/1/2016 11:47:09 AM Page 118 of 174

VOID riority ssigned 1 equester	Building Status To	Area Number Description	/30/2016 Order By Loc Deferred By Reason	Until	=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
ocation:	Riverside	FS							
51827					4/22/2016		40		\$0.00
/ledium	Work In Progress			1/22/2	4/22/2010 016 7:45:46 AM	1	-10		ψ0.00
/artinez, M	-	Need to replace units.	e all filters through ou			•			
Mario Marti	inez								
53049					5/12/2016		20		\$0.00
/ledium	Work In Progress			5/12/2	016 7:54:06 AM	1			
mbriz, Jos	se	Need Jose A. to #16.	o fix leaking heat pip	e over head i	n room				
Marti Marti	inez				2//2/22/2				•
40231					9/18/2015		257		\$0.00
/ledium	Work In Progress			9/18/2	015 2:33:41 PM	1			
mbriz, Jos	se	Need Jose A. to freeezing over.	o check Library A/C เ	unit which is s	still				
Marti Marti	inez								
51906					4/25/2016		37		\$0.00
/ledium	Work In Progress			4/25/20	16 10:35:22 AM	1			
mbriz, Jos	se		install heating and of from gym to office.	cooling vent ir	nto				
Marti Marti	inez								
49989					3/22/2016		71		\$0.00
/ledium	Work In Progress			3/22/2	016 9:32:37 AM	1			
/artinez, M			novate second and t estrooms. I will take						
Mario Marti	inez				1/00/0010				A 0 00
52006					4/26/2016		36		\$0.00
/ledium	Work In Progress			4/26/2	016 2:52:14 PM	1			
ara, Ralph			novate second and t estrooms need new		ng				
Martio Marti	inez				4/40/0010		4.4		Ф0.00
51528					4/18/2016		44		\$0.00
/ledium	Work In Progress			4/18/2	016 2:55:11 PM	1			
Martinez, M	<i>l</i> ario	Need to renova	te middle wing boys	and girls rest	rooms.				
Mario Marti	inez								
/ario Marti	inez								

6/1/2016 11:47:09 AM Page 119 of 174

WOID	Building		rred By	= = = = = = = = = = = = = = = = = = =	Target Comp Date	Days	Labor	
Priority	Status	Area Number Reas	on	Created Date/Time	•	Aged	Hours	
Assigned		Description			Action Taken			
Requeste								
Location:	Riverside	ES						
151182				4/12/2016		50		\$0.00
Medium	Work In Progress			4/12/2016 10:08:56 AM	1			
Martinez, I	Mario	Summer project!!! nee						
Mario Mar	tinez							
142531				10/29/2015		216		\$0.00
Medium	Work In Progress			10/29/2015 8:00:00 AM	1			
Gonzalez,	Salvador	Need Sal to fabricate n science portable.	new ramps and	stairs for new				
Mario Mar	tinez							
152890				5/10/2016		22		\$0.00
Medium	Work In Progress			5/10/2016 1:45:57 PM	Л			
Castillo, C	Carlos	Need Carlos C. to pure boys and girls restroor						
Mario Mar	tinez							
153470				5/18/2016		14		\$0.00
Medium	Work In Progress	room 16		5/18/2016 4:02:16 PM	Л			
Castillo, C	Carlos	Classroom will be con to install power outlets computers. (Mrs. Mart	s and internet co					
Norma Ma	artinez							
149980				3/22/2016		71		\$0.00
Medium	Work In Progress			3/22/2016 8:19:58 AM	1			
Martinez, I	Mario	Need to paint and insta at north wing boys and		· ·				
Mario Mar	tinez							
153657				5/23/2016		9		\$0.00
Medium	Work In Progress			5/23/2016 7:27:03 AN	1			
Ronquillo	, Ruben	Vandalism. broken wii	ndow!!! Need w	indow replacement				
Mario Mar	tinez							
152299				5/1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress			5/1/2016 1:03:34 AN	1			
Vallejo, Al	bert	Monthly - Riverside ES PMschedule details.	S Fire Suppress	sion Insp Refer to				
Margret Vi	illalobos							

6/1/2016 11:47:09 AM Page 120 of 174

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Loca Area Deferred By Area Number Reason Description		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Riverside	ES					
154040			5/31/2016	7/1/2016	1		\$0.00
Medium	Work In Progress		5/31/2016 12:54:37 AM	3, 3, 2			******
Martinez, N	_	Yearly - Riverside ES A-2 Gas/Elec to PMschedule details.					
Margret Vil	llalobos	to i moonodalo dotallo.					
152415			5/1/2016	5/7/2016	31		\$0.00
Medium	Work In Progress		5/1/2016 1:06:45 AM				
Martinez, N	Mario	Monthly - Riverside ES Monthly FE I PMschedule details.	npsection - Refer to				
Margret Vil	llalobos						
143289			11/9/2015		205		\$0.00
Medium	Work In Progress		11/9/2015 8:15:00 AM				
Moncayo,	Fernando	ICE IS BUILDING UP IN FREEZER SNP MANAGER SANTA NAVA 589.2					
Maritza Go	onzalez						
150397			4/1/2016		61		\$0.00
Medium	Work In Progress		4/1/2016 10:40:15 AM				
Moncayo,	Fernando	FREEZER-ICE BUILD AROUND DO MANAGER SANTA N. 589.2550	OOR. SNP				
Maritza Go	onzalez						
145799			1/7/2016		146		\$0.00
Medium	Work In Progress		1/7/2016 3:24:58 PM				
Moncayo,	Fernando	AS PER ADELES MONITORING RE WALK IN STILL ACCUMILATING ICI SANTA N.589.2550.					
Maritza Go	onzalez						
145503			1/4/2016		149		\$0.00
Medium	Work In Progress		1/4/2016 8:04:15 AM				
Gonzalez,	Salvador	Need to repair damaged canopy pol playground.	es at Kinder wing				
Mario Mart	tinez						
143287			11/9/2015		205		\$0.00
Medium	Work In Progress		11/9/2015 8:03:52 AM				
Gonzalez,	Salvador	Need welder Sal to cut and reverse r that they face in opposite direction.	netal benches so				
Mario Mart	tinez						

6/1/2016 11:47:09 AM Page 121 of 174

WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Location, Status Area Deferred By Until Request Date Target Comp Date Area Number Reason Created Date/Time Actual Comp Date Description Action Taken	Days Aged	Labor Hours	Costs
Location:	Riverside	ES			
150345		3/31/2016	62		\$0.00
Medium	Work In Progress	Gym 3/31/2016 3:42:41 PM			
Lara, Ralpl	h	**2nd Request** Double doors at the gym need a push bar. (Mr. Flavian)			
Norma Ma	rtinez				
146666		1/25/2016	128		\$0.00
Medium	Work In Progress	1/25/2016 12:03:11 PM			
Lara, Ralpl	h	Need to replace portable door at science lab.			
Mario Mart	inez				
152891		5/10/2016	22		\$0.00
Medium	Work In Progress	5/10/2016 1:49:50 PM			
Lara, Ralpl	h	Need Rafa L. to call partion people for new installation of partions at restrooms in middle wings.			
Mario Mart	inez				
152948		5/11/2016	21		\$0.00
Medium	Work In Progress	5/11/2016 7:41:28 AM			
Martinez, N		Need to replace 12 I-25 360 degree sprinkler heads at soccer field.			
Mario Mart	inez	E/40/2046	13		\$0.00
153505	\\\	5/19/2016	13		\$0.00
Medium Lara, Ralpl	Work In Progress h	5/19/2016 1:47:06 PM Need Rafa L. to install panic bars, tighten all loose door knobs, and lubricate all exterior padlocks and check all doors are functioning properly.			
Mario Mart	inez				
148384		2/24/2016	98		\$0.00
Medium	Work In Progress	2/24/2016 3:45:22 PM			
Martinez, N	<i>M</i> ario	2/24/2016. Summer project. Need to replace all 6 inch X6 inch broken tiles at all side walks.			
Mario Mart	inez				
153696		5/23/2016	9		\$0.00
Medium	Work In Progress	5/23/2016 3:06:06 PM			
Martinez, N	<i>M</i> ario	Need to snake out all drains and and pour drain cleaners down drains in order to keep line flowing and fresh smelling.			

6/1/2016 11:47:09 AM Page 122 of 174

	D . =///00/15 0	/00/00/40 O I D I		•				Tota
Building	Dates:7/1/2015 - 6 Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Costs
Status	Area Number	Reason	Crea	ted Date/Time	Actual Comp Date	Aged	Hours	
Го	Description				Action Taken			
Name								
Riverside	e ES							
				10/22/2015		223		\$0.00
Work In Progress			10/22	2/2015 11:02:29	1			
า			iter cabinet ar	nd				
inez								
				5/26/2016		6		\$0.00
Work In Progress			5/26/2	016 9:29:52 AM	1			
n								
rtinez								
				5/26/2016		6		\$0.00
Work In Progress			5/26/2	016 9:32:41 AM	1			
n	• •	•	ge room to the	F62				
rtinez								
Work Orders	Α	vg. Age of WO's 7	' 4		Total for Riversid	e ES	0	\$0.00
	Building Status Fo Name Riverside Work In Progress In Intez Work In Progress In Intez Work In Progress In Intez Intez	Building Area Status Area Number To Description Name Riverside ES Work In Progress Need Rafa L. to gates. And to he gates. And to he staff during surface. Work In Progress Change cylinder key. (Mrs. Martiratinez	Building Area Deferred By Status Area Number Reason To Description Name Riverside ES Work In Progress Need Rafa L. to re key locks for wa gates. And to have two padlocks. inez Work In Progress Need Master key to open back gate Staff during summer school/progratinez Work In Progress Change cylinder of custodial/storage key. (Mrs. Martinez)	Status Area Number Reason Creaton Description Name Riverside ES Work In Progress 10/22 Need Rafa L. to re key locks for water cabinet argates. And to have two padlocks. In Need Master key to open back gate for the cafete Staff during summer school/program. (Mr. Martin rtinez Work In Progress 5/26/2 Change cylinder of custodial/storage room to the key. (Mrs. Martinez)	Building Area Deferred By Until Request Date Status Area Number Reason Created Date/Time To Description Name Riverside ES 10/22/2015 Work In Progress Need Rafa L. to re key locks for water cabinet and gates. And to have two padlocks. In Need Rafa L. to re key locks for water cabinet and gates. And to have two padlocks. In Need Master key to open back gate for the cafeteria Staff during summer school/program. (Mr. Martinez) Prinez 5/26/2016 Work In Progress 5/26/2016 9:32:41 AM Change cylinder of custodial/storage room to the F62 key. (Mrs. Martinez)	Need Name Nork Name Nork Nork Nork Norgress Norg	Building Area Number Reason Created Date/Time Actual Comp Date Poscription Name Riverside ES Need Rafa L. to re key locks for water cabinet and gates. And to have two padlocks. Need Master key to open back gate for the cafeteria Staff during summer school/program. (Mr. Martinez) Need Master key to open back gate for the cafeteria Staff during summer school/program. (Mr. Martinez) Change cylinder of custodial/storage room to the F62 key. (Mrs. Martinez)	Building Area Number Reason Created Date Target Comp Date Aged Hours To Description Name Riverside ES 10/22/2015 223 Work In Progress Need Rafa L. to re key locks for water cabinet and gates. And to have two padlocks. In Need Rafa L. to re key locks for water cabinet and gates. And to have two padlocks. In Need Master key to open back gate for the cafeteria Staff during summer school/program. (Mr. Martinez) Riverside ES 5/26/2016 9:29:52 AM Need Master key to open back gate for the cafeteria Staff during summer school/program. (Mr. Martinez) Rinez Change cylinder of custodial/storage room to the F62 key. (Mrs. Martinez)

6/1/2016 11:47:09 AM Page 123 of 174

1141 - Work Orders In Progress (Fiscal Year)

	te Range for Request	Dates:7/1/2015 - 6 Area			Poguact Data	Target Comp Date	Dove	Labor	Costs
WOID Priority	Building Status	Area Number	Deferred By	Until	=	Target Comp Date Actual Comp Date	Days Aged	Hours	
Assigned 1		Description	Neason	0100	atou Buto, I iiiio	Action Taken			
Requester		•							
Location:	RTC - Alli	ance							
144375		Portables			12/4/2015		180		\$0.00
Medium	Work In Progress			12/4/2	015 1:03:29 PM	1			
Moncayo, F	Fernando	secure nails in	e an paint plank on o plaœ 2-6450 prior comino						
Gloria Del	gado								
141364		Portables			10/9/2015		236		\$0.00
Medium	Work In Progress			10/9/2	015 1:39:23 PM	1			
Gonzalez,	Salvador		donated by the Pea ace in the back by						
Gloria Del	gado								
148426					2/25/2016		97		\$0.00
Medium	Work In Progress			2/25/20	16 10:49:10 AM	1			
Gonzalez,	Salvador	need an old rim hose for our Sc	and metal post bu ience class	ild to store our	water				
Gloria Del	gado								
141681		Classroom			10/14/2015		231		\$0.00
Medium	Work In Progress	Ms. Hirsch		10/1	4/2015 11:27:51				
Moncayo, F	Fernando	tried to reset a been 30 min. a	ass air conditioner l nd turn back but ha nd has not turned o Student in class a	s not worked. n. Please send	lt has d				
Gloria Del	gado								
153471					5/18/2016		14		\$0.00
Medium	Work In Progress			5/18/2	016 4:15:15 PM	1			
Moncayo, F	ernando	need all air cor	nditioner filters char	nged for summ	er				
Gloria Del	gado								
153472					5/18/2016		14		\$0.00
Medium	Work In Progress			5/18/2	016 4:17:44 PN	1			
Moncayo, F	ernando	need campus	cleaned weeds etc	Thank you					
Gloria Del	gado								
	ork Orders	•	vg. Age of WO's	129		Total for RTC - Alli	ance	0	\$0.00

6/1/2016 11:47:09 AM Page 124 of 174

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Days Labor Area **Deferred By** Until Hours Aged Area Number Reason Created Date/Time Actual Comp Date **Priority Status Assigned To Description Action Taken** Requester Name Location: San Miguel ES 153012 5/11/2016 21 \$0.00 Medium Work In Progress 5/11/2016 3:34:31 PM Need to cover all windows with plywood due to Vega, Danny vandalism (Case# 2016-03712) Albert Vallejo Count: 1 Work Orders Avg. Age of WO's 21 **Total for San Miguel ES** 0 \$0.00

6/1/2016 11:47:09 AM Page 125 of 174

WOID Priority Assigned		Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa ES						
146521				1/21/2016		132		\$0.00
Medium	Work In Progress			1/21/2016 3:22:23 PM				
Moncayo, F	- ernando		ENT SINK FACUETS RINA R. 589.3439	S LEAKING. SNP				
Maritza Go	nzalez							
136192				7/21/2015		316		\$0.00
Medium	Work In Progress			7/21/2015 11:28:26 AM				
Gonzalez,	Salvador	Attach ramps to	portables.					
Albert Valle	ejo							
151842	Main Building			4/22/2016		40		\$0.00
Medium	Work In Progress	whole building		4/22/2016 12:24:23 PM				
Ambriz, Ju	an	Need to replace	e filters in all cooling	units				
Juan Ambi	riz							
146825				1/27/2016		126		\$0.00
Medium	Work In Progress			1/27/2016 8:37:07 AM				
Ambriz, Ju	an	Need one surv	eillance sign.					
Juan Ambi	riz							
152893	Main Building	Portables		5/10/2016		22		\$0.00
Medium	Work In Progress	A-B		5/10/2016 2:11:06 PM				
Ambriz, Ju	an	Need to replace	e restroom sink fauc	et in Portable A/B				
Juan Ambi	riz							
153851	Main Building	Exterior		5/24/2016		8		\$0.00
Medium	Work In Progress	back grass field	t	5/24/2016 3:03:28 PM				
Ambriz, Ju	an	Need to check	sprinklersystem					
Juan Ambi	riz							
153514		Classroom		5/19/2016		13		\$0.00
Medium	Work In Progress			5/19/2016 2:36:57 PM				
Lara, Ralpl	h	need to service	locks and worked o	n door cylinders,				
Ralph Lara				•				
140238	Main Building	Classroom		9/18/2015		257		\$0.00
Medium	Work In Progress	Room 101		9/18/2015 3:01:26 PM				
Lara, Ralpl Rita Mende	h		keys for room 101 key is a backup key	One if for Ms. Linck for school. Key				

6/1/2016 11:47:10 AM Page 126 of 174

WOID Priority Assigned Requester	Building Status To	Area Area Number Description	/30/2016 Order By Loc Deferred By Reason		arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa ES						
149567	Main Building	Kitchen		3/14/2016		79		\$0.00
Medium	Work In Progress			3/14/2016 12:31:23 PM				
Villalobos,	David	Having probler	ns with hot water					
Juan Amb	riz							
149569	Main Building	Parking Lot		3/14/2016		79		\$0.00
Medium	Work In Progress			3/14/2016 12:45:44 PM				
Gonzalez,	Salvador	As per Ms. Tari of school	n need to Install pos	ts with chain in front				
Juan Amb	riz			-11/0010	-//			
152301				5/1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress			5/1/2016 1:03:35 AM				
Vallejo, Alk		Monthly-Santa Refer to PMsch	Teresa ES Fire Suppledule details.	oression Insp				
Margret Vil	Main Building	Portables		3/1/2016		92		\$0.00
Medium	Work In Progress	all portables		3/1/2016 8:43:40 AM		32		ψ0.00
	· ·	·						
Lara, Ralp		Need to install	peep holes on all poi	table doors				
Juan Amb 149663	Main Building	Computer Lab		3/15/2016		78		\$0.00
Medium	Work In Progress	2 computer lab	6	3/15/2016 3:24:28 PM		70		ψ0.00
	ŭ	•						
Lara, Ralp		Need to install	cylinder locks to lock	iioiii iiiside				
Juan Amb 151890	Main Building	Classroom		4/25/2016		37		\$0.00
Medium	Work In Progress	Room #202		4/25/2016 8:08:14 AM				*****
Lara, Ralp			e restroom door. Cra					
Juan Amb		14000 to replace	21031100111 0001. 010	oncurrate to open				
140070	Main Building	Parking Lot		9/16/2015		259		\$0.00
Medium	Work In Progress	Exterior lighting	1	9/16/2015 12:03:20 PM				·
Castillo, C	_		, e some exterior lighti					
Juan Amb				3				
149572	Main Building	Exterior		3/14/2016		79		\$0.00
Medium	Work In Progress	back field		3/14/2016 1:28:24 PM				
Ambriz, Ju		Need to fertilize	e back field					
Juan Amb								

6/1/2016 11:47:10 AM Page 127 of 174

Selected Da WOID Priority	te Range for Request Building Status	Dates:7/1/2015 - 6 Area Area Number	Deferred By	Until	=	Target Comp Date Actual Comp Date	Days Aged	Labor Hours	Costs
Assigned [*]	То	Description				Action Taken			
Requester	Name								
Location:	Santa Te	resa ES							
151752					4/21/2016		41		\$0.00
Medium	Work In Progress			4/21/2	016 8:12:39 AM	1			
Chavez, Sa	antos	Please install s portable.	upplementarygrou	ınd rod at east		4/22/16 - Asp Albert	route to	Santos	
Albert Valle	ejo								
151753					4/21/2016		41		\$0.00
Medium	Work In Progress			4/21/2	016 8:16:17 AM	1			
Chavez, Sa		Please install a with NEC at ea	n exterior main elec st portable.	ctrical cutoff to	comply	4/22/16 - Asp Albert	route to	Santos	
Albert Valle	-				4/40/0040		4.44		
146042	Main Building	Exterior			1/12/2016		141		\$0.00
Medium	Work In Progress	outside wall of		1/12/2	016 8:43:11 AM	1			
Castillo, C	arlos	Need to replace	elights						
Juan Amb									
152513	Main Building	Classroom			5/3/2016		29		\$0.00
Medium	Work In Progress	several		5/3/2	016 9:19:23 AM	1			
Ambriz, Ju	an	Need to paint s	everal class rooms						
Juan Amb	riz								
152515	Main Building	Portables			5/3/2016		29		\$0.00
Medium	Work In Progress			5/3/2	016 9:24:01 AM	1			
Ambriz, Ju	an	As per Ms. Tari	n need to paint porta	ables doors, fr	ames				
Juan Amb									
152514	Main Building	Foyer			5/3/2016		29		\$0.00
Medium	Work In Progress	all front doors		5/3/2	016 9:22:07 AM	1			
Ambriz, Ju		As per Ms. Tari front foyer	n need to paint all do	oors and frame	es in				
Juan Amb					= 10 10 0 A 0				
152516	Main Building	Hallway/Corrid	or		5/3/2016	_	29		\$0.00
Medium	Work In Progress			5/3/2	016 9:51:07 AM	1			
Ambriz, Ju	an	Need to paint h	allways						
Juan Amb	riz								

6/1/2016 11:47:10 AM Page 128 of 174

WOID Priority Assigned ¹ Requester	Building Status To	Area Area Number Description	/30/2016 Order By Loca Deferred By Reason	Until Request Da	te Target Comp Date ne Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Santa Te	resa HS						
153264	Cafeteria (2005)	Kitchen		5/16/20	16	16		\$0.00
High	Work In Progress			5/16/2016 12:59:11	PM			
Moncayo, I	- ernando	Freezer at 24°	SNP Manager Olga E	3. (575) 589-5332				
Dino Facio)							
145711				1/6/20	16	147		\$0.00
Medium	Work In Progress			1/6/2016 2:06:46	PM			
Marquez, (Gerardo	Door should be	a 6' door between roo e situated at the south urther instruction.					
Albert Valle	ejo							
147239				2/1/20	16	121		\$0.00
Medium	Work In Progress			2/1/2016 4:13:12	PM			
Marquez, (Gerardo		A PRICE QUOTE FON OF A 6-0X7-0 DR					
Gerardo M	arquez							
148362	Main Building	Classroom		2/24/20	16	98		\$0.00
Medium	Work In Progress	305		2/24/2016 3:22:00	PM			
Lara, Ralp	h	door hinge is b	roken					
Lorraine D	ominguez							
135501	Library	Hallway/Corric	or	7/6/20	15	331		\$0.00
Medium	Work In Progress	200 Hall Stude	nt	7/6/2015 10:50:05	PM			
Lara, Ralp	h	Please replace	all existing stall parti to heavy graffiti	tions with new black				
Nicholas V	Vohlgemuth							
136357	Main Building	Restroom		7/23/20	15	314		\$0.00
Medium	Work In Progress	300 hallway		7/23/2015 2:41:30	PM			
Lara, Ralp	h		s need replacing, doo y are in bad shape	or is missing on one				
Lorraine D								
154077	Main Building	Classroom		5/31/20	16	1		\$0.00
Medium	Work In Progress	305		5/31/2016 1:21:19	PM			
Lara, Ralp	h	Door hinge is b	roken					
	ominguez							

6/1/2016 11:47:10 AM Page 129 of 174

1141 - Work Orders In Progress (Fiscal Year)

WOID	Building	Area	3/30/2016 Order By Loca Deferred By	Until Request Date	Target Comp Date	Days Aged	Labor Hours	Costs
Priority	Status -	Area Number	Reason	Created Date/Time	•	Ageu	rioui s	
Assigned ⁻ Requester		Description			Action Taken			
Location:	Santa Te	roca US						
				0/4/0045		202		<u>Фо</u> оо
137214	Library	Library		8/4/2015		302		\$0.00
Medium	Work In Progress	library		8/4/2015 2:28:04 PM	Л			
Lara, Ralp	n .	Emergencydo	ors not functioning					
	ominguez			. = 6				
145830				1/7/2016		146		\$0.00
Medium	Work In Progress			1/7/2016 3:55:49 PM	Л			
Gonzalez,	Salvador	Install window	guards on 700-702					
Albert Valle	ejo							
153005				5/11/2016		21		\$0.00
Medium	Work In Progress			5/11/2016 3:28:21 PM	Л			
Diaz, David	d	5/11/16 Need to check room 700.	roof for pin holes wate	r draining into				
David Diaz	2							
153260				5/16/2016		16		\$0.00
Medium	Work In Progress			5/16/2016 11:16:32 AN	1			
Diaz, David	d	5/16/16 Need to order 1 Summer Proje	l 0 exit combos for cafe ct	eteria room.				
David Diaz								
153262				5/16/2016		16		\$0.00
Medium	Work In Progress			5/16/2016 11:21:12 AN	1			
Diaz, David	d	5/16/16 Need to order of Project	ceiling tiles for the gym	area. Summer				
David Diaz								
153263				5/16/2016		16		\$0.00
Medium	Work In Progress			5/16/2016 11:25:18 AN	1			
Diaz, David	d		d burnt light bulbs in cl out. Summer Project	assrooms that need				
David Diaz								
149160	GYM (2009)	Gym		3/7/2016		86		\$0.00
Medium	Work In Progress	varsity gym		3/7/2016 3:18:50 PM	Л			
Diaz, David	d	Hang sign in g	ym					
Lorraine D	ominguez							

6/1/2016 11:47:10 AM Page 130 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da	ate Range for Request Building	Dates:7/1/2015 - 6/30/2016 Order By Loc Area Deferred By		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number Reason	Created Date/Time	-	Aged	Hours	
Assigned		Description		Action Taken			
Requester	r Name	·					
Location:	Santa Te	resa HS					
141057		Classroom	10/5/2015		240		\$0.00
Medium	Work In Progress	MR.	10/5/2015 1:03:46 PM	I			
Diaz, Davi	id	LAB C-4 NEEDS BOARD MOUNTE	D.				
Marylou Ji	menez						
151848	Vocational	Classroom	4/22/2016		40		\$0.00
Medium	Work In Progress	801	4/22/2016 2:58:57 PM	I			
Diaz, Davi	d	Classroom in need of an exhaust ve see teacher for further direction	entand cover. Please				
Lorraine D	Dominguez						
136365	Main Building	Classroom	7/23/2015		314		\$0.00
Medium	Work In Progress	410	7/23/2015 2:57:12 PM	I			
Diaz, Davi	d	Take down board and replace with I see Ms. Soriano	bulletin board please				
Lorraine D	Dominguez						
148702		ComputerLab	3/1/2016		92		\$0.00
Medium	Work In Progress	MRS.	3/1/2016 11:51:00 AM				
Diaz, Davi	id	MOUNT 4 X 6 BOARD IN COMPUT	ER LAB C-1.				
Marylou Ji	menez						
153831	Main Building	Computer Lab	5/24/2016		8		\$0.00
Medium	Work In Progress	Computerlabs	5/24/2016 11:03:05 AM				
Diaz, Davi	d	Install white board and/or bulletin be with height of white board All computer labs	oards align all boards				
Lorraine D	Dominguez						
147479			2/5/2016		117		\$0.00
Medium	Work In Progress		2/5/2016 1:39:26 PM	l			
Hernande	ez, Carlos	need air filters for units in café area					
Carlos He	ernandez						
153832	Main Building	Classroom	5/24/2016		8		\$0.00
Medium	Work In Progress	300 hallway	5/24/2016 11:04:42 AM				
Diaz, Davi	d	Install white boards and relocate buneeded 314,313,312,	ulletin board as				
Lorraine D	Dominguez						

6/1/2016 11:47:10 AM Page 131 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da	ate Range for Request Building	Dates:7/1/2015 - 6 Area	6/30/2016 Order By Loca Deferred By		Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•		=	Actual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requeste	r Name								
Location:	Santa Te	resa HS							
153834	Main Building	Classroom			5/24/2016		8		\$0.00
Medium	Work In Progress	200 hallway		5/24/201	6 11:09:22 AM	1			
Diaz, Davi	id	Install whitebo boards	ards in classrooms ar	nd replace bu	lletin				
Lorraine [Dominguez								
153835	Main Building	Classroom			5/24/2016		8		\$0.00
Medium	Work In Progress	408		5/24/201	6 11:17:02 AM	1			
Diaz, Davi	id	Install white bo	oard and 2 bulletin boa	rds					
Lorraine [Dominguez								
153836	Main Building	Classroom			5/24/2016		8		\$0.00
Medium	Work In Progress	500 Hallway		5/24/201	6 11:19:28 AM	1			
Diaz, Davi	id		ard and relocate bullet 01,500,502,504,505,50		everal				
Lorraine [Dominguez								
153813	Main Building	Classroom			5/24/2016		8		\$0.00
Medium	Work In Progress	606		5/24/20)16 9:50:35 AM	1			
Diaz, Davi	id	Blinds in smal	l window, check for bro	ken window					
Lorraine [Dominguez								
154073	Main Building	Classroom			5/31/2016		1		\$0.00
Medium	Work In Progress	309		5/31/20)16 1:16:23 PN	1			
Diaz, Davi	id	ceiling tiles ne	ed replacing (summer	2016)					
Lorraine [Dominguez								
154074	Main Building	Classroom			5/31/2016		1		\$0.00
Medium	Work In Progress	300		5/31/20)16 1:17:32 PN	1			
Diaz, Davi		classroom in r windows	eed of 2 flag brackets	please place	over				
	Dominguez								
154075	Main Building	Classroom			5/31/2016		1		\$0.00
Medium	Work In Progress	300		5/31/20)16 1:19:32 PN	Л			
Diaz, Davi		sign outside ol needed after re	d dark room removed a emoval	and patch wa	all up if				
	Dominguez								
154079	Main Building	Classroom			5/31/2016		1		\$0.00
Medium	Work In Progress	305		5/31/20)16 1:23:27 PN	1			
Diaz, Davi		window is very	difficult to open and d	loes not stay	open				
Lorraine [Dominguez								

6/1/2016 11:47:10 AM Page 132 of 174

1141 - Work Orders In Progress (Fiscal Year)

WOID Priority Assigned T Requester Location:	Santa Tel Main Building Work In Progress	Area Area Number Description resa HS Classroom	Deferred By Reason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Assigned T Requester Location:	Santa Tel Main Building Work In Progress	resa HS			Action Taken			
Location:	Santa Tel Main Building Work In Progress							
	Main Building Work In Progress							
154080	Work In Progress	Classroom						
	-			5/31/2016		1		\$0.00
Medium		305		5/31/2016 1:25:40 PM	I			
Diaz, David		cover for electr	ic outlet is missing					
Lorraine D	ominguez							
153663				5/23/2016		9		\$0.00
High	Work In Progress			5/23/2016 8:26:15 AM				
Lara, Ralph	ı	Teresa High Sethe Construction Espinoza or Ja	son Lermus eaux of	oon as possible in checked out to Roger				
Dominique	Esparza							
153763	Main Building	Classroom		5/24/2016		8		\$0.00
Medium	Work In Progress	610		5/24/2016 8:26:53 AM				
Hernandez		remove white b of the window i		nstall on wall t the left				
Lorraine Do		Ctororo		40/4/0045		400		<u>Фо оо</u>
144126	Main Building	Storage		12/1/2015		183		\$0.00
Medium	Work In Progress	Equipment		12/1/2015 3:40:22 PN	l			
Hernandez			e light fixtures in stora torage room all conr					
Lorraine D		1.1		0/0/0040				ФО ОО
148780	Main Building	Library		3/2/2016		91		\$0.00
Medium	Work In Progress	lobbyarea		3/2/2016 12:29:48 PM				
Hernandez			ing needs to be repa eed of scraping and p	ired, as well as entry painting				
Lorraine D								
148340	Main Building	Classroom		2/24/2016		98		\$0.00
Medium	Work In Progress	603		2/24/2016 2:41:09 PM	I			
Hernandez	, Carlos	Mountdisplay	ooards for art class r	ooms if possible				
Lorraine D								
151005	Main Building	Classroom		4/8/2016		54		\$0.00
Medium	Work In Progress	various		4/8/2016 3:25:57 PM	l			
Hernandez	, Carlos	801,803,807,8	oms.Exterior doors	include football hallway, 500				
Lorraine D	ominguez							

6/1/2016 11:47:10 AM Page 133 of 174

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Loca Area Deferred By Area Number Reason Description	tion, Status Until Request Date Tar Created Date/Time Ac	•		Costs
Location:	Santa Te	resa HS				
154081	Main Building	Classroom	5/31/2016	1		\$0.00
Medium	Work In Progress	302	5/31/2016 1:26:36 PM			
Hernande	z, Carlos	Light bulbs need replacing				
Lorraine D	Dominguez					
154082	Main Building	Classroom	5/31/2016	1		\$0.00
Medium	Work In Progress	308	5/31/2016 1:28:21 PM			
Hernande	z, Carlos	Window in class room needs screen open and close. Door handle needs difficult to open and close the door.				
Lorraine D	Dominguez					
153830	Main Building	Classroom	5/24/2016	8		\$0.00
Medium	Work In Progress	400 hallway	5/24/2016 11:00:51 AM			
Hernande	z, Carlos	Install 4x6 dry erase boards in the foll 401, 402, 403, 405, 407, 409, 410, 40 up paint where boards are removed of	8, as well as touch			
	Dominguez					
153799	Main Building	Classroom	5/24/2016	8		\$0.00
Medium	Work In Progress	303	5/24/2016 9:33:51 AM			
Hernande	z, Carlos	Wall where board was preciously at				
	Dominguez					
153787	Vocational	Classroom	5/24/2016	8		\$0.00
Medium	Work In Progress	807	5/24/2016 9:09:19 AM			
Hernande	z, Carlos	replace ceiling tiles				
Lorraine D	Dominguez					
153794	Vocational	Classroom	5/24/2016	8		\$0.00
Medium	Work In Progress	702	5/24/2016 9:16:25 AM			
Hernande	z, Carlos	mini blinds need to be replaced				
Lorraine D	Dominguez					
153777	Main Building	Classroom	5/24/2016	8		\$0.00
Medium	Work In Progress	409	5/24/2016 8:53:10 AM			
Hernande	z, Carlos	remove old white board				
Lorraine D	Dominguez					
153788	Vocational	Classroom	5/24/2016	8		\$0.00
Medium	Work In Progress	bandroom/choir	5/24/2016 9:10:39 AM			
Diaz, Davi	d	Replace tiles in percussion room Choir storage room door needs repa	ir			
Lorraine D	Dominguez					
6/1/2016	11:47:10 AM				Page 13	34 of 174

WOID Priority Assigned Requester			eferred By		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS						
153804	Main Building	Classroom		5/24/2016		8		\$0.00
Medium	Work In Progress	314		5/24/2016 9:39:28 AM				
Diaz, David	d	Bulletin board if a	vailable for south w	all on east end				
Lorraine D	ominguez							
153800	Main Building	Classroom		5/24/2016		8		\$0.00
Medium	Work In Progress	314		5/24/2016 9:37:03 AM				
Diaz, David	d	Windows need se	ealing					
Lorraine D	ominguez							
153797	Main Building	Classroom		5/24/2016		8		\$0.00
Medium	Work In Progress	404		5/24/2016 9:29:25 AM				
Diaz, David	d	Television stand r	needs to be mounte	d				
Lorraine D	ominguez							
153808	Main Building	Classroom		5/24/2016		8		\$0.00
Medium	Work In Progress	306		5/24/2016 9:46:30 AM				
Diaz, David	d	Dry ease board ne	eeds to be secured	to hang maps				
Lorraine D	ominguez							
153781	Vocational	Classroom		5/24/2016		8		\$0.00
Medium	Work In Progress	703		5/24/2016 8:55:45 AM				
Diaz, David	d	Replace ceiling in	nsulation as it appe	ars to be damaged.				
Lorraine D	ominguez							
153782	Vocational	Classroom		5/24/2016		8		\$0.00
Medium	Work In Progress	703		5/24/2016 8:56:38 AM				
Diaz, David	d	replace light bulbs	3					
Lorraine D	ominguez							
153759	Vocational	Classroom		5/24/2016		8		\$0.00
Medium	Work In Progress	805		5/24/2016 8:22:32 AM				
Diaz, David	d	Several requests level area	for equipment to be	moved from upper				
Lorraine D	ominguez							
153756	Main Building	Classroom		5/24/2016		8		\$0.00
Medium	Work In Progress	nurses office		5/24/2016 8:18:21 AM				
Diaz, David	d	hang new medica	ation cabinet					
Diaz, David Lorraine D		hang new medica	ation cabinet					

6/1/2016 11:47:10 AM Page 135 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da WOID	te Range for Request Building	Dates:7/1/2015 - 6 Area	/30/2016 Order By Locati Deferred By		quest Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•		=	Actual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requeste	r Name								
Location:	Santa Te	resa HS							
153839	Vocational	Classroom			5/24/2016		8		\$0.00
Medium	Work In Progress	801		5/24/2016	11:20:40 AM	1			
Diaz, Davi	d	install bulletin l	ooard near the entrance	е					
Lorraine D	Dominguez								
153766	Vocational	Classroom			5/24/2016		8		\$0.00
Medium	Work In Progress	801		5/24/2016	8:30:21 AM	1			
Hernande	z, Carlos	remove existin office.	g lockers and reinstall i	in ms olga per	ez				
Lorraine D	Dominguez								
153909					5/25/2016		7		\$0.00
Medium	Work In Progress			5/25/2016	3:25:28 PN	1			
Ronquillo	, Ruben	need 2 windov close .	s replaced in room 30	7 can't open or					
Carlos He	rnandez								
153785	Main Building	Classroom			5/24/2016		8		\$0.00
Medium	Work In Progress	215		5/24/2016	8:59:22 AM	1			
Lara, Ralp	h		near exit door patio nee		as				
Lorraine D	Dominguez								
154076	Main Building	Classroom			5/31/2016		1		\$0.00
Medium	Work In Progress	301		5/31/2016	6 1:20:24 PN	1			
Lara, Ralp	h	Lock on storag	e is broken and is need	dofrepair					
Lorraine D	Dominguez								
153757	Main Building	Classroom			5/24/2016		8		\$0.00
Medium	Work In Progress	lab c-1		5/24/2016	6 8:20:14 AM	1			
Lara, Ralp	h	cabinet door in	lab office in need of rep	oair					
Lorraine D	Dominguez								
154071	-				5/31/2016		1		\$0.00
Medium	Work In Progress			5/31/2016	11:41:53 AM	1			
Ambriz, Jo	se	5/31/16 Having probler	ns with ac unit in library	/area.					
David Dia	Z								
153786	Main Building	Classroom			5/24/2016		8		\$0.00
.00.00	\\\	215		5/24/2016	9:08:08 AM	1			
Medium	Work In Progress								
	· ·		actor does not work						

6/1/2016 11:47:10 AM Page 136 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da	te Range for Request Building	Dates:7/1/2015 - 6 Area	3/30/2016 Order By Loca Deferred By	tion, Status Until	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•	Crea	=	Actual Comp Date	Aged	Hours	
Assigned [•]	Го	Description				Action Taken			
Requester	Name								
Location:	Santa Te	resa HS							
150305	Main Building	Classroom			3/31/2016		62		\$0.00
Medium	Work In Progress	508/511 storaç	ge	3/31/20	16 11:13:26 AN	1			
Lara, Ralp	h	shelving down	abinets along one wa middle of both storag ge of chemicals and s	e rooms for p	oroper				
Rosalinda	Rodriguez								
153513		Classroom			5/19/2016		13		\$0.00
Medium	Work In Progress			5/19/2	016 2:35:46 PN	1			
Lara, Ralp	h	need to service	locks and worked on	door cylinde	rs,				
Ralph Lara	а								
153397					5/18/2016		14		\$0.00
Medium	Work In Progress			5/18/2	016 8:25:16 AN	1			
Lara, Ralp	h		e out core/keys by Jul shing gym floors on 、						
Jimmy Ca	rbajal								
153518					5/19/2016		13		\$0.00
Medium	Work In Progress			5/19/2	016 2:54:30 PN	1			
Lara, Ralp	h	doors to room	610 having hard time ι	ınlocking					
Carlos He	rnandez								
153519					5/19/2016		13		\$0.00
Medium	Work In Progress			5/19/2	016 2:56:15 PN	1			
Lara, Ralp	h		all exit doors need adju ard time locking also ir						
Carlos He	rnandez								
153795	Dressing Rooms	Dressing Roon	n		5/24/2016		8		\$0.00
Medium	Work In Progress	football locker		5/24/2	016 9:25:34 AN	1			
Lara, Ralp	h		s have broken handles not shut correctly.	as well as o	coaches				
Lorraine D	ominguez								
153755	Main Building	Classroom			5/24/2016		8		\$0.00
Medium	Work In Progress	nurses office		5/24/2	016 8:17:27 AN	1			
Villalobos,	David	clogged drain							
Lorraine D	ominguez								

6/1/2016 11:47:10 AM Page 137 of 174

WOID	te Range for Request Building	Area Deferred By	Until Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number Reason	Created Date/Time	·-	Aged	Hours	
Assigned 1		Description		Action Taken			
Requester							
Location:	Santa Te						
151183	Main Building	Restroom	4/12/2016		50		\$0.00
Medium	Work In Progress	400 Hallway	4/12/2016 10:21:50 AM	I			
Lara, Ralph	า	Re-Keylock cylinder in 400 hallwastaff can access using their class					
Nicholas V	Vohlgemuth						
146984			1/29/2016		124		\$0.00
Medium	Work In Progress		1/29/2016 10:36:18 AM	I			
Lara, Ralph	1	1/29/16 Need to replace Complete steel of the ROTC building. Doors are fall					
David Diaz							
143494	GYM (2009)		11/12/2015		0		\$0.00
Medium	Work In Progress		11/12/2015 3:44:07 PM	11/12/2015			
Lara, Ralph	n	DOORS NEED TO BE AJUSTED LACHES ON ALL DOORS AT GY					
Ralph Lara							
153778	Vocational	Classroom	5/24/2016		8		\$0.00
Medium	Work In Progress	703	5/24/2016 8:54:04 AN	I			
Villalobos,	David	remove sink from classroom, sea	al plumbing on wall				
Lorraine D	ominguez						
153752	Main Building	Classroom	5/24/2016		8		\$0.00
Medium	Work In Progress	500	5/24/2016 8:14:44 AM	I			
Villalobos,	David	sink in need of repair missing kno	obs				
Lorraine D	ominguez						
142007			10/20/2015		225		\$0.00
Medium	Work In Progress		10/20/2015 1:27:58 PM				
Villalobos,	David	Boys soccer locker room urinal ne	eeds to be replaced.				
Jaime Mija	ırez						
145988			1/11/2016		142		\$0.00
Medium	Work In Progress		1/11/2016 12:22:05 PM				
Villalobos,	David	trouble resetting water heater in n	nechanical room				
Carlos Hei		· ·					
148364	Main Building	Classroom	2/24/2016		98		\$0.00
Medium	Work In Progress	610	2/24/2016 3:22:53 PM	1			
Villalobos,	-	Dishwasher is leaking					
villalobos,	Davia	Disting 15 is isolarly					

6/1/2016 11:47:10 AM Page 138 of 174

1141 - Work Orders In Progress (Fiscal Year)

WOID Priority	Building Status	Area Area Number	/30/2016 Order By Loca Deferred By Reason		=	Days Aged	Labor Hours	Costs
Assigned ⁻		Description			Action Taken			
Requester		UC						
Location:	Santa Te							
135788	Gymnasium	Classroom		7/13/2015		324		\$0.00
Medium	Work In Progress	weightroom		7/13/2015 2:34:55 PN	Л			
Estrada, Je	esus	floor in weight r	oom is lifting					
Lorraine D	ominguez							
146671	Main Building	Cafeteria		1/25/2016		128		\$0.00
Medium	Work In Progress	Stage area		1/25/2016 2:06:33 PN	Л			
Carbajal, J	immy	Theater curtain	is torn and needs me	ending.	As per Albert, assig	n to Jimr	my C.	
Lorraine D	ominguez							
153772	Main Building	Classroom		5/24/2016		8		\$0.00
Medium	Work In Progress	608		5/24/2016 8:46:10 AN	1			
Castillo, C	arlos	one of the light	switches doesn't wor	k				
Lorraine D	ominguez	· ·						
154116	g	Office		5/31/2016		1		\$0.00
Medium	Work In Progress	REGISTRAR'S		5/31/2016 3:52:51 PN	Л			
Gonzales,	Camilo	PICK UP 6 BO AT WAREHOU	XES AND TAKE TO T SE.	RACE SWINFORD				
Marylou Jir	menez							
150978	Main Building	Athletic Field		4/8/2016		54		\$0.00
Medium	Work In Progress	football field		4/8/2016 8:58:56 AM	1			
Lara, Ralpl	n		driven through and i					
Lorraine D	ominguez							
150743				4/5/2016		57		\$0.00
Medium	Work In Progress			4/5/2016 9:09:12 AN	1			
Holguin, A	fredo		spose out dated che ss storage Rm.511 -					
Alfredo Ho	lguin							
152246				4/29/2016		33		\$0.00
Medium	Work In Progress			4/29/2016 4:02:09 PN	Л			
Vallejo, Alb	pert	Constructnew	baseball backstop.					
Albert Valle	ejo							
153591				5/20/2016		12		\$0.00
Medium	Work In Progress			5/20/2016 9:09:39 AM	1			
Vallejo, Alb	pert	Repair drive ga	ate at STHS					
Albert Valle		· ·						

6/1/2016 11:47:10 AM Page 139 of 174

WOID Priority	Building Status	Area Area Number	6/30/2016 Order By Loc Deferred By Reason		·-	Days Aged	Labor Hours	Costs
Assigned [•]		Description			Action Taken			
Requester	· Name							
Location:	Santa Te	resa HS						
153170				5/13/2016		19		\$0.00
Medium	Work In Progress			5/13/2016 2:39:10 PM	1			
Vallejo, All	pert	Constructnew	softball backstop sys	stem.				
Albert Valle	ejo							
151523	•			4/18/2016		44		\$0.00
Medium	Work In Progress			4/18/2016 12:57:32 PM				
Carbajal,	Jimmy	NEED GYM FL AUX)	OORS TO BE REFIN	IISHED (MAIN &				
Jimmy Ca	rbajal							
153792	Main Building	Classroom		5/24/2016		8		\$0.00
Medium	Work In Progress	204		5/24/2016 9:14:18 AM				
Diaz, Davi	d	Air filter needs	replacing					
Lorraine D	ominguez							
152456				5/2/2016		30		\$0.00
Medium	Work In Progress			5/2/2016 3:17:02 PM	1			
Hernande	z, Carlos	need to finish s	ervicing a/c units					
Carlos He	rnandez							
141349	Locker Room	Hallway/Corric	dor	10/9/2015		236		\$0.00
Medium	Work In Progress			10/9/2015 8:50:43 AM				
Lara, Ralp	h	lose it and look	netic Door Holder mo ss damaged. It needs I re-attached to the wa	to be replaced if				
Alfredo Ho	lguin							
141547	GYM (2009)	Athletic Field		10/12/2015		233		\$0.00
Medium	Work In Progress	Baseball		10/12/2015 3:46:32 PM				
Gonzalez,	Salvador		g caged to be remove ds . Requesting two fr					
Lorraine D	ominguez							
153425				5/18/2016		14		\$0.00
Medium	Work In Progress			5/18/2016 2:58:29 PM	1			
Ambriz, Jo	se	need to replace	e water fountain in ma	ain hallway (broken)				
Carlos He	rnandez							

6/1/2016 11:47:10 AM Page 140 of 174

WOID Priority Assigned Requester			Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS						
153426				5/18/2016		14		\$0.00
Medium	Work In Progress			5/18/2016 3:00:42 PM	1			
Ambriz, Jos	se	5/18/16 Needs to solde pit in varsity gym a		leading to ac on Parra				
David Diaz	2							
153702				5/23/2016		9		\$0.00
Medium	Work In Progress			5/23/2016 3:37:31 PM	1			
Ambriz, Jos	se	need to check a	a/c in library.					
Carlos He	rnandez							
144910		Athletic Field		12/11/2015		173		\$0.00
Medium	Work In Progress			12/11/2015 3:54:51 PM	l			
Ontiveros,	Guadalupe		up around third bas ecycled chain link a					
D: 1.1.		To be done by 0	Grounds Dept.					
Rick Llane	Vocational	Classroom		5/24/2016		8		\$0.00
Medium	Work In Progress	208		5/24/2016 8:34:35 AN	1	Ü		φυ.σσ
	_		and air ann dition a					
Ambriz, Jos		replace all liller	and air conditione	r needs lixing				
151200	ominguez			4/12/2016		50		\$0.00
Medium	Work In Progress			4/12/2016 12:46:42 PM	ı	00		φυ.ου
Villalobos,	•			ems with on off switch o as well as hose cap				
Jimmy Ca	rbaial	andrieeds nos	es and nose claim	o as well as nose cap				
151203				4/12/2016		50		\$0.00
Medium	Work In Progress			4/12/2016 12:50:40 PM				
Villalobos,	_	vacuum #045 n	eed maintenance					
Jimmy Car								
151355	i Dajai			4/14/2016		48		\$0.00
Medium	Work In Progress			4/14/2016 7:39:34 AM	1			
	9							

6/1/2016 11:47:10 AM Page 141 of 174

WOID Priority Assigned Requester		20.0						Labor Hours	
Location:	Santa Te	rasa HS							
	- Janua 16				2/22/2040		74		<u>ФО 00</u>
149990				- / /-	3/22/2016	_	71		\$0.00
Medium	Work In Progress			3/22/20	016 9:42:57 AN	1			
,			a work order to the c Week of March 21-2 B. 589-5332		ean				
Maritza Go	nzalez								
153327	Cafeteria (2005)	Kitchen			5/17/2016		15		\$0.00
Medium	Work In Progress			5/17/20	016 9:39:23 AM	1			
Carbajal, J	limmy	Kitchen Floors B. (575) 589-53	need deep cleaning 332	. SNP Manage	r Olga				
Dino Facio)								
153774	GYM (2009)	Gym			5/24/2016		8		\$0.00
Medium	Work In Progress	lockerrooms		5/24/20	016 8:47:14 AM	1			
Carbajal, J	limmy	power wash the	e locker rooms						
Lorraine D	ominguez								
152302					5/1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress			5/1/20	016 1:03:36 AM	1			
Vallejo, Alb	pert	Monthly-Santa Refer to PMsch	Teresa HS Fire Sup nedule details.	pression Insp	ı				
Margret Vil	lalobos								
153765	Vocational	Classroom			5/24/2016		8		\$0.00
Medium	Work In Progress	801		5/24/20	016 8:28:43 AM	1			
Castillo, C	arlos	electrical outlet	ts to add extra row of	computers.					
Lorraine D	ominguez								
149728	Vocational	Classroom			3/16/2016		77		\$0.00
Medium	Work In Progress	801		3/16/20	16 11:23:13 AM	1			
Castillo, C	arlos		sroom are loose and be a need for more o reasing.						
Lorraine D	ominguez								
152602	Main Building	Classroom			5/4/2016		28		\$0.00
Medium	Work In Progress	505		5/4/201	16 11:14:46 AM	1			
Castillo, C	arlos	Please check e	electrical outlets in cl	assroom					
l arraina D	ominguez								

6/1/2016 11:47:10 AM Page 142 of 174

1141 - Work Orders In Progress (Fiscal Year)

WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2015 - 6 Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa HS						
148919	Main Building	Classroom		3/4/2016		89		\$0.00
Medium	Work In Progress	403		3/4/2016 10:31:09 AM	1			
Castillo, C	· ·	Projector need	s power for use of sma	artboard				
	ominguez	,	•					
154083	Main Building	Classroom		5/31/2016		1		\$0.00
Medium	Work In Progress	308		5/31/2016 1:29:13 PM	1			
Castillo, C	arlos	Electrical outle	ts are not working					
	ominguez		Ç					
154084	Main Building	Classroom		5/31/2016		1		\$0.00
Medium	Work In Progress	washerroom		5/31/2016 1:42:21 PM	1			
Castillo, C	arlos	electrical boxin	washer room needs t	to be reinstalled				
	ominguez							
153760	Main Building	Classroom		5/24/2016		8		\$0.00
Medium	Work In Progress	505		5/24/2016 8:23:36 AM	1			
Villalobos,	, David	Back sink fauce	ethandle is broken, ne	eds to be replaced				
Lorraine C	ominguez			·				
153764	Main Building	Classroom		5/24/2016		8		\$0.00
Medium	Work In Progress	610		5/24/2016 8:27:38 AM	1			
Villalobos,	, David	dishwasherin	need of repair					
Lorraine D	ominguez							
153817	Main Building	Classroom		5/24/2016		8		\$0.00
Medium	Work In Progress	600		5/24/2016 9:56:54 AM	1			
Villalobos,	, David	Washer and dr	yer hook up needed fo	r new appliances				
Lorraine D	ominguez							
153818	Main Building	Classroom		5/24/2016		8		\$0.00
Medium	Work In Progress	600		5/24/2016 9:57:48 AM	1			
Villalobos,	, David	need ventilation	n for dryer as they will b	e installing new				
Lorraine D	ominguez							
152600	Main Building	Classroom		5/4/2016		28		\$0.00
Medium	Work In Progress	505		5/4/2016 11:13:24 AM	1			
Villalobos,	,David Dominguez	Please check v utilized next yea	vater and gas in classı ar	room as it will be				

6/1/2016 11:47:10 AM Page 143 of 174

1141 - Work Orders In Progress (Fiscal Year)

WOID Priority	Building Status	Area Area Number	/30/2016 Order By Loca Deferred By Reason		•	Days Aged	Labor Hours	Costs
Assigned ⁻ Requester		Description			Action Taken			
Location:	Santa Te	resa HS						
151759	GYM (2009)	Athletic Field		4/21/2016		41		\$0.00
Medium	Work In Progress	Football/socce	•	4/21/2016 9:24:07 AN	1	••		ψ0.00
Llanez, Ric	-		tball field needs to wi					
Lorraine D	ominguez							
153762	Main Building	Classroom		5/24/2016		8		\$0.00
Medium	Work In Progress	610		5/24/2016 8:25:33 AM	1			
Lara, Ralpl	า	Several cabine	ts have broken locks					
Lorraine D	ominguez							
154078	Main Building	Classroom		5/31/2016		1		\$0.00
Medium	Work In Progress	305		5/31/2016 1:22:26 PN	1			
Lara, Ralpl	า	Desk lock is bro	oken as well as two fi	ing cabinets locks				
Lorraine D								
153790	Main Building	Classroom		5/24/2016		8		\$0.00
Medium	Work In Progress	204		5/24/2016 9:12:46 AM	1			
Lara, Ralpl	า	cabinets in nee	ed of locks					
Lorraine D	ominguez							
144362	Main Building	Classroom		12/4/2015		180		\$0.00
Medium	Work In Progress	nurses office		12/4/2015 11:14:14 AM	1			
Lara, Ralpl	า	change door kr	nob on door					
Lorraine D	ominguez							
148367	Vocational	Classroom		2/24/2016		98		\$0.00
Medium	Work In Progress	805		2/24/2016 3:25:18 PN	1			
Lara, Ralpl	า	Flammable cal	oinets need to be reke	eyed to keep locked				
Lorraine D								
153809	Main Building	Classroom		5/24/2016		8		\$0.00
Medium	Work In Progress	306		5/24/2016 9:47:17 AM	1			
Lara, Ralpl	า	Fix door knob a	s it does n't allow doo	r to close properly				
Lorraine D	ominguez							
153801	Main Building	Classroom		5/24/2016		8		\$0.00
Medium	Work In Progress	314		5/24/2016 9:38:01 AM	1			
Lara, Ralpl	n	Cylinder locks replacing	on cupboards and file	e cabinet need				
Lorraine D	ominguez							

6/1/2016 11:47:10 AM Page 144 of 174

WOID Priority	Building Status	Dates:7/1/2015 - 6/30/2016 Order By I Area Deferred By Area Number Reason		Target Comp Date Actual Comp Date	Days Aged	Labor Hours	Costs
Assigned		Description	Ordatou Buto, Illino	Action Taken			
Requeste		·					
Location:	Santa Te	resa HS					
153758	Main Building	Classroom	5/24/2016		8		\$0.00
Medium	Work In Progress	lab c-1	5/24/2016 8:21:18 AN	1			
Lara, Ralp	bh	lock in storage room needs repai	r				
Lorraine D	Dominguez						
148369	Vocational	Classroom	2/24/2016		98		\$0.00
Medium	Work In Progress	805	2/24/2016 3:26:54 PN	1			
Ontiveros	, Guadalupe	Machines need to be moved from level. Will require machinery any contact David for further instructi	questions, please				
Lorraine [Dominguez						
154037			5/31/2016	7/1/2016	1		\$0.00
Medium	Work In Progress		5/31/2016 12:54:35 AM	1			
Hernande	ez, Carlos	Yearly - Santa Teresa HS A-2 H/to PMschedule details.	C Units Yearly - Refer				
Margret Vi	Ilalobos						
152263			5/1/2016		31		\$0.00
Medium	Work In Progress		5/1/2016 1:03:07 AM	l			
Villalobos		Monthly - STH-UV-0517 PM Serv schedule details.	ice - Refer to PM				
Margret Vi	llalobos		F /4.7/0.040		45		Φο οο
153347		Football Field	5/17/2016	_	15		\$0.00
Medium	Work In Progress		5/17/2016 3:05:12 PN	1			
Castillo, C	Carlos	Check football field electrical and	lighting systems.				
Carlos Ca							
153067	Main Building	Classroom	5/12/2016		20		\$0.00
Medium	Work In Progress	c4	5/12/2016 11:09:58 AM	1			
Castillo, C	Carlos	Classroom needs electrical work	done for smartboard				
Lorraine D	Dominguez						
152499		Office	5/2/2016		30		\$0.00
Medium	Work In Progress	RECEPTIONIST	5/2/2016 5:02:48 PM	1			
Castillo, C	Carlos	NEED AN OUTLET ON WALL OF RECEPTION LOBBY	F FRONT OFFICE				
Marylou Ji	menez						
153498			5/19/2016		13		\$0.00
Medium	Work In Progress		5/19/2016 11:40:48 AM	1			
Castillo, C	Carlos	Small section of bleachers, need only, comes out half way asp PM					
David Dia	z						
6/1/2016	11:47:10 AM					Page 1	45 of 174

6/1/2016 11:47:10 AM Page 145 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da	ite Range for Request Building	Dates:7/1/2015 - 6	5/30/2016 Order By Lo Deferred By	cation, Status Until	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	_		=	Actual Comp Date	Aged	Hours	
Assigned		Description	rtou oon	5.55		Action Taken			
Requester		•							
Location:	Santa Te	resa HS							
153267					5/16/2016		16		\$0.00
Medium	Work In Progress			5/16/2	016 2:35:17 PN	1			
Castillo, C	arlos		power to install a cor en lights go off.	nbo exit sign i	n room				
David Diaz	Z								
153953		Classroom			5/26/2016		6		\$0.00
Medium	Work In Progress	314		5/26/20	16 10:49:15 AN	1			
Castillo, C	arlos	Projector does electrical in Ma	not have electrical s rch)	ource (submi	tted for				
Rodriguez	z, Rosalinda								
149332	Main Building	Classroom			3/9/2016		84		\$0.00
Medium	Work In Progress	c-4,		3/9/2	016 3:01:24 PN	1			
Castillo, C	arlos		have been installed t power to them for f						
Lorraine D	Oominguez								
145712					1/6/2016		147		\$0.00
Medium	Work In Progress			1/6/2	016 2:11:24 PN	1			
Castillo, C	arlos		sh circuits for new ceext to pump room)	omputer lab a	room				
Albert Vall	ejo								
150655					4/4/2016		58		\$0.00
Medium	Work In Progress			4/4/2	016 9:03:25 AN	1			
Castillo, C	arlos	need to replace	e lights in varsity gyn	า					
Carlos He	rnandez								
147186					2/1/2016		121		\$0.00
Medium	Work In Progress			2/1/20	16 12:59:15 PN	1			
Castillo, C	arlos	need to replace	e light fixtures in equ	ipmentroom					
Carlos He	rnandez								
153906					5/25/2016		7		\$0.00
Medium	Work In Progress			5/25/2	016 1:43:49 PN	1			
Castillo, C	arlos	5/25/16 Need to replac class rooms. V	e ballasts and repla VO 153782	ce lamps in R	отс				
David Diaz	Z								

6/1/2016 11:47:10 AM Page 146 of 174

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Area Deferrore Area Number Reason Description	ed By Until Request Date 1		ays Labor ged Hours	Costs
Location:	Santa Te	resa HS				
153784	Main Building	Classroom	5/24/2016		8	\$0.00
Medium	Work In Progress	215	5/24/2016 8:57:56 AM			
Diaz, David			g, please use same colors and if ncluding changing areas			
Lorraine D 153816	Main Building	Classroom	5/24/2016		8	\$0.00
Medium	Work In Progress	600	5/24/2016 9:55:53 AM		· ·	φυ.σσ
Diaz, David	_	Classroom needs paint				
		Ciassiooni needs paini	ng			
Lorraine D 153770	Vocational	Classroom	5/24/2016		8	\$0.00
Medium	Work In Progress	801	5/24/2016 8:43:59 AM			,
Diaz, David	•	paint wall where lockers	are removed			
Lorraine D		paint waii who to tooke to	, and rolling vou			
153750	Main Building	Classroom	5/24/2016		8	\$0.00
Medium	Work In Progress	607	5/24/2016 8:12:16 AM			
Hernandez	z, Carlos	Classroom in need of p	ain t ing			
Lorraine D	ominguez	·	•			
153754	Main Building	Classroom	5/24/2016		8	\$0.00
Medium	Work In Progress	nurses office	5/24/2016 8:16:46 AM			
Hernandez	z, Carlos	office in need of painting	1			
Lorraine D	ominguez					
136351	Main Building	Restroom	7/23/2015	31	14	\$0.00
Medium	Work In Progress	by library	7/23/2015 2:35:07 PM			
Diaz, David	d	Ceiling needs painting				
Lorraine D	ominguez					
153837	Vocational	Classroom	5/24/2016		8	\$0.00
Medium	Work In Progress	805	5/24/2016 11:19:56 AM			
Hernandez	z, Carlos	in need of painting				
Lorraine D	ominguez					
153796	Main Building	Classroom	5/24/2016		8	\$0.00
Medium	Work In Progress	404	5/24/2016 9:27:30 AM			
Hernandez	z, Carlos	Walls in need of painting	9			
Lorraine D	ominguez					

6/1/2016 11:47:10 AM Page 147 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da	ate Range for Request Building	Dates:7/1/2015 - 6/30/2016 Order By Location Area Deferred By	on, Status Jntil Request Date Targ	et Comp Date Days	Labor	Costs
Priority	Status	Area Number Reason	Created Date/Time Actu	A	Hours	
Assigned	То	Description		Action Taken		
Requeste	r Name					
Location:	Santa Te	resa HS				
136350	Main Building	Classroom	7/23/2015	314		\$0.00
Medium	Work In Progress	209	7/23/2015 2:34:10 PM			
Diaz, Davi	id	Please paint where tv stand was remov	<i>y</i> ed.			
Lorraine [Dominguez					
154090	Main Building	Classroom	5/31/2016	1		\$0.00
Medium	Work In Progress	several	5/31/2016 2:40:45 PM			
Diaz, Davi	id	Several rooms in need of painting 300,301,305,500,801,608,303,314,40	4,805,503			
Lorraine [Dominguez					
147782			2/11/2016	111		\$0.00
Medium	Work In Progress		2/11/2016 8:26:41 AM			
Holguin, A	Alfredo	Running Track - Repair cracks in rubbe	erized surface			
Alfredo Ho	olguin					
146848		Athletic Field	1/27/2016	126		\$0.00
Medium	Work In Progress		1/27/2016 2:33:21 PM			
Holguin, A	Nfredo	Football field Artificial Turf - Perform Sp cleaning service, Seam Repairs and a				
Alfredo Ho						
151412	Main Building	Classroom	4/14/2016	48		\$0.00
Medium	Work In Progress	215	4/14/2016 3:50:09 PM			
Llanez, Ri	ck	If a can crusher can be installed in pation pillar.	o on one of the			
Lorraine [Dominguez					
150172	Main Building	Athletic Field	3/30/2016	63		\$0.00
Medium	Work In Progress	baseball	3/30/2016 9:15:58 AM			
Llanez, Ri	ck	Dirt needs to be placed in back of base	ball field			
Lorraine [Dominguez					
Count: 14	9 Work Orders	Avg. Age of WO's 53	Total f	or Santa Teresa HS	0	\$0.00

6/1/2016 11:47:10 AM Page 148 of 174

WOID Priority Assigned	Building Status To	Area Area Number Description	Deferred By Reason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Requester	Name							
Location:	Santa Te	resa MS						
153138	North Building	Classroom		5/13/2016		19		\$0.00
Medium	Work In Progress			5/13/2016 7:53:02 AM	I			
Gallegos,	Rafael	5:00am North I	se set the air conditio Building 2 floor I work I when I start cleanin	on this area and is				
Ismael Ro	odriguez							
153238	South Building	Office		5/16/2016		16		\$0.00
Medium	Work In Progress	SECURITY		5/16/2016 9:04:04 AM	I			
Prospero,	Manuel	PAINT OFFICE						
Laura Par	ra							
153224	North Building	Office		5/16/2016		16		\$0.00
Medium	Work In Progress	WHOLE BLDG	ì	5/16/2016 8:42:37 AN	I			
Prospero,	Manuel	PAINT ALL EXT IN BLACK	TERIOR DOORS/RAI	LS AND FRAMES				
Laura Par								
153225	South Building	Office		5/16/2016		16		\$0.00
Medium	Work In Progress	WHOLE BLDG	i	5/16/2016 8:43:18 AN	I			
Prospero,		PAINT ALL EXT FRAMES IN BL	TERIOR HANDRAILS ACK	DOORS AND				
Laura Par		O#:		44/0/0045		205		<u>ФО 00</u>
143316	South Building	Office	_	11/9/2015		205		\$0.00
Medium Prospero,	Work In Progress Manuel		E M INSIDE AND OUTS OMS-BLACK PAINT	11/9/2015 2:24:01 PM SIDE OF OFFICES	1			
Laura Par	ra	7112 11201110	one benefit have					
153222	South Building	Classroom		5/16/2016		16		\$0.00
Medium	Work In Progress	CHOIR ROOM		5/16/2016 8:40:56 AM	I			
Prospero,	Manuel	PAINT CHOIR	ROOM AND OFFICE	S INSIDE ROOM				
Laura Par								
153227	North Building	Restroom		5/16/2016		16		\$0.00
Medium	Work In Progress	RESTROOMS		5/16/2016 8:45:39 AM	I			
	- 3							
Prospero,	Manuel	PAINT ALL REIN BLACK	STROOMS PARTITIC	NS AND DOORS				

6/1/2016 11:47:10 AM Page 149 of 174

1141 - Work Orders In Progress (Fiscal Year)

Assigned To Requestry Services Description Action Taken Requestry Services Clocation: Santa Testes Medium South Building Restorm 5/16/2016 8:47:08 AM 16 5/16/2016 8:47:08 AM Prospero, Important Services PAINT ALL RESTROOM PARTITIONS AND DOORS BLACK 16 \$0	Selected Da WOID Priority	ate Range for Request Building Status	Dates:7/1/2015 - 6 Area Area Number	6/30/2016 Order By Loca Deferred By Reason		Target Comp Date Actual Comp Date	Days Aged	Labor Hours	Costs
Deathon: Santa Teresa MS	-					=			
153228 South Building Restroom 5/16/2016 16 \$€ Medium Work in Progress ALL 5/16/2016 8:47:08 AM Prospero, Manuel Pall TALL RESTROOM PARTITIONS AND DOORS BLACK Laura Parra 153228 QMr (1997) Gym 5/16/2016 16 16 \$€ Medium Work in Progress SEE MS 5/16/2016 8:41:42 AM Prospero, Manuel Pall TALL RESTROOM PARTITIONS AND DOORS Laura Parra 153228 QMr (1997) Gym 5/16/2016 8:41:42 AM Prospero, Manuel Pall TGM AND OFFICES Laura Parra 153228 QMr (1997) Gym 5/16/2016 16 \$€ Medium Work in Progress RESTROOMS PARTITIONS AND DOORS RESTROOMS PARTITIONS AND DOORS IN BLACK Laura Parra 151970 4/26/2016 8:44:58 AM Prospero, Manuel Pall TGM AND PROGRES Laura Parra 15328 QMr (1997) Gym 4/26/2016 8:20:41 AM Castillo, Carlos SNP GESSICA M.589.9836 Medium Work in Progress A/26/2016 8:20:41 AM Castillo, Carlos SNP GESSICA M.589.9836 Medium Work in Progress Parra M.5/25/2016 7 \$€ Medium Work in Progress Parra M.5/25/2016 7 \$€ Medium Work in Progress Parra M.5/25/2016 9:11:08 AM Castillo, Carlos Carlos Carlos Covers AND OUTLETS NEED 5 REPLACED. Laura Parra 150921 South Building Parking Lot 4/7/2016 55 \$€ Medium Work in Progress Parking Lot 4/7/2016 55 \$€ Medium Work in Progress Parking Lot 4/7/2016 55 \$€ Medium Work in Progress Parking Lot 4/7/2016 55 \$€ Medium Work in Progress Parking Lot 4/7/2016 55 \$€ Medium Work in Progress Parking Lot 4/7/2016 55 \$€ Medium Work in Progress Parking Lot 4/7/2016 55 \$€ Medium Work in Progress Parking Lot 4/7/2016 55 \$€ Medium Work in Progress Parking Lot 4/7/2016 55 \$€ Medium Work in Progress Parking Lot 4/7/2016 55 \$€ Medium Work in Progress Parking Lot 4/7/2016 55 \$€ Medium Work in Progress Parking Lot 4/7/2016 55 \$€ Medium Work in Progress Parking Lot 4/7/2016 55 \$€ Medium Work in Progress Parking Lot 4/7/2016 55 \$€ Medium Work in Progress Parking Lot 4/7/2016 55 \$€ Medium Work in Progress Parking Lot 4/7/2016 55 \$€ Medium Work in Progress Parking Lot 4/7/2016 55 \$€ Medium Work in Progress Parking Lot 4/7/2016 55 \$€ Medium Work in Progress Parking Lot 4/7/2016 55 \$€ Medium Work in Progress Parking Lot	Requester	r Name							
Medium Work In Progress ALL 5/16/2016 8:47:08 AM Prospero, Hamel PalNT ALL RESTROOM PARTITIONS AND DOORS Laura Pars 153228 Vm (1997) Gym 5/16/2016 16 \$0 Medium Vork In Progress SEE MS 5/16/2016 8:41:42 AM Forespero, Medium PalNT GYM AND OFFICES Laura Pars Work In Progress RESTROOMS 5/16/2016 8:44:58 AM Forespero, Medium Prospero, Medium PalNT ALL RESTROOMS PARTITIONS AND DOORS IN SECURITY IN	Location:	Santa Te	resa MS						
Prospero	153228	South Building	Restroom		5/16/2016		16		\$0.00
BLACK Laura Paras Sym (1997) Gym (1997) Gym (1907) 16 SC Medium Work in Progress SEE MS 5/16/2016 8.41.42 AM SEE MS SEE MS 5/16/2016 8.41.42 AM SEE MS SEE MS 5/16/2016 8.41.42 AM SEE MS SEE MS SEE MS 5/16/2016 8.41.42 AM SEE MS SEE MS </td <td>Medium</td> <td>Work In Progress</td> <td>ALL</td> <td></td> <td>5/16/2016 8:47:08 AM</td> <td>1</td> <td></td> <td></td> <td></td>	Medium	Work In Progress	ALL		5/16/2016 8:47:08 AM	1			
153223	Prospero,	Manuel		STROOM PARTITION	S AND DOORS				
Medium Work In Progress SEE MS 5/16/2016 8:41:42 AM Prospero, Manuel PAINT GYM AND OFFICES Laura Parrat 153226 Gym (1997) Gym 5/16/2016 8:44:58 AM Prospero, Manuel PAINT ALL RESTROOMS PARTITIONS AND DOORS IN BLACK PAINT ALL RESTROOMS PARTITIONS AND DOORS IN BLACK Laura Parrat TS1970 4/26/2016 36 36 \$C Medium Work In Progress KITCHEN-DOOR BELL NEEDS TO BE INSTALLED. SNP GESSICA M.589.9836 TS25/2016 9:11:08 AM 7 \$C Medium Work In Progress FZ25/2016 9:11:08 AM 7 \$C Castillo, Carlos REPLACE OUTLET COVERS (LOCKS). STUDENTS HAVE DAMAGED COVERS AND OUTLETS NEED 5 \$C \$C Laura Parrat TS0921 South Building Parking Lot 4/7/2016 55 \$C Medium Work In Progress 4/7/2016 12:06:19 PM \$C \$C \$C Castillo, Carlos south bidg. Light pole not turning on. \$C \$C \$C Carlos Castillo, Carlos South progress \$EE MR 2/18/2016 11:27:43 AM \$C \$C <	Laura Par								
Prospero, Manuel PAINT GYM AND OFFICES Laura Parra 153226 Sym (1997) Gym 5/16/2016 16 \$C Medium Work In Progress RESTROOMS 5/16/2016 8:44:58 AM Prospero, Manuel PAINT ALL RESTROOMS PARTITIONS AND DOORS IN BLACK Prospero, Manuel PAINT ALL RESTROOMS PARTITIONS AND DOORS IN BLACK Prospero, Manuel 36 \$C Laura Parra 151970 4/26/2016 36 \$C Medium Work In Progress 4/26/2016 8:20:41 AM Prospero, Manuel \$C Castillo, Carlos SNP GESSICA M.589.9836 \$C \$C \$C Medium Work In Progress KITCHEN-DOOR BELL NEEDS TO BE INSTALLED. SNP GESSICA M.589.9836 \$C \$C Medium Progress FEPLACE OUTLET COVERS (LOCKS). STUDENTS SNEED SNP GESSICA M.589.9836 \$C \$C \$C Castillo, Carlos South Building Parking Lot \$A(7/2016 12:06:19 PM) \$C \$C \$C Castillo, Carlos South bidg.Lightpole notturning on. \$C \$C \$C \$C \$C	153223	Gym (1997)	Gym		5/16/2016		16		\$0.00
Laura Parrs 153226 Gym (1997) Gym 5/16/2016 16 \$C Medium Work In Progress RESTROOMS 5/16/2016 8:44:58 AM C C Prospero, Manuel PAINT ALL RESTROOMS PARTITIONS AND DOORS IN BLACK C<	Medium	Work In Progress	SEE MS		5/16/2016 8:41:42 AM	1			
153226 Gym (1997) Gym 5/16/2016 16 SC	Prospero,	Manuel	PAINT GYM AN	ID OFFICES					
Medium Work In Progress RESTROOMS 5/16/2016 8:44:58 AM Prospero, Manuel PAINT ALL RESTROOMS PARTITIONS AND DOORS IN BLACK Laura Parra 151970 4/26/2016 36 \$C Medium Work In Progress 4/26/2016 8:20:41 AM 36 \$C Castillo, Carlos KITCHEN-DOOR BELL NEEDS TO BE INSTALLED. SNP GESSICA M589.9836 ************************************	Laura Par	ra							
Prospero, Manuel Parrate Parra	153226	Gym (1997)	Gym		5/16/2016		16		\$0.00
N BLACK	Medium	Work In Progress	RESTROOMS		5/16/2016 8:44:58 AM	1			
151970	Prospero,	Manuel		STROOMS PARTITIO	NS AND DOORS				
Medium Work In Progress KITCHEN-DOOR BELL NEEDS TO BE INSTALLED. SNP GESSICA M.589.9836 Marritza Gonzalez 153894 Gym (1997) Gym 5/25/2016 7 \$0 Medium Work In Progress 5/25/2016 9:11:08 AM Castillo, Carlos REPLACE OUTLET COVERS (LOCKS). STUDENTS HAVE DAMAGED COVERS AND OUTLETS NEED 5 REPLACED. Laura Parra 150921 South Building Parking Lot 4/7/2016 55 \$0 Medium Work In Progress 4/7/2016 12:06:19 PM Castillo, Carlos castillo Carlos Castillo Carlos Castillo Work In Progress SEE MR 2/18/2016 11:27:43 AM Castillo, Carlos NEED ELECTRICITY RUN OUT TO THE BASEBALL AND SOFTBALL FIELDS FROM THE NORTH BUILDING ALONG THE FENCE LINE TO TUFF SHED. INSTALL A MULTIPLE ELECTRICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL FIELDS FROM THE TUFF SHED.	Laura Par	ra							
Castillo, Carlos KITCHEN-DOOR BELL NEEDS TO BE INSTALLED. SNP GESSICA M:589.9836 Marritza Go-zalez 153894 Gym (1997) Gym 5/25/2016 7 \$C Medium Work In Progress 5/25/2016 9:11:08 AM Castillo, Carlos REPLACE OUTLET COVERS (LOCKS). STUDENTS HAVE DAMMAGED COVERS AND OUTLETS NEED 5 REPLACED. Laura Parra 150921 South Building Parking Lot 4/7/2016 55 \$C Medium Work In Progress 4/7/2016 12:06:19 PM Castillo, Carlos castillo Carlos Castillo Work In Progress SEE MR 2/18/2016 11:27:43 AM Castillo, Carlos SEE MR 2/18/2016 11:27:43 AM Castillo, Carlos Need AND OUTLET SHED. INSTALL FIELDS FROM THE NORTH BUILDING ALONG THE FENCE LINE TO TUFF SHED. INSTALL A MULTIPLE ELECTRICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICHING MACHINES NEXT TO THE TUFF SHED.	151970				4/26/2016		36		\$0.00
SNP GESSICA M.589.9836 Marritza Gonzalez 153894 Gym (1997) Gym 5/25/2016 7 \$C Medium Work In Progress 5/25/2016 9:11:08 AM Castillo, Carlos REPLACE OUTLET COVERS (LOCKS), STUDENTS HAVE DAMAGED COVERS AND OUTLETS NEED 5 REPLACED. Laura Parra 150921 South Building Parking Lot 4/7/2016 55 \$C Medium Work In Progress 4/7/2016 12:06:19 PM Castillo, Carlos south bldg. Light pole not turning on. Carlos Castillo 147979 Storage 2/18/2016 104 \$C Medium Work In Progress SEE MR 2/18/2016 11:27:43 AM Castillo, Carlos See MR 1:27:43 AM Castillo, Carlos See MR 2/18/2016 11:27:43 AM Castillo, Carlos Medium Work In Progress SEE MR 2/18/2016 11:27:43 AM Castillo, Carlos NEED ELECTRICITY RUN OUT TO THE BASEBALL AND SOFTBALL FIELDS FROM THE NORTH BUILDING ALONG THE FENCE LINE TO TUFF SHED. INSTALL A MULTIPLE ELECTRICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICHING MACHINES NEXT TO THE TUFF SHED.	Medium	Work In Progress			4/26/2016 8:20:41 AM	1			
153894 Gym (1997) Gym 5/25/2016 7 \$C Medium Work In Progress 5/25/2016 9:11:08 AM Castillo, Carlos REPLACE OUTLET COVERS (LOCKS). STUDENTS HAVE DAMAGED COVERS AND OUTLETS NEED 5 REPLACED. Laura Parra 150921 South Building Parking Lot 4/7/2016 55 \$C Medium Work In Progress 4/7/2016 12:06:19 PM Castillo, Carlos south bldg.Light pole not turning on. Carlos Castillo 147979 Storage 2/18/2016 104 \$C Medium Work In Progress SEE MR 2/18/2016 11:27:43 AM Castillo, Carlos NEED ELECTRICITY RUN OUT TO THE BASEBALL AND SOFTBALL FIELDS FROM THE NORTH BUILDING ALONG THE FENCE LINE TO TUFF SHED. INSTALL A MULTIPLE ELECTRICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICHING MACHINES NEXT TO THE TUFF SHED.	Castillo, C	arlos			BE INSTALLED.				
Medium Work In Progress 5/25/2016 9:11:08 AM Castillo, Carlos REPLACE OUTLET COVERS (LOCKS). STUDENTS HAVE DAMAGED COVERS AND OUTLETS NEED 5 REPLACED. Laura Parra 150921 South Building Parking Lot 4/7/2016 55 \$C Medium Work In Progress 4/7/2016 12:06:19 PM Castillo, Carlos south bldg.Lightpole not turning on. Carlos Castillo 147979 Storage 2/18/2016 10:27:43 AM Castillo, Carlos SEE MR 2/18/2016 11:27:43 AM Castillo, Carlos NEED ELECTRICITY RUN OUT TO THE BASEBALL AND SOFTBALL FIELDS FROM THE NORTH BUILDING ALONG THE FENCE LINE TO TUFF SHED. INSTALL A MULTIPLE ELECTRICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICHING MACHINES NEXT TO THE TUFF SHED.	Maritza Go								
Castillo, Carlos REPLACE OUTLET COVERS (LOCKS). STUDENTS HAVE DAMAGED COVERS AND OUTLETS NEED 5 REPLACED. Laura Parra 150921 South Building Parking Lot 4/7/2016 55 \$0 Medium Work In Progress 4/7/2016 12:06:19 PM Castillo, Carlos south bldg.Light pole not turning on. Carlos Castillo 147979 Storage 2/18/2016 104 \$0 Medium Work In Progress SEE MR 2/18/2016 11:27:43 AM Castillo, Carlos NEED ELECTRICITY RUN OUT TO THE BASEBALL AND SOFTBALL FIELDS FROM THE NORTH BUILDING ALONG THE FENCE LINE TO TUFF SHED. INSTALL A MULTIPLE ELECTRICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICHING MACHINES NEXT TO THE TUFF SHED.	153894	Gym (1997)	Gym		5/25/2016		7		\$0.00
HAVE DAMAGED COVERS AND OUTLETS NEED 5 REPLACED. Laura Parra 150921 South Building Parking Lot 4/7/2016 55 \$C Medium Work In Progress 4/7/2016 12:06:19 PM Castillo, Carlos south bldg.Lightpole not turning on. Carlos Castillo 147979 Storage 2/18/2016 104 \$C Medium Work In Progress SEE MR 2/18/2016 11:27:43 AM Castillo, Carlos NEED ELECTRICITY RUN OUT TO THE BASEBALL AND SOFTBALL FIELDS FROM THE NORTH BUILDING ALONG THE FENCE LINE TO TUFF SHED. INSTALL A MULTIPLE ELECTRICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICHING MACHINES NEXT TO THE TUFF SHED.	Medium	Work In Progress			5/25/2016 9:11:08 AM	1			
150921 South Building Parking Lot 4/7/2016 55 \$0 Medium Work In Progress 4/7/2016 12:06:19 PM Castillo, Carlos south bldg.Light pole not turning on. Carlos Castillo 147979 Storage 2/18/2016 104 \$0 Medium Work In Progress SEE MR 2/18/2016 11:27:43 AM Castillo, Carlos NEED ELECTRICITY RUN OUT TO THE BASEBALL AND SOFTBALL FIELDS FROM THE NORTH BUILDING ALONG THE FENCE LINE TO TUFF SHED. INSTALL A MULTIPLE ELECTRICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICHING MACHINES NEXT TO THE TUFF SHED.	Castillo, C	carlos	HAVE DAMAGE						
Medium Work In Progress south bldg.Light pole not turning on. Carlos Castillo 147979 Storage 2/18/2016 104 \$0 Medium Work In Progress SEE MR 2/18/2016 11:27:43 AM Castillo, Carlos NEED ELECTRICITY RUN OUT TO THE BASEBALL AND SOFTBALL FIELDS FROM THE NORTH BUILDING ALONG THE FENCE LINE TO TUFF SHED. INSTALL A MULTIPLE ELECTRICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICHING MACHINES NEXT TO THE TUFF SHED.	Laura Par								
Castillo, Carlos south bldg.Light pole not turning on. Carlos Castillo 147979 Storage 2/18/2016 104 \$C Medium Work In Progress SEE MR 2/18/2016 11:27:43 AM Castillo, Carlos NEED ELECTRICITY RUN OUT TO THE BASEBALL AND SOFTBALL FIELDS FROM THE NORTH BUILDING ALONG THE FENCE LINE TO TUFF SHED. INSTALL A MULTIPLE ELECTRICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICHING MACHINES NEXT TO THE TUFF SHED.	150921	South Building	Parking Lot		4/7/2016		55		\$0.00
Carlos Castillo 147979 Storage 2/18/2016 104 \$0 Medium Work In Progress SEE MR 2/18/2016 11:27:43 AM Castillo, Carlos NEED ELECTRICITY RUN OUT TO THE BASEBALL AND SOFTBALL FIELDS FROM THE NORTH BUILDING ALONG THE FENCE LINE TO TUFF SHED. INSTALL A MULTIPLE ELECTRICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICHING MACHINES NEXT TO THE TUFF SHED.	Medium	Work In Progress			4/7/2016 12:06:19 PN	Л			
147979 Storage 2/18/2016 104 \$0 Medium Work In Progress SEE MR 2/18/2016 11:27:43 AM Castillo, Carlos NEED ELECTRICITY RUN OUT TO THE BASEBALL AND SOFTBALL FIELDS FROM THE NORTH BUILDING ALONG THE FENCE LINE TO TUFF SHED. INSTALL A MULTIPLE ELECTRICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICHING MACHINES NEXT TO THE TUFF SHED.	Castillo, C	carlos	south bldg.Lig	ht pole not turning on.					
Medium Work In Progress SEE MR 2/18/2016 11:27:43 AM Castillo, Carlos NEED ELECTRICITY RUN OUT TO THE BASEBALL AND SOFTBALL FIELDS FROM THE NORTH BUILDING ALONG THE FENCE LINE TO TUFF SHED. INSTALL A MULTIPLE ELECTRICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICHING MACHINES NEXT TO THE TUFF SHED.	Carlos Ca	stillo							
Castillo, Carlos NEED ELECTRICITY RUN OUT TO THE BASEBALL AND SOFTBALL FIELDS FROM THE NORTH BUILDING ALONG THE FENCE LINE TO TUFF SHED. INSTALL A MULTIPLE ELECTRICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICHING MACHINES NEXT TO THE TUFF SHED.	147979		Storage		2/18/2016		104		\$0.00
AND SOFTBALL FIELDS FROM THE NORTH BUILDING ALONG THE FENCE LINE TO TUFF SHED. INSTALL A MULTIPLE ELECTRICAL BOX TO SUPPLY ELECTRICITY FOR BASEBALL AND SOFTBALL PITICHING MACHINES NEXT TO THE TUFF SHED.	Medium	Work In Progress	SEE MR		2/18/2016 11:27:43 AM	1			
Laura Parra	Castillo, C	carlos	AND SOFTBAL BUILDING ALC INSTALL A MU ELECTRICITY	L FIELDS FROM THE DNG THE FENCE LIN LTIPLE ELECTRICAL FOR BASEBALL AND	E NORTH E TO TUFF SHED. . BOX TO SUPPLY) SOFTBALL				
Eddid F dild	Laura Par	ra							

6/1/2016 11:47:10 AM Page 150 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Dat	te Range for Request Building	Dates:7/1/2015 - 6 Area	3/30/2016 Order By Lo Deferred By	cation, Status Until	Reguest Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•		-	Actual Comp Date	Aged	Hours	
Assigned 1		Description				Action Taken			
Requester	Name								
Location:	Santa Te	resa MS							
148333	North Building	Storage			2/24/2016		98		\$0.00
Medium	Work In Progress	UTVS		2/24/2	:016 2:12:50 PN	1			
Castillo, C	arlos	THE UTVS WH 2- NEED OUTS BLDG FACING	TS INSIDE THE STOPE JEN WORKING AT IN SIDE LIGHTS FOR TOPE EASTSIDE OF THE HE LIGHT IN PARK	NIGHT. THE 3 STORA E STORAGE	GE				
Laura Parr	a								
148982					3/6/2016		87		\$0.00
Medium	Work In Progress			3/6/20	16 12:40:38 AN	1			
Prospero,	Manuel	Yearly - Santa Refer to PMsch	Teresa MS A10 (He nedule details.	at Pump)(Yea	ırly) -				
Margret Vil	lalobos								
150252					3/31/2016		62		\$0.00
Medium	Work In Progress			3/31/20	16 12:46:08 AN	1			
Prospero,	Manuel	Monthly - Santa Refer to PMsch	a Teresa MS A16 (F nedule details.	an Exh.)(Mont	hly) -				
Margret Vil	lalobos								
150513					4/3/2016	4/11/2016	59		\$0.00
Medium	Work In Progress			4/3/20	16 12:43:25 AN	1			
Prospero,	Manuel	Monthly - Santa PMschedule d	a Teresa MS Roof Ir etails.	spection - Re	efer to				
Margret Vil	lalobos								
152303					5/1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress			5/1/2	016 1:03:37 AN	1			
Vallejo, Alb	pert	Monthly - Santa Refer to PMsch	a Teresa MS Fire Su nedule details.	ippression In:	sp				
Margret Vil									
146142	North Building	Custodial			1/13/2016		140		\$0.00
Medium	Work In Progress			1/13/20	16 11:06:43 AN	1			
Flores, Pet	te	Pressure wash	ner doesn't work nee	ed to be fix					
Ismael Ro	driguez								
141985	South Building				10/20/2015		225		\$0.00
Medium	Work In Progress			10/20/2	:015 8:06:34 AN	1			
Miranda, D	anny		- cover two pocket one-		ay				
Alfredo Ho	lguin								

6/1/2016 11:47:10 AM Page 151 of 174

Total Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs WOID Building Area Until **Request Date Target Comp Date Davs** Labor **Deferred By** Aged Hours Area Number Reason Status Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description Requester Name Location: Santa Teresa MS 136401 Office 7/23/2015 314 \$0.00 Medium Work In Progress 7/23/2015 4:17:14 PM PLEASE GET A PRICE QUOTE FOR NEW STAFF Marquez, Gerardo MAILBOX AND BASE CABINETS FOR WORKRM. Gerardo Marquez 22 5/10/2016 \$0.00 152909 Medium Work In Progress 5/10/2016 3:39:47 PM Prospero, Manuel 5/10/16. 5/10/16 .5HR CHECK E MAIL. 6HRS WO .150465. 1HR CHANGED LIGHT SWITCH ROOM 54. .5HR ENTER LOG. 8HRS TOTAL Manuel Prospero 153525 5/19/2016 13 \$0.00 Medium 5/19/2016 3:34:24 PM Work In Progress 5/19/16 Prospero, Manuel 5/19/16. .5HR CHECK E MAIL. 4HRS REMOVE TABLES CHAIRS AND STAGE ON GYM AREA. 4HRS WO 153222. .5HR ENTER LOG. 8HRS TOTAL Manuel Prospero South Building Choral 5/25/2016 7 \$0.00 153914 Medium Work In Progress 5/25/2016 3:35:04 PM Prospero, Manuel 5/25/16. 5/25/16. .5HR CHECK E MAIL. 7HRS WP 153222. .5HR ENTER LOG. 8 HRS TOTAL. Manuel Prospero 153857 South Building 5/24/2016 \$0.00 Medium Work In Progress 5/24/2016 3:38:38 PM 5/24/16 5/24/16. Prospero, Manuel .5HR CHECK E MAIL. 7HRS WO 153222. .5HR ENTER LOG.

6/1/2016 11:47:10 AM Page 152 of 174

8HR TOTAL

Manuel Prospero

WOID	Building	Area Deferred By		Target Comp Date	Days Aged	Labor Hours	
Priority	Status	Area Number Reason	Created Date/Time	•	Ageu	i ioui 3	
Assigned ⁻ Requester		Description		Action Taken			
Location:	Santa Te	roco MS					
	Santa Te	resa ws	- (- , (, -				•
154100			5/31/2016		1		\$0.00
Medium	Work In Progress		5/31/2016 3:40:49 PM	1			
Prospero,	Manuel	5/31/16. .5HR CHECK E MAIL 7HRS WO 153238. .5HR ENTER LOG. 8HR TOTAL		5/31/16			
Manuel Pr	ospero						
153998			5/27/2016		5		\$0.00
Medium	Work In Progress		5/27/2016 11:26:57 AM	l			
Prospero,	Manuel	5/27/16. .5HRS CHECK E MAIL. 3HRS WO 153222. .5HR ENTER LOG. 4HRS TOTAL		5/27/16			
Manuel Pro	ospero						
153974			5/26/2016		6		\$0.00
Medium	Work In Progress		5/26/2016 3:46:24 PM	1			
Prospero,	Manuel	5/26/16. .5HR CHECK E MAIL. 7HRS WO 153222. .5HR ENTER LOG. 8HRS TOTAL.		5/26/16			
Manuel Pro	ospero						
150667	North Building	Custodial	4/4/2016		58		\$0.00
Medium	Work In Progress		4/4/2016 12:02:17 PM	1			
Villalobos,	Jose	Gator not working need to be check					
Ismael Ro	driguez						
146077	South Building	Classroom	1/12/2016		141		\$0.00
Medium	Work In Progress		1/12/2016 3:35:17 PM	1			
Prospero,	Manuel	1/12/16. HAVING PROBLEMS HEATER ROO	M31.				
Manuel Pro	<u> </u>						
145200	South Building		12/17/2015		167		\$0.00
Medium	Work In Progress		12/17/2015 10:20:58				
Medium	ū						

6/1/2016 11:47:10 AM Page 153 of 174

Manuel Prospero 151109 Gym (1997) Roof Medium Work In Progress Ambriz, Jose WE N CON Manuel Prospero 151110 Gym (1997) Roof Medium Work In Progress Ambriz, Jose NEE Manuel Prospero	16. NEED CHANGED BIG A/C 1500		ı	51	\$0.00
151108 Gym (1997) Roof Medium Work In Progress Ambriz, Jose 4/11/ WE N NUM Manuel Prospero 151109 Gym (1997) Roof Medium Work In Progress Ambriz, Jose WE N CON Manuel Prospero 151110 Gym (1997) Roof Medium Work In Progress Ambriz, Jose NEE Manuel Prospero	16. NEED CHANGED BIG A/C 1500	4/11/2016 1:10:09 PM 0 ON GYM A/S	I	51	\$0.00
Medium Work In Progress Ambriz, Jose 4/11/ WE N NUM Manuel Prospero 151109 Gym (1997) Roof Medium Work In Progress Ambriz, Jose WE N CON Manuel Prospero 151110 Gym (1997) Roof Medium Work In Progress Ambriz, Jose NEE Manuel Prospero	'16. NEED CHANGED BIG A/C 1500 I 1.	4/11/2016 1:10:09 PM 0 ON GYM A/S	I	51	\$0.00
Ambriz, Jose Ambriz, Jose Manuel Prospero 151109 Gym (1997) Roof Medium Work In Progress Ambriz, Jose WE N CON Manuel Prospero 151110 Gym (1997) Roof Medium Work In Progress Ambriz, Jose Ambriz, Jose Manuel Prospero NEE Manuel Prospero	NEED CHANGED BIG A/C 1500 11.	0 ON GYM A/S	I		
Manuel Prospero 151109 Gym (1997) Roof Medium Work In Progress Ambriz, Jose WE N CON Manuel Prospero 151110 Gym (1997) Roof Medium Work In Progress Ambriz, Jose NEE Manuel Prospero	NEED CHANGED BIG A/C 1500 11.				
151109 Gym (1997) Roof Medium Work In Progress Ambriz, Jose WE N CON Manuel Prospero 151110 Gym (1997) Roof Medium Work In Progress Ambriz, Jose NEE Manuel Prospero					
Medium Work In Progress Ambriz, Jose WE N CON Manuel Prospero 151110 Gym (1997) Roof Medium Work In Progress Ambriz, Jose NEE Manuel Prospero					
Ambriz, Jose WE N CON Manuel Prospero 151110 Gym (1997) Roof Medium Work In Progress Ambriz, Jose NEE Manuel Prospero		4/11/2016		51	\$0.00
Manuel Prospero 151110 Gym (1997) Roof Medium Work In Progress Ambriz, Jose NEE Manuel Prospero		4/11/2016 1:13:05 PM	I		
151110 Gym (1997) Roof Medium Work In Progress Ambriz, Jose NEE Manuel Prospero	NEED REPLACE BIG A/C 1500 DITION. A/C NUM2.	ON GYM BAD			
Medium Work In Progress Ambriz, Jose NEE Manuel Prospero					
Ambriz, Jose NEE Manuel Prospero		4/11/2016		51	\$0.00
Manuel Prospero		4/11/2016 1:14:39 PM	I		
•	D TO REPLACE A/C 1500 GYM	AREA A/C NUM3.			
153708 South Building Clas					
	sroom	5/23/2016		9	\$0.00
Medium Work In Progress		5/23/2016 3:41:25 PM	I		
7HR .5HR	16. CHECK E MAIL. S WO 153222. ENTER LOG. S TOTAL		5/23/16.		
Manuel Prospero					
147955		2/16/2016		106	\$0.00
Medium Work In Progress		2/16/2016 3:51:15 PM	I		
Gonzalez, Salvador Cons	struct batting cages (see Albert	for drawings)			
Albert Vallejo		.			
<u> </u>	sroom	4/15/2016		47	\$0.00
Medium Work In Progress ADM	IN	4/15/2016 11:31:59 AM			
RES'	AUST FANS FOR BOTH WOME TROOMS IN ADMIN AREA NEE AIRED OR REPLACED.				
Laura Parra					
151451 North Building Clas	sroom	4/15/2016		47	\$0.00
Medium Work In Progress ADM	IN	4/15/2016 11:33:17 AM			
RES'	AUST FANS FOR BOTH WOME TROOMS IN THE ADMIN AREA AIRED AND OR REPLACED.				
Laura Parra					

6/1/2016 11:47:10 AM Page 154 of 174

WOID Priority Assigned Requester		Area Number Description	Deferred By		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa MS						
		Athletic Field		5/24/2016		8		\$0.00
153783	Mariala Deserva	Auneuc Field				O		φυ.υυ
Medium	Work In Progress			5/24/2016 8:57:36 AM				
Ontiveros,	Guadalupe	CONCRETE S	CING FOR SOFTBAL LAB FOR DUG OUT DUG OUTS, CREAT SES.	S, INSTALL				
		THANK YOU						
Terry Alvar								
152968	South Building	Office		5/11/2016		21		\$0.00
Medium	Work In Progress			5/11/2016 9:37:56 AM				
Ronquillo,	Ruben	Replace windo office to block t	w blinds in south off he sun rays.	ice and principal				
Ismael Ro								
151287	Gym (1997)	Gym		4/13/2016		49		\$0.00
Medium	Work In Progress			4/13/2016 8:57:03 AM				
Carbajal, J	limmy	Resurface the g	gym floor on this dat	e 7-18-16 thru 7-22-				
Ismael Ro								
153595	Gym (1997)	Gym		5/20/2016		12		\$0.00
Medium	Work In Progress			5/20/2016 10:45:35 AM				
Lara, Ralpi	h		es in the gym on this questions contact N 105					
Ismael Ro	driguez							
153240	South Building	Classroom		5/16/2016		16		\$0.00
Medium	Work In Progress	46 MEDRANO		5/16/2016 9:07:38 AM				
Prospero,	Manuel	SHORT ON LIC	HT SWITCH					
Laura Pari	a							
153404	North Building	Office		5/18/2016		14		\$0.00
Medium	Work In Progress			5/18/2016 9:02:10 AM				
Lara, Ralpl	h	Replace North shape.	Office doors with ne	w ones there in bad				
Ismael Ro	driguez	•						
138502		Restroom		8/21/2015		285		\$0.00
Medium	Work In Progress			8/21/2015 1:34:48 PM				
Lara, Ralpl	h	Please acquire restrooms.	quote for urinal par	itions 18' for boys				
Albert Valle	eio							

6/1/2016 11:47:10 AM Page 155 of 174

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order E Area Deferred By Area Number Reason Description		arget Comp Date Days ctual Comp Date Agec Action Taken	Costs
Location:	Santa Te	resa MS			
	Gym (1997)	Dressing Room	5/4/2016	28	\$0.00
152617	, , ,			20	φυ.υυ
Medium Villalobos,	Work In Progress , David	BOYS AND NO WATER COMING OUT OF WASH	5/4/2016 2:54:52 PM THE SINK/HAND		
Laura Parı	ra				
153239	South Building	Classroom	5/16/2016	16	\$0.00
Medium	Work In Progress	40-CORDOVA	5/16/2016 9:06:03 AM		
Prospero,	Manuel	STUDENT TABLE LEGS NEE THEY ARE NOT SCREWED O TABLE TOPS ARE LOOSE			
Laura Parı	ra				
153406	North Building	Cafeteria	5/18/2016	14	\$0.00
Medium	Work In Progress		5/18/2016 9:05:03 AM		
Lara, Ralp	h	Replace cafeteria kitchen doo	rs with new ones.		
Ismael Ro	odriauez				
153217	North Building	Parking Lot	5/16/2016	16	\$0.00
Medium	Work In Progress	PARKING LOT	5/16/2016 8:33:29 AM		
Prospero,	Manuel	REPAINT PARKING LOT STR	IPES		
Laura Pari		TEL FULL FACTORIES	20		
153230	Gym (1997)	Gym	5/16/2016	16	\$0.00
Medium		ENTIRE BLDG	5/16/2016 8:49:16 AM	10	ψ0.00
	Work In Progress				
Prospero,	Manuel	REPLACE ALL DOOR SWEEI	PS ON EVERY DOOR		
Laura Pari					
153510	North Building	Classroom	5/19/2016	13	\$0.00
Medium	Work In Progress		5/19/2016 2:28:06 PM		
Lara, Ralp		need to service locks on gates door cylinders.	and worked on doors and		
Ralph Lara			T (0 (0 0 1 0		# 0.00
152757	South Building	Classroom	5/6/2016	26	\$0.00
Medium	Work In Progress	39-DIAZ-SUB	5/6/2016 2:33:15 PM		
Lara, Ralp		PLEASE REKEY FILING CABI NOT HAVE A KEY	NET. CABINET DOES		
Laura Pari		01	. / . /		A
145694	North Building	Classroom	1/6/2016	147	\$0.00
Medium	Work In Progress	9-CORDOVA	1/6/2016 9:48:23 AM		
Lara, Ralp	h	METAL FILING CABINET NEE CABINET IS LOCKED	DS TO BE RE-KEYED.		
Laura Pari	ro				

6/1/2016 11:47:10 AM Page 156 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status Costs Building WOID Until **Request Date Target Comp Date Davs** Labor Area **Deferred By** Aged Hours Created Date/Time Actual Comp Date **Priority** Status Area Number Reason **Action Taken Assigned To** Description Requester Name Santa Teresa MS Location: 139307 North Building Office 9/3/2015 272 \$0.00 ASST 9/3/2015 3:22:50 PM Medium Work In Progress Lara, Ralph OUTSIDE DOOR IN ASST PRINCIPALS OFFICE DOES NOT WORK PROPERLY, HARD TO OPEN AND **CLOSE** Laura Parra 2/18/2016 104 \$0.00 147978 South Building Storage Medium Work In Progress SEE MR 2/18/2016 11:23:47 AM AT THE SAME LOCATION WHERE TUFF SHED HAS Vallejo, Albert BEEN PLACED, FENCE NEEDS TO BE CUT AND GATE INSTALLED. TUFF SHED IS PLACED ON THE FLUSH NEXT TO THE FENCE AND ON THE BASE SCREENING. INSTALL A 5' FOOT FENCE ALL AROUND TUFF SHED WITH FRONT GATE TO GAIN ACCESS. Laura Parra 10/9/2015 236 141420 \$0.00 Work In Progress 10/9/2015 4:13:39 PM Medium Kitchen Lara, Ralph Dining room doors are being secured with chains and pad locks. Inspect and repair so that pad locks don't need to be used. As per ergonomic inspections an access route to this clear space must be maintained at all times. Please call Cynthia with any questions 882-6949 Cynthia Maes 9/15/2015 260 \$0.00 139979 Medium Work In Progress 9/15/2015 12:50:46 PM Install a door in security office hallway. As per Lara, Ralph Administration, the office needs to secure confiscated items. See security officer for details. Albert Vallejo 5/11/2016 21 \$0.00 South Building Library 152964 Medium Work In Progress 5/11/2016 9:25:11 AM Lara, Ralph Librarian is requesting to replace doors in library 2nd request... Ismael Rodriguez

6/1/2016 11:47:10 AM Page 157 of 174

WOID Priority Assigned ⁻ Requester		Area Area Number Description	Deferred By Reason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Santa Te	resa MS						
146083				1/12/2016		141		\$0.00
Medium	Work In Progress			1/12/2016 3:41:57 PM	1			
Prospero,	Manuel	1/12/16. .5HR CHECK E 2HRS CHEKING 2HRS TROUBL AND NURCES G 3HRS WO 146G .5HR ENTER LG	S HEATERS CAF E SOOTER HEA' DFFICE. 177.	ETERIA. TERS PORTABLE 2				
Manuel Pro	<u> </u>							
148332	North Building	Office		2/24/2016		98		\$0.00
Medium	Work In Progress	MR		2/24/2016 2:08:50 PM	1			
Prospero,	Manuel	ASSEMBLE 8 AD	MINISTRATIVE	CHAIRS				
Laura Parr								
153234	South Building	Office		5/16/2016		16		\$0.00
Medium	Work In Progress	ENTIRE BLDG		5/16/2016 8:55:31 AN	1			
Prospero,	Manuel	REPLACE ALL ((EXTERIOR)	OOR SWEEPS	ON EVER DOOR				
Laura Pari		000		5 /4 0 /0 0 4 0		40		Φο οο
153235	Gym (1997)	Office		5/16/2016	-	16		\$0.00
Medium	Work In Progress	ENTIRE BLDG		5/16/2016 8:58:12 AM	1			
Prospero, Laura Pari		REPLACE HOO (TRAFFIC)	KS THAT HOLD	DOORS OPEN				
153236	North Building	Office		5/16/2016		16		\$0.00
Medium	Work In Progress	ENTIRE BLDG		5/16/2016 8:58:34 AM	1			
Prospero,	ŭ	REPLACE HOO (TRAFFIC)	KS THAT HOLD					
Laura Parı	a	,						
153237	South Building	Office		5/16/2016		16		\$0.00
Medium	Work In Progress	ENTIRE BLDG		5/16/2016 8:59:04 AM	1			
Prospero,	Manuel	REPLACE HOO (TRAFFIC)	KS THAT HOLD	DOORS OPEN				
Laura Parr								
153683	North Building	Classroom		5/23/2016		9		\$0.00
Medium	Work In Progress	10-ESCOBEDO		5/23/2016 12:42:32 PM				
Prospero,	Manuel	REPAIR TABLES VERY LOOSE M		GS HAVE BECOME WOBBLY				

6/1/2016 11:47:10 AM Page 158 of 174

WOID Priority Assigned ⁻			Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester								
Location:	Santa Te	resa MS						
153684	North Building	Classroom		5/23/2016		9		\$0.00
Medium	Work In Progress	1- MEISTER		5/23/2016 12:43:48 PM				
Prospero,	Manuel		R TO CLASSROOM OR LEAKS WHEN	INEEDS WEATHER IT RAINS.				
Laura Parr								
153685	North Building	Classroom		5/23/2016		9		\$0.00
Medium	Work In Progress	2 GLASS		5/23/2016 12:44:27 PM				
Prospero,	Manuel	REPAIR WEATH TO CLASSROC		N OUTSIDE DOOR				
Laura Parr				E (00 (00 to				A 0 00
153686	North Building	Classroom		5/23/2016		9		\$0.00
Medium	Work In Progress	3 -PORTILLO		5/23/2016 12:45:06 PM				
Prospero,		REPAIR WEATH TO CLASSROC		N OUTSIDE DOOR				
Laura Pari	ra North Building	Office		5/16/2016		16		\$0.00
153231	· ·					10		φυ.υυ
Medium	Work In Progress	ENTIRE BLDG		5/16/2016 8:49:57 AM				
Prospero,		(EXTERIOR)	DOOR SWEEPS O	N EVERY DOOR				
Laura Parr 153232	South Building	Office		5/16/2016		16		\$0.00
Medium	Work In Progress	ENTIRE BLDG		5/16/2016 8:50:47 AM		10		ψ0.00
	· ·		D 014/55D0 011 51					
Prospero,		(EXTERIOR)	R SWEEPS ON E\	/ERY DOOR				
Laura Parı 153218	ra North Building	Office		5/16/2016		16		\$0.00
Medium	_	WHOLE		5/16/2016 8:34:35 AM		10		ψ0.00
	Work In Progress							
Prospero,		REPLACE DAM	AGED STAINED CI	EILING TILES				
Laura Pari		O#:		F /4 C /004 C		40		<u>Фо оо</u>
153219	South Building	Office		5/16/2016		16		\$0.00
Medium	Work In Progress	WHOLE		5/16/2016 8:35:35 AM				
Prospero,	Manuel	REPLACE DAM	AGED AND STAINE	ED CEILING TILES				
Laura Pari		0.00		= 1, - 1				A
153220	North Building	Office		5/16/2016		16		\$0.00
Medium	Work In Progress	EXTERIOR		5/16/2016 8:37:41 AM				
Prospero,	Manuel	REPLACE EXT	ERIOR WATER FO	JNTAINS				
Laura Parr	ra							

6/1/2016 11:47:11 AM Page 159 of 174

		0.0.0		(,				Total
WOID Priority Assigned	Building Status To	Dates:7/1/2015 - 6 Area Area Number Description	i/30/2016 Order By Loca Deferred By Reason	Until	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester									
Location:	Santa Te	resa MS							
153687	North Building	Portables			5/23/2016		9		\$0.00
Medium	Work In Progress	3A		5/23/20	16 12:46:44 PM	1			
Herrera, M	larin		TUBS OF OUTDATEI	O TEACHIN	G				
Laura Par	ra								
141506					10/12/2015		233		\$0.00
Medium	Work In Progress			10/12/2	.015 2:28:22 PM	1			
Orozco, Da	aniel		HOT WATER ON DIS NP MANAGER GESSI						
Maritza Go	onzalez								
Count: 76	Work Orders	A	vg. Age of WO's 60		To	otal for Santa Teres	a MS	0	\$0.00

6/1/2016 11:47:11 AM Page 160 of 174

1141 - Work Orders In Progress (Fiscal Year)

Jaime Mijarez

Selected Dai	te Range for Request Building	Dates:7/1/2015 - 6 Area	5/30/2016 Order By Loc Deferred By	cation, Status Until	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•	Crea	-	Actual Comp Date	Aged	Hours	
Assigned ⁻	Го	Description				Action Taken			
Requester	Name								
Location:	Sunland	Park ES							
141920	Main Building	Parking Lot			10/19/2015		226		\$0.00
Medium	Work In Progress			10/1	9/2015 11:06:16	3			
Mijarez, Ja	ime	South Side of E weeds.	Building/Back Entries	s - cut and ren	nove	Route to Jaime on 1	1/16/15		
Alfredo Ho	lguin								
151667					4/20/2016		42		\$0.00
Medium	Work In Progress			4/20/2	.016 8:14:55 AN	1			
Villalobos,	David	has not been w cement is brok	ter fountain was bad vorking since I don't k en and copper line is ke to have it working	know when. T s broken off. F	ne				
Jaime Mija	ırez								
143762		Library			11/18/2015		196		\$0.00
Medium	Work In Progress	LIBRARY		11/18/2	.015 8:22:59 AN	1			
Mijarez, Ja	ime	LIBRARY- MOR SEE MRS. MO	RENO- NEED DOOF RENO	RS PAINTED	BLUE				
Maribel Ga	ımboa								
143763		Library			11/18/2015		196		\$0.00
Medium	Work In Progress	LIBRARY		11/18/2	.015 8:25:55 AN	1			
Mijarez, Ja	ime	FINISHED IN L	RENO- NEED TO HA LIBRARY WALLS. LIG GON COMPLETELY	GHT ARE STI					
Maribel Ga	ımboa								
138311					8/19/2015		287		\$0.00
Medium	Work In Progress	25		8/19/20	15 10:16:35 AN	1			
Mijarez, Ja	ime		GUIN- PLEASE PAIN DOM-2ND NOTICE	NT THE DOE	SIN	Route to Jaime on 1	1/16/15		
Maribel Ga	ımboa								
144739				<u> </u>	12/9/2015		175		\$0.00
Medium	Work In Progress			12/9/2	.015 3:19:12 PN	1			
Mijarez, Ja	ime	Paint portable need 5 gallons	interior walls with Va	nilla Bean pa	int. I				

6/1/2016 11:47:11 AM Page 161 of 174

WOID Priority Assigned 1 Requester		Area Deferred By Area Number Reason Description	Until Request Date Tai Created Date/Time Ac	•	Days Aged	Labor Hours	
Location:	Sunland	Park ES					
148783			3/2/2016		91		\$0.00
Medium	Work In Progress	LIBRARY	3/2/2016 2:57:31 PM				
Mijarez, Ja	ime	LIBRARY- MORENO- NEED TO COME AND TAKE A LOOK AT T LIGHTS THEY ARE NO LONGE WHEN SWITCH IS FIRST USEI NOTICE FOR THIS INCIDENCE	THE NEW CEILING FR TURNING ON D. THIS IS THE THIRD				
Maribel Ga	mboa						
145325			1/3/2016	2/3/2016	150		\$0.00
Medium	Work In Progress		1/3/2016 12:43:32 AM				
Mijarez, Ja	me	Yearly - Sunland Park ES Backf PMschedule details.	flow Inspection - Refer to				
Margret Vil	lalobos						
148563			2/29/2016	3/31/2016	93		\$0.00
Medium	Work In Progress		2/29/2016 12:58:13 AM				
Mijarez, Ja	me	Yearly - Sunland Park ES C-11 Refer to PMs chedule details.	Evap Coolers Yearly -				
Margret Vil	lalobos						
148585			2/29/2016		93		\$0.00
Medium	Work In Progress		2/29/2016 12:58:30 AM				
Mijarez, Ja	ime	Monthly - Sunland Park ES A-16 Refer to PMschedule details.	6 Fan Exh Semiannual -				
Margret Vil	lalobos						
148984			3/6/2016		87		\$0.00
Medium	Work In Progress		3/6/2016 12:40:40 AM				
Mijarez, Ja	ime	Yearly - Sunland Park ES A-10 Refer to PMschedule details.	HP Rooftop Yearly -				
Margret Vil	lalobos						
154029			5/31/2016	7/1/2016	1		\$0.00
Medium	Work In Progress		5/31/2016 12:54:29 AM				
Mijarez, Ja	ime	Yearly - Sunland Park ES A-2 S Refer to PMs chedule details.	plit System Yearly -				
Margret Vil	lalobos						
148997			3/6/2016	3/22/2016	87		\$0.00
Medium	Work In Progress		3/6/2016 12:40:50 AM				
Mijarez, Ja	me	Monthly - Sunland Park ES A-1	Wall Ref Semiannual -				

6/1/2016 11:47:11 AM Page 162 of 174

WOID Priority Assigned	te Range for Request Building Status	Area Number Description	Deferred By	Until Re	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester		Description				Action Taken			
Location:	Sunland	Park ES							
152407					5/1/2016	5/7/2016	31		\$0.00
Medium	Work In Progress			5/1/2016	6 1:06:31 AM	1			
Mijarez, Ja	me	Monthly - Sunla Refer to PMsch	and Park ES Monthly nedule details.	/FE Inspection -					
Margret Vil	lalobos								
152356					5/1/2016	5/9/2016	31		\$0.00
Medium	Work In Progress			5/1/2016	6 1:05:27 AM	1			
Mijarez, Ja	me	Monthly - Sunla Refer to PMsch	and Park ES Exit Sig nedule details.	n Insp: Monthly-					
Margret Vil	lalobos								
152357					5/1/2016	5/9/2016	31		\$0.00
Medium	Work In Progress			5/1/2016	6 1:05:27 AM	1			
Mijarez, Ja	ime	Monthly - Sunla Refer to PMsch	and Park ES Emer L nedule details.	ight Test: Monthl	y -				
Margret Vil	lalobos								
152304					5/1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress			5/1/2016	6 1:03:41 AM	1			
Orozco, Da	niel	Monthly-Sunla Refer to PMsch	nd Park ES Fire Sup nedule details .	pression Insp					
Margret Vil	lalobos								
152800					5/8/2016	5/24/2016	24		\$0.00
Medium	Work In Progress			5/8/2016	12:31:46 AM	1			
Mijarez, Ja	me	Monthly - Sunla PMschedule d	and Park ES Playgro etails.	ound Insp - Refer	to				
Margret Vil	lalobos								
154133					6/1/2016		0		\$0.00
Medium	Work In Progress	CAFETERIA		6/1/2016	8:28:31 AM	1			
Lucero, Je	sus	CAFETERIA- N CEILING CLEA	EED TO HAVE THE NED	WALLS AND					
Maribel Ga	mboa								
149556					3/14/2016		79		\$0.00
Medium	Work In Progress			3/14/2016	8:51:12 AM	1			
Mijarez, Ja	me		d Ruben I will be pa lease order 50 gallo						

6/1/2016 11:47:11 AM Page 163 of 174

WOID Priority Assigned Requester		Area Area Number Description	Deferred By	Until	=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunland	Park ES							
153838					5/24/2016		8		\$0.00
Medium	Work In Progress			5/24/20	16 11:20:38 AM	I			
Villalobos	, Jose	Loan burnishe	r 8995 to Custodial						
Jimmy Ca	rbaial								
146926					1/28/2016		125		\$0.00
Medium	Work In Progress			1/28/2	.016 2:55:42 PM	1			
Ambriz, Jo	se		n O/Atemp sensors rs booster pumps fo		n and				
Jaime Mija	arez								
151749	Main Building	Custodial			4/21/2016		41		\$0.00
Medium	Work In Progress			4/21/2	:016 7:32:11 AV	I			
Villalobos	, Jose		Honda pressure was ould please check it		d wont				
Jesus Luc	cero								
151750	Main Building	Custodial			4/21/2016		41		\$0.00
Medium	Work In Progress			4/21/2	:016 7:35:17 AM	I			
Villalobos	, Jose		ratton pressure was out to another buildir orking. thanks						
Jesus Luc									
148039	Main Building	Custodial			2/19/2016		103		\$0.00
Medium	Work In Progress			2/19/20	16 10:28:35 AM	I			
Carbajal,	Jimmy	burnisher after functioning like please check it	returning from being it was prior to it brea out thanks	g fixed is not king down. if	we can				
Jesus Luc	cero								
153279					5/16/2016		16		\$0.00
Medium	Work In Progress			5/16/2	016 3:39:43 PM	1			
Carrasco,	Danny		an coil unit filter size: nd 2 boxes (20"x20"x						
Jaime Mija	arez								
148041					2/19/2016		103		\$0.00
Medium	Work In Progress			2/19/20	16 10:52:26 AM	I			
Vallejo, Al	bert	Create new op	ening for entry to off	ice					
Albert Vall	ejo								
	•								

6/1/2016 11:47:11 AM Page 164 of 174

WOID Priority Assigned Requester			Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunland	Park ES						
151215				4/12/2016		50		\$0.00
Medium	Work In Progress	bathroom in the		4/12/2016 3:30:01 PM				
Villalobos,	David	KNOB DO NOT	OOM IN THE HALL\ FLOW WORK PRO ITH ONE HAD TO C	OPERLY YOU				
Maribel Ga	mboa							
148911				3/4/2016		89		\$0.00
Medium	Work In Progress			3/4/2016 12:07:21 AM				
Marquez, C	Gerardo	PLEASE CHEC COUNTER IN M	K IF ITS POSSIBLE IAIN OFFICE.	TO MOVE				
Gerardo M	arquez							
153508				5/19/2016		13		\$0.00
Medium	Work In Progress			5/19/2016 2:22:10 PM				
Lara, Ralpl	1	Pad lock with ch open door to sto		d also teacher can't				
Jaime Mija	rez							
154135				6/1/2016		0		\$0.00
Medium	Work In Progress			6/1/2016 8:33:39 AM				
Flores, Pet	e	Maintenance Tr	uck 141 is over heat	ting bad.				
Jaime Mija	rez							
141871				10/16/2015		229		\$0.00
Medium	Work In Progress			10/16/2015 3:39:05 PM				
Flores, Per	e	tractor 970 4x4 (dont work(worked	before they took it to				
Carlos He	rnandez							
143765		Library		11/18/2015		196		\$0.00
Medium	Work In Progress	LIBRARY		11/18/2015 8:36:45 AM				
Mijarez, Ja	ime	_	ENO- NEEDS TO H TALLED SEE MRS.					
Maribel Ga	mboa							
141950				10/19/2015		226		\$0.00
Medium	Work In Progress			10/19/2015 3:36:43 PM				
Ronquillo,	Ruben		atform and one crac qullio was going to d up)					
Carlos Ha	rnandez							

6/1/2016 11:47:11 AM Page 165 of 174

WOID Priority Assigned Requester	Building Status To	Area Area Number Description	/30/2016 Order By Loc Deferred By Reason		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunland	Park ES						
136740				7/30/2015		307		\$0.00
Medium	Work In Progress			7/30/2015 11:23:17 AM	1			
Ronquillo,	Ruben	need platforms	for bridge broken(ha	azard)				
Carlos He	rnandez							
146909				1/28/2016		125		\$0.00
Medium	Work In Progress			1/28/2016 11:39:21 AV	1			
Mijarez, Ja	ime		RENO- NEED TO HA TIGHTEN. Table ha					
Maribel Ga	amboa							
141381				10/9/2015		236		\$0.00
Medium	Work In Progress			10/9/2015 3:31:47 PM	1			
Mijarez, Ja Jimmy Ca		floor tile in bath	room need to be repl	aced in room 38	1/25/15 - route to bu Jimmy, the tile is sti			
146581				1/22/2016	came unglued	131		\$0.00
Medium	Work In Progress	21		1/22/2016 9:43:54 AN	1	.0.		Ψ0.00
Mijarez, Ja	-		Z- NEED A TEACHE		•			
Maribel Ga		KIVIII- I LIKL	E-NEED A TEACHE	NO DEGIT LEAGE				
145195	amboa			12/17/2015		167		\$0.00
Medium	Work In Progress	21		12/17/2015 8:46:35 AV		101		Ψ0.00
Mijarez, Ja	_	RM#21- PERE	Z - WANTS TO PUT I NT 6 MORE CHAIRS	NAILS ON THE	•			
Maribel Ga	amboa							
148784				3/2/2016		91		\$0.00
Medium	Work In Progress	LIBRARY		3/2/2016 3:01:00 PM	1			
Mijarez, Ja	ime	TABLES TIGHT HAVE BECOME	RENO - NEED TO HA ENED. THE LEGS (E VERY LOOSE AND HAZARD. SECOND	ON THE TALBLES ARE STARTING				
Maribel Ga	amboa							
151671				4/20/2016		42		\$0.00
Medium	Work In Progress	NURSE OFFIC	E	4/20/2016 9:04:28 AM	1			
Mijarez, Ja	ime	NURSE OFFIC CABINET PUT	E NEEDS TO HAVE UP	A MEDICINE				
Maribel Ga	amboa							

6/1/2016 11:47:11 AM Page 166 of 174

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/20 Area Defo Area Number Rea Description	erred By	Until Request D	ate Target Comp Date me Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunland	Park ES						
150914		Office		4/7/20	016	55		\$0.00
Medium	Work In Progress			4/7/2016 10:16:57	' AM			
Mijarez, Ja	aime	OFFICE - NEW FUR TOGETHER AND PI HER OLD FURNITU DUQUES OFFICE.	JT IN PRINCIF	PAL OFFICE AND				
Maribel Ga	amboa							
144112		Classroom		12/1/2	015	183		\$0.00
Medium	Work In Progress	24		12/1/2015 3:15:00) PM			
Mijarez, Ja	aime	RM#24-MARRUFO- ONTHE PILASTERS TO HANG FARMED SEE ME AT MY ROO	IN THE HALL ARTWORK PL	WAYS IN ORDER				
Maribel Ga	amboa							
137110		Classroom		8/3/20	015	303		\$0.00
Medium	Work In Progress	25		8/3/2015 3:04:41	PM			
Mijarez, Ja	aime	RM#25- GARCIA- PI DOORS	LEASE PAINT	CLASSROOM	Route to Jaime on 1	1/16/15		
Maribel Ga	amboa							
146362		Classroom		1/19/2	016	134		\$0.00
Medium	Work In Progress	21		1/19/2016 12:53:31	PM			
Mijarez, Ja	aime	RM#21 - PEREZ- EX COMPUTER. PAINT TO HANG WHITEBO ROOM FOR STORA	AROUND WHOARD. SHELVE	ITEBOARD. NAILS				
Maribel Ga	amboa							
145703		Classroom		1/6/20	016	147		\$0.00
Medium	Work In Progress	21		1/6/2016 11:46:56	S AM			
Mijarez, Ja	aime	RM#21- CLAUDIA P OF WASHER AND D BOARD 3) NAILS OI 4) 1 LONG TABLE F DESK	ORY. 2) PAINT N WALL FOR E	AROUND HITACHI BULLETIN BOARD				
Maribel Ga	amboa							
145614	Main Building			1/5/20	016	148		\$0.00
Medium	Work In Progress			1/5/2016 10:11:45	5 AM			
Mijarez, Ja	aime	Jaime, EC playgrour so that it can be rea Front of building is fu against the front cha	dy when stude ıll of sand and	nts can go out to play.				
Rosa Kah	ioe	<u> </u>						
rtoou rturi								

6/1/2016 11:47:11 AM Page 167 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da WOID	Building	Dates:7/1/2015 - 6/30/2016 Order By Location, Status Area Deferred By Until Request D	ate Target Comp Date	Days L	Costs abor
Priority	Status	Area Number Reason Created Date/Ti	me Actual Comp Date	Aged H	lours
Assigned [*]	То	Description	Action Taken		
Requester	r Name				
Location:	Sunland	Park ES			
144786		Cafeteria 12/10/2	015	174	\$0.00
Medium	Work In Progress	12/10/2015 7:36:06	S AM		
Moncayo,	Fernando	NO HOT WATER IN KITCHEN - SNP MGR IGNACIA 589-2545			
Jacqueline	e Aguilar				
153417		Kitchen 5/18/2	016	14	\$0.00
High	Work In Progress	5/18/2016 12:44:16	PM		
Moncayo,	Fernando	Replace fuse on Serving Line. SNP Manager Ignacia C. (575) 589-2545			
Dino Facio	0				
154131		6/1/2	016	0	\$0.00
Medium	Work In Progress	6/1/2016 8:25:14	I AM		
Herrera, M	l arin	I need fuel for the maintenance orange truck and small tracker mower.			
Jaime Mija	arez				
152065	Main Building	Custodial 4/27/2	016	35	\$0.00
Medium	Work In Progress	4/27/2016 10:50:05	5 AM		
Briones, E	inrique	requesting fire prof dolly for moving some furniture.			
Jesus Luc	cero				
148226		2/23/2	016	99	\$0.00
Medium	Work In Progress	2/23/2016 2:43:24	PM		
Ontiveros,	Guadalupe	I am going to need the Bobcat with the brush so I can sweep the walkways around the school.			
Jaime Mija	arez				
Count: 52	Work Orders	Avg. Age of WO's 107	Total for Sunland Par	k ES	0 \$0.00

6/1/2016 11:47:11 AM Page 168 of 174

o Name	Area Number Reason Created Date/Time Description	Action Taken	Aged	Hours	
Sunrise E	 ES				
	5/10/2016		22		\$0.00
Work In Progress	5/10/2016 1:35:56 PM	1			
an	need paint room 310 304 206 212 potable 3 and main office				
ıs					
	4/18/2016		44		\$0.00
Work In Progress	4/18/2016 3:29:20 PM	1			
nzo	NEED HELP TO FIX CAFETERIA A/C MAKE UPER				
ıs					
	5/1/2016	5/9/2016	31		\$0.00
Work In Progress	5/1/2016 1:05:05 AM				
an	Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PMschedule details.				
alobos					
	5/1/2016	5/9/2016	31		\$0.00
Work In Progress	5/1/2016 1:05:06 AM				
	Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PMschedule details.				
alobos	T. W. 100.10	E 10.0 10.0 4.0			Φο οο
			31		\$0.00
Work In Progress	5/1/2016 1:03:20 AM				
	Monthly-Sunrise ES Range Hood Cleaning - Refer to PMschedule details.				
alobos	E /24 /2046	7/4/2046			<u>ФО ОО</u>
			1		\$0.00
Work In Progress	5/31/2016 12:54:36 AM				
	Yearly - Sunrise ES A2 (H/C Unit)(Yearly) - Refer to PM schedule details.				
alobos	5/1/2016	5/22/2016	31		\$0.00
Work In Progress			JI		ψυ.υυ
_	Monthly-Sunrise ES Fire Suppression Insp Refer to				
alobos					
	5/31/2016		1		\$0.00
Work In Progress	5/31/2016 3:11:12 PM	1			
-					
	Work In Progress an Work In Progress an alobos S/10/2016 1:35:56 PM	S/10/2016 S/10/2016 1.35:56 PM need paint room 310 304 206 212 potable 3 and main office A/18/2016 A/1	S/10/2016 22	S/10/2016 22	

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2015 - 6/30/2016 Order By Loc Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Sunrise I	ES					
152449		Hallway/Corridor	5/2/2016		30		\$0.00
Medium	Work In Progress	EL SOL	5/2/2016 1:20:16 PM				
Chavez, Sa	antos	JOANNE MUNOZ, SOL WORKROC OUTLET CHECKED OUT FOR CO SAYING THERE IS A POWESURGE TO MAKE SURE EVERYTHING IS C OUTLET.	PIER. DAHILL IS E AND WE NEED				
Joanne Mu							
147323	Main Building	Library	2/3/2016		119		\$0.00
Medium	Work In Progress		2/3/2016 10:12:50 AM				
Chavez, Sa	antos	Need to replace lenses on several 4	1 x 2 light fixtures				
Santos Ch	navez						
153577			5/20/2016		12		\$0.00
Medium	Work In Progress		5/20/2016 8:11:46 AM				
Marquez, 0	Gerardo	CHECK DRS. FOR PROPER OPER	RATION.				
Gerardo M	larquez						
152607		Kitchen	5/4/2016		28		\$0.00
High	Work In Progress		5/4/2016 1:11:30 PM				
Appelzolle	r, Fred	Top Oven on the right not working. Glenda Gore (575) 824-3194	SNP Manager				
Dino Facio)						
152892			5/10/2016		22		\$0.00
Medium	Work In Progress		5/10/2016 2:09:46 PM				
Vargas, Ju	an	need replace lamps in class room					
Juan Varg	as						
152951			5/11/2016		21		\$0.00
Medium	Work In Progress		5/11/2016 8:03:41 AM				
Vargas, Ju	an	need replace double door threshold	d in 200 wing				
Juan Varg	as						
152989			5/11/2016		21		\$0.00
Medium	Work In Progress		5/11/2016 12:54:16 PM				
Vargas, Ju	an	fix celingtiles in all class rooms					
Juan Varg	as						
153061			5/12/2016		20		\$0.00
Medium	Work In Progress		5/12/2016 10:09:39 AM				
Vargas, Ju	an	need fix cafeteria wall cove base					
Juan Varg							
	11:47:11 AM					Page 1	70 of 174

Total
Selected Date Range for Request Dates:7/1/2015 - 6/30/2016 Order By Location, Status

Costs

WOID Building Area Deferred By Until Request Date Target Comp Date Days Labor
Priority Status Area Number Reason Created Date/Time Actual Comp Date Aged Hours

Assigned To Description Action Taken

Requester Name

Location: Sunrise ES

Count: 16 Work Orders Avg. Age of WO's 29 Total for Sunrise ES 0 \$0.00

6/1/2016 11:47:11 AM Page 171 of 174

Requester	Status o Name	Area Number Reason Description	ntil Request Date T	Actual Comp Date Action Taken	Days Labor Aged Hours	
Location:	Vado ES					
153329		Kitchen	5/17/2016		15	\$0.00
Medium	Work In Progress		5/17/2016 9:48:36 AM			
Miranda, Danny		Kitchen area ceiling tiles need replacing SNP Manager Elizabeth M. (575) 233-2	, c			
Dino Facio						
153153			5/13/2016		19	\$0.00
Medium	Work In Progress		5/13/2016 1:00:44 PM			
Hernandez	, Guillemo	Range hood on and off switch not workin Manager Elizabeth M. 233.2945	ng. SNP			
Maritza Gor	nzalez					
153401			5/18/2016		14	\$0.00
Medium	Work In Progress		5/18/2016 8:43:50 AM			
Miranda, Da	anny	NEED SIX FUSES (FRS-15 600-V)				
Danny Mira	nda					
153403			5/18/2016		14	\$0.00
Medium	Work In Progress		5/18/2016 8:49:48 AM			
Miranda, Danny		NEED TO REPLACE V-BELTS ON REC WHEELS AND KITCHEN HOOD MOTO	-			
Danny Mira	nda					
151521			4/18/2016		44	\$0.00
Medium	Work In Progress		4/18/2016 12:39:20 PM			
Miranda, Da	anny	need to replace air filters to a/c units				
Danny Mira	nda					
153568			5/20/2016		12	\$0.00
Medium	Work In Progress		5/20/2016 7:56:30 AM			
Marquez, G	erardo	CHECK DRS. FOR PROPER OPERATION	ON.			
Gerardo Ma	arquez					
153155			5/13/2016		19	\$0.00
Medium	Work In Progress		5/13/2016 1:01:17 PM			
Diaz, Armando		Ceiling tiles need to be cleaned. SNP Ma Elizabeth M. 233.2945	anager ı	route to Mandis asp A	Nfredo	
Maritza Gor	nzalez					
144866			12/11/2015		173	\$0.00
Medium	Work In Progress		12/11/2015 10:31:24			
Chavez, Santos		need to replace emer. ballast in rooms and teachers lounge	103,107,208,303,			

6/1/2016 11:47:11 AM Page 172 of 174

WOID Priority Assigned		Area Deferred By United Street Programmer Deferred By United Street Programmer Description	ntil Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Requester	Vado ES						
Location:	vado ES	120.1	F/47/0040		45		Φο οο
153328		Kitchen	5/17/2016		15		\$0.00
Medium	Work In Progress		5/17/2016 9:46:07 AM				
Chavez, Santos		On and Off switch on range hood not w M. (575) 233-2945	orking. Elizabeth				
Dino Facio	1						
143363			11/10/2015		204		\$0.00
Medium	Work In Progress		11/10/2015 7:56:40 AM	I			
Appelzolle	r, Fred	need to replace booster pump in 100-wi	ng boiler room				
Danny Mira	anda						
150825			4/6/2016		56		\$0.00
Medium	Work In Progress		4/6/2016 9:22:14 AM	I			
Appelzoller, Fred		need to replace lav's in 200-wing boys r. boys r.r. going out to bus area	r. and one in				
Danny Mira	anda						
149245			3/8/2016		85		\$0.00
Medium	Work In Progress		3/8/2016 2:22:33 PM	1			
Marquez, Gerardo		need to re key double doors by office to teachers keys	open with all				
Danny Mira	anda						
149482			3/11/2016		82		\$0.00
Medium	Work In Progress		3/11/2016 2:32:25 PM	1			
Vallejo, Alb	ert	Create drainage for playground area.					
Albert Valle	ejo						
151368	<u>-</u>		4/14/2016		48		\$0.00
Medium	Work In Progress		4/14/2016 9:56:04 AM	I			
Vallejo, Alb	ert	Build enclosed area for trash dumpsters					
Alfredo Ho		·					
148681	.94	Custodial	3/1/2016		92		\$0.00
Medium	Work In Progress		3/1/2016 7:55:18 AM	I			
Carbajal, Jimmy		Requesting to trade old extractor for a new one . Thank you!					
Armando [Diaz	,					
153960			5/26/2016		6		\$0.00
Medium	Work In Progress		5/26/2016 3:07:14 PM	1			
Carrasco,	Danny	need some insect repellent					
Danny Mira	•	· · · · · · · · ·					

6/1/2016 11:47:11 AM Page 173 of 174

1141 - Work Orders In Progress (Fiscal Year)

Selected Da	ate Range for Request Building	Dates:7/1/2015 - 6 Area	6/30/2016 Order By Lo Deferred By	ocation, Status Until	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•		=	Actual Comp Date	Aged	Hours	
Assigned		Description				Action Taken			
Requester	r Name	-							
Location:	Vado ES								
152306					5/1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress			5/1/2	2016 1:03:45 AM	1			
Orozco, Daniel		Monthly - Vado schedule detai	ES Fire Suppressions.	on Insp Ref	er to PM				
Margret Vi	llalobos								
152283					5/1/2016	5/22/2016	31		\$0.00
Medium	Work In Progress			5/1/2	2016 1:03:21 AM	1			
Orozco, Daniel		Monthly - Vado schedule detai	ES Range Hood Cils.	leaning - Ref	er to PM				
Margret Vi	llalobos								
154030					5/31/2016	7/1/2016	1		\$0.00
Medium	Work In Progress			1					
Miranda, Danny		Yearly - Vado E to PMschedule	ES A-2 Package Uni e details.	t Elec Yearly	Refer				
Margret Vi	llalobos								
153482					5/19/2016		13		\$0.00
Medium	Work In Progress			5/19/20	016 10:03:42 AM	1			
Solis, Lorenzo		NEED TO CK. FREON	UNIT IN MAINT. RO	OM LOW ON					
Danny Mir	anda								
152974					5/11/2016		21		\$0.00
Medium	Work In Progress			5/11/2	2016 9:56:24 AM	1			
Miranda, Danny		NEED TO PAIN	NT CLASSROOMS A	AS NEEDED					
Danny Mir	anda								
150299	Main Building	Parking Lot			3/31/2016		62		\$0.00
Medium	Work In Progress	Front of the		3/31/20	016 10:29:01 AM	1			
Vallejo, Albert		the front. Paint	n parking lot, drop of t the front doors of th poles that are locate	ne lobby and	cafeteria.				
Sylvia Car	У								
Count: 22 Work Orders			Avg. Age of WO's	48		Total for Vac	lo ES	0	\$0.00
Count: 11	141 Work Orders	A	vg. Age of WO's	71		Grand Total		6	\$348.59

6/1/2016 11:47:11 AM Page 174 of 174