730 - Work Orders In Progress (Fiscal Year)

		Dates:7/1/2016 - 12/31/			a Target Comp Date	Dava	Labor	Costs
WOID	Building Status	Area Number Rea	ferred By	•	e Target Comp Date e Actual Comp Date	Days Aged	Labor Hours	
Priority Assigned		Description	a5011	Created Date/Tilling	Action Taken	3		
Requester		Description			Action raken			
Location:		a Early College HS						
166190		Storage		12/14/201	6	26		\$0.00
Medium	Work In Progress	Back Storage		12/14/2016 4:07:44 P	M			
Gonzales,	Camilo	PICK UP FURNITU NEEDS TO BE DIS 1. DESKS 2. CHAIRS 3. BROKEN WHIRE	CARDED:	MENT THAT				
Yvette Cor	tez							
165841		Pump House		12/8/201	6	32		\$0.00
Medium	Work In Progress			12/8/2016 9:03:00 A	M			
Carrasco,	Danny	I'm requesting a 50 you.	feet extension co	ord for mysite thank				
Alfredo Am	nbriz							
165633				12/5/201	6	35		\$0.00
Medium	Work In Progress			12/5/2016 11:26:34 A	M			
Ontiveros,	Guadalupe	2 notice can you ple tubes from behind to OSHA comes and ir	the pee potable o	n the ramp before				
Alfredo Am	nbriz							
162199		Portables		10/4/201	6	97		\$0.00
Medium	Work In Progress			10/4/2016 1:59:48 F	PM			
Lara, Ralp	h	Need to remove deatomorrow morning.	adbolts and blan	k them out, 1st thing				
Albert Vall	ejo							
Count: 4 W	Vork Orders	Avg. A	Age of WO's 4	Total for A	Alta Vista Early Colleg	ge HS	0	\$0.00

1/9/2017 3:07:19 PM Page 1 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Da	ite Range for Request Building	Dates:7/1/2016 - 1 Area	2/31/2016 Order By L		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Aged	Hours	
Assigned ¹	То	Description			Action Taken			
Requester	Name							
Location:	Anthony	- On Track Pre-	K (Village)					
156807				7/20/2016	3	173		\$0.00
Medium	Work In Progress			7/20/2016 4:09:38 P	М			
Marquez, (Gerardo		ET CONTRACTORS AT NEED TO BE O	ABOUT STORAGE RDERED AND				
Gerardo M	1arquez							
158402				8/10/2016	5	152		\$0.00
Medium	Work In Progress			8/10/2016 12:58:56 PI	М			
Chavez, Sa	antos	directly to the le		nstalled in the space t the POA center. It is thonyPre-k. Thank				
Elisa Sant	tillano							
157210				7/27/2016	3	166		\$0.00
Medium	Work In Progress			7/27/2016 11:37:54 A	M			
Nunez, Art			l of the pre-k buildi Sandyor Laura thai	ng different colors. any nk you				
Laura Vaz	quez			7/10/001		4		
156588				7/18/2016		175		\$0.00
Medium	Work In Progress	882-1904		7/18/2016 8:16:39 A	M			
Nunez, Art	uro	paint front offic	e door red ASAP					
Laura Vaz	quez							
156870		Portables		7/21/2016	3	53		\$0.00
Medium	Work In Progress			7/21/2016 3:35:36 P	M 9/12/2016			
Chavez, Sa	antos	classroom win	od light to provide liggs during evening pritched on or off astion sensor.	parent visits. Ideally				
Alfredo Ho	olguin							
164052				11/4/2016	3	66		\$0.00
Medium	Work In Progress	882-6236		11/4/2016 8:30:14 A	M			
Chavez, Sa	antos	T.V Wall Mount room 103-104 Thank you	cyprogram with Mrs t and to add an outl please call or ask J	et for the electricity.				
Laura Vaz	quez							

1/9/2017 3:07:19 PM Page 2 of 122

0

\$0.00

730 - Work Orders In Progress (Fiscal Year)

Count: 7 Work Orders

Total Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Area Number Reason Created Date/Time Actual Comp Date **Priority Status Assigned To Description Action Taken** Requester Name Location: Anthony - On Track Pre-K (Village) 156764 7/20/2016 173 \$0.00 Medium Work In Progress 7/20/2016 1:11:02 PM remove the diaper changing table (cabinet) that is in the Nunez, Arturo restroom in room 111 Laura Vazquez

Total for Anthony - On Track Pre-K (Village)

Avg. Age of WO's 137

1/9/2017 3:07:19 PM Page 3 of 122

Selected Da WOID	Building	Area	2/31/2016 Order By Lo Deferred By		Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•	Create	ed Date/Time	Actual Comp Date	Aged	Hours	
Assigned ¹	Го	Description				Action Taken			
Requester	Name								
Location:	Anthony	ES							
166130					12/14/2016		26		\$0.00
Medium	Work In Progress			12/14/201	16 5:59:07 AM	1			
Villalobos	Jose	vacuum cleane	er serial#5381 needs	repair brushes					
David Veg	a			·					
165520					12/4/2016	12/12/2016	36		\$0.00
Medium	Work In Progress			12/4/2016	6 12:43:20 AV	1			
Nunez, Art	uro	Monthly - Antho PMschedule d	ony ES Exit Sign Insp etails.	: Monthly - Refe	er to				
Margret Vil	lalobos								
165977					12/11/2016	12/27/2016	29		\$0.00
Medium	Work In Progress			12/11/2	2016 12:38:10	1			
Nunez, Art	uro	Monthly - Antho to PMschedule	ony ES Monthly Playg e details.	round Insp R	Refer				
Margret Vil	lalobos								
164173					11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress			11/6/2016	6 12:40:35 AM	1			
Medina, E	ric	Monthly - Antho PMschedule d	ony ES Fire Suppress etails.	sion Insp Ref	fer to				
Margret Vil	lalobos								
164152					11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress			11/6/2016	6 12:40:21 AM	1			
Medina, E	ric	Monthly - Antho PMschedule d	ony ES Range Hood (etails.	Cleaning - Ref	er to				
Margret Vil	lalobos								
164147					11/6/2016		64		\$0.00
Medium	Work In Progress			11/6/2016	6 12:40:17 AV	1			
Medina, E	ric	Yearly - Anthor schedule detai	ny ES - Grease Trap - ls.	Refer to PM					
Margret Vil	lalobos								
165226					11/30/2016		40		\$0.00
Medium	Work In Progress			11/30/201	16 8:36:14 AM	1			
Chavez, Sa	antos	Need some lig	hts changed in Room	n 111.					
Susie Ran	nos Lara								

1/9/2017 3:07:20 PM Page 4 of 122

Total Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID **Deferred By Request Date Target Comp Date Davs** Labor Area Until Aged Hours Area Number Reason Created Date/Time Actual Comp Date Status **Priority** Assigned To Description **Action Taken** Requester Name Location: Anthony ES 155743 7/1/2016 192 \$0.00 Work In Progress 7/1/2016 3:54:30 PM Medium Chavez, Santos Need to install a 120v electric outlet next to the air handler in room 106 at APKV. Please see Art for location. Guillermo Hernandez 7/27/2016 166 \$0.00 157245 Work In Progress Medium 7/27/2016 3:28:29 PM Nunez. Arturo Mr. Nunez Please check all toilet commodes for leaks thank you Jessica Lopez 171 7/22/2016 \$0.00 156957 7/22/2016 2:14:14 PM Medium Work In Progress Nunez, Arturo Please send a technician to remove all the shelves in room 120. They are not using the shelves anymore and would like to have them removed from the wall. We would like to have this done so that when they schedule the pick up of all the other items these will also go too. Thank you. Susie Ramos Lara 9/27/2016 104 \$0.00 161600 Medium Work In Progress 9/27/2016 2:48:17 PM Nunez, Arturo All carpets in class rooms need to be secured to floor. Arturo Nunez 162809 10/17/2016 \$0.00 Work In Progress 250 10/17/2016 9:43:23 AM Medium Nunez, Arturo Mr. Nunez. Please set up a 4 X 4 garden bed room #250 Mrs. Holguin Jessica Lopez 12/16/2016 24 \$0.00 166266 Medium Work In Progress **ROOM 111** 12/16/2016 8:24:53 AM Nunez, Arturo Please remove shelves in room 111. We will have a new instructional specialist join us at the beginning of the new year and would like to have that area ready for her. Please contact Susie if you have any questions. Susie Ramos Lara

1/9/2017 3:07:20 PM Page 5 of 122

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2016 - 12/31/2016 Area Deferre Area Number Reason Description	ed By Until	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Anthony	ES						
166268				12/16/2016		24		\$0.00
Medium	Work In Progress	Room 111 &	12/16/20	16 9:10:24 AM				
Nunez, Art	turo	of staff member that we need to make it a functio to paint office rooms # 2	fices accommodate the number have in our department. In have in our department on ing work space. So we number that they beceed to arrange the office	We eed are				
Susie Rar	mos Lara							
158097		Kitchen		8/5/2016		157		\$0.00
Medium	Work In Progress		8/5/20	16 3:40:28 PM				
Medina, E	ric	Assessment on the curt SNP Mgr. Lorena B. (57	ains inside the walk in free (5) 882-3507	ezer.				
Dino Facio	0							
161082		Kitchen		9/19/2016		112		\$0.00
High	Work In Progress		9/19/201	6 10:16:44 AM				
Medina, E	ric	Ice machine down not v (575) 882-3507	vorking. SNP Mgr. Lorena	В.				
Dino Facio	0							
159482		Parking Lot		8/25/2016		137		\$0.00
Medium	Work In Progress		8/25/201	6 11:22:55 AM				
Chavez, S	antos	Need to relocate marqu	ee					
Santos Ch	navez							
163769				11/1/2016		69		\$0.00
Medium	Work In Progress		11/1/20	16 9:00:12 AM				
Chavez, S	antos	As per Ms. Perez traffic are out please check as	flashing lights on Church soon as possible.	street				
		(Silver is still out on Leav	ve)					
Jessica L	opez							
164702		Kitchen		11/14/2016		56		\$0.00
High	Work In Progress		11/14/20	16 3:34:06 PM				
Villalobos	, David	Dishwasher started ma Mgr. Lorena B. (575) 882	king noise and smoking. S 2-3507	NP				
Dino Facio	0							
165121		Kitchen		11/29/2016		41		\$0.00
High	Work In Progress		11/29	/2016 10:24:14				
Villalobos			middle sink does not hold Mgr. Lorena B. (575) 882-3					
Dino Facio	0							
1/9/2017 1	3:07:20 PM						D	6 of 122

1/9/2017 3:07:20 PM Page 6 of 122

Total Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Created Date/Time Actual Comp Date **Priority Status** Area Number Reason **Assigned To Description Action Taken** Requester Name Location: **Anthony ES** 165696 12/6/2016 34 \$0.00 Medium Work In Progress 12/6/2016 9:02:31 AM TWO TOP OVENS ARE NOT CLOSING RIGHT. SNP Villalobos, David MANAGER LORENA B. 882.3507 Maritza Gonzalez Count: 21 Work Orders 0 \$0.00 Avg. Age of WO's 81 **Total for Anthony ES**

1/9/2017 3:07:20 PM Page 7 of 122

Selected Dat WOID Priority Assigned 1 Requester		Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Berino ES							
165159				11/29/2016		41		\$0.00
Medium	Work In Progress			11/29/2016 3:22:40 PM	I			
Villalobos,	David		LEAKING, NOT MAK SANA H.882.2417	ING ICE. SNP				
Maritza Go	nzalez							
163336		Kitchen		10/25/2016		76		\$0.00
High	Work In Progress			10/25/2016 10:31:34	ļ			
Facio, Dinc		back/front, no c	ence in kitchen area urtain or back door se by 10/31/16 as pe	blower. Corrective	10/25/16 - WO 1633 Electrician.	82 for bl	ower route	ed to
Dino Facio		12.4		10/05/0040		70		Φο οο
163337		Kitchen		10/25/2016		76		\$0.00
High	Work In Progress			10/25/2016 10:40:04	ļ			
Marquez, G			om door not self-clos se by 1/31/17 as per					
Dino Facio				0 /0 0 /0 0 4 0		404		* * * * * * * * * * * * * * * * * * *
161846				9/30/2016		101		\$0.00
Medium	Work In Progress			9/30/2016 11:29:17 AN	1			
Appelzollei	r, Fred	Need assistan at Berino.	ce to replace 2" wate	r valve for boiler #1				
Guillermo	Hernandez							
163339		Kitchen		10/25/2016		76		\$0.00
High	Work In Progress			10/25/2016 10:51:51				
Medina, Er Dino Facio			-in flooring not smoo rective Action Respo		Asp Albert, The wall equipment, much like may need to contact Kolpak that works or panels. Reassigned to the assessment	ke a refrig a compa n or repla d work or	gerator. The any such as aces the der to Erica	ey S to
158177		Kitchen		8/8/2016		154		\$0.00
High	Work In Progress			8/8/2016 9:27:18 AM	1			
Medina, Er	ic	Oven down not 2417	working NP Mgr. Su	ısana H. (575) 882-				
Dino Facio								
165789				12/7/2016		33		\$0.00
Medium	Work In Progress			12/7/2016 1:44:54 PM	1			
Medina, Er	ic		ING A LOUD BUZZI SANA H. 882.2417	NG NOISE. SNP				

1/9/2017 3:07:20 PM Page 8 of 122

WOID Priority Assigned 1 Requester		Area Number Description	Deferred By		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Berino ES	3						
161506				9/26/2016		105		\$0.00
Medium	Work In Progress			9/26/2016 3:37:38 PM				
Gonzalez,	Salvador	Need to install r	netal ramps on po	ortables 7 thank you				
Sebastian	Diaz			·				
161505				9/26/2016		105		\$0.00
Medium	Work In Progress			9/26/2016 3:35:09 PM				
Diaz, Seba	stian	For ESC you	THE A/C on kitch	en not work well thank				
Sebastian	Diaz							
159475				8/25/2016		137		\$0.00
Medium	Work In Progress			8/25/2016 10:38:15 AM				
Diaz, Seba	stian	Need paint for v	vall on main office	thank you				
Sebastian	Diaz							
165925				12/9/2016		31		\$0.00
Medium	Work In Progress			12/9/2016 10:40:44 AM				
Chavez, Sa	ntos	Need to fix outs	ide lights bybus es	s area thank you				
Sebastian	Diaz							
164142				11/6/2016		64		\$0.00
Medium	Work In Progress			11/6/2016 12:40:14 AM				
Medina, Er	ic	Yearly - Berino schedule detail	ES - Grease Trap s.	- Refer to PM				
Margret Vil	alobos							
165924				12/9/2016		31		\$0.00
Medium	Work In Progress			12/9/2016 10:37:23 AM				
Ontiveros,	Guadalupe	Need tractor for	r remove Sand or	n DP thank you				
Sebastian	Diaz							
164153				11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress			11/6/2016 12:40:22 AM				
Medina, Er	ic	Monthly - Berind PMschedule de		l Cleaning - Refer to				
Margret Vil	alobos							
164174				11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress			11/6/2016 12:40:36 AM				
Medina, Er	ic	Monthly - Berind PMschedule de		ssion Insp Refer to				

1/9/2017 3:07:20 PM Page 9 of 122

Total Selected Date Range for Request Dates:7/1/2016 - 12/31/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Area Number Reason Created Date/Time Actual Comp Date Status **Priority Description Action Taken Assigned To** Requester Name Location: Berino ES 166000 12/12/2016 28 \$0.00 Medium Work In Progress 12/12/2016 9:10:11 AM AS PER ENVIRONMENT DEPT INSPECTION Villalobos, Margret Em Waiver REPORT- KITCHEN/CAFETERIA NEEDS TO BE 12/12/16 FOGGED FOR FLIES. Maritza Gonzalez 75 10/26/2016 \$0.00 163451 Medium Work In Progress 10/26/2016 3:11:38 PM Ronquillo, Ruben Signs 4 signs to access roofs 1 for Pre K 1 for K to 1st 1 for 2nd to 6th THANK YOU Sebastian Diaz 12/15/2016 25 \$0.00 166254 Medium Work In Progress 12/15/2016 3:58:31 PM Hernandez, Guillermo Need to check heater on portable 157 thank you Sebastian Diaz 12/13/2016 \$0.00 166083 12/13/2016 12:09:05 Medium Work In Progress Diaz, Sebastian Need to change a bulb in room 108 thank you Michelle Guerra Count: 19 Work Orders Avg. Age of WO's 69 Total for Berino ES \$0.00

1/9/2017 3:07:20 PM Page 10 of 122

Total Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs WOID Building Area Until **Request Date Target Comp Date Davs** Labor **Deferred By** Aged Hours Area Number Reason Status Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description Requester Name Chaparral ES Location: 166202 12/15/2016 25 \$0.00 Medium Work In Progress 12/15/2016 7:48:42 AM Tellez, Hector Please locate by today Richard from Metro is trying to get utility locates on the west side of the 300 wing so that he can tie in sewer lines on that side of the building. He tells me that they call in every 2 weeks (to One Call) and no one has come out for these locates. Can you get someone with GISD to come mark this area? Rafael Gallegos 165346 12/1/2016 39 \$0.00 Medium Work In Progress 12/1/2016 3:00:28 PM CARVER ELECTRIC Tellez, Hector Company. Main Contact Phone: (575) 644-4313 Address: PO BOX 1469 City, St, Zip: MESILLA PARK, NM 88047 Main Contact Email: carver@carverelectric.com Company Phone: (575) 527-2127 Alternate Contact: DANIEL CARVER Alternate Contact Phone: (575) 649-9142 Main Contact: **BOBBY CARVER** Spotting Instructions SPOT PER THE WORK PLAN Dominique Esparza 12/6/2016 34 \$0.00 165721 Medium Work In Progress 12/6/2016 2:16:12 PM

METRO MECHANICAL Tellez, Hector Company.

Main Contact Phone: (575) 649-5554

Address: 745 S COMPRESS RD City, St, Zip: LAS CRUCES, NM 88005 Main Contact Email: mmi@qwestoffice.net CompanyPhone: (575) 527-1044 Company Fax: (575) 527-8309 Main Contact: RICHARD MUNOZ

Spotting Instructions ENTIRE PROPERTY

Dominique Esparza

1/9/2017 3:07:20 PM Page 11 of 122

Total Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs WOID Building Area Until **Request Date Target Comp Date Davs** Labor **Deferred By** Aged Hours Area Number Reason Status Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description Requester Name Chaparral ES Location: 163869 11/2/2016 68 \$0.00 Medium Work In Progress 11/2/2016 10:32:53 AM Tellez, Hector EL PASO EXCAVATIONS Company. Main Contact Phone: (575) 642-0041 Address: PO BOX 962710 City, St, Zip: EL PASO, TX 79996 Main Contact Email: ISELWELLS@GMAIL.COM CompanyPhone: (915) 856-7975 Alternate Contact: JACOB OCON Alternate Contact Phone: 915-216-5734 Main Contact: **BILL BREEDING** Spotting Instructions SPOT: 200FT RAD OF THE AREA MARKED IN WHITE Esparza, Dominique 11/3/2016 67 \$0.00 163977 11/3/2016 9:38:27 AM Medium Work In Progress Tellez, Hector CARVER ELECTRIC Company. Main Contact Phone: (575) 644-4313 Address: PO BOX 1469 City, St, Zip: MESILLA PARK, NM 88047 Main Contact Email: carver@carverelectric.com CompanyPhone: (575) 527-2127 DANIEL CARVER Alternate Contact: Alternate Contact Phone: (575) 649-9142 Main Contact: **BOBBY CARVER**

Spotting Instructions

SPOT PER THE WORK PLAN...Please verify

communication lines as well.

Dominique Esparza

164963 11/18/2016 52 \$0.00

Medium Work In Progress 11/18/2016 12:13:46

METRO MECHANICAL Tellez, Hector Company. Main Contact Phone:

(575) 649-5554

Address: 745 S COMPRESS RD City, St, Zip: LAS CRUCES, NM 88005 Main Contact Email: mmi@qwestoffice.net

CompanyPhone: (575) 527-1044 Company Fax: (575) 527-8309 Main Contact: RICHARD MUNOZ

Spotting Instructions **ENTIRE PROPERTY**

& Please verify communication lines as well.

Dominique Esparza

1/9/2017 3:07:20 PM Page 12 of 122

Total Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs WOID Building Area Until **Request Date Target Comp Date Davs** Labor **Deferred By** Aged Hours Area Number Reason Status Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description Requester Name Chaparral ES Location: 164965 11/18/2016 52 \$0.00 Medium Work In Progress 11/18/2016 12:19:02 Tellez, Hector CARVER ELECTRIC Company. Main Contact Phone: (575) 644-4313 Address: PO BOX 1469 City, St, Zip: MESILLA PARK, NM 88047 Main Contact Email: carver@carverelectric.com Company Phone: (575)527-2127Alternate Contact: DANIEL CARVER Alternate Contact Phone: (575) 649-9142 Main Contact: **BOBBY CARVER** Spotting Instructions SPOT PER THE WORK PLAN & Please verify communication lines as well. Dominique Esparza 10/20/2016 81 \$0.00 163096 10/20/2016 12:45:42 Medium Work In Progress Tellez, Hector Company. CARVER ELECTRIC Main Contact Phone: (575) 644-4313 Address: PO BOX 1469 City, St, Zip: MESILLA PARK, NM 88047 Main Contact Email: carver@carverelectric.com CompanyPhone: (575) 527-2127 Alternate Contact: DANIEL CARVER Alternate Contact Phone: (575) 649-9142 Main Contact: **BOBBY CARVER** Spotting Instructions SPOT PER THE WORK PLAN Dominique Esparza 163099 10/20/2016 81 \$0.00 Medium Work In Progress 10/20/2016 12:59:29 CARVER ELECTRIC Tellez, Hector Company. Main Contact Phone: (575) 644-4313 Address: PO BOX 1469 City, St, Zip: MESILLA PARK, NM 88047 Main Contact Email: carver@carverelectric.com CompanyPhone: (575) 527-2127 Alternate Contact: DANIEL CARVER Alternate Contact Phone: (575) 649-9142

Driving Directions

CHAPARRAL ELEMENTARY SCHOOL

Main Contact:

Dominique Esparza

1/9/2017 3:07:20 PM Page 13 of 122

BOBBY CARVER

730 - Work Orders In Progress (Fiscal Year)

Paul Quinones

Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID **Deferred By Request Date Target Comp Date Days** Labor Area Until Aged Hours Created Date/Time Actual Comp Date Status Area Number Reason **Priority Action Taken Assigned To** Description Requester Name Location: Chaparral ES 164431 11/8/2016 62 \$0.00 Medium Work In Progress 11/8/2016 11:27:47 AM requesting fan and limit switches for wall heaters for Quinones, Paul restock **Paul Quinones** Kitchen 12/1/2016 39 \$0.00 165302 Work In Progress 12/1/2016 7:38:29 AM High Freezer down not working. SNP Mgr. Maria C. (575) 824 -0048 Dino Facio Office 25 \$0.00 12/15/2016 166219 12/15/2016 12:00:13 Medium Work In Progress Gonzales, Camilo Pick up obsolete items and deliver to the Instructional Materials Warehouse for disposal. Thank you. Theresa Ramirez 11/6/2016 11/27/2016 \$0.00 64 164175 Medium Work In Progress 11/6/2016 12:40:37 AM Monthly-Chaparral ES Fire Suppression Insp. - Refer Medina, Eric to PMschedule details. Margret Villalobos 11/6/2016 11/27/2016 64 \$0.00 164154 Medium Work In Progress 11/6/2016 12:40:22 AM Medina, Eric Monthly-Chapparal ES Range Hood Cleaning - Refer to PMschedule details. Margret Villalobos 164143 11/6/2016 64 \$0.00 11/6/2016 12:40:15 AM Medium Work In Progress Yearly - Chaparral ES - Grease Trap - Refer to PM Medina, Eric schedule details. Margret Villalobos 12/15/2016 25 \$0.00 166220 Work In Progress 12/15/2016 12:26:25 Medium Gonzalez, Salvador playground climbing equipment broken weld

1/9/2017 3:07:20 PM Page 14 of 122

WOID Priority Assigned 1 Requester	Building Status To	Dates:7/1/2016 - 12/31/2016 Order By L Area Deferred By Area Number Reason Description	Until Request Date Target Comp Da Created Date/Time Actual Comp Da Action Take	te Aged	Labor Hours	Costs
Location:	Chaparra	al ES				
163512			10/27/2016	74		\$0.00
Medium	Work In Progress		10/27/2016 8:43:42 AM			
Ronquillo,	Ruben	need appropriate signs as follows adult supervision required appropriate age range needing 3 of each signs				
Paul Quinc	ones					
164501			11/9/2016	61		\$0.00
Medium	Work In Progress		11/9/2016 10:04:16 AM			
Quinones,	Paul	need self drilling screws to install	blinds			
Paul Quinc	ones					
161438	E.Building	Restroom	9/23/2016	108		\$0.00
Medium	Work In Progress	restroom	9/23/2016 2:39:50 PM			
Quinones,	Paul	Can you put in work order for Pau stalls in boy's bathroom. They are them. See admin				
Jennifer Co	orral					
163613	E.Building		10/28/2016	73		\$0.00
Medium	Work In Progress	restrooms	10/28/2016 11:21:24			
Quinones,	Paul	fix or replace stall doors in outside are stating the doors do not close p need privacy.				
Jennifer Co	orral					
166147			12/14/2016	26		\$0.00
Medium	Work In Progress		12/14/2016 1:19:44 PM			
Quinones,	Paul	motors for heating roof top units bl	owerwheels			
Paul Quino	ones					
165156	Main Building	Parking Lot	11/29/2016	41		\$0.00
Medium	Work In Progress	outside	11/29/2016 3:11:31 PM			
Quinones,	Paul	Rope for flag tore and we need to repossible. See Danny/Office for rop				
Jennifer Co	orral					
159780			8/30/2016	132		\$0.00
Medium	Work In Progress		8/30/2016 3:25:14 PM			
Marquez, G	Gerardo	List and order cores for CE Renove project. Plans need to be checked office and returned when core list i You	out form construction			
Dominique	e Esparza					

1/9/2017 3:07:20 PM Page 15 of 122

Total Selected Date Range for Request Dates:7/1/2016 - 12/31/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Area Number Reason **Created Date/Time Actual Comp Date Status Priority Assigned To Description Action Taken Requester Name** Location: Chaparral ES 162728 Kitchen 10/14/2016 87 \$0.00 10/14/2016 10:16:38 High Work In Progress Medina, Eric Food slicer switch not working properly. Corrective action response by 10/23/16 as per Health Insp. SNP Mgr. Maria C. (575) 824-0048 Dino Facio 76 10/25/2016 \$0.00 163408 Medium Work In Progress 10/25/2016 3:57:55 PM Marquez, Gerardo NEED TO ADJ. R.RM. DRS. BETWEEN RMS. 209 AND Gerardo Marquez Count: 25 Work Orders 0 Avg. Age of WO's 61 Total for Chaparral ES \$0.00

1/9/2017 3:07:20 PM Page 16 of 122

Total Selected Date Range for Request Dates:7/1/2016 - 12/31/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Area Number Reason Created Date/Time Actual Comp Date **Status Priority Assigned To Description Action Taken** Requester Name Location: Chaparral High - Pre-K 164850 Parking Lot 11/16/2016 54 \$0.00 Medium 11/16/2016 11:13:59 Work In Progress Pre-K requesting barriers so the high school students Vallejo, Albert don't cross through the parking lot to go to the High school with the cars.

Alfredo Ortiz

Count: 1 Work Orders Avg. Age of WO's 54 Total for Chaparral High - Pre-K 0 \$0.00

1/9/2017 3:07:20 PM Page 17 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID **Deferred By Request Date Target Comp Date Davs** Labor Area Until Aged Hours Area Number Reason Created Date/Time Actual Comp Date Status **Priority** Assigned To Description **Action Taken** Requester Name Location: Chaparral HS 160477 9/8/2016 123 \$0.00 9/8/2016 3:35:56 PM Medium Work In Progress Ontiveros, Guadalupe Attention to grounds Forman need any type of sweeper for grass clippings, please For Pedro grounds keeper. Alfredo Ortiz 11/27/2016 164150 11/6/2016 64 \$0.00 11/6/2016 12:40:20 AM Medium Work In Progress Medina, Eric Monthly-Chaparral HS Range Hood Cleaning - Refer to PMschedule details. Margret Villalobos 11/27/2016 11/6/2016 64 \$0.00 164193 Medium Work In Progress 11/6/2016 12:40:50 AM Monthly-Chaparral HS Fire Suppression Insp. - Refer Medina, Eric to PMschedule details. Margret Villalobos 11/6/2016 64 \$0.00 164146 Medium Work In Progress 11/6/2016 12:40:17 AM Medina, Eric Yearly - Chaparral HS - Grease Trap - Refer to PM schedule details. Margret Villalobos Field House Classroom 10/28/2016 73 \$0.00 163593 Medium Work In Progress 10/28/2016 8:21:20 AM Tellez, Hector In the weight room All the key switches for the lights need to be replaced to regular switches. Alfredo Ortiz 166070 Field House Athletic Field 12/13/2016 27 \$0.00 12/13/2016 8:00:26 AM Medium Work In Progress Fence Please fixfence on Lobo Lane east side. There is an Ontiveros, Guadalupe area with a hole as if the fence was cut, another where post is coming down and another that looks like it needs to be stretched. (Michelle Ballard, AP) Mireya Meza A-Wing Roof 12/12/2016 28 \$0.00 166044 12/12/2016 3:47:18 PM Medium Work In Progress Need to raise vent pipe in Nurse roof the smell is going Appelzoller, Fred in the heater unit and the class rooms. Alfredo Ortiz

1/9/2017 3:07:20 PM Page 18 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Da	te Range for Request Building	Dates:7/1/2016 - 1 Area	2/31/2016 Order By Deferred By		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	_	Created Date/Time	-	Aged	Hours	
Assigned '	То	Description			Action Taken			
Requester	Name							
Location:	Chaparra	II HS						
166033	A-Wing			12/12/2016		28		\$0.00
Medium	Work In Progress			12/12/2016 3:41:16 PM	I			
Appelzolle	r, Fred	Need to install	Eye wash in Nurse	office.				
Alfredo Or	tiz							
158589		Cafeteria		8/12/2016		150		\$0.00
High	Work In Progress	Cafeteria		8/12/2016 10:39:29 AM	1			
Appelzolle		over the stand a we are steppin someone migh	g all over the drippi	tenance on it because ng water and ne water is coming out				
Mireya Me		01		4.4 /0.0 /0.04.0		40		# 0.00
165243	Q-Wing	Classroom		11/30/2016		40		\$0.00
Medium	Work In Progress	Q4		11/30/2016 11:10:39				
Tellez, He	ctor	Need male and (Mr. Lawler, Q		outlets for iron work.				
Mireya Me								
161830	G-Wing	Exterior		9/30/2016		101		\$0.00
Medium	Work In Progress			9/30/2016 9:16:58 AM	1			
Tellez, He	ctor		ide lights stayon al Electrical checked.	l dayneed to check				
Alfredo Or	tiz							
161170	R-Wing	Classroom		9/20/2016		111		\$0.00
Medium	Work In Progress	R kitchen		9/20/2016 9:02:54 AM	1			
Tellez, He	ctor			lone as to putting corative lights. (Mrs.				
Mireya Me	za							
163323	A-Wing	Classroom		10/25/2016		76		\$0.00
Medium	Work In Progress	A-109		10/25/2016 8:50:05 AM	1			
Tellez, He	ctor			ground socket in the fixed. (Mrs. Karns, A-				
Mireya Me	za							
164065	Field House	Roof		11/4/2016		66		\$0.00
Medium	Work In Progress			11/4/2016 1:17:52 PM	1			
Tellez, He	ctor	Need to install office.	powerforasplitsy	stem for Trainers				
		UIIICE.						

1/9/2017 3:07:20 PM Page 19 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID **Deferred By Request Date Target Comp Date Days** Labor Area Until Aged Hours Created Date/Time Actual Comp Date Status Area Number Reason **Priority Action Taken Assigned To** Description Requester Name Location: Chaparral HS 163350 Parking Lot 10/25/2016 76 \$0.00 10/25/2016 12:43:56 Medium Work In Progress The parking lot lights do not turn on at night, need Tellez, Hector Electrician to work on timer. Alfredo Ortiz Athletic Field 9/14/2016 117 160860 \$0.00 Medium 9/14/2016 3:49:03 PM Work In Progress Tellez. Hector Softball Coach needs an extra outlet on the other end of the batting cage. Alfredo Ortiz 52 F-Wing Classroom 11/18/2016 \$0.00 165002 Medium Work In Progress 11/18/2016 3:57:03 PM Tellez, Hector Need a wire mold electric outlet in the middle of the class room in F-7 to remove extension cords. Ahazard. Alfredo Ortiz Classroom 8/18/2016 144 \$0.00 159002 Q-Wing Medium Work In Progress 8/18/2016 12:23:10 PM Tellez, Hector I need 2 - 230V I-Phase plug for plasma cutter and for TIG machine. (Mr. Lawler, Q4) Mireya Meza Mechanical 10/26/2016 75 \$0.00 163449 Medium Work In Progress 10/26/2016 3:04:36 PM Ortiz, Alfredo Need to order and install roof access labels Alfredo Ortiz 166273 A-Wing Library 12/16/2016 24 \$0.00 Medium Work In Progress Libraryrestroom 12/16/2016 11:48:12 Ortiz, Alfredo Fluores cent bulb is out in the staff bathroom in the library work room. (Ms. DeVine, library) Mireya Meza 11/4/2016 \$0.00 164055 Medium Work In Progress 11/4/2016 9:12:52 AM Ortiz, Alfredo Need to replace several security light bulbs outside the wings. Alfredo Ortiz

1/9/2017 3:07:20 PM Page 20 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID **Deferred By Request Date Target Comp Date Days** Labor Area Until Aged Hours Created Date/Time Actual Comp Date Status Area Number Reason **Priority Action Taken Assigned To** Description Requester Name Chaparral HS Location: 166072 A-Wing Exterior 12/13/2016 27 \$0.00 **Guard Shack** 12/13/2016 8:03:53 AM Medium Work In Progress Ortiz, Alfredo Please paint door in guard shack, it is very worn out and peeling. (Michelle Ballard) Mireya Meza 144 \$0.00 159006 H-Wing Dressing Room 8/18/2016 8/18/2016 1:14:48 PM Medium Work In Progress Boys locker Solis, Lorenzo Please put an air conditioning unit in the boys PE office. (Coach Y) Mireya Meza Kitchen 75 10/26/2016 \$0.00 163425 High Work In Progress 10/26/2016 9:32:57 AM Villalobos, David Need to replace the oven control faces not working properly. SNP Mgr. Juanita M. (575) 824-4461 Dino Facio Kitchen 12/13/2016 27 \$0.00 166076 Work In Progress 12/13/2016 9:03:20 AM High Villalobos, David Oven not working properly (not heating). SNP Mgr. Juanita M. (575 824-4461 Dino Facio I-Wing Classroom 12/14/2016 26 \$0.00 166160 High Work In Progress Band room 12/14/2016 3:38:13 PM Flores, Pete The band truck's air brake valve came loose and came off. I did screw back in but am afraid that it might get stripped when pulled again. (Mr. Rios, band) Mireya Meza 10/31/2016 70 \$0.00 163694 High Work In Progress 10/31/2016 9:20:00 AM Villalobos, Jose JD 997 Mower need to check rear tire bolts. Guadalupe Ontiveros Kitchen 11/3/2016 \$0.00 163989 67 High Work In Progress 11/3/2016 10:50:34 AM Villalobos, David One of the ovens not heating at the proper range. SNP Mgr. Juanita M. (575) 824-4461

1/9/2017 3:07:20 PM Page 21 of 122

Dino Facio

730 - Work Orders In Progress (Fiscal Year)

Selected Da	te Range for Request Building	Dates:7/1/2016 - 1 Area	2/31/2016 Order By Lo Deferred By		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•	Created Date/Time	-	Aged	Hours	
Assigned ⁻	Го	Description			Action Taken			
Requester	Name							
Location:	Chaparra	al HS						
161427	Q-Wing	Exterior		9/23/2016		108		\$0.00
Medium	Work In Progress			9/23/2016 11:46:47 AM	1			
Tellez, Hed	ctor	The outside lig	hts don't turn on at ni	ght.				
Alfredo Ort	iiz							
165870	H-Wing	Auditorium		12/8/2016		32		\$0.00
High	Work In Progress	Westside		12/8/2016 2:51:03 PM	1			
Tellez, Hed	ctor	working with th	on the west side of the ne key. We have to m se fix. (Mark Rupcich	nanually pull them				
Mireya Mez	za							
158288	C-Wing	Classroom		8/9/2016		153		\$0.00
High	Work In Progress	C6		8/9/2016 10:19:17 AM	1			
Tellez, Hed	ctor	There is no ele working. (Ms. I	ctricityin room C6. W Basden, C6)	all sockets are not				
Mireya Mez	za							
160729	Field House			9/13/2016		118		\$0.00
Medium	Work In Progress			9/13/2016 2:55:54 PM	1			
Tellez, Hed	ctor	before we get Alfredo Ortizfo scheduled to g	ut an electrician to ch Trane involved. Have r details. Field House o on, but apparentlyt edule. Thanks - R. G	them visit with lights are heyare not coming				
Albert Valle	ejo							
165616	E-Wing	Classroom		12/5/2016		35		\$0.00
High	Work In Progress	E4		12/5/2016 8:46:00 AM	1			
Tellez, Hed	ctor		re not working. This i It been able to do labs					
Mireya Mez								
157852	A-Wing	Kitchen		8/3/2016		159		\$0.00
Medium	Work In Progress			8/3/2016 7:57:13 AN	1			
Appelzolle	r, Fred	need High limi for stock?	t switch for boiler to b	e replaced, and one				
Fred Appe	Izoller							
160556		Exterior		9/9/2016		122		\$0.00
Medium	Work In Progress			9/9/2016 12:52:10 PM	1			
Gonzalez,	Salvador	Need to weld o	utside tables to the g	round.				
Alfredo Ort	iz							

1/9/2017 3:07:20 PM Page 22 of 122

WOID	Building	Area Deferred By Un	=	Target Comp Date	Days	Labor	
Priority	Status	Area Number Reason	Created Date/Time	=	Aged	Hours	
Assigned [*]		Description		Action Taken			
Requester							
Location:	Chaparra	al HS					
164317	A-Wing	Mechanical	11/7/2016		63		\$0.00
Medium	Work In Progress		11/7/2016 7:41:00 AM	1			
Vallejo, All	bert	The Electric Fire Pump keeps turning on I some to see what the problem is. It turn Sunday, and today.					
Alfredo Or	tiz						
156908		Exterior	7/22/2016		171		\$0.00
Medium	Work In Progress		7/22/2016 8:07:20 AM	1			
·	Guadalupe	Attention to LUPE Ontiveros Need shade John Deer 3220 and also for 997 Mower					
Alfredo Or	tiz		0/40/0040		450		Φο οο
158572			8/12/2016		150		\$0.00
Medium	Work In Progress		8/12/2016 8:01:52 AM	1			
Ortiz, Alfre	do	Need to anchor small bleachers with ties.		Routed to BM 11/28	/16		
Alfredo Ho	olguin						
162478		Kitchen	10/11/2016		90		\$0.00
High	Work In Progress		10/11/2016 3:12:08 PM	1			
Medina, E	ric	Disposer making loud noise. SNP Mgr. J 824-4461	uanita M. (575)				
Dino Facio							
159574	Field House	Athletic Field	8/26/2016		136		\$0.00
Medium	Work In Progress	Baseballarea	8/26/2016 2:02:34 PN	1			
Ontiveros,	Guadalupe	Please repair green screen on baseball fentrance of school by marque and around screen is torn in many areas and worn out (Mark Rupcich)	darea. The				
Mireya Me	za						
166168	I-Wing	Classroom	12/14/2016		26		\$0.00
Medium	Work In Progress	Band room	12/14/2016 3:46:26 PM	1			
Urquidi, Je	esus	Band room carpet needs cleaning. (Mr. R room)	tios, band				
Mireya Me	za						
165134			11/29/2016		41		\$0.00
Medium	Work In Progress		11/29/2016 12:08:46	3			
Tellez, He	ctor	Line Locates are need at CHS all areas E gym to South of tennis courts to East of p (parking lot/ driveway area), also locates a North of gym between gym and band rocarea.	oaved area are needed				
Dominique	e Esparza						

1/9/2017 3:07:20 PM Page 23 of 122

Total Selected Date Range for Request Dates:7/1/2016 - 12/31/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Area Number Reason **Created Date/Time Actual Comp Date Status Priority Assigned To Description Action Taken** Requester Name Location: Chaparral HS 160842 Athletic Field 9/14/2016 117 \$0.00 Medium 9/14/2016 3:42:59 PM Work In Progress Vallejo, Albert Attention to Albert. Need to repair sidewalks between baseball and softball field broken trip hazard. Also around school several areas need to be replaced. Alfredo Ortiz 175 Q-Wing Mechanical 7/18/2016 \$0.00 156594 7/18/2016 8:59:08 AM Medium Work In Progress Solis, Lorenzo Need to replace GEO thermal water pump. Alfredo Ortiz 0 \$0.00 Count: 44 Work Orders Avg. Age of WO's 84 **Total for Chaparral HS**

1/9/2017 3:07:20 PM Page 24 of 122

Chaparral MS	WOID Priority Assigned Requester	Building Status To	Dates:7/1/2016 - 12/31/2016 Order By Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Medium Work in Progress 12/7/2016 8:20.05 AM Maritza Gonzalez 8/4/2016 3 COMPARTMENT SINK IS LEAKING. SNP MANAGER SANDRA D. 824.4376 Medium Work in Progress 8/4/2016 12:05:09 PM Medium Work in Progress WARMER TAKES TO LONG TO WARM UP. DOORS ARE HANGING A LITTLE FROM HINCES. SNP MANAGER SANDRA D. 824-4376 Maritza Gonzalez Custodial 9/8/2016 10:49:20 AM Medium Work In Progress SENESECITA AREGLAR CANDADO DELAS PUERTAS QUE CUMUNICAN EL LOBBY Y MAIN ENTRANCE GRACIAS M. Carmen Perez BIORITA REGLAR CANDADO DELAS PUERTAS QUE CUMUNICAN EL LOBBY Y MAIN ENTRANCE GRACIAS 8/17/2016 3:27:10 PM Medium Work in Progress Secretaryl Data 8/17/2016 3:27:10 PM Marquez, Gerardo Please put Secretaries office back on master key Gidget Morus Senesecits areglar candado dela office de Gidget se atora la yave GRACIAS M. Carmen Perez Senesecits areglar candado dela office de Gidget se atora la yave GRACIAS M. Carmen Perez Classroom 8/23/2016 1:00:29 PM	Location:		ni MS					
Valia Val	165773			12/7/2016		33		\$0.00
SANDRA D. 824.4376 Maritza Gonzalez	Medium	Work In Progress		12/7/2016 8:20:05 AM	1			
157972	Villalobos	, David		KING. SNP MANAGER				
Medium Work In Progress 8/4/2016 12:05:09 PM Medina, Eric WARMER TAKES TO LONG TO WARM UP. DOORS ARE HANGING A LITTLE FROM HINGES.SNP MANAGER SANDRA D. 824-4376 Maritza Gonzalez 160452 Custodial 9/8/2016 10:49:20 AM Marquez, Gerardo SENESECITA AREGLAR CANDADO DELAS PUERTAS QUE CUMUNICAN EL LOBBY Y MAIN ENTRANCE GRACIAS M. Carmen Perez 158917 Main Building Office 8/17/2016 3:27:10 PM Marquez, Gerardo Please put Secretaries office back on master key Gidget Mora 159295 Office 8/23/2016 10:00:29 PM Medium Work In Progress 8/23/2016 1:00:29 PM Marquez, Gerardo senesecits areglar candado dela office de Gidget se atora la yave GRACIAS M. Carmen Perez 159293 Classroom 8/23/2016 12:56:13 PM Medium Work In Progress 8/23/2016 12:56:13 PM Marquez, Gerardo senesecita areglar puerta dela classroom 301 del corridor 300 esta caida se esta que brando porque topa en el marco dela puerta GRACIAS Marquez, Gerardo senesecita areglar puerta dela classroom 301 del corridor 300 esta caida se esta que brando porque topa en el marco dela puert	Maritza Go	onzalez						
Medina, Eric WARMER TAKES TO LONG TO WARM UP. DOORS ARE HANGING A LITTLE FROM HINGES.SNP MANAGER SANDRA D. 824-4376 Maritza Gonzalez 160452 Custodial 9/8/2016 10:49:20 AM Medium Work In Progress 9/8/2016 10:49:20 AM Marquez, Gerardo SENESECITA AREGLAR CANDADO DELAS PUERTAS QUE CUMUNICAN EL LOBBY Y MAIN ENTRANCE GRACIAS PUERTAS QUE CUMUNICAN EL LOBBY Y MAIN ENTRANCE GRACIAS M. Carmen Perez 158917 Main Building Office 8/17/2016 3:27:10 PM Medium Work In Progress Secretaryl Data 8/17/2016 3:27:10 PM Marquez, Gerardo Please put Secretaries office back on master key Gidget Mora 159295 Office 8/23/2016 1:00:29 PM Medium Work In Progress 8/23/2016 1:00:29 PM Marquez, Gerardo senesecits areglar candado dela office de Gidget se atora la yave GRACIAS 139 M. Carmen Perez Classroom 8/23/2016 1:2:56:13 PM Medium Work In Progress 8/23/2016 12:56:13 PM Marquez, Gerardo senesecita areglar puerta dela class room 301 de corridor 300 esta caida se esta que brando porque topa en el marco dela puerta GRACIAS M. Carmen Perez Kitchen <t< td=""><td>157972</td><td></td><td></td><td>8/4/2016</td><td></td><td>158</td><td></td><td>\$0.00</td></t<>	157972			8/4/2016		158		\$0.00
Maritza Gonzalez	Medium	Work In Progress		8/4/2016 12:05:09 PN	Л			
160452	Medina, E	ric	ARE HANGING A LITTLE FROM	HINGES.SNP				
Medium Work In Progress 9/8/2016 10:49:20 AM Marquez, Gerardo SENESECITA AREGLAR CANDADO DELAS PUERTAS QUE CUMUNICAN EL LOBBY Y MAIN ENTRANCE GRACIAS M. Carmen Perez 158917 Main Building Office 8/17/2016 3:27:10 PM Medium Work In Progress Secretary/ Data 8/17/2016 3:27:10 PM Marquez, Gerardo Please put Secretaries office back on master key Gidget Mora 159295 Office 8/23/2016 1:00:29 PM Medium Work In Progress 8/23/2016 1:00:29 PM Marquez, Gerardo senesecits areglar candado dela office de Gidget se atora la yave GRACIAS 48/23/2016 1:00:29 PM M. Carmen Perez 159293 Classroom 8/23/2016 1:00:29 PM Medium Work In Progress 8/23/2016 1:2:56:13 PM Medium Work In Progress 8/23/2016 1:2:56:13 PM Marquez, Gerardo senesecita areglar puerta dela classroom 301 del corridor 300 esta caida se esta que brando porque topa en el marco dela puerta GRACIAS M. Carmen Perez Kitchen 12/2/2016 2:33:27 PM Mediun, Eric Reach In Refrigerator at 48° (Internal Temp) SNP Mgr.	Maritza Go	onzalez						
Marquez, Gerardo SENESECITA AREGLAR CANDADO DELAS PUERTAS QUE CUMUNICAN EL LOBBY Y MAIN ENTRANCE GRACIAS M. Carmen Perez M. Medium Perez Medium Work In Progress Secretary/ Data 8/17/2016 3:27:10 PM Marquez, Gerardo Please put Secretaries office back on master key Gidget Mora 159295 Office 8/23/2016 1:00:29 PM Medium Work In Progress 8/23/2016 1:00:29 PM Marquez, Gerardo senesecits areglar candado dela office de Gidget se atora la yave GRACIAS M. Carmen Perez 159293 Classroom 8/23/2016 12:56:13 PM Medium Work In Progress 8/23/2016 12:56:13 PM Marquez, Gerardo senesecita areglar puerta dela class room 301 del corridor 300 esta caida se esta que brando porque topa en el marco dela puerta GRACIAS M. Carmen Perez 165446 Kitchen 12/2/2016 38 High Work In Progress Kitchen 12/2/2016 2:33:27 PM Medina, Eric Reach In Refrigerator at 48° (Internal Temp) SNP Mgr.	160452		Custodial	9/8/2016		123		\$0.00
M. Carmen Perez 158917 Main Building Office 8/17/2016 145 Medium Work In Progress Secretary/ Data 8/17/2016 3:27:10 PM Marquez, Gerardo Please put Secretaries office back on master key Gidget Mora 159295 Office 8/23/2016 139 Medium Work In Progress 8/23/2016 1:00:29 PM Marquez, Gerardo senesecits areglar candado dela office de Gidget se atora la yave GRACIAS M. Carmen Perez Classroom 8/23/2016 139 Medium Work In Progress R/23/2016 12:56:13 PM Marquez, Gerardo senesecita areglar puerta dela classroom 301 del corridor 300 esta caida se esta que brando porque topa en el marco dela puerta GRACIAS Marquez, Gerardo senesecita areglar puerta dela classroom 301 del corridor 300 esta caida se esta que brando porque topa en el marco dela puerta GRACIAS 38 M. Carmen Perez Kitchen 12/2/2016 2:33:27 PM Medina, Eric Reach In Refrigerator at 48° (Internal Temp) SNP Mgr.	Medium	Work In Progress		9/8/2016 10:49:20 AM	1			
158917 Main Building Office 8/17/2016 145 Medium Work In Progress Secretary/ Data 8/17/2016 3:27:10 PM Marquez, Gerardo Please put Secretaries office back on master key Gidget Mora 159295 Office 8/23/2016 139 Medium Work In Progress 8/23/2016 1:00:29 PM Marquez, Gerardo senesecits areglar candado dela office de Gidget se atora la yave GRACIAS 139 M. Carmen Perez Classroom 8/23/2016 139 Medium Work In Progress 8/23/2016 12:56:13 PM Marquez, Gerardo senesecita areglar puerta dela class room 301 del corridor 300 esta caida se esta que brando porque topa en el marco dela puerta GRACIAS M. Carmen Perez Kitchen 12/2/2016 38 High Work In Progress 12/2/2016 2:33:27 PM Medina, Eric Reach In Refrigerator at 48° (Internal Temp) SNP Mgr.	Marquez, (Gerardo	PUERTAS QUE CUMUNICAN E					
Medium Work In Progress Secretary/ Data 8/17/2016 3:27:10 PM Marquez, Gerardo Please put Secretaries office back on master key Gidget Mora 159295 Office 8/23/2016 139 Medium Work In Progress 8/23/2016 1:00:29 PM Marquez, Gerardo senesecits areglar candado dela office de Gidget se atora la yave GRACIAS M. Carmen Perez 159293 Classroom 8/23/2016 139 Medium Work In Progress 8/23/2016 12:56:13 PM Marquez, Gerardo senesecita areglar puerta dela classroom 301 del corridor 300 esta caida se esta que brando porque topa en el marco dela puerta GRACIAS M. Carmen Perez Kitchen 12/2/2016 38 High Work In Progress Reach In Refrigerator at 48° (Internal Temp) SNP Mgr. Reach In Refrigerator at 48° (Internal Temp) SNP Mgr.	M. Carme							
Marquez, Gerardo Please put Secretaries office back on master key Gidget Mora 159295 Office 8/23/2016 1:00:29 PM Medium Work In Progress 8/23/2016 1:00:29 PM Marquez, Gerardo senesecits areglar candado dela office de Gidget se atora la yave GRACIAS M. Carmen Perez 159293 Classroom 8/23/2016 12:56:13 PM Medium Work In Progress 8/23/2016 12:56:13 PM Marquez, Gerardo senesecita areglar puerta dela classroom 301 del corridor 300 esta caida se esta que brando porque topa en el marco dela puerta GRACIAS M. Carmen Perez M. Carmen Perez M. Carmen Perez M. Carmen Perez Reach In Refrigerator at 48° (Internal Temp) SNP Mgr.	158917	Main Building	Office	8/17/2016		145		\$0.00
Gidget Mora 159295 Office 8/23/2016 139 Medium Work In Progress 8/23/2016 1:00:29 PM Marquez, Gerardo senesecits areglar candado dela office de Gidget se atora la yave GRACIAS M. Carmen Perez 159293 Classroom 8/23/2016 139 Medium Work In Progress 8/23/2016 12:56:13 PM Marquez, Gerardo senesecita areglar puerta dela classroom 301 del corridor 300 esta caida se esta que brando porque topa en el marco dela puerta GRACIAS M. Carmen Perez 165446 Kitchen 12/2/2016 38 High Work In Progress 12/2/2016 2:33:27 PM Medina, Eric Reach In Refrigerator at 48° (Internal Temp) SNP Mgr.	Medium	Work In Progress	Secretary/ Data	8/17/2016 3:27:10 PN	Л			
159295 Office 8/23/2016 1:00:29 PM Medium Work In Progress 8/23/2016 1:00:29 PM Marquez, Gerardo senesecits areglar candado dela office de Gidget se atora la yave GRACIAS M. Carmen Perez 159293 Classroom 8/23/2016 12:56:13 PM Medium Work In Progress 8/23/2016 12:56:13 PM Marquez, Gerardo senesecita areglar puerta dela classroom 301 del corridor 300 esta caida se esta que brando porque topa en el marco dela puerta GRACIAS M. Carmen Perez 165446 Kitchen 12/2/2016 2:33:27 PM Medina, Eric Reach In Refrigerator at 48° (Internal Temp) SNP Mgr.	Marquez, 0	Gerardo	Please put Secretaries office bac	ck on master key				
Medium Work In Progress 8/23/2016 1:00:29 PM Marquez, Gerardo senesecits areglar candado dela office de Gidget se atora la yave GRACIAS M. Carmen Perez 159293 Classroom 8/23/2016 12:56:13 PM Medium Work In Progress 8/23/2016 12:56:13 PM Marquez, Gerardo senesecita areglar puerta dela classroom 301 del corridor 300 esta caida se esta que brando porque topa en el marco dela puerta GRACIAS M. Carmen Perez 165446 Kitchen 12/2/2016 38 High Work In Progress 12/2/2016 2:33:27 PM Medina, Eric Reach In Refrigerator at 48° (Internal Temp) SNP Mgr.	Gidget Mo	ra						
Marquez, Gerardo senesecits areglar candado dela office de Gidget se atora la yave GRACIAS M. Carmen Perez 159293 Classroom 8/23/2016 139 Medium Work In Progress 8/23/2016 12:56:13 PM Marquez, Gerardo senesecita areglar puerta dela classroom 301 del corridor 300 esta caida se esta que brando porque topa en el marco dela puerta GRACIAS M. Carmen Perez 165446 Kitchen 12/2/2016 38 High Work In Progress Reach In Refrigerator at 48° (Internal Temp) SNP Mgr.	159295		Office	8/23/2016		139		\$0.00
atora la yave GRACIAS M. Carmen Perez 159293 Classroom 8/23/2016 12:56:13 PM Medium Work In Progress 8/23/2016 12:56:13 PM Marquez, Gerardo senesecita areglar puerta dela classroom 301 del corridor 300 esta caida se esta que brando porque topa en el marco dela puerta GRACIAS M. Carmen Perez 165446 Kitchen 12/2/2016 38 High Work In Progress 12/2/2016 2:33:27 PM Medina, Eric Reach In Refrigerator at 48° (Internal Temp) SNP Mgr.	Medium	Work In Progress		8/23/2016 1:00:29 PN	Л			
Classroom 8/23/2016 139 Medium Work In Progress 8/23/2016 12:56:13 PM Marquez, Gerardo senesecita areglar puerta dela classroom 301 del corridor 300 esta caida se esta que brando porque topa en el marco dela puerta GRACIAS M. Carmen Perez 165446 Kitchen 12/2/2016 38 High Work In Progress 12/2/2016 2:33:27 PM Medina, Eric Reach In Refrigerator at 48° (Internal Temp) SNP Mgr.	Marquez, (Gerardo		a office de Gidget se				
Medium Work In Progress 8/23/2016 12:56:13 PM Marquez, Gerardo senesecita areglar puerta dela class room 301 del corridor 300 esta caida se esta que brando porque topa en el marco dela puerta GRACIAS M. Carmen Perez 165446 Kitchen 12/2/2016 38 High Work In Progress 12/2/2016 2:33:27 PM Medina, Eric Reach In Refrigerator at 48° (Internal Temp) SNP Mgr.	M. Carme	n Perez						
Marquez, Gerardo senesecita areglar puerta dela classroom 301 del corridor 300 esta caida se esta que brando porque topa en el marco dela puerta GRACIAS M. Carmen Perez 165446 Kitchen 12/2/2016 38 High Work In Progress 12/2/2016 2:33:27 PM Medina, Eric Reach In Refrigerator at 48° (Internal Temp) SNP Mgr.	159293		Classroom	8/23/2016		139		\$0.00
corridor 300 esta caida se esta que brando porque topa en el marco dela puerta GRACIAS M. Carmen Perez 165446 Kitchen 12/2/2016 38 High Work In Progress 12/2/2016 2:33:27 PM Medina, Eric Reach In Refrigerator at 48° (Internal Temp) SNP Mgr.	Medium	Work In Progress		8/23/2016 12:56:13 PM	1			
165446 Kitchen 12/2/2016 38 High Work In Progress 12/2/2016 2:33:27 PM Medina, Eric Reach In Refrigerator at 48° (Internal Temp) SNP Mgr.	Marquez, (Gerardo	corridor 300 esta caida se esta q	ue brando porque topa				
High Work In Progress 12/2/2016 2:33:27 PM Medina, Eric Reach In Refrigerator at 48° (Internal Temp) SNP Mgr.	M. Carme	n Perez						
Medina, Eric Reach In Refrigerator at 48° (Internal Temp) SNP Mgr.	165446		Kitchen	12/2/2016		38		\$0.00
	High	Work In Progress		12/2/2016 2:33:27 PN	Л			
Sandra D. (575) 824-4376	Medina, E	ric	Reach In Refrigerator at 48° (Int Sandra D. (575) 824-4376	ernal Temp) SNP Mgr.				

1/9/2017 3:07:20 PM Page 25 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Da	te Range for Request Building	Dates:7/1/2016 - 1 Area	2/31/2016 Order By Lo Deferred By	ocation, Status Until Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•	Created Date/Time		Aged	Hours	
Assigned [•]	То	Description			Action Taken			
Requester	Name							
Location:	Chaparra	al MS						
159865		Kitchen		8/31/2016		131		\$0.00
Medium	Work In Progress			8/31/2016 1:49:42 PN	1			
Medina, E	ric	Vent tube on th (575) 824-4376	ne dryer is torn. SNP S	Mgr. Sandra D.				
Dino Facio)							
163172				10/21/2016		80		\$0.00
Medium	Work In Progress			10/21/2016 1:33:17 PM	I			
Vallejo, Alt	pert		e . Very rusted out ar	lack pipe 90 degree nd needs to be				
Johnny Ac	una							
164357	Main Building	Classroom		11/7/2016		63		\$0.00
Medium	Work In Progress	P-3		11/7/2016 11:48:50 AM	1			
Marquez, 0	Gerardo	door handle ne	eds to be replace.					
Maria Gard	cia							
165303	Phase II New	Classroom		12/1/2016		39		\$0.00
Medium	Work In Progress			12/1/2016 7:44:23 AM	1			
Quinones	, Paul		#301 se nesecita rer allway GRACIAS	mplasarfocos que no				
M. Carmer	n Perez							
161267	Main Building	Classroom		9/21/2016		110		\$0.00
Medium	Work In Progress	several rooms		9/21/2016 12:01:19 PM	I			
Quinones	, Paul	Install blinds o Please see Ma	n classroom door wi ıria G. Castillo.	ndows, and offices.				
Maria Gard	cia							
162738	Main Building	Classroom		10/14/2016		87		\$0.00
Medium	Work In Progress	405B		10/14/2016 11:16:00)			
Quinones	, Paul	Molding needs ~ Requestby N		ing has water marks.				
Maria Gard	cia							
157642	Main Building	Classroom		8/1/2016		161		\$0.00
Medium	Work In Progress	311		8/1/2016 10:12:22 AM	1			
Quinones	, Paul	Cabinet door h needs a handle	inges need screws a	and cabinet door				
Gidget Mo	ra							

1/9/2017 3:07:20 PM Page 26 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Da	ate Range for Request Building	Dates:7/1/2016 - 1	12/31/2016 Order By L Deferred By		ate Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•	-	ne Actual Comp Date	Aged	Hours	
Assigned		Description			Action Taken			
Requeste	r Name							
Location:	Chaparra	al MS						
160640	Main Building	Restroom (Gir	1s)	9/12/20)16	119		\$0.00
Medium	Work In Progress	300 hall RR		9/12/2016 9:52:38	AM			
Quinones	, Paul	Several Light E flush.	Bulbs out. Toilet doe:	s not completely				
Maria Gar	cia							
156411	Main Building	Gym		7/13/20	016	180		\$0.00
Medium	Work In Progress	BpysLocker		7/13/2016 2:19:48	PM			
Quinones	, Paul	please replace	e tile in last stall					
Gidget Mo	ora							
165619				12/5/20	016	35		\$0.00
Medium	Work In Progress			12/5/2016 9:12:24	AM			
Gonzalez,	Salvador	gate needs to l	be weld on hinges to	o open.				
Guadalup	e Ontiveros							
156415	Main Building			7/13/20)16	180		\$0.00
Medium	Work In Progress	Pond		7/13/2016 2:25:34	PM			
Concha, E	Ernesto		area and cut back bu lilypads from pond	shes and trees.				
Gidget Mo								
160266	Main Building	Exterior		9/6/20	116	125		\$0.00
Medium	Work In Progress	Portable 3&4		9/6/2016 9:43:52	AM			
Acuna, Jo	-	Please paint h as portable 1&		e 3&4 same blue color				
Maria Gar								
156416	Main Building	Gym		7/13/20		180		\$0.00
Medium	Work In Progress			7/13/2016 2:30:27	PM			
Quinones		Please paint a locker room Bl		clocker room and PE				
Gidget Mo	ora			2 (2 /2 /				
160449		Restroom		9/8/20		123		\$0.00
Medium	Work In Progress			9/8/2016 10:05:51	AM			
Tellez, He		senesecita ch hhallway GRA	ecar lampara delos CIAS	banos del #100				
M. Carme		Ol-		○ l= /○	140	401		Φο οσ
160367	Main Building	Classroom		9/7/20		124		\$0.00
Medium	Work In Progress	409		9/7/2016 11:36:25	AM			
Tellez, He		Many lights are	e out					
Maria Gar	cia							

1/9/2017 3:07:20 PM Page 27 of 122

WOID Priority Assigned 1 Requester	Building Status o	Dates:7/1/2016 - 12/31/2016 Order By Location, Status Area Deferred By Until Request Date Target Comp Date Area Number Reason Created Date/Time Actual Comp Date Description Action Taken				Days Aged	Labor Hours	Costs
Location:	Chaparra	I MS						
159195				8/22/2016	3	140		\$0.00
Medium	Work In Progress			8/22/2016 3:16:22 PI	М			
Tellez, Hed	ctor	outlet box next to in the restroom (Right now the	o the electrical bed t to be re-installed flu	ne outside of the wall				
Johnny Acı	ına							
157118				7/26/2016	3	167		\$0.00
Medium	Work In Progress			7/26/2016 10:33:39 AM	М			
Tellez, Hed	etor	Data outlet doe	s not work. Please r	eplace				
Gidget Mor	a							
162714				10/13/2016	3	88		\$0.00
Medium	Work In Progress			10/13/2016 4:14:38 PM	Л			
Tellez, Hed	etor	check lights in	boys rest rm. front l	obby.				
Paul Quino	nes							
164155				11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress			11/6/2016 12:40:23 AM	М			
Medina, Er	ic	Monthly-Chapp to PMschedule	oaral MS Range Hoo details.	od Cleaning - Refer				
Margret Vil	alobos							
164316				11/6/2016	3	64		\$0.00
Medium	Work In Progress			11/6/2016 12:42:24 AM	М			
Medina, Er	ic	Yearly - Chapa schedule detail	rral MS - Grease Tra s.	ap - Refer to PM				
Margret Vil	alobos							
164176				11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress			11/6/2016 12:40:37 AM	М			
Medina, Er	ic	Monthly - Chap to PMschedule		ession Insp Refer				
Margret Vil	alobos							
165531				12/4/2016	12/12/2016	36		\$0.00
Medium	Work In Progress			12/4/2016 12:43:28 AM	М			
Acuna, Johnny		Monthly - Chap Refer to PMsch	arral MS Emer. Ligh	nt Test: Monthly-				

1/9/2017 3:07:20 PM Page 28 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2016 - 12/31/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Created Date/Time Actual Comp Date Status Area Number Reason **Priority Action Taken Assigned To** Description Requester Name Location: Chaparral MS 165533 12/4/2016 36 \$0.00 Medium Work In Progress 12/4/2016 12:43:29 AM Monthly - Chaparral MS - Clothes Dryer (Monthly) -Acuna, Johnny Refer to PMschedule details. Margret Villalobos 12/4/2016 1/4/2017 36 \$0.00 165534 Medium Work In Progress 12/4/2016 12:43:30 AM Acuna, Johnny Monthly - Chaparral MS Bleacher Inspection - Refer to PMschedule details. Margret Villalobos 152 \$0.00 8/10/2016 158366 8/10/2016 8:18:35 AM Medium Work In Progress Carbajal, Jimmy needing new floor for wieght rm. @ chm. portable #2. **Paul Quinones** 10/20/2016 81 \$0.00 163086 10/20/2016 9:49:14 AM Medium Work In Progress Gonzalez, Salvador As per Ms. Nouges need to install shade on dug-out home site and visitor safety for foul balls. Guadalupe Ontiveros Count: 33 Work Orders **Total for Chaparral MS** 0 \$0.00 Avg. Age of WO's 104

1/9/2017 3:07:20 PM Page 29 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID **Deferred By Request Date Target Comp Date Days** Labor Area Until Aged Hours Area Number Reason Created Date/Time Actual Comp Date Status **Priority** Assigned To Description **Action Taken** Requester Name Desert Pride HS Location: 163763 11/1/2016 69 \$0.00 Work In Progress 11/1/2016 7:58:06 AM Medium Need to install metal ramp on portable 7 on DP thank Gonzalez, Salvador Sebastian Diaz 34 \$0.00 165700 Cafeteria 12/6/2016 12/6/2016 9:44:29 AM Medium Work In Progress new building Marquez, Gerardo contractor done need to install core to remaining doors to new buildings. David Acosta 55 11/15/2016 \$0.00 164788 Medium Work In Progress 11/15/2016 1:34:08 PM Need to install diamond plate on ramps to all (4) Gonzalez, Salvador portables. If you have any?'s please see Albert. Albert Vallejo 12/7/2016 33 \$0.00 165837 Parking Lot Medium 12/7/2016 4:27:54 PM Work In Progress Chavez, Santos Could you please set timer on the parking lot lights to come on at 4:30 am and to turn off at 6:00pm its dark when custodian arrives in the morning and its dark when students are leaving at night it is a safety concern. thank you Jimmy Carbajal **Portables** 9/16/2016 115 \$0.00 160976 room #11 9/16/2016 8:53:01 AM Medium Work In Progress Chavez, Santos Ballast burn out to one of the light fixtures in class room. David Acosta Exterior 9/15/2016 116 \$0.00 160919 Medium Work In Progress 9/15/2016 3:16:00 PM Ontiveros, Guadalupe Please remove dead palm trees. Consult with maintenance department to see if small palm trees can be purchased and planted. Palm trees are no longer under warranty. Dominique Esparza Count: 6 Work Orders **Total for Desert Pride HS** 0 \$0.00 Avg. Age of WO's 70

1/9/2017 3:07:20 PM Page 30 of 122

WOID	Building	Area Deferred By	· =	Target Comp Date	Days	Labor Hours	
Priority	Status -	Area Number Reason	Created Date/Time	•	Aged	nours	
Assigned		Description		Action Taken			
Requester							
Location:	Desert Ti	rail ES					
165052		Kitchen	11/28/2016		42		\$0.00
High	Work In Progress		11/28/2016 1:42:05 PM				
Villalobos	, David	The tray door on the dishwas Patricia C. (575) 824-3822	her not locking. SNP Mgr.				
Dino Facio	0						
160707			9/13/2016		118		\$0.00
Medium	Work In Progress		9/13/2016 8:56:42 AM	1			
Medina, E	ric	AS PER ENVIRONMENT HE 9.12.16-WALK IN, DAMAGED SEAL. (CORRECTIVE ACTIO	REGRIGERATOR DOOR				
Maritza Go	onzalez						
164613		Kitchen	11/10/2016		60		\$0.00
High	Work In Progress		11/10/2016 3:07:50 PM				
Villalobos	, David	Dryer not working properly. S 3822	NP Mgr. Patricia C. (575)				
Dino Facio	0						
163988		Kitchen	11/3/2016		67		\$0.00
High	Work In Progress		11/3/2016 10:48:15 AN	1			
Villalobos		One of the ovens is not heati SNP Mgr. Pat C. (575) 824-3					
Dino Facio	0	100.1	4.4.4.0./0.04.0				
164616		Kitchen	11/10/2016		60		\$0.00
High	Work In Progress		11/10/2016 3:14:05 PM				
Medina, E		Walk In Door not closing righ (575) 824-3822	t. SNP Mgr. Patricia C.				
Dino Facio	0						
160054		Kitchen	9/2/2016		129		\$0.00
High	Work In Progress		9/2/2016 12:47:44 PM	1			
Medina, E	ric	Walk In Refrigerator door not down below also rubber mole Pat C. (575) 824-3822					
Dino Facio	o						
158705	Main Building	Classroom	8/15/2016		147		\$0.00
Medium	Work In Progress	412	8/15/2016 2:51:30 PM	1			
Acuna, Jol	hnny	Window blind broken					
Julia Elise	-						

1/9/2017 3:07:20 PM Page 31 of 122

WOID Priority Assigned T Requester	Building Status o	Dates:7/1/2016 - 12/31/2016 Order By Lo Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert Ti	rail ES					
166217			12/15/2016		25		\$0.00
Medium	Work In Progress	PORTABLE 411	12/15/2016 11:27:23				
Gonzales,0	-	Please have warehouse pick up EC Portable 411 from DTE to GSAC (C designated for SPED storage) The land labeled Early Childhood; there labeled. The material are from an E closed at DT and will be redistributed can use them.	cafeteria Back Room materials are boxed are 37 items clearly C room that was				
Susie Ram	ios Lara						
159954	Main Building	Classroom	9/1/2016		130		\$0.00
Medium	Work In Progress	417	9/1/2016 11:34:38 AM				
Marquez, G	Gerardo	We need key for portable 417. The and 417 is the same.	key for portable 416				
Elizabeth F	lernandez						
164775		Kitchen	11/15/2016		55		\$0.00
High	Work In Progress		11/15/2016 9:19:44 AM				
,		Freezer door and lock not working closing properly. SNP Mgr. Patricia					
Dino Facio							
164177			11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress		11/6/2016 12:40:38 AM				
Medina, Eri	ic	Monthly - Desert Trail ES - Fire Sup Refer to PMschedule details.	ppression Insp				
Margret Vill	alobos						
165602			12/4/2016	12/10/2016	36		\$0.00
Medium	Work In Progress		12/4/2016 12:44:19 AM				
Acuna, Joh	-	Monthly - Desert Trail ES - Monthly Refer to PMschedule details.	FE Inpsection -				
Margret Vill	alobos		40/4/0040	10/10/0010			Φο οο
165510			12/4/2016	12/12/2016	36		\$0.00
Medium	Work In Progress		12/4/2016 12:43:13 AM				
Acuna, Joh	nny	Monthly - Desert Trail ES- Emer Lig Refer to PMschedule details.	ght Insp:Monthly-				
Margret Vill	alobos						
165511			12/4/2016	12/12/2016	36		\$0.00
Medium	Work In Progress		12/4/2016 12:43:13 AM				
Acuna, Joh	nny	Monthly - Desert Trail ES - Exit Sigr Refer to PMschedule details.	n Insp:Monthly-				
Margret Vill	alobos						

1/9/2017 3:07:20 PM Page 32 of 122

Total Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID **Deferred By Request Date Target Comp Date Davs** Labor Area Until Aged Hours Area Number Reason Created Date/Time Actual Comp Date Status **Priority Action Taken Assigned To** Description Requester Name **Desert Trail ES** Location: 165512 12/4/2016 36 \$0.00 Medium Work In Progress 12/4/2016 12:43:14 AM Monthly - Desert Trail ES -Clothes Dryer (Monthly) -Acuna, Johnny Refer to PMschedule details. Margret Villalobos 12/27/2016 \$0.00 165984 12/11/2016 29 Medium 12/11/2016 12:38:17 Work In Progress Acuna, Johnny Monthly - Desert Trail ES - Playground Insp - Refer to PMschedule details. Margret Villalobos 11/27/2016 11/6/2016 64 \$0.00 164156 Medium Work In Progress 11/6/2016 12:40:24 AM Medina, Eric Monthly - Desert Trail ES - Range Hood Cleaning -Refer to PMs chedule details. Margret Villalobos 10/13/2016 88 \$0.00 162638 Medium Work In Progress 10/13/2016 8:58:31 AM Tellez, Hector DT: Need to connect electrical to Bard refrigeration unit in portable #401. Johnny Acuna 111 Main Building 9/20/2016 \$0.00 161182 Medium Work In Progress 9/20/2016 11:10:58 AM Ontiveros, Guadalupe We need sage shrubs removed because afraid snakes might hide in there and lay down gravel on that area. Elizabeth Hernandez 164144 11/6/2016 64 \$0.00 11/6/2016 12:40:15 AM Medium Work In Progress Yearly - Desert Trail ES - Grease Trap - Refer to PM Medina, Eric schedule details. Margret Villalobos Main Building Classroom 8/26/2016 136 \$0.00 159578 Work In Progress 8/26/2016 2:47:31 PM Medium Tellez. Hector Mrs. Soto needs to have a light installed in her walk in closet

1/9/2017 3:07:21 PM Page 33 of 122

Elizabeth Hernandez

730 - Work Orders In Progress (Fiscal Year)

WOID	Building	Area	2/31/2016 Order By Loc Deferred By	Until Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Created Date/Time	•	Aged	Hours	
Assigned ⁻		Description			Action Taken			
Requester								
Location:	Desert Ti	rail ES						
163088	Main Building	Classroom		10/20/2016		81		\$0.00
Medium	Work In Progress	107		10/20/2016 10:15:35	i			
Acuna, Joh	nny	The nurse offic	e needs to be painted					
Elizabeth H	Hernandez							
163531				10/27/2016		74		\$0.00
Medium	Work In Progress			10/27/2016 12:51:19)			
Solis, Lore	n <i>z</i> o	Need corrugate and #401	ed sheet metal covers	for portable #400				
Johnny Ac	una							
165448				12/2/2016		38		\$0.00
Medium	Work In Progress			12/2/2016 2:51:02 PM	1			
Solis, Lore	n <i>z</i> o		lectric heater installed . (Main Building)	in Room #399				
Johnny Ac	una							
164612				11/10/2016		60		\$0.00
Medium	Work In Progress			11/10/2016 3:03:47 PM	I			
Solis, Lore	n <i>z</i> o	Need a gas val Trail Elem.	ve for boiler heating sy	stem at Desert				
Johnny Ac								
163249	Main Building	Parking Lot		10/24/2016		77		\$0.00
Medium	Work In Progress	parking lot		10/24/2016 12:02:32				
Ronquillo,	Ruben	we need 3 park vice principals	king lotsigns that sayo sign.	office beside the				
	Hernandez							
163591				10/28/2016		73		\$0.00
Medium	Work In Progress			10/28/2016 8:14:22 AM	1			
Ronquillo,	Ruben	Need 2 signs for	or playground.					
		1 sign: For Chil Required)	dren Ages 3-8 Years	(Adult Supervision				
			dren Ages 9-12 Years	(Adult Supervision				
Johnny Ac	una							
163970				11/3/2016		67		\$0.00
Medium	Work In Progress			11/3/2016 8:26:53 AM	1			
Acuna, Joh	nny	Need Heating f	filters for Desert Trail E	Elem.				
Johnny Ac	una							

1/9/2017 3:07:21 PM Page 34 of 122

Total Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID **Deferred By Request Date Target Comp Date Davs** Labor Area Until Aged Hours Area Number Reason Created Date/Time Actual Comp Date Status **Priority** Assigned To Description **Action Taken** Requester Name **Desert Trail ES** Location: 166012 Custodial 12/12/2016 28 \$0.00 12/12/2016 12:51:25 Medium Work In Progress Villalobos, Jose Hola .Jose la aspiradora Num .2234 el jendel no se detiene .por favor de revisarla gracias Laura Sandoval 123 160455 Custodial 9/8/2016 \$0.00 9/8/2016 11:58:24 AM Medium Work In Progress Vasquez, Jose Buenos dias .Jose la aspiradora num. 0048 la extencion esta dando problema, por favor de revisarla gracias Laura Sandoval Custodial 53 11/17/2016 \$0.00 164905 Medium Work In Progress 11/17/2016 10:44:51 Buenos Dias . Jose la aspiradora Num. 0214 no prende Villalobos, Jose se apago de repente y salio chispas por favor de revisarla gracias Laura Sandoval Custodial 12/1/2016 39 \$0.00 165300 Medium Work In Progress 12/1/2016 7:20:55 AM Villalobos, Jose Buenos Dias .Jose la aspiradora Num.0255 el enchufe esta fallando, por favor de revisarla gracias Laura Sandoval 163250 Main Building Parking Lot 10/24/2016 77 \$0.00 Medium Work In Progress 10/24/2016 12:50:01 Vallejo, Albert could you please install a small slab of cement on the southeast corner of the bldg. for the rain runoff by the bus turn around Laura Sandoval 12/1/2016 39 \$0.00 165369 Medium Work In Progress 12/1/2016 3:44:21 PM Vallejo, Albert Playground - Wood-chip upgrade Albert Vallejo 12/6/2016 \$0.00 165703 Medium Work In Progress 12/6/2016 9:57:45 AM WALK IN IS AT 60 DEGREES. SNP MANAGER PAT C. Facio, Dino 12/7/16 As per Eric compressor down will 824-3822 not have in stock. Called A&M at 10:15 Maritza Gonzalez Count: 35 Work Orders Avg. Age of WO's 68 **Total for Desert Trail ES** 0 \$0.00

1/9/2017 3:07:21 PM Page 35 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Dat WOID Priority Assigned 1 Requester	Building Status o	Dates:7/1/2016 - 1 Area Area Number Description	2/31/2016 Order By Loc Deferred By Reason		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Desert V	iew ES						
156602				7/18/2016		175		\$0.00
Medium	Work In Progress			7/18/2016 10:01:24 AM	1			
Gallegos, F	Rafael	Under warranty Tiles that are go be replaced	y etting stained from the	units and need to				
Ruben Orti	Z							
165145				11/29/2016		41		\$0.00
Medium	Work In Progress			11/29/2016 1:14:39 PM	1			
Ortiz, Rube	n	Change all the	airfilters					
Ruben Orti	Z							
163974		Custodial		11/3/2016		67		\$0.00
Medium	Work In Progress			11/3/2016 9:11:50 AM	1			
Herrera, Ma		#FS481V-ES10 time it was take a quarter a the there was som	o need a propane tank O-Mreplaced or repair en for a refill it was or tank and it was mentic ething wrong with the lled to it's full capacity	ed, because last lly brought back with ned to us that	as per Jimmy, w/o w	4010104	tod to Wall	
165862	ya ————————————————————————————————————	Classroom		12/8/2016		32		\$0.00
Medium	Work In Progress	307		12/8/2016 12:29:23 PM		02		Ψ0.00
	-		abla fartha aamautari		•			
Ortiz, Rube		ASSEMBLESIX	able for the computer l	ab. (Gonzalez)				
Guadalupe	e Gonzalez			12/7/2016		33		<u> </u>
165822				12/7/2016		33		\$0.00
Medium	Work In Progress			12/7/2016 3:51:51 PM	Л			
Castillo, Ca		I need the scis Thank you, Ru	sor lift to put up the ro ben	pes of the flag.				
Ruben Orti	Z			0/0/0040		450		Ф0.00
157865				8/3/2016		159		\$0.00
Medium	Work In Progress			8/3/2016 10:07:14 AM	1			
Ontiveros,	Guadalupe		Inder warranty; there is ooks dead. Thank you		No longer under wa Margaret for re-assi		ent back to	
Ruben Orti	Z							
164137				11/6/2016		64		\$0.00
Medium	Work In Progress			11/6/2016 12:40:11 AM	1			
Medina, Er		Yearly - Desert schedule detai	t View ES - Grease Tra ls.	ap - Refer to PM				

1/9/2017 3:07:21 PM Page 36 of 122

WOID Priority	Building Status	Area Deferred By Area Number Reason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date	Days Aged	Labor Hours	
Assigned [*]		Description		Action Taken			
Requester	Name						
Location:	Desert V	iew ES					
164157			11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress		11/6/2016 12:40:25 AM				
Medina, Eı	ric	Monthly - Desert View ES Range to PMschedule details.	Hood Cleaning - Refer				
Margret Vil	lalobos						
161948			10/2/2016		99		\$0.00
Medium	Work In Progress		10/2/2016 12:48:21 AM				
Vallejo, Alb		Monthly - DesertView ES - Storm Refer to PMschedule details.	Sewer Drain Inlets -				
Margret Vil	lalobos		44/0/0040	44/07/0040	0.4		ФО 00
164178			11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress		11/6/2016 12:40:39 AM				
Medina, Ei		Monthly - Desert View ES Fire Sup to PMschedule details.	ppression Insp Refer				
Margret Vil	lalobos		40/7/0040		22		<u>ФО ОС</u>
165814	\\\		12/7/2016		33		\$0.00
Medium	Work In Progress		12/7/2016 3:48:50 PN	l			
Lara, Ralp		The door to the cafeteria is not clo Ruben	osing right. Thank you,				
Ruben Ort	IZ		11/29/2016		41		\$0.00
Medium	Work In Progress		11/29/2016 9:43:42 AM		71		ψ0.00
	Work In Progress	T . 6					
Ortiz, Rube		The flagpole needs repair to instal	li the flags. (Gonzalez)				
	e Gonzalez	Darking Lat	9/15/2016		116		\$0.00
160920	\\\	Parking Lot			110		\$0.00
Medium	Work In Progress		9/15/2016 3:17:38 PN	l			
Gonzalez,		Need 6 guards for the flood drains					
Ruben Ort	iz		0/0/0040		450		# 0.00
157861	Market B		8/3/2016		159		\$0.00
Medium	Work In Progress		8/3/2016 9:57:59 AM				
Gonzalez,		Need a drag made for the Polaris.	Thank you, Ruben				
Ruben Ort	iz				4.		0.5.5.
165143			11/29/2016		41		\$0.00
Medium	Work In Progress		11/29/2016 1:12:56 PM				
Lara, Ralp	h	Room 205 needs a stopper and a Thank you, Ruben	latch to leave it open.				

1/9/2017 3:07:21 PM Page 37 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2016 - 12/31/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Area **Deferred By** Until **Days** Labor Hours Aged Area Number Reason Status Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description Requester Name Location: **Desert View ES** 165717 12/6/2016 34 \$0.00 Medium Work In Progress 12/6/2016 1:47:36 PM Lara, Ralph Could you open a work order for the back kitchen door? Seems that the door closer arm has an issue as it does not closer and it requires additional force to close it. Maritza Gonzalez 11/3/2016 67 \$0.00 163993 Medium Work In Progress 11/3/2016 12:41:15 PM Gonzalez, Salvador We need a metal base for the Little Library. Thank you, Ruben Ruben Ortiz 124 160350 9/7/2016 \$0.00 Work In Progress 9/7/2016 8:41:28 AM Medium Gonzalez, Salvador Guards for the flood drains, I need 6 of them. Thank you, Ruben Ruben Ortiz 9/14/2016 117 \$0.00 160816 Medium Work In Progress 9/14/2016 10:19:50 AM Castillo, Carlos KITCHEN NEEDS BACK DOOR BELL INSTALED. SNP MANAGER ELIZABETH D. 589.2425 Maritza Gonzalez Count: 19 Work Orders Avg. Age of WO's 81 Total for Desert View ES \$0.00

1/9/2017 3:07:21 PM Page 38 of 122

Castillo, Car Karla Quesa 163707	ada Work In Progress rlos	Kitchen C-WING AS PER FERNANDO MONCAYO NI CONNECT ELECTRICAL WATER I THE KITCHEN SINK IN C-WING. TI As per Mr. Yturralde, may you pleas light be put on in all restrooms. That	IEATER UNDER		76		\$0.00
Medium N Castillo, Car Karla Quesa 163707 Medium N	ada Work In Progress	C-WING AS PER FERNANDO MONCAYO NI CONNECT ELECTRICAL WATER I THE KITCHEN SINK IN C-WING. TI As per Mr. Yturralde, may you pleas	10/25/2016 9:04:35 AM EED OUTLETS TO HEATER UNDER HANK YOU!!!				\$0.00
Castillo, Car Karla Quesa 163707 Medium	ada Work In Progress	AS PER FERNANDO MONCAYO NI CONNECT ELECTRICAL WATER IT THE KITCHEN SINK IN C-WING. THE KITCHEN SINK IN C-WING.	EED OUTLETS TO HEATER UNDER HANK YOU!!!		70		
Karla Quesa 163707 Medium	ada Work In Progress rlos	CONNECT ELECTRICAL WATER FOR THE KITCHEN SINK IN C-WING. T	HEATER UNDER HANK YOU!!! 10/31/2016		70		
163707 Medium	Work In Progress rlos				70		
Medium \	rlos				70		
	rlos		10/31/2016 12:00:02				\$0.00
Castillo, Car							
	ano	g Do paron in an room boilio. Inai					
Elisa Santill							
164068			11/4/2016		66		\$0.00
Medium \	Work In Progress		11/4/2016 1:46:58 PM				
Ontiveros, Jo	oe	May I please have someone replace the restroom located in front of the re thank you.					
Elisa Santilla	ano						
165020		Kitchen	11/28/2016		42		\$0.00
High \	Work In Progress		11/28/2016 9:06:51 AM				
Gonzalez, Sa	alvador	Need bracket welded on fan motor. (575) 882-6784	SNP Mgr. Irma V.				
Dino Facio							
165256			11/30/2016		40		\$0.00
Medium \	Work In Progress	Vehicle #135	11/30/2016 3:24:59 PM				
Flores, Pete		vehicle #135 spilling oil. Need to ha provided.	ve fix and loaner				
		thank you					
Cora Ramire	ez						
164954			11/18/2016		52		\$0.00
Medium \	Work In Progress		11/18/2016 8:12:10 AM				
Medina, Eric	;	WALK IN IS AT 50 DEGREES. SNP V. 882.6784	MANAGER IRMA				
Maritza Gonz	zalez						
164000			11/3/2016		67		\$0.00
Medium \	Work In Progress		11/3/2016 2:39:37 PM				
Moncayo, Fe	ernando	May I please have someone check it working outside near the doors arouthe pre-k please. Thank you.		Asp Cali, route to BN	M 11/7/16	5	

1/9/2017 3:07:21 PM Page 39 of 122

Margret Villalobos

Selected Da WOID	Building	Dates: 7/1/2016 - 1 Area	2/31/2016 Order By Lo Deferred By		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•	Created Date/Time	•	Aged	Hours	
Assigned	То	Description			Action Taken			
Requester	Name							
Location:	GAC							
164341				11/7/2016		63		\$0.00
Medium	Work In Progress			11/7/2016 9:09:55 AM	1			
Moncayo,	Fernando		ave someone change ed in front of the rece k you.					
Elisa Sant	tillano							
164343				11/7/2016		63		\$0.00
Medium	Work In Progress			11/7/2016 10:10:10 AM	1			
Moncayo,	Fernando		oved from the wall in filled in. When proje e the holes.					
		the floor moldin	ng is falling off					
Cora Ram	irez							
162546				10/12/2016		89		\$0.00
Medium	Work In Progress			10/12/2016 9:14:41 AM	1			
Moncayo,	Fernando	in the building.	ave all the restrooms May I also please ha vell. Thank you.					
Elisa Sant	tillano							
162547				10/12/2016		89		\$0.00
Medium	Work In Progress			10/12/2016 9:18:42 AM	1			
Moncayo,	Fernando		ave a few tiles to be ere broken off when you.					
Elisa Sant	tillano							
165856				12/8/2016		32		\$0.00
Medium	Work In Progress			12/8/2016 11:14:27 AM	1			
Moncayo,		have a new peg Calixto office.	g board that needs to	be hung up in				
Cora Ram	irez							
164179				11/6/2016		64		\$0.00
Medium	Work In Progress			11/6/2016 12:40:39 AM	1			
Medina, E	ric	Monthly - GAC schedule detai	Fire Suppression In ls.	sp Refer to PM				

1/9/2017 3:07:21 PM Page 40 of 122

			Togress (i		ai j				Tota
Selected Da WOID	ite Range for Request Building	Dates:7/1/2016 - 1 Area	2/31/2016 Order By Loc Deferred By		uest Date	Target Comp Date	Days	Labor	Cost
Priority	Status	Area Number	Reason	Created D	ate/Time	Actual Comp Date	Aged	Hours	
Assigned ¹	То	Description				Action Taken			
Requester	Name								
Location:	GAC								
164170					11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress			11/6/2016 12	2:40:33 AM	1			
Medina, E	ric	Monthly - GAC schedule detai	Range Hood Cleanir ls.	ng - Refer to PM					
Margret Vil	llalobos								
164135					11/6/2016		64		\$0.00
Medium	Work In Progress			11/6/2016 12	2:40:09 AM	1			
Medina, E	ric	Yearly - GAC - details.	Grease Trap - Refer	to PM schedule					
Margret Vil	llalobos								
160786				!	9/14/2016		117		\$0.00
Medium	Work In Progress			9/14/2016 8	3:05:45 AM	1			
Moncayo,	Fernando	and batteries v	to be replace cordles von't last, manifold ga ks,small tube cutter, k	uge has a broken					
Fernando	Moncayo								
Count: 16	Work Orders	P	Avg. Age of WO's 66	i		Total for	GAC	0	\$0.00

1/9/2017 3:07:21 PM Page 41 of 122

Total Selected Date Range for Request Dates:7/1/2016 - 12/31/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Area Until **Days** Labor **Deferred By** Aged Hours Area Number Reason Status Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description Requester Name Location: GAC - Pre-K 158602 Parking Lot 8/12/2016 150 \$0.00 Medium Work In Progress 8/12/2016 11:39:45 AM We would like to eliminate one parking space towards Moncayo, Fernando the entrance of our paved parking lot by the light post. It is next to a NO parking space. Our bus is having difficulty turning in due to its wide turns. Leticia Tangonan Exterior 8/29/2016 133 \$0.00 159659 Medium Work In Progress 8/29/2016 11:37:53 AM Request sprinkler system for outdoor trees and planters. Ontiveros, Guadalupe Amanda Flores 11/29/2016 41 \$0.00 165126 Medium Work In Progress Vehicle #57 11/29/2016 11:11:28 suburban 57 at the GAC light (letter) have turn on saying Flores. Pete that it needs an oil change soon Laura Vazquez \$0.00 11/9/2016 61 164502 Medium Work In Progress playground 11/9/2016 10:07:11 AM Rodriguez, Arturo please empty out trash can located in the play ground Leticia Tangonan Count: 4 Work Orders Total for GAC - Pre-K Avg. Age of WO's 96 0 \$0.00

1/9/2017 3:07:21 PM Page 42 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Da	ite Range for Request Building				Target Comp Date	Dovo	Labor	Costs
Priority	Status	Area Area Number	Deferred By	Until Request Date Created Date/Time	Target Comp Date	Days Aged	Hours	
Assigned		Description	iteason	Groutou Buto/Timo	Action Taken	_		
Requester		•						
Location:	Gadsden	ES						
164509		Custodial		11/9/2016		61		\$0.00
Medium	Work In Progress			11/9/2016 11:34:10 AM	1			
Chavez, S	antos	need to change teachers lounge	e light bulbs in wom e	en staff rr by the				
Jose Pino	n							
161162				9/20/2016		111		\$0.00
Medium	Work In Progress			9/20/2016 8:04:15 AM	1			
Ontiveros,	Joe	Needed 1/2 at have in Servies	nd 3/4 Pexand Char s truck.	nnel lock tool set to				
Joe Ontive	eros							
165786		Custodial		12/7/2016		33		\$0.00
Medium	Work In Progress			12/7/2016 12:10:38 PM	1			
Pacheco, I	Hector	girls rr lincoln h flushing	nallwaylast stall get	stuck and keeps				
Jose Pino	n							
164171				11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress			11/6/2016 12:40:34 AM	1			
Medina, E	ric	Monthly-Gads to PMschedule	den ES - Range Hoo e details .	od Cleaning - Refer				
Margret Vi	llalobos							
164172				11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress			11/6/2016 12:40:35 AM	1			
Medina, E	ric	Monthly-Gads to PMschedule	den ES - Fire Suppre e details .	ession Insp - Refer				
Margret Vi	llalobos							
164133				11/6/2016		64		\$0.00
Medium	Work In Progress			11/6/2016 12:40:07 AM	1			
Medina, E	ric	Yearly - Gadsd schedule detail	len ES - Grease Tra ls.	p - Refer to PM				
Margret Vi	llalobos							
160043		Classroom		9/2/2016		129		\$0.00
Medium	Work In Progress	106		9/2/2016 10:54:14 AM	1			
Escobar, [David		ıst fan are not workir ppreciate your assis	ng at this stance in this matter				
Loraine G	andara							

1/9/2017 3:07:21 PM Page 43 of 122

WOID Priority Assigned Requester		Area Area Number Description	Deferred By Reason	=	nte Target Comp Date ne Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Gadsden	ES						
165403		Kitchen		12/2/20	016	38		\$0.00
High	Work In Progress			12/2/2016 7:39:46	AM			
Villalobos,	David	3 compartmen H. (575) 882-34	tsink notholding wat 410	er. SNP Mgr. Laura				
Dino Facio)							
166200		Kitchen		12/15/20)16	25		\$0.00
High	Work In Progress			12/15/2016 7:45:10	AM			
Villalobos,	David	Serving Line cl (575) 882-3410	ogged not draining. (SNP Mgr. Laura H.				
Dino Facio)							
162632		Kitchen		10/13/20	016	88		\$0.00
High	Work In Progress			10/13/2016 8:36:58	AM			
Villalobos,		Washing mach B. (575) 882-34	nine not working prop 410	erly. SNP Mgr. Laura				
Dino Facio)	Mitch an		44/40/06	24.0			ФО ОО
164581		Kitchen		11/10/20		60		\$0.00
High	Work In Progress			11/10/2016 9:04:35	AM			
Villalobos,		Stand drain line 3410	es leaking. SNP Mgr.	Laura H. (575) 882-				
Dino Facio)	Vitab an		44/40/00	04.0			<u>ФО 00</u>
164589		Kitchen		11/10/20		60		\$0.00
High	Work In Progress			11/10/2016 9:15:55	AM			
Villalobos,		Secure vegetal 882-3410	ole sink (loose). SNP	Mgr. Laura H. (575)				
Dino Facio)	Table 1		4.4.4.0.10.6				
164579		Kitchen		11/10/20		60		\$0.00
High	Work In Progress			11/10/2016 8:58:54	AM			
Medina, Eı	ic	lce build up on (575) 882-3410	entrance of freezer.	SNP Mgr. Laura H.				
Dino Facio)							
164585		Kitchen		11/10/20	016	60		\$0.00
High	Work In Progress			11/10/2016 9:09:06	AM			
Medina, Eı	ric	Need Ice make (575) 882-3410	er filters replaced. SN	IP Mgr. Laura H.				
Dino Facio)							

1/9/2017 3:07:21 PM Page 44 of 122

Total Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Area Number Reason Created Date/Time Actual Comp Date **Priority Status Assigned To Description Action Taken** Requester Name Location: Gadsden ES 164490 Kitchen 11/9/2016 61 \$0.00 Work In Progress 11/9/2016 8:15:34 AM High Curtain replacements for Walk In Refrigerator and Medina, Eric Freezer. SNP Mgr. Laura H. (575) 882-3410

Dino Facio

Count: 15 Work Orders Avg. Age of WO's 65 Total for Gadsden ES 0 \$0.00

1/9/2017 3:07:21 PM Page 45 of 122

WOID Priority Assigned	Building Status	Area Deferred By Area Number Reason Description	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Requeste		2000 iption		Action randin			
Location:		HS					
156087			7/7/2016		0		\$0.00
Medium	Work In Progress		7/7/2016 10:16:29 AM	7/7/2016			
Martinez,	Salvador	Need a shop vac for cleaning pum Agrease gun and grease for greas Afaucet and sink for cleaning labe tubing for transferring liquids to co	sing motors. equipment.				
Salvador	Martinez						
159480			8/25/2016		137		\$0.00
Medium	Work In Progress		8/25/2016 10:53:13 AM	1			
Medina, E	Eric	OVENS- PLEASE ORDER 6' CAS INSTALL. MAINTENANCE WILL A ARE READY TO ASSIST.					
Maritza Go	onzalez						
156387			7/13/2016		180		\$0.00
Medium	Work In Progress		7/13/2016 7:43:08 AN	1			
Marquez,	Gerardo	Remove cores and prep for new hadoors.	ardware on cafeteria				
David Esc	cobar						
164567			11/10/2016		60		\$0.00
Medium	Work In Progress		11/10/2016 8:29:21 AN	1			
Ontiveros	, Guadalupe	Paint field side of the backstop (c questions. (Paint - Gloss Maroon)	all Albert) for				
Albert Val	lejo						
161183			9/20/2016		111		\$0.00
Medium	Work In Progress		9/20/2016 11:23:25 AM	1			
Lara, Ralp	oh	Requested by Velia-The Cafeteria Mailbox Key, mailbox # 130. The r -keyed and 3 keys need to be ma mailboxneed to be made to Ms. Fr	mailbox needs to be re de. Cost of re-keying				
Velia Alar	con						
164908			11/17/2016		53		\$0.00
Medium	Work In Progress		11/17/2016 2:20:48 PM	I			
Hernande	ez, Guillermo	replace transformer at CTE works	hop BCU.				
David Esc	cobar						
159363		Kitchen	8/24/2016		138		\$0.00
High	Work In Progress		8/24/2016 7:37:21 AN	1			
Chavez, S		Kitchen back door buzzard not wo Frances B. (575) 882-5522	orking SNP Mgr.				
Dino Faci	0						
1/0/2017	3:07:21 PM						46 of 123

1/9/2017 3:07:21 PM Page 46 of 122

WOID Priority Assigned	Building Status	Dates:7/1/2016 - 12/31/2016 Order By Loca Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester		Description		Action Taken			
Location:	Gadsden	не					
	Gaustien		0/00/0040		400		A 0 00
161749		Kitchen	9/29/2016		102		\$0.00
High	Work In Progress		9/29/2016 12:22:16 PM				
Chavez, S	antos	Light above back door to kitchen bro Frances B. (575) 882-5522	ken. SNP Mgr.				
Dino Facio	0						
158605			8/12/2016		150		\$0.00
Medium	Work In Progress		8/12/2016 11:49:18 AM	I			
Chavez, S	antos	please on the tech building south we compactor Steel Light Poles are not we the morning thank you					
Luis Sauc	edo						
158884			8/17/2016		145		\$0.00
Medium	Work In Progress		8/17/2016 10:03:35 AM	I			
Chavez, S	antos	light pole on south side l=of campus a BM for pole count.	are out. please see				
David Esc	obar						
159183			8/22/2016		140		\$0.00
Medium	Work In Progress		8/22/2016 1:22:38 PM	1			
Appelzolle	er, Fred	please check float device in girls gym is not shutting off or pumping out water					
David Esc	obar						
158573			8/12/2016		150		\$0.00
Medium	Work In Progress		8/12/2016 8:02:25 AV	I			
Escobar, [David	Need to anchor small bleachers with	ties.	Routed to BM 11/28	3/16		
Alfredo Ho	olguin						
160024			9/2/2016		129		\$0.00
Medium	Work In Progress		9/2/2016 8:03:36 AV	I			
Escobar, I	David	media for coolers at varsity gym. 44x	48x12				
David Esc	obar						
159655			8/29/2016		133		\$0.00
Medium	Work In Progress		8/29/2016 11:08:42 AV	I			
Escobar, [_	KITCHEN- WET CEILING TILES POS MANAGER FRANCES B.	SSIBLE LEAK.SNP				

1/9/2017 3:07:21 PM Page 47 of 122

Maritza Gonzalez

Total Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID **Request Date Target Comp Date Davs** Labor Area **Deferred By** Until Aged Hours Area Number Reason Created Date/Time Actual Comp Date Status **Priority Assigned To** Description **Action Taken** Requester Name Gadsden HS Location: 165642 12/5/2016 35 \$0.00 Medium Work In Progress 12/5/2016 2:18:12 PM Escobar, David CHECMICAL ROOM-OVEN CLEANER BUSTED DAMAGED WALL AND TILES LIFTING SNP MANAGER FRANCES B. 882.5522 Maritza Gonzalez 12/14/2016 26 \$0.00 166195 Medium Work In Progress 12/14/2016 6:46:15 PM Escobar, David as per coach on the south side lights poles the timer need to be adjust is to dark for the students (safety) and co-workers. thank you Luis Saucedo Kitchen 11/4/2016 66 \$0.00 164050 High Work In Progress 11/4/2016 8:22:24 AM Medina, Eric Reach-In refrigerator on Red & Green side is starting to drain water again. SNP Mgr. Frances B. (575) 882-5522 Dino Facio 8/18/2016 144 \$0.00 158993 Work In Progress 8/18/2016 11:00:29 AM Medium Requested by Mr. Anthony Sapien Rm. 515 CTE Lara, Ralph Building Panther Hut-Sometime during the week of July 25th, Mr. Sapien went into the Panther Hut and found a key stuck in the cylinder of the Panther Hut Kitchen Pantry. The key was removed from the cylinder, but the key to that door does not lock the pantry any more. Mr. Sapien needs this fixed as soon as possible since he has NOT been able to lock the door all these weeks. Velia Alarcon \$0.00 8/18/2016 144 158996 Medium Work In Progress 8/18/2016 11:12:36 AM Lara, Ralph Requested by Velia-Work Order # 158586 and 157872 HAVE NOW BEEN COMPLETED. However, the

cylinder was complete changed. There are two teachers sharing this classroom and one of the teacher already had a key, but not CANNOT access the classroom. One teacher has been given a key already, but now I need two more keys made as soon as possible.

two more keys made as soon as possible.

Velia Alarcon

1/9/2017 3:07:21 PM Page 48 of 122

Total Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID **Request Date Target Comp Date Davs** Labor Area **Deferred By** Until Aged Hours Area Number Reason Created Date/Time Actual Comp Date Status **Priority Assigned To** Description **Action Taken** Requester Name Gadsden HS Location: 159955 Main Building Office 9/1/2016 130 \$0.00 9/1/2016 11:42:49 AM Medium Work In Progress nurses office Lara, Ralph This is for Gadsden ELEM not the high school. We have 3 file cabinets with no keys. Could you please make keys for all 3. Colleen Runyan Office 7/26/2016 167 \$0.00 157137 Nursing Center Medium Work In Progress 7/26/2016 1:39:29 PM Lara, Ralph Requested by Minnie Singh for Nurse's Office-Needs keys made for one of the filing cabinets and the medication cabinets, as soon as possible please. CHECK WITH MINNIE FOR NUMBER OF KEYS THAT NEED TO BE MADE. Velia Alarcon 158078 New Admin Bldg 8/5/2016 157 \$0.00 Medium Work In Progress 8/5/2016 2:04:44 PM Requested by Velia for Mail Box# 30-The key does not Lara, Ralph unlock the mailbox. We're having a hard time turning the key. Velia Alarcon 12/12/2016 28 \$0.00 165993 Medium Work In Progress 12/12/2016 8:21:33 AM Lara, Ralph requesting key made for portables at GHS. See BM for portable. David Escobar 156384 Cafeteria 7/12/2016 181 \$0.00 Work In Progress 7/12/2016 4:00:14 PM Medium Marquez, Gerardo AS PER ALLEN JOURNEY (GEN CON) NEED TO CHANGE OPOUT CORES FOR NEW DR. HARDWARE. Gerardo Marquez 11/3/2016 67 \$0.00 163986 Medium Work In Progress 11/3/2016 10:23:51 AM Lara, Ralph Requested by Mr. Francisco Velez-Teacher has lost set of keys or keys have been stolen. Teacher cannot find keys. Keys are 1HK3, HE1, HE43, HE125, HE157, HK9, and Q13. Cost of re-keying and/or replacing keys need to be made to Mr. Francisco Velez. Teacher is also the Head Wrestling Coach and a new set of keys is needs as soon as possible. Since the Wrestling Season has begun. Velia Alarcon

1/9/2017 3:07:21 PM Page 49 of 122

Total Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID **Request Date Target Comp Date Davs** Labor Area **Deferred By** Until Aged Hours Created Date/Time Actual Comp Date Status Area Number Reason **Priority Assigned To** Description **Action Taken** Requester Name Gadsden HS Location: 163167 10/21/2016 80 \$0.00 Medium Work In Progress 10/21/2016 11:13:58 Requested by Ms. Rebecca Rodriguez for Back Gate by Lara, Ralph Haas ville Rd.-Please have gate key changed and provide a copy to Velia Alarcon only. The request is to provide security and safety to the G.H.S. Campus. In addition please follow up with Ms. Rebecca Rodriguez an approval or denied request. Velia Alarcon 12/9/2016 31 \$0.00 165938 Medium Work In Progress 12/9/2016 2:33:24 PM Hernandez, Guillermo replace burnt relayand wires at band portable. David Escobar 12/14/2016 26 \$0.00 166186 Work In Progress Medium 12/14/2016 3:54:01 PM UTV15-05 needs fuel. Carrasco, Danny David Escobar 7/27/2016 166 \$0.00 157279 Medium Work In Progress 7/27/2016 7:11:49 PM Lara, Ralph please as per coach on the girls gym in the locker room the door needs to be replace is very damage and he has value items the cost a lot of money. thank you Luis Saucedo 12/8/2016 32 \$0.00 165845 Medium Work In Progress 12/8/2016 9:45:53 AM as per Mr. Giron on the main office faculty restroom the Lara, Ralph partitions are vandalize with a knife needs to be replace.i tries to take off but no luck. thank you Luis Saucedo 10/17/2016 \$0.00 162881 Medium Work In Progress 10/17/2016 3:55:25 PM Ontiveros, Guadalupe Requested by Mr. William Dickson for Baseball and Softball Fields-Need to get the fields lined grass burned where lines go and infield trimmed. Softball will be holding games on Sundayup until December 2nd (game prep both fields). Velia Alarcon

1/9/2017 3:07:21 PM Page 50 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID **Request Date Target Comp Date Davs** Labor Area **Deferred By** Until Aged Hours Area Number Reason Created Date/Time Actual Comp Date Status **Priority Assigned To** Description **Action Taken** Requester Name Gadsden HS Location: 160040 9/2/2016 129 \$0.00 Work In Progress 9/2/2016 10:45:04 AM Medium Requested by Coach Scott Spivey for Tennis Courts-Not Ontiveros, Guadalupe all, but most of the bottom fence around the Tennis Courts is curled up. to the point where all the balls roll out. Please add bars from post to post to hold down the bottom of the fence where needed. SEE COACH SPIVEY WITH ANY QUESTIONS. Velia Alarcon Classroom 12/6/2016 34 \$0.00 165694 Old English Bldg Medium Work In Progress 12/6/2016 8:58:55 AM Lara, Ralph Requested by Ms. Vicky Aranda Rm. 132 Old English Building-Needs to have door fixed. She's having a hard time closing the door. She would also like a door stop. Velia Alarcon 11/30/2016 165265 40 \$0.00 Medium Work In Progress 11/30/2016 3:31:05 PM Carrasco, Danny requesting cabinate pegs. David Escobar 12/9/2016 \$0.00 165939 Medium Work In Progress 12/9/2016 2:40:41 PM Carrasco, Danny requesting 3/8ths all thread. David Escobar 10/25/2016 \$0.00 163347 Medium Work In Progress 10/25/2016 12:34:21 Gonzalez, Salvador Requested by Mr. Ramon Quiroga Rm. 516 CTE Flower Shop-Installation of a 10 x 12 pergala to be placed outside in the garden area behind the class room. SEE MR. QUIROGA FOR FURTHER INSTRUCTIONS. Velia Alarcon Pool 9/27/2016 104 \$0.00 161598 Medium Work In Progress 9/27/2016 2:16:56 PM Gonzalez, Salvador Need to make some adjustable ground 6" pipe stands for the pool pump house re-circulation pipes. For more details contact Sal or Mario. This is for the welder. Salvador Martinez

1/9/2017 3:07:21 PM Page 51 of 122

Total Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID **Request Date Target Comp Date Days** Labor Area **Deferred By** Until Aged Hours Area Number Reason Created Date/Time Actual Comp Date Status **Priority** Assigned To Description **Action Taken** Requester Name Gadsden HS Location: 162563 10/12/2016 89 \$0.00 Work In Progress 10/12/2016 11:22:38 Medium Requested by Mr. Chris Villa Rm. 519 Annex Building-Flores, Pete The lift gate on the Band Truck is not working. In recent weeks, the gate would have power, but die quickly upon use. Starting the truck would take care of this problem. Today, there is no power at all to the lift-gate control box. Band cannot load large items on the truck until the gate is repaired. Velia Alarcon 12/2/2016 38 \$0.00 165433 Cafeteria (1998) Restroom Medium Work In Progress 12/2/2016 12:42:57 PM Requested by Frances Black for the Cafeteria-The Villalobos, David toilets in the kitchen are backed up. Velia Alarcon 9/2/2016 129 160039 Cafeteria (1998) Cafeteria \$0.00 Medium Work In Progress 9/2/2016 10:38:34 AM Requested by Mr. David Martinez for Cafeteria-There is Ronquillo, Ruben a broken window at on of the front entrances and will need to be replaced. Velia Alarcon 12/15/2016 25 \$0.00 166223 Medium Work In Progress 12/15/2016 1:03:41 PM Escobar, David Requested by Coach Velezfor New Wrestling Room-Needs to have a white board hung up in New Wrestling Room. Velia Alarcon 165442 12/2/2016 38 \$0.00 12/2/2016 1:29:09 PM Medium Work In Progress Escobar, David Requested by Maria Grubaugh for an Outside Light-Light on the outside south east side wall (by Panther Hut) blinks and blinks. Needs to be checked for a short, it's very annoying. Velia Alarcon 165402 12/2/2016 38 \$0.00 Medium Work In Progress 12/2/2016 7:34:16 AM in the old main building in the hallway close to room 102 Escobar, David there is a hole in the drywall. Luis Saucedo

1/9/2017 3:07:21 PM Page 52 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID **Deferred By Request Date Target Comp Date Days** Labor Area Until Aged Hours Area Number Reason Created Date/Time Actual Comp Date Status **Priority** Assigned To Description **Action Taken** Requester Name Gadsden HS Location: 163162 Varsity Gym Gym 10/21/2016 80 \$0.00 10/21/2016 10:55:19 Medium Work In Progress Escobar, David Requested by Mr. David Martinez for Entrance Doors into Varsity Gym-Fix area near doors so they will remain open. PLEASE CONTACT MR. D. MARTINEZ REGARDING ISSUE. Velia Alarcon 73 \$0.00 163599 Classroom 10/28/2016 Medium Work In Progress 10/28/2016 10:14:55 Escobar, David Requested by Ms. Mary Lucero Rm. 605 Science Building-Bookcase in back of class room is missing several shelf support pegs. Shelves are wobbly. One is missing all four pegs and is sitting on top of the unit. Pegs need to be replaced. Velia Alarcon 11/2/2016 163883 68 \$0.00 Medium Work In Progress 11/2/2016 1:00:45 PM Chavez, Santos Requested by Ms. Margarita Miller for Theater Building-One light has a short (5th light) above the stage, even when the light switch is on the off position light flickers. SEE MS. MILLER FOR FURTHER INSTRUCTION. Velia Alarcon 8/3/2016 159 \$0.00 157887 Medium Work In Progress 8/3/2016 1:22:43 PM Chavez, Santos please on the south side by the fence Steel Light Poles are not working is to dark in the morning also around the old English building thank you Luis Saucedo 8/3/2016 159 \$0.00 157938 8/3/2016 4:09:53 PM Medium Work In Progress Chavez, Santos AC unit in room 331 is not working. need to trouble shoot from electric panel to ac. David Escobar 10/18/2016 83 \$0.00 162902 Medium Work In Progress 10/18/2016 9:24:20 AM Chavez, Santos need to hook up new a/c unit at grounds shop.

1/9/2017 3:07:21 PM Page 53 of 122

Guadalupe Ontiveros

Total Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID **Deferred By Request Date Target Comp Date Days** Labor Area Until Aged Hours Created Date/Time Actual Comp Date Status Area Number Reason **Priority Action Taken Assigned To** Description Requester Name Gadsden HS Location: 163587 10/28/2016 73 \$0.00 Medium Work In Progress 10/28/2016 7:39:10 AM Chavez, Santos Need to re-route conduit for the water pump in the green house from below the media to above the media to include the GFI on the east wall. (rusted conduit) Guillermo Hernandez 10/25/2016 76 \$0.00 163349 Medium Work In Progress 10/25/2016 12:38:16 Requested by Mr. Ramon Quiroga Rm. 516 CTE Flower Appelzoller, Fred Shop-Installation of a water faucet for the outside flower beds. Velia Alarcon 11/3/2016 67 \$0.00 163996 11/3/2016 1:03:15 PM Medium Work In Progress Appelzoller, Fred need to order solenoid coils and armature for science Coil # SC-100 and armature # SP-210. David Escobar 11/30/2016 40 \$0.00 165251 Medium Work In Progress 11/30/2016 2:00:09 PM need to have an electrical outlet installed behind Varsity Chavez, Santos Gym stage (where old PAsystem is located) call Silver with questions Cora Ramirez 165415 12/2/2016 \$0.00 Medium Work In Progress 12/2/2016 9:37:24 AM Requested by Mr. Ramon Quiroga Rm. 516 CTE Chavez, Santos Building-For outside electricity. Please provide electricity for water timer. Velia Alarcon 11/15/2016 55 \$0.00 164745 11/15/2016 8:02:07 AM Medium Work In Progress Yearly-Gadsden HS-Mow (0408/0419/0428) Grounds -Villalobos, Jose Refer to PMschedule details. Margret Villalobos

1/9/2017 3:07:21 PM Page 54 of 122

WOID Priority Assigned Requester	Building Status To	Area Number Description	2/31/2016 Order By Lo Deferred By Reason	Until	=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	HS							
164746					11/15/2016		55		\$0.00
Medium	Work In Progress			11/15/20	16 8:02:07 AM				,
Villalobos	-	Yearly - Gadsde Refer to PMsch	en HS- Mow (0408/04						
Margret Vil	llalobos	TOOL TO I WISO	icadic actans.						
164747					11/15/2016		55		\$0.00
Medium	Work In Progress			11/15/20	16 8:02:08 AM	1			
Villalobos	, Jose	Yearly - Gadsde Refer to PMsch	en HS- Mow (0408/04 redule details.	419/0428) Gro	unds -				
Margret Vil	llalobos								
164130					11/6/2016		64		\$0.00
Medium	Work In Progress			11/6/201	6 12:40:05 AM	1			
Medina, E	ric	Yearly - Gadsd schedule detail	en HS - Grease Trap s.	o - Refer to PN	Л				
Margret Vil	llalobos								
164158					11/6/2016		64		\$0.00
Medium	Work In Progress			11/6/201	6 12:40:25 AM	1			
Medina, E	ric	Monthly-Gads PMscheduled	den HS Range Hood etails.	Cleaning - Re	fer to				
Margret Vil	llalobos								
164180					11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress			11/6/201	6 12:40:40 AM	1			
Medina, E		Monthly-Gadso PMscheduled	den HS Fire Suppres etails.	ssion Insp Re	efer to				
Margret Vil	llalobos								
165637		Office			12/5/2016		35		\$0.00
Medium	Work In Progress			12/5/20	16 1:28:27 PN	Л			
Gonzales,	Camilo	on pallets. Deli	te items in Rm. 504. ver to the Instructionarehouse for disposa	al Materials	em				
Theresa R	Ramirez								
156843					7/21/2016		172		\$0.00
Medium	Work In Progress			7/21/201	6 11:12:02 AM	1			
Lara, Ralp	h		os on the south side ne alarms are not wo		he	8/25/16 Assign to Ra APCO- asp Albert	afa, will b	oe installed	d by
Luis Sauc	edo								

1/9/2017 3:07:21 PM Page 55 of 122

WOID Priority Assigned Requester	Building Status To	•	-	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Location:	Gadsden	HS					
158181			8/8/2016		154		\$0.00
Medium	Work In Progress	8/8/2016 1	0:05:49 AN	1			
Vallejo, All	bert	Resurface Locker room office floors.					
Albert Vall	ejo						
166088	Varsity Gym	Gym 1	12/13/2016		27		\$0.00
Medium	Work In Progress	FRANK VELEZ - 12/13/2016	2:12:21 PM	1			
Ontiveros,	Guadalupe	LUPE ONTIVEROS, CAN YOU PLEASE PICKUP ONI (1) WRESTLING MAT FROM SANTA TERESA HS ON WED., JAN 4TH AND TRANSPORT IT OVER TO GHS BY 10AM. THEN PICKUP MAT FROM GHS BY NEXT DAY TO TRANSPORT IT BACK TO STHS BEFORE 3PM. THANK YOU, TERRY					
Terry Alvar	rado	,					
165625			12/5/2016		35		\$0.00
Medium	Work In Progress	12/5/2016 1	0:25:31 AN	1			
Villalobos	, Jose	please the bearing is broken on the right side of the do	olly				
Luis Sauc	edo						
166272		1	12/16/2016		24		\$0.00
Medium	Work In Progress	12/16/20	16 11:27:51				
Villalobos	, Jose	wet and dry fronts queegee broken down #5382					
Luis Sauc	edo						
165768			12/6/2016		34		\$0.00
Medium	Work In Progress	12/6/2016	6:25:32 PN	Л			
Villalobos	, Jose	please i need a back pack vacuum cleaner.					
		thank you					
Luis Sauc	edo	,					
157846			8/2/2016		160		\$0.00
Medium	Work In Progress	8/2/2016	8:05:18 PN	Л			
Carbajal,	Jimmy	please i need cores drill to installed paper dispensers thank you					
Luis Sauc	edo						
162533			10/11/2016		90		\$0.00
Medium	Work In Progress	10/11/2016	6:48:27 PN	1			
Carbajal,	Jimmy	Can you please get me magnetic nut driver set.					
		thank you					
Luis Sauc	edo						
1/9/2017	3:07:21 PM					Page 5	56 of 122

Total Selected Date Range for Request Dates:7/1/2016 - 12/31/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Status Area Number Reason Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description Requester Name Location: Gadsden HS 165729 Grounds Shop 12/6/2016 34 \$0.00 12/6/2016 3:25:20 PM Medium Work In Progress Martinez, Salvador Need to order some tools - long nose needle pliers, duckbill pliers, slip joint pliers, claw hammer, wire strippers, 15' measuring tape, outside and inside caliper, 3' ruler, square, pen flash light, utility knife, utility carrier for retrieving samples and taking meters for analyses. These could be found at Grainger.com Salvador Martinez 12/6/2016 34 \$0.00 165702 Medium Work In Progress 12/6/2016 9:52:49 AM Carrasco, Danny requesting 10 gals of paint. (collie P-2 1005) Paint for old main bldg. David Escobar Count: 71 Work Orders Avg. Age of WO's 85 **Total for Gadsden HS** 0 \$0.00

1/9/2017 3:07:21 PM Page 57 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Da WOID Priority Assigned Requester	Building Status To	Dates:7/1/2016 - 1 Area Area Number Description	2/31/2016 Order By Loc Deferred By Reason		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	MS						
164772		Kitchen		11/15/2016		55		\$0.00
High	Work In Progress			11/15/2016 9:06:11 AM	1			
Soria, Mar	tin	Clean ceiling fa 882-2824	ans in kitchen. SNP M	gr. Teresa P. (575)	Asp Mario, route to I	Martin 11	/28/16	
Dino Facio)							
166213		Custodial		12/15/2016		25		\$0.00
Medium	Work In Progress	0908		12/15/2016 9:59:57 AM	1			
Flores, Pe	te	Please replace Thank you.	e on of the light bulbs o	n the gator 0908				
Martin Sor				40/44/0040				
162437	Gym			10/11/2016		90		\$0.00
Medium	Work In Progress			10/11/2016 7:49:14 AM	1			
Ontiveros,		Remove showe gym.	er colums in boys/gilr	s locker room in				
Albert Vall	ејо			11/4/2016		66		\$0.00
	Mork In Drogram					00		φυ.υυ
Medium	Work In Progress	011011111111111111111111111111111111111	-0. DI	11/4/2016 2:02:10 PN	/1			
Flores, Pe		SNP Vehicle 15	50 - Please wash.					
Maritza Go	nzalez			11/4/2016				\$0.00
164073	W 11 B			11/4/2016		66		\$0.00
Medium	Work In Progress			11/4/2016 2:02:47 PN	/1			
Flores, Pe		SNP Vehicle 17	72 - Please wash.					
Maritza Go	nzalez	O#:		40/45/0040				
166214		Office		12/15/2016		25		\$0.00
Medium	Work In Progress	Rm#123/Ms.		12/15/2016 10:20:23	3			
Herrera, M	ario	Heater is not w	vorking again. My offic	e gets really cold.				
Hilda Adle								
165165	East Mechanical			11/29/2016		41		\$0.00
Medium	Work In Progress			11/29/2016 3:38:57 PM	I			
Hernande	z, Guillermo	Need to replace	e booster pump to boi	ler				
Mario Her	era							
163706	Gym	Gym		10/31/2016		70		\$0.00
Medium	Work In Progress			10/31/2016 11:23:57	•			
Vallejo, Al		need AK sales	to come out and repa	r a basketball court				
Mario Her	ега							

1/9/2017 3:07:22 PM Page 58 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Da	te Range for Request Building	Dates:7/1/2016 - 1 Area	2/31/2016 Order By L Deferred By		te Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	-		ne Actual Comp Date	Aged	Hours	
Assigned [*]	То	Description			Action Taken			
Requester	Name							
Location:	Gadsden	MS						
163897	C-Wing			11/2/20	16	68		\$0.00
Medium	Work In Progress			11/2/2016 2:30:46	PM			
Vallejo, All	pert	Nurses Portab	le - Need to replace	roof.				
Albert Valle	ejo							
162696	Gym			10/13/20	16	88		\$0.00
Medium	Work In Progress			10/13/2016 3:50:21	PM			
Vallejo, All	pert		to come take a look chers one of the cha	at both bleachers in ins broke				
Mario Herr								
165310	Main Building	Office		12/1/20	16	39		\$0.00
High	Work In Progress			12/1/2016 8:40:49	AM			
Carbajal,	Jimmy	Requesting to data entry offic	replace carpet in atto es	endance office and				
Mario Herr	rera							
164129				11/6/20	16	64		\$0.00
Medium	Work In Progress			11/6/2016 12:40:04	AM			
Medina, E	ric	Yearly - Gadsd schedule detai	len MS - Grease Tra ls.	p - Refer to PM				
Margret Vil	llalobos							
164159				11/6/20	16 11/27/2016	64		\$0.00
Medium	Work In Progress			11/6/2016 12:40:26	AM			
Medina, E	ric	Monthly - Gads PMschedule d		od Cleaning - Refer to				
Margret Vil	llalobos							
164838		Kitchen		11/16/20	16	54		\$0.00
High	Work In Progress			11/16/2016 7:52:34	AM			
,		Walk In Refrige 882-2824	erator at 42° SNP M	gr. Teresa P. (575)				
Dino Facio								
165833	Main Building	Office		12/7/20	16	33		\$0.00
Medium	Work In Progress			12/7/2016 3:59:19	PM			
Carbajal, c	Jimmy	attendance offi	eplace carpet in data ce due to bad allerg ⁄/ario for anyquestio	ies and bad order				
Mario Herr	rera							

1/9/2017 3:07:22 PM Page 59 of 122

WOID Priority Assigned 7			Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Gadsden	MS						
163793	Gym	Gym		11/1/2016		69		\$0.00
Medium	Work In Progress			11/1/2016 12:51:25 PM				
Ronquillo,	Ruben	we need Rodrig panels here in the		come out repair some				
Mario Herr	era							
156286	C-Wing	Classroom		7/11/2016		182		\$0.00
Medium	Work In Progress	AVECHS-		7/11/2016 12:49:14 PM				
Chavez, Sa	antos		et in the ceiling to order a.s.a.p. (hood)	connect the projector				
Rosa Que								
166194	C-Wing	Office		12/14/2016		26		\$0.00
Medium	Work In Progress	AVECHS-		12/14/2016 4:52:20 PM				
Gonzales,	Camilo		20 student desks at Union to the mai	and chairs from the n campus (Hood)				
Rosa Que	zada							
164181				11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress			11/6/2016 12:40:41 AM				
Medina, Er	ric	Monthly - Gadso PMschedule de		ression Insp Refer to				
Margret Vil								
163530	Main Building	Hallway/Corrido	or	10/27/2016		74		\$0.00
Medium	Work In Progress			10/27/2016 10:47:25				
Chavez, Sa	antos	have several en	nergency lights ou	it here at GMS				
Mario Herr	era							
166270	Vocational	Classroom		12/16/2016		24		\$0.00
Medium	Work In Progress			12/16/2016 11:02:44				
Herrera, M	ario	Requesting pair	nt to paint cooking	classroom				
Mario Herr	era							
163794	Gym	Gym		11/1/2016		69		\$0.00
Medium	Work In Progress			11/1/2016 12:56:04 PM				
Chavez, Sa	antos	need some ball	ast changed here	in the gym				
Mario Herr	era		-	-				
157317				7/28/2016		165		\$0.00
Medium	Work In Progress			7/28/2016 12:21:02 PM				
Chavez, Sa	_	Need wire exha	ustfan in Room 1					
	era	Need wile exila	uotiairiiriXUUIII T	JO AITA TOZ				

1/9/2017 3:07:22 PM Page 60 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Da WOID Priority	ate Range for Request Building Status	Dates:7/1/2016 - 1 Area Area Number	12/31/2016 Order By Loc Deferred By Reason		Target Comp Date Actual Comp Date	Days Aged	Labor Hours	Costs
Assigned	То	Description			Action Taken			
Requeste	r Name							
Location:	Gadsden	MS						
158262	Main Building			8/9/2016		153		\$0.00
Medium	Work In Progress			8/9/2016 8:01:53 AM	1			
Chavez, S	antos	Please add a c	outlet boxso we can plu	ıg in sprinkler box				
Mario Her	rera							
158263	Band Room			8/9/2016		153		\$0.00
Medium	Work In Progress			8/9/2016 8:02:59 AN	1			
Chavez, S	antos	Requesting ne	ew lighting for band roo	m				
Mario Her	rera							
166065				12/13/2016		27		\$0.00
Medium	Work In Progress			12/13/2016 7:32:59 AM	1			
Chavez, S	antos		electric power to existi the boys and girls lock lle School.					
Guillermo	Hernandez							
164521	Gym	Restroom		11/9/2016		61		\$0.00
Medium	Work In Progress			11/9/2016 12:34:20 PM	l			
Ontiveros	, Joe	Toilet in the boy Please take a Thank you.	ys restroom has low w look at it.	ater pressure.				
Martin Soi	ria							
163973	Gymnasium	Restroom		11/3/2016		67		\$0.00
Medium	Work In Progress			11/3/2016 9:04:32 AM	1			
Ontiveros	, Joe	the time check	e toilet in boys restroor chase and water is pa s to be stuck in there.					
Mario Her								
160526	Main Building	Restroom (Gir	ls)	9/9/2016		122		\$0.00
Medium	Work In Progress			9/9/2016 9:57:46 AM	1			
Ontiveros	, Joe	Clogged sink i take a look at i Thank you	n the girls restroom in t.	the B-wing please				
Martin Soi	ria							
158206	Annex	Restroom (Gir	ls)	8/8/2016		154		\$0.00
Medium	Work In Progress	Annex Girls		8/8/2016 2:58:00 PM	1			
Ontiveros	, Joe	Please repair v Water is alway	water faucet in girls res s running.	troom in the annex.				
Hilda Adle	er							

1/9/2017 3:07:22 PM Page 61 of 122

730 - Work Orders In Progress (Fiscal Year)

WOID	Building	Area	2/31/2016 Order By Lo	Until Request Date	Target Comp Date	Days Aged	Labor Hours	Costs
Priority Assigned	Status	Area Number	Reason	Created Date/Time	Actual Comp Date Action Taken	Ageu	Hours	
Requester		Description			Action raken			
Location:	Gadsden	MS						
				44/4/0040				<u> </u>
164079	Vocational	Classroom		11/4/2016		66		\$0.00
Medium	Work In Progress	Rm#300/Rodri	g	11/4/2016 2:18:23 PN	Л			
Ontiveros,			n is not working. In gets hot but doesn	't bake food evenly.				
Hilda Adle		01		40/40/0040				<u> </u>
165992	Main Building	Classroom		12/12/2016		28		\$0.00
Medium	Work In Progress			12/12/2016 7:57:24 AN	1			
Ronquillo	, Ruben	Requesting to	tint the other side of s	chool (B- Wing)				
Mario Her	rera							
158266				8/9/2016		153		\$0.00
Medium	Work In Progress			8/9/2016 8:05:47 AN	1			
Ontiveros,	Guadalupe	Need to run wa poles)	ater to flower bed in f	ont of school (Flag				
Mario Her	rera							
158268				8/9/2016		153		\$0.00
Medium	Work In Progress			8/9/2016 8:06:38 AN	1			
Ontiveros,	Guadalupe	Need to rewire of B wing	sprinklers in front of L	ibraryand in front				
Mario Her	rera							
159817	Cafeteria	Cafeteria		8/30/2016		132		\$0.00
Medium	Work In Progress	Cafeteria/Quin	0	8/30/2016 5:10:02 PM	Л			
Herrera, N	l ario		e cafeteria doors. The school was back in s					
Hilda Adle	r							
163235				10/24/2016		77		\$0.00
Medium	Work In Progress			10/24/2016 9:52:53 AM	1			
Herrera, M	l ario	requesting filte	rs for A/C, Heater unit	S				
Mario Her	rera							
165200	Annex			11/29/2016		41		\$0.00
Medium	Work In Progress	BookRoom/Gu	JZ	11/29/2016 4:39:53 PM	1			
Herrera, M	_	Walls in book r Thank you.	oom need to be paint	ed please.				
Hilda Adle	er	,						

1/9/2017 3:07:22 PM Page 62 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Date	te Range for Request Building	Dates:7/1/2016 - 1 Area	2/31/2016 Order By L Deferred By		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	-	Created Date/Time	•	Aged	Hours	
Assigned 1		Description			Action Taken			
Requester	Name	-						
Location:	Gadsden	MS						
164516	Annex	Restroom (Girl	s)	11/9/2016		61		\$0.00
Medium	Work In Progress			11/9/2016 12:25:02 PM	I			
Herrera, M	ario	Partition door is it. Thank you	s missing the safety	/latch.please replace				
Martin Sori	а	THATIK YOU						
158059	<u> </u>	Classroom		8/5/2016		157		\$0.00
Medium	Work In Progress	BWing RM#12	1	8/5/2016 10:17:36 AM	1			
Herrera, M	ario	removed. Plea	ainted where a bulle se let me know befo pers i put to cover it	ore you do so i can				
Hilda Adle	<u>r</u>							
158617	Vocational	Classroom		8/12/2016		150		\$0.00
Medium	Work In Progress	Voc		8/12/2016 1:44:50 PM	1			
Herrera, M	ario	Please paint w	as behind smart bo	ard				
Hilda Adle	r							
161108	Main Building			9/19/2016		112		\$0.00
Medium	Work In Progress			9/19/2016 3:12:04 PM	1			
Herrera, M	ario	Requesting Reschool	ed Traffic paint to pa	aint fire line in front of				
Mario Herr	era							
161257	Main Building			9/21/2016		110		\$0.00
Medium	Work In Progress			9/21/2016 7:51:32 AM	1			
Ronquillo,	Ruben		uesting Letters to s OOL" above outside	pell out " GADSDEN of east wing				
Mario Herr	era							
165991				12/12/2016		28		\$0.00
Medium	Work In Progress			12/12/2016 7:56:32 AM	1			
Ontiveros,	Guadalupe	Need grounds baseball and s		ench at Sta Teresa Mid				
Carlos Ca								
165141	C-Wing			11/29/2016		41		\$0.00
Medium	Work In Progress	Nursing		11/29/2016 12:56:51				
Herrera, M	ario	The wind blew Nursing Depar	off the gutter on the	e east side of the				
Priscilla M	artinez							

1/9/2017 3:07:22 PM Page 63 of 122

Total Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID **Deferred By Request Date Target Comp Date Davs** Labor Area Until Aged Hours Created Date/Time Actual Comp Date Status Area Number Reason **Priority Action Taken Assigned To** Description Requester Name Gadsden MS Location: 165927 Gym Storage 12/9/2016 31 \$0.00 12/9/2016 10:52:05 AM Medium Work In Progress Equipment Marquez, Gerardo Please fix door in the gym to the equipment storage, as per Mr. Mora. Thank you Hilda Adler Kitchen 25 \$0.00 166224 12/15/2016 12/15/2016 1:15:15 PM High Work In Progress Villalobos, David Stove knobs not working properly (gas smell). SNP Mgr. Mercedes F. (575) 882-2824 Dino Facio Kitchen 40 11/30/2016 \$0.00 165247 11/30/2016 12:21:47 High Work In Progress Villalobos, David Oven not working smells like gas. SNP Mgr. Teresa P. (575) 882-2824 Dino Facio Kitchen 11/30/2016 40 \$0.00 165222 Work In Progress 11/30/2016 8:01:16 AM High Gas smell in kitchen area ovens and stoves wont turn on Villalobos, David pilot light very low. SNP Mgr. Teresa P. (575) 882-2824 Dino Facio Kitchen 11/7/2016 63 \$0.00 164347 High Work In Progress 11/7/2016 11:00:48 AM Villalobos, David Faucet on the vegetable sink is leaking. SNP Mgr. Teresa P. (575) 882-2824 Dino Facio 162575 Kitchen 10/12/2016 89 \$0.00 10/12/2016 2:03:07 PM High Work In Progress No cold water to the three compartment sink, faucets Villalobos, David are loose and the air gaps leak from the drain. SNP Mgr. Teresa P. (575) 882-2824 Dino Facio 7/11/2016 182 \$0.00 156261 7/11/2016 9:12:39 AM Safety Work In Progress Room 308 does not have running water to eye wash Ontiveros, Joe station asp PM155845.

1/9/2017 3:07:22 PM Page 64 of 122

Mario Herrera

Selected Da WOID	ate Range for Request Building	Dates:7/1/2016 - 12/31/2016 Order By Location Area Deferred By Un		Target Comp Date D	ays Labor	Costs
Priority	Status	Area Number Reason	Created Date/Time	_	ged Hours	
Assigned		Description		Action Taken		
Requeste	r Name					
Location:	Gadsden	MS				
163084			10/20/2016		81	\$0.00
Medium	Work In Progress		10/20/2016 8:53:06 AM			
Ontiveros	, Joe	Repair and label domestic water shut-off	valves.			
Albert Vall	lejo					
166262	•		12/16/2016		24	\$0.00
Medium	Work In Progress		12/16/2016 7:39:57 AM			
Ontiveros	, Joe	Need to raise the vents on the gas regula Boiler and the Annex Bldg.	tor at East			
Albert Vall	lejo					
158569			8/12/2016	1	50	\$0.00
Medium	Work In Progress		8/12/2016 7:59:57 AM			
Herrera, M	<i>M</i> ario	Need to anchor small bleachers with ties		Routed to BM 11/28/16	3	
Alfredo Ho	olguin					
159171	C-Wing		8/22/2016	1	40	\$0.00
Medium	Work In Progress		8/22/2016 11:54:28 AM			
Vasquez,	Jose	Sprinklers at early college annex are not v	working			
Mario Her	rera					
158094		Kitchen	8/5/2016	1	57	\$0.00
High	Work In Progress		8/5/2016 3:35:05 PM			
Chavez, S	Santos	Need kitchen bathroom light fixture replace exposed SNP Mgr. Teresa P. (575) 882-2				
Dino Faci	0					
159494		Kitchen	8/25/2016	1	37	\$0.00
High	Work In Progress		8/25/2016 12:59:10 PM			
Chavez, S	Santos	Electrical plug in the Kitchen office not sa when in use SNP Mgr. Teresa P. (575) 88				
Dino Faci	0					
Count: 57	Work Orders	Avg. Age of WO's 83		Total for Gadsden M	IS 0	\$0.00

1/9/2017 3:07:22 PM Page 65 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID **Deferred By Request Date Target Comp Date Davs** Labor Area Until Aged Hours Area Number Reason Status Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description Requester Name La Union ES Location: 161725 Custodial 9/29/2016 102 \$0.00 Medium Work In Progress 9/29/2016 8:23:45 AM SHOWER SCRUBBER 3510122302707 BOTTOM Villalobos, Jose awaiting price quote on parts as of SCRUBBING PLATE IS ONLY HALF-WAY ON. 11/10/2016 BOTTOM WATER FILTER HOSE KEEPS COMING OFF. ALSO BATTERIES DO NOT HOLD CHARGE. Rudy Ramos 12/1/2016 39 \$0.00 165362 Medium Work In Progress 12/1/2016 3:41:50 PM Vallejo, Albert Playground - Wood-chip upgrade Albert Vallejo 11/3/2016 \$0.00 164002 67 Medium Work In Progress 11/3/2016 3:01:58 PM Villalobos. Jose troy-bilt blower gas line brocken need repair, thank you equipment has not been brought in for for your help repair as of 11/10/2016 Patricio Aguilar 11/30/2016 40 \$0.00 165225 Medium Work In Progress 11/30/2016 8:32:36 AM Carrasco, Danny need the use of scissor lift to change the filters in gym thank you for the help Patricio Aguilar 12/2/2016 38 \$0.00 165450 Medium Work In Progress 12/2/2016 3:07:19 PM Ambriz, Juan Girls RR - Sink fell down, need to secure water lines. Vicente Sanchez 11/16/2016 54 \$0.00 164845 Medium Work In Progress 11/16/2016 9:23:52 AM PADLOCK ON WALK IN IS NOT WORKING Lara, Ralph PROPERLY.SNP MANAGER LINDA Y.589-2040 Maritza Gonzalez 12/8/2016 165840 \$0.00 Medium Work In Progress 12/8/2016 7:58:27 AM Aguilar, Patricio wo to myself - need to repair rest room stall door latch for girl restroom old wing Patricio Aguilar

1/9/2017 3:07:22 PM Page 66 of 122

WOID Priority Assigned ⁻ Requester	Building Status To	Dates:7/1/2016 - 12/31/2016 Order By Lo Area Deferred By Area Number Reason Description		arget Comp Date ctual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	La Union	ES					
163508			10/27/2016		74		\$0.00
Medium	Work In Progress		10/27/2016 8:38:14 AM				
Ronquillo,	Ruben	need 1 sign playground 1st to 6th w	vith adult supervision				
Patricio Ag			·				
165622			12/5/2016		35		\$0.00
Medium	Work In Progress		12/5/2016 9:44:50 AM				
Ontiveros,	Joe	will be needing sink - faucets - drain rest room old wing	n - hoses - broken girl				
Patricio Ag	uilar						
165224			11/30/2016		40		\$0.00
Medium	Work In Progress		11/30/2016 8:17:04 AM				
Castillo, C	arlos	asper MR Sanchez need front parki - safety hazard	ng post light repaired				
Patricio Ag	uilar						
164182			11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress		11/6/2016 12:40:42 AM				
Medina, Er	ic	Monthly - La Union ES Fire Suppre PMschedule details.	ssion Insp Refer to				
Margret Vil	lalobos						
164160			11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress		11/6/2016 12:40:27 AM				
Medina, Er		Monthly - La Union ES Range Hoo PMschedule details.	d Cleaning - Refer to				
Margret Vil	lalobos		44/0/0040				
164131			11/6/2016		64		\$0.00
Medium	Work In Progress		11/6/2016 12:40:05 AM				
Medina, Er	ic	Yearly - La Union ES - Grease Trapschedule details.	o - Refer to PM				
Margret Vil	lalobos						
166081			12/13/2016		27		\$0.00
Medium	Work In Progress		12/13/2016 11:25:54				
Castillo, C	arlos	asper Mr Sanchez-need more electrion 102. only 1 outlet on that wall.	ct. outlet installed in				
Patricio Ag	uilor						

1/9/2017 3:07:22 PM Page 67 of 122

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2016 - 12/31/2016 Order By Loc Area Deferred By Area Number Reason Description		Farget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Loma Lin	ida ES					
158536		Restroom	8/11/2016		151		\$0.00
Medium	Work In Progress		8/11/2016 3:46:54 PM				
Chavez, S	antos	Need assistance change out ballas restroom	t boys 5th grade wing				
Hector Pa	checo						
164128			11/6/2016		64		\$0.00
Medium	Work In Progress		11/6/2016 12:40:03 AM				
Medina, E	ric	Yearly - Loma Linda ES - Grease Tr schedule details.	rap - Refer to PM				
Margret Vi	llalobos						
164161			11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress		11/6/2016 12:40:27 AM				
Medina, E	ric	Monthly-Loma Linda ES Range Hoo to PMschedule details.	od Cleaning - Refer				
Margret Vi	llalobos						
164183			11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress		11/6/2016 12:40:42 AM				
Medina, E	ric	Monthly-Loma Linda ES Fire Suppreto PMschedule details.	ession Insp Refer				
Margret Vi	llalobos						
165515			12/4/2016	12/12/2016	36		\$0.00
Medium	Work In Progress		12/4/2016 12:43:16 AM				
Pacheco,	Hector	Monthly - Loma Linda ES Emer. Lig Refer to PMschedule details.	ht Test: Monthly -				
Margret Vi							
162895	Main Building	Classroom	10/18/2016		83		\$0.00
Medium	Work In Progress		10/18/2016 8:23:56 AM				
Chavez, S	antos	Need assistance to repair emergen 212,214,101,105,216,Nurse restroction office,Conference room,1 at 5th grade emergencylight,1 emergencylight and entrance,emergencylights in Restroction 4112,110,108.	om,Principals de hallway middle ut main				
Hector Pa							
156906	Main Building	Classroom	7/22/2016		171		\$0.00
Medium	Work In Progress		7/22/2016 7:56:03 AM				
Chavez, S	antos	2 outlets in Sped portable are not wo	orking.				
David Sor	iano						

1/9/2017 3:07:22 PM Page 68 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Da	te Range for Request Building	Dates:7/1/2016 - 1 Area	2/31/2016 Order By Loc Deferred By		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•	Created Date/Time		Aged	Hours	
Assigned ¹	То	Description			Action Taken			
Requester	· Name							
Location:	Loma Lin	nda ES						
163991	Main Building	Mechanical		11/3/2016		67		\$0.00
Medium	Work In Progress	Hot water tank		11/3/2016 12:17:07 PM	1			
Appelzolle	r, Fred	Hot water tank nipple.	in mechanical room le	eaking at 2 inch				
Hector Pa	checo							
161191		Hallway/Corric	dor	9/20/2016		111		\$0.00
Medium	Work In Progress			9/20/2016 12:23:30 PM	1			
Chavez, Sa	antos		ice to replace 6 ballas ing in hallway next to b					
Hector Pa	checo							
166005		Classroom		12/12/2016		28		\$0.00
Medium	Work In Progress	110		12/12/2016 10:16:04	1			
Pacheco, I	Hector	Need to replace	e toilet handle and flo	oat valve.				
Hector Pa	checo							
165051	Main Building	Exterior		11/28/2016		42		\$0.00
Medium	Work In Progress			11/28/2016 1:24:23 PM	1			
Pacheco, I	Hector	Need to replac	e 5 GFI outlets at exter	rior outside walls.				
Hector Pa	checo							
164664				11/14/2016		56		\$0.00
Medium	Work In Progress			11/14/2016 9:05:32 AN	Л			
Villalobos	, David	ICE MACHINE R. 882.4707	IS DOWN. SNP MAN	AGER DOLORES				
Maritza Go	nzalez							
158305		Kitchen		8/9/2016	i	153		\$0.00
Medium	Work In Progress			8/9/2016 1:51:36 PM	Л			
Chavez, Sa	antos		cked out air door unit. lled (This is a matter o					
Gerardo M	1arquez							
163232				10/24/2016		77		\$0.00
Medium	Work In Progress			10/24/2016 9:19:24 AN	Л			
Medina, E	ric	NEEDS DOOR R.882.4707	CLOSURE. SNP MA	NAGER DOLORES				
Maritza Go	nzalez							

1/9/2017 3:07:22 PM Page 69 of 122

WOID Priority Assigned I Requester		Area Area Number Description	Deferred By		arget Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Loma Lin	ida ES						
159725				8/30/2016		132		\$0.00
Medium	Work In Progress	OFFICE		8/30/2016 8:01:06 AM				
Marquez, Gerardo			TO HAVE ALL ELI A LOCK THAT WE	ECTRICAL BOXES CAN OPEN WITH				
Maribel Ga	mboa							
159962		Kitchen		9/1/2016		130		\$0.00
Medium	Work In Progress			9/1/2016 1:00:13 PM				
Pacheco, H	Hector	Need to clean c	eiling tiles and repl	acesome.				
Hector Pac	checo							
160057	Main Building	Hallway/Corrido	or	9/2/2016		129		\$0.00
Medium	Work In Progress			9/2/2016 1:07:20 PM				
Marquez, C	Gerardo	In need of 4 heal	keys for locks on	doors that have hex				
David Sori	ano							
165364				12/1/2016		39		\$0.00
Medium	Work In Progress			12/1/2016 3:42:29 PM				
Vallejo, Alb	pert	Playground - We	ood-chip upgrade					
Albert Valle	ejo							
164056	Main Building	Classroom		11/4/2016		66		\$0.00
Medium	Work In Progress			11/4/2016 9:19:55 AM				
Carbajal, J	immy			placed. It is bulging Preferably tile to be				
David Sori								
166143	Main Building			12/14/2016		26		\$0.00
Medium	Work In Progress			12/14/2016 10:30:09				
Villalobos,	Jose		er is not working pro elieve it is the exten	perly. It shuts down sion cord. Serial				
David Soria	ano							
159729	Main Building	Classroom		8/30/2016		132		\$0.00
Medium	Work In Progress			8/30/2016 8:44:44 AM				
Carbajal, J	immy	middle of the cla		s a big run down the is asking if tile can be #109				

1/9/2017 3:07:22 PM Page 70 of 122

Total Selected Date Range for Request Dates:7/1/2016 - 12/31/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Area Number Reason Created Date/Time Actual Comp Date **Status Priority Assigned To Description Action Taken** Requester Name Location: Loma Linda ES 159728 Main Building Office 8/30/2016 132 \$0.00 Medium 8/30/2016 8:41:47 AM Work In Progress Carpets need to be replaced in main office. All 3 rooms Carbajal, Jimmy have runs in the carpet (Principal, Assistant principal, and secretaries).

David Soriano

Count: 22 Work Orders Avg. Age of WO's 89 Total for Loma Linda ES 0 \$0.00

1/9/2017 3:07:22 PM Page 71 of 122

WOID Priority	Building Status	Area Number Reason Created Date/Tim	te Target Comp Date e Actual Comp Date	Days Aged	Labor Hours	Costs
Assigned Requester		Description	Action Taken			
		. FO				
Location:	Mesquite					
166009		12/12/20		28		\$0.00
Medium	Work In Progress	12/12/2016 11:48	42			
Villalobos	, Jose	vacuum# c08c00000089 Would like to request a new vacuum but if not possible the power cord on vacuum is loose vacuum keep shuting off on its own while its pluged in				
Mario Vall	es					
165368		12/1/20	16	39		\$0.00
Medium	Work In Progress	12/1/2016 3:43:48	PM			
Vallejo, Al	bert	Playground - Wood-chip upgrade				
Albert Vall	ejo					
166008		12/12/20	16	28		\$0.00
Medium	Work In Progress	12/12/2016 10:32	33			
Gonzalez,	Salvador	need to reinforce newly installed window guards.				
Joe Rami	rez					
164066		11/4/20	16	66		\$0.00
Medium	Work In Progress	11/4/2016 1:20:20	PM			
Appelzolle		Please repair 1" back flow preventor at Mesquite Environmental Park.				
Albert Vall	ejo	7//4/00	10	400		Φο οο
156293		7/11/20		182		\$0.00
Medium	Work In Progress	7/11/2016 2:54:46	PM			
Medina, E		REACH IN REFRIGERATOR HAS A LEAK. SNP MANAGER EMILIA C. 233.2341				
Maritza Go	onzalez	10/14/20	16	07		<u> </u>
162726		10/14/20		87		\$0.00
Medium Solis, Lore	Work In Progress	10/14/2016 9:37:27 we continue to have problems with the heating and	AM			
•		cooling unit in portable 609				
Joe Rami	rez					A
161261		9/21/20		110		\$0.00
Medium	Work In Progress	9/21/2016 8:30:36	AM			
Ronquillo	, Ruben	need to replace a section of tubular slide the components are from playworld.				
. – .						

1/9/2017 3:07:22 PM Page 72 of 122

Joe Ramirez

Selected Da WOID Priority Assigned	Building Status	Dates:7/1/2016 - 12/31/20 Area Deferorman Area Number Reas Description	rred By	Until	=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Requester	r Name	-							
Location:	Mesquite	ES							
159207					8/22/2016		140		\$0.00
Medium	Work In Progress			8/22/2	016 3:30:20 PN	Л			
Chavez, S	antos	need elect. to re-wire elounge	emerg light fixt	ure in the sou	th				
Joe Rami	rez								
161519					9/26/2016		105		\$0.00
Medium	Work In Progress			9/26/2	016 3:46:46 PN	Л			
Chavez, S	antos	As per Angela Silvagg electrical drop installe machines asap. Thar	d in lobbyhally						
Sandra Mo	ora								
164184					11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress			11/6/20	16 12:40:43 AN	1			
Medina, E	ric	Monthly - Mesquite ES PMschedule details.	S Fire Suppres	sion Insp I	Refer to				
Margret Vi	llalobos								
166001					12/12/2016		28		\$0.00
Medium	Work In Progress			12/12/2	016 9:11:07 AN	1			
Villalobos	, Margret	AS PER ENVIRONME REPORT- KITCHEN/O FOGGED FOR FLIES	CAFETERIA NI			Em Waiver 12/12/16			
Maritza Go	onzalez								
164162					11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress			11/6/20	16 12:40:28 AN	1			
Medina, E	ric	Monthly - Mesquite ES PMschedule details.	S Range Hood	Cleaning - F	Refer to				
Margret Vi	Ilalobos								
164140					11/6/2016		64		\$0.00
Medium	Work In Progress			11/6/20	16 12:40:13 AN	1			
Medina, E	ric	Yearly - Mesquite ES schedule details.	- Grease Trap	- Refer to Pl	М				
Margret Vi	llalobos								
Count: 13	Work Orders	Avg. Ag	e of WO's 77	,		Total for Mesqui	te ES	0	\$0.00

1/9/2017 3:07:22 PM Page 73 of 122

WOID Priority Assigned ⁻ Requester		Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	North Va	lley ES						
166265				12/16/2016		24		\$0.00
Medium	Work In Progress			12/16/2016 8:13:41 AM				
Vallejo, Alt	pert	bottom of the s	ide and a broken ti I requesting new sli					
Joaquin R	omero							
158610				8/12/2016		150		\$0.00
Medium	Work In Progress			8/12/2016 1:15:35 PM	I			
Medina, Er	ic	Smell coming uroom.	p greese trap from	he washing machine				
Maritza Go	nzalez							
166067				12/13/2016		27		\$0.00
Medium	Work In Progress			12/13/2016 7:40:04 AM				
Gonzalez,	Salvador	Install steel bal pickup-drop off	ards between side at North Valley.	walk and parent				
Alfredo Ho	lguin							
156328				7/12/2016		181		\$0.00
Medium	Work In Progress			7/12/2016 7:47:22 AM				
Chavez, Sa	antos		ast lamp is out byte it still wont lite-ha	achers lounge/both lway byoffice				
Danny Veg	a							
162643				10/13/2016		88		\$0.00
Medium	Work In Progress			10/13/2016 9:49:11 AM				
Chavez, Sa	antos		xit doors hand drye smell and sparks (a	r needs asi) brand-the one on				
Danny Veg	а							
166013				12/12/2016		28		\$0.00
Medium	Work In Progress			12/12/2016 12:54:17				
Chavez, Sa	antos	100 wing found rooms need to	13 exit signs in corr be replaced	idor and in class				
Joaquin R	omero							
166014				12/12/2016		28		\$0.00
Medium	Work In Progress			12/12/2016 12:56:58				
Chavez, Sa	antos	main corridor fo	ound 11 exits sighs	not working and need				

1/9/2017 3:07:22 PM Page 74 of 122

WOID Priority	Building Status	Area Number	2/31/2016 Order By Lo Deferred By Reason	Until	=	Target Comp Date Actual Comp Date	Days Aged	Labor Hours	Costs
Assigned 1		Description	Reason	Orou	iod Bato, Illilo	Action Taken			
Requester									
Location:	North Va	lley ES							
166015					12/12/2016		28		\$0.00
Medium	Work In Progress			12/12	2/2016 12:59:50				
Chavez, Sa	antos	gym and kitche replaced	en area found 6 exits	sighs that nee	ed to be				
Joaquin Ro	omero								
166016					12/12/2016		28		\$0.00
Medium	Work In Progress			12/12/20	016 1:02:33 PM				
Chavez, Sa	antos		lor and class rooms t need to be replaced		sighs				
Joaquin Ro	omero								
162645					10/13/2016		88		\$0.00
Medium	Work In Progress			10/13/20	016 9:55:57 AM				
Ontiveros,	Guadalupe	need 3ea trees	at plygrd area/orde	r and plant					
Danny Veg	a								
164139					11/6/2016		64		\$0.00
Medium	Work In Progress			11/6/20	16 12:40:12 AM				
Medina, Er	ic	Yearly - North \ schedule detai	/alley ES - Grease T s.	rap - Refer to	PM				
Margret Vil	lalobos								
164151					11/6/2016		64		\$0.00
Medium	Work In Progress			11/6/20	16 12:40:20 AM				
Medina, Er	ic	Monthly - North Refer to PMsch	Valley ES - Range I nedule details.	Hood Cleanin	g -				
Margret Vil	lalobos								
164186					11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress			11/6/20	16 12:40:45 AM				
Medina, Er	ic	Monthly - North to PMschedule	Valley ES Fire Supp details.	ression Insp	Refer				
Margret Vil	lalobos								
163429					10/26/2016		75		\$0.00
Medium	Work In Progress			10/26	5/2016 11:06:19				
Romero, Jo	oaquin	attention Dann valleyelement	yCarrasco request fo ary	or new tools fo	r North				
Joaquin Ro	omero								

1/9/2017 3:07:22 PM Page 75 of 122

Total Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID **Deferred By Request Date Target Comp Date Davs** Labor Area Until Aged Hours Area Number Reason Status Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description Requester Name Location: Northern On-Track Pre-K (LM) 162936 10/18/2016 83 \$0.00 Medium Work In Progress 10/18/2016 3:16:09 PM Chavez, Santos requesting for rooms 101,102,103, and 104 to install GFI outlets. we need 1 outlet installed per-room because we have water tanks connected to regular outlets Brian Pacheco 11/29/2016 41 \$0.00 165128 Medium Work In Progress Vehicle #162 11/29/2016 11:22:21 vehicle 162 Monica Social Worker need an oil change. is Flores, Pete over the mileage Laura Vazquez 7/20/2016 173 \$0.00 156798 Medium Work In Progress 7/20/2016 3:52:34 PM Ontiveros, Guadalupe Need to build canopy over sandbox. Albert Vallejo 178 156524 7/15/2016 \$0.00 Medium Work In Progress 7/15/2016 9:53:17 AM Ontiveros, Guadalupe Mr. Lupe Ontiveros, we need for front trees to be trimmed the branches are 3ft. from ground and we also have a dead tree that needs to cut down on back school playground. Thank You! Concepcion Montalvo 10/25/2016 76 \$0.00 163356 Medium Work In Progress 10/25/2016 1:28:16 PM requesting for our front office to be repainted. Romero, Joaquin Brian Pacheco 8/12/2016 150 \$0.00 158568 8/12/2016 7:52:24 AM Medium Work In Progress Carbajal, Jimmy request for a cordless power drill for use in class rooms. Brian Pacheco Count: 6 Work Orders Avg. Age of WO's 117 Total for Northern On-Track Pre-K (LM) \$0.00

1/9/2017 3:07:22 PM Page 76 of 122

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2016 - 12/31/2016 Order By Loc Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Physical	Plant Complex					
166319			12/31/2016		9		\$0.00
Medium	Work In Progress		12/31/2016 12:58:06	•			
Apodaca, I	Mario	Monthly - PPD/GHS - WW Monthly Sa PMschedule details.	ampling - Refer to				
Margret Vil	llalobos						
166017			12/12/2016		28		\$0.00
Medium	Work In Progress		12/12/2016 1:15:43 PM	l			
Villalobos,	, Jose	backpack blower needs to be service	Э.				
Guadalupe	e Ontiveros						
163217			10/23/2016	11/8/2016	78		\$0.00
Medium	Work In Progress		10/23/2016 12:32:32				
Medina, Eı	ric	Monthly - PPD-FS Walk-In Refrigera Refer to PMs chedule details.	tor K-109 (Semi) -				
Margret Vil	llalobos						
163219			10/23/2016	11/8/2016	78		\$0.00
Medium	Work In Progress		10/23/2016 12:32:33	ł			
Medina, Eı	ric	Monthly - PPD-FS Walk-In Freezer K Refer to PMschedule details.	-109A (Semi) -				
Margret Vil	llalobos						
165600			12/4/2016	12/10/2016	36		\$0.00
Medium	Work In Progress		12/4/2016 12:44:17 AN	1			
Herrera, M	lario	Monthly - Physical Plant FE Inspection schedule details.	on - Refer to PM				
Margret Vil							
163433	Main Warehouse		10/26/2016		75		\$0.00
Medium	Work In Progress		10/26/2016 11:21:36				
Gonzalez,	Salvador	Please get quote for getting R panel i Physical plant building.	installed on the				
160800	Purchasing		9/14/2016		117		\$0.00
Medium	Work In Progress		9/14/2016 9:22:32 AN	1			
Gonzalez,	Salvador	PLEASE MAKE MODIFICATIONS TO TRAP DOOR ON SAFE WHICH IS LI TRUCK.	_				
Enrique Bı	riones						

1/9/2017 3:07:22 PM Page 77 of 122

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2016 - 12/31/2016 Order By L Area Deferred By Area Number Reason Description		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:		Plant Complex					
163670		•	10/31/2016		70		\$0.00
Medium	Work In Progress		10/31/2016 1:00:38 AM				·
Herrera, M	ŭ	Monthly - PPD-Warehouse A-16 E Refer to PMschedule details.					
Margret Vi	llalobos						
160015			9/1/2016		130		\$0.00
Low	Work In Progress		9/1/2016 3:59:42 PM	1			
Marquez,	Gerardo	PLEASE PREP AND INSTALL CO AT MAIN. EQUIP. WHS.	RE FOR NEW DOOR				
Gerardo N	Marquez						
161491			9/26/2016		105		\$0.00
High	Work In Progress		9/26/2016 12:23:13 PM	1			
Chavez, S	antos	SNP Warehouse two freezer doors (Electrical door openers) Warehou C. (575) 882-6927					
Dino Faci	0						
165628			12/5/2016		35		\$0.00
Medium	Work In Progress		12/5/2016 10:43:11 AM	1			
Gonzalez,	Salvador	PELASE FABRICATE METAL BIT MOBILE HOME ANCHORS W/GASYOU!	_				
164911	Motor Vehicle		11/17/2016		53		\$0.00
Medium	Work In Progress	vehicle#55	11/17/2016 3:01:18 PM	1			
Flores, Pe	_	please service as required					
Pete Flore		F					
165928	Motor Vehicle		12/9/2016		31		\$0.00
Medium	Work In Progress	vehicle#36	12/9/2016 11:07:05 AM	1			
Flores, Pe	-	service required, please check and					
Pete Flore		oorwoo roquirou, prouco cricontario	adanoo				
157328			7/28/2016		165		\$0.00
High	Work In Progress		7/28/2016 2:44:55 PN				
Marquez,	· ·	North District Kitchens - Need to re Doors. Only SNP Dept should hav Albert, to discuss exactly what nee you proceed). Thank you	ekeyall Kitchen e keys. (Please see				
Albert Vall	ejo						

1/9/2017 3:07:22 PM Page 78 of 122

Total Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID **Deferred By Request Date Target Comp Date Davs** Labor Area Until Aged Hours Area Number Reason Created Date/Time Actual Comp Date Status **Priority Assigned To** Description **Action Taken** Requester Name Location: Physical Plant Complex 165871 12/8/2016 32 \$0.00 12/8/2016 2:54:30 PM Medium Work In Progress SNP WAREHOUSE- FIX BUSTED WATER PIPE Villalobos, David INSIDE WAREHOUSE BY BAY DOOR # 2. Maritza Gonzalez 110 161314 9/21/2016 \$0.00 Medium 9/21/2016 3:51:34 PM Work In Progress Flores. Pete black dump trailer not holding charge. Guadalupe Ontiveros 161497 Main Warehouse 9/26/2016 105 \$0.00 9/26/2016 3:08:31 PM Medium Work In Progress TAGS HAVE ARRIVED FOR THE FOLLOWING Flores. Pete **UTILITY TRAILERS:** 1994 BIG TEXTRAILER - Trailer not on inventory 1994 BIG TEX TRAILER - Trailer not on inventory 2013 CARRY ON TRAILER - TR-STM-0776 2014 CARRY ON TRAILER - TR-STH-0778 2014 CARRY ON TRAILER - TR-GHS-0779 PLATES ARE IN MY OFFICE. Lisa Sanchez 132 159772 Motor Vehicle 8/30/2016 \$0.00 Vehicle #101 8/30/2016 3:09:10 PM Medium Work In Progress Flores, Pete vehicle's rear brakes noisy and emergency brake not holding. please check and advise Pete Flores Motor Vehicle 11/2/2016 68 \$0.00 163874 Medium Work In Progress maintenance 11/2/2016 11:23:09 AM Flores, Pete please order tires for maintenance trucks and requesting inner tubes for gator & mower tires (2 inner tubes) Pete Flores 9/6/2016 125 \$0.00 160286 Work In Progress 9/6/2016 1:55:11 PM Medium Herrera, Mario SNP WAREHOUSE - It appears that we have a roof No longer under warranty. Sent to Margret leak on the dry side isle that's by the freezer walls. I to re-assign - Dominique have attached a picture for your review. Please advise Jose Rodriguez

1/9/2017 3:07:22 PM Page 79 of 122

Location: 159878	Physical			Groutou Buto, rumo	Actual Comp Date Action Taken	Aged	Hours	
	,	Plant Complex						
				8/31/2016		131		\$0.00
Medium	Work In Progress			8/31/2016 3:27:23 PM	Л			
Gonzalez,	Salvador	Good Afternoon I'm cage built that will be up right. And mount wheel hub. Due to smuch	e able to hold (4 ted down in veh) cylinders standing				
Marin Her				40/05/0040		70		
163343	Main Warehouse			10/25/2016		76		\$0.00
Medium	Work In Progress			10/25/2016 11:40:46	5			
Gonzalez,	Salvador	Requesting metals	teps for dock at	new warehouse.				
Danny Ca								
163862	Main Warehouse			11/2/2016		68		\$0.00
Medium	Work In Progress			11/2/2016 8:07:33 AM	1			
Ontiveros	, Joe	Please relocate plu so that they can be p		ıl for washer and dryer 's old shop. thanks.				
162634	Main Warehouse			10/13/2016		88		\$0.00
Medium	Work In Progress			10/13/2016 8:41:39 AN	1			
Herrera, N	<i>M</i> ario	Need a/c copper wa new PPD WHS(eas		d for water leak at				
Danny Ca	rrasco							
165772				12/7/2016		33		\$0.00
Medium	Work In Progress			12/7/2016 8:17:41 AM	1			
Apodaca,	Mario	ghs pool certified po	ool operator clas	ss in Feb. 8 and 9				
Mario Apo	daca							
164045				11/4/2016		66		\$0.00
Medium	Work In Progress			11/4/2016 7:45:00 AN	1			
Herrera, N	<i>M</i> ario	PPD Bldg - please p	aint front entrar	nce doors.				
Jessica H	lerrera							
166068				12/13/2016		27		\$0.00
Medium	Work In Progress			12/13/2016 7:41:26 AN	1			
Herrera, N	<i>M</i> ario	Repaint speed bur westside of GMS lea						
Alfredo Ho	olguin							

1/9/2017 3:07:22 PM Page 80 of 122

WOID	te Range for Request Building	Dates:7/1/2016 - 1 Area	Deferred By		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Aged	Hours	
Assigned '		Description			Action Taken			
Requester	Name							
Location:	Physical	Plant Complex						
155964				7/5/2016		188		\$0.00
Medium	Work In Progress			7/5/2016 8:19:57 AM	1			
Chavez, S	antos	7-5-16 Santos SHOP, Thank you	need outlets for SER	S AND WELDING				
Salvador 0	Gonzalez							
156348	Maintenance			7/12/2016		181		\$0.00
Medium	Work In Progress			7/12/2016 2:35:46 PM	1			
Chavez, S	antos	Need to relocat different area (s	te electrical switch (b see Ruben).	ynew window) to a				
Ruben Ro	nquillo							
156519				7/15/2016		178		\$0.00
Medium	Work In Progress			7/15/2016 7:30:52 AM	1			
Chavez, S	antos	at your earliest in Mary office	convenience, need l	ight switch relocated				
Mary Sitter	S							
159741	Maintenance			8/30/2016		132		\$0.00
Medium	Work In Progress	PPD/ Auto Sho	р	8/30/2016 11:13:09 AM	1			
Chavez, S	antos		e current auto shop l pair or replacement	ighting, and obtain				
Pete Flore	s							
163849				11/1/2016		69		\$0.00
Medium	Work In Progress			11/1/2016 3:57:45 PM	1			
Castillo, C	arlos	Need to order e screwdrivers.	electric saws all and	replacement				
Carlos Ca	stillo							
161339				9/22/2016		109		\$0.00
Medium	Work In Progress			9/22/2016 8:10:44 AM	1			
Lara, Ralp	h	NEED TO ORD OF DIST. WIDE	DER CLASS ROOM I	LOCKS FOR USE				
Ralph Lar	a							
158382	Maintenance	Office		8/10/2016		152		\$0.00
Medium	Work In Progress			8/10/2016 9:58:19 AM	1			
Chavez, S	antos	install power, li	ghting in and data dı	ops for new office				

1/9/2017 3:07:22 PM Page 81 of 122

Santos Chavez

WOID Priority Assigned	Building Status To	Area Area Number Description	2/31/2016 Order By Lo Deferred By Reason		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Requester								
Location:	Physical	Plant Complex						
163785	Main Warehouse			11/1/2016		69		\$0.00
Medium	Work In Progress			11/1/2016 11:24:41 AM	1			
Chavez, Sa	antos		e plumbing/electrica be placed in Jimmy	l for washer and dryer 's old shop. thanks.				
165724	Motor Vehicle			12/6/2016		34		\$0.00
Medium	Work In Progress			12/6/2016 2:46:27 PM	1			
Chavez, Sa	antos	Install a light or Albert.	n the south side of Au	to Shop, please see				
Albert Valle	ejo							
163245				10/24/2016		77		\$0.00
High	Work In Progress	Old SNP		10/24/2016 11:03:22	2			
Chavez, Sa	antos		nstalled 2-220 volt o oot florescent lights i	utlets, 4 Way 110 volt n the old SNP				
Dino Facio)							
163346	Motor Vehicle			10/25/2016		76		\$0.00
Medium	Work In Progress	auto shop		10/25/2016 12:32:51				
Chavez, Sa	antos	please re-wire	lift next to wash bay					
Pete Flore	s							
165627				12/5/2016		35		\$0.00
Medium	Work In Progress	Equip#0512		12/5/2016 10:40:55 AM	1			
Flores, Pe	te	PLEASE SERV THANK YOU!	ICE FORKLIFT #05	12 MAINT. WHS.				
165245	Main Warehouse			11/30/2016		40		\$0.00
Medium	Work In Progress	auto shop		11/30/2016 11:21:52	2			
Flores, Pe	te	requesting 3 to	ggle switches					
Pete Flore	s							
165408	Motor Vehicle			12/2/2016		38		\$0.00
Medium	Work In Progress	TR-0772		12/2/2016 8:39:08 AM	1			
Flores, Pe	te		tires on trailer #0772 or lift to job sites	2. often used to				
Pete Flore	•							

1/9/2017 3:07:22 PM Page 82 of 122

WOID Priority Assigned Requester			Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:		Plant Complex						
	Tilysical			12/5/2016		35		\$0.00
165629	W 11 B					33		φυ.υυ
Medium	Work In Progress			12/5/2016 10:46:04 AM				
Ronquillo,	, Ruben	NEED 2' X 2' ME LOUVERS.	ETAL WINDOW SC	REENS FOR SNP				
Ruben Ro	nquillo							
164492		Pump House		11/9/2016		61		\$0.00
Medium	Work In Progress			11/9/2016 8:21:02 AM				
Apodaca, I	Mario	need to order sp wastewater	pare parts for the U	IV unit to disinfect the				
Mario Apod	daca							
161735				9/29/2016		102		\$0.00
Medium	Work In Progress			9/29/2016 8:34:49 AM				
Apodaca, I	Mario	the annual calib GHS,PPD/GMS	ration of was tewate	er flow meter at				
Mario Apod	daca							
165872				12/8/2016		32		\$0.00
Medium	Work In Progress			12/8/2016 2:55:33 PM	1			
Medina, Er	ric		JSE- FIX INSULATI 1, PIPE IS EXPOS					
Maritza Go	onzalez							
165873				12/8/2016		32		\$0.00
Medium	Work In Progress			12/8/2016 2:58:38 PM	1			
Medina, Er	ric	SNP WAREHOUBUILDUP.	JSE- FREEZER # 5	5 HAS ALOT OF ICE				
Maritza Go	onzalez							
165912				12/9/2016		31		\$0.00
Medium	Work In Progress			12/9/2016 7:55:35 AM				
Medina, Er	ric	for the middle ro	Il up door in the wa	e another work order rehouse. The belt on e put back in place				
Maritza Go	onzalez	-						
164846				11/16/2016		54		\$0.00
Medium	Work In Progress			11/16/2016 9:48:57 AM				
Medina, Er	_		LL CORK BOARDS TERIA AREAS. 2 F					

1/9/2017 3:07:22 PM Page 83 of 122

Maritza Gonzalez

WOID Priority Assigned T Requester	Building Status o	Area Number Description	2/31/2016 Order By L Deferred By Reason		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:		Plant Complex						
161563				9/27/2016		104		\$0.00
High	Work In Progress			9/27/2016 8:27:50 AM				Ψ0.00
,	Work in Togress		e air ventilator not w io C. (575) 882-692	orking properly. SNP				
Dino Facio								
165101				11/29/2016		41		\$0.00
Medium	Work In Progress			11/29/2016 7:43:43 AM				
Hernandez	, Guillermo	Need to relocat	e furnace in mainte	nance storage.				
Guillermo I	Hernandez							
165769				12/7/2016		33		\$0.00
Medium	Work In Progress			12/7/2016 7:35:45 AM				
Hernandez	z, Guillermo	Need to replace	e stick meter.					
Guillermo I	Hernandez	•						
163855	Motor Vehicle			11/1/2016		69		\$0.00
Medium	Work In Progress	vehicle #163		11/1/2016 4:22:33 PM				
Flores, Pet	е	service air bag	light turned on (nee	ds to go to dealer)				
Maria Ruiz			· ·	,				
157202	Motor Vehicle			7/27/2016		166		\$0.00
Medium	Work In Progress	Vehicle #147		7/27/2016 8:54:49 AM				
Flores, Pet	e	check cranking speed	noise when gas is _l	oressed at a slow				
Maria Ruiz				40/40/0040				Φο οο
166073				12/13/2016		27		\$0.00
High	Work In Progress	Vehicle #190		12/13/2016 8:36:33 AM				
Flores, Peter		SNP Van#190 r conditions).	needs all tires repla	ced (all in bad				
Dino Facio 166135				12/14/2016		26		\$0.00
Medium	Work In Progress	Vehicle #117		12/14/2016 8:09:33 AM		20		Ψ0.00
	-							
Flores, Pet		done.	needs complete ser	vice maintenance				
Dino Facio 161346				9/22/2016		109		\$0.00
High	Work In Progress			9/22/2016 9:44:57 AM		. 00		Ψ0.00
,	Work iii Togress	SNP Vehicle#1	36 making noise whection.					
Dino Facio		cor olator dil						

1/9/2017 3:07:22 PM Page 84 of 122

Selected Da WOID	te Range for Request Building	Dates:7/1/2016 - 1 Area	2/31/2016 Order By Lo Deferred By		Date Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•	•	ime Actual Comp Date	A	Hours	
Assigned '		Description			Action Taken			
Requester	· Name							
Location:	Physical	Plant Complex						
163776				11/1/2	2016	69		\$0.00
High	Work In Progress			11/1/2016 10:24:5	8 AM			
,		Need safetyins #142 making tr	spection for SNP Veh ip to LC	icles#54,#131,				
Dino Facio)							
163320	Motor Vehicle			10/25/2	2016	76		\$0.00
Medium	Work In Progress			10/25/2016 8:24:1	1 AM			
Villalobos	, Jose		rburetor to repair ser arburetor on unit is b		parts received on 1	1/07/2016		
Jose Villal	obos							
163965	Purchasing	Custodial		11/3/2	2016	67		\$0.00
Medium	Work In Progress			11/3/2016 8:14:3	6 AM			
Villalobos	, Jose		could you please che it is leaking water fro w hoses.					
Jimmy Ca	rbajal							
164077	Motor Vehicle			11/4/2	2016	66		\$0.00
Medium	Work In Progress	vehicle #187		11/4/2016 2:14:1	3 PM			
Flores, Pe	te	having problem	ns with transmission					
Maria Ruiz	<u>z</u>							
162906	Purchasing			10/18/2	2016	83		\$0.00
Medium	Work In Progress	vehicle # 92		10/18/2016 9:52:1	8 AM			
Flores, Pe	te	losing power						
Pete Flore	S							
158622	Maintenance			8/12/2	2016	150		\$0.00
Medium	Work In Progress			8/12/2016 1:56:4	2 PM			
Carrasco,	Danny		NEW PRICE GUN T IN MAINT. WHS.	O REPLACE OLD				
Danny Ca								
Count: 62	Work Orders	A	vg. Age of WO's 7	9 Tota	I for Physical Plant Cor	nplex	0	\$0.00

1/9/2017 3:07:22 PM Page 85 of 122

WOID Priority Assigned ¹ Requester		Area Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Riverside	ES						
166211				12/15/2016		25		\$0.00
Medium	Work In Progress			12/15/2016 9:03:39 AM				
Lara, Ralpl	า		spector two panic ba I at East side double	ars need to installed e door main				
Mario Mart	inez							
165236				11/30/2016		40		\$0.00
Medium	Work In Progress			11/30/2016 10:35:20				
Martinez, N	<i>l</i> ario	11/30/2016 Requesting we for broken ones		al auger replacement				
Mario Mart	inez							
166206				12/15/2016		25		\$0.00
Medium	Work In Progress			12/15/2016 8:46:16 AM				
Castillo, C	arlos	Need Carlos C middle wing cu	to replace broken e stodial room.	mergencylightin				
Mario Mart	inez							
166207				12/15/2016		25		\$0.00
Medium	Work In Progress			12/15/2016 8:48:26 AM				
Castillo, C	arlos	Need Carlos C middle wing bo	to replace broken e ys restroom.	mergencylightin				
Mario Mart	inez							
166208				12/15/2016		25		\$0.00
Medium	Work In Progress			12/15/2016 8:53:40 AM				
Castillo, C	arlos	electrical plugs	to replace two round at floor level at Libr ed out two way outle	ary. And need him to				
Mario Mart	inez							
163768				11/1/2016		69		\$0.00
Medium	Work In Progress			11/1/2016 8:38:22 AM				
Martinez, N	<i>l</i> ario	Need to replace season.	all air filters for up c	coming winter				
Mario Mart	inez							
165150				11/29/2016		41		\$0.00
Medium	Work In Progress			11/29/2016 2:33:01 PM				
Ambriz, Jos	20	Need lose A to	n fiv faulty heating u	nit for roof top gym-A.				

1/9/2017 3:07:22 PM Page 86 of 122

Total Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID **Deferred By Request Date Target Comp Date Days** Labor Area Until Aged Hours Created Date/Time Actual Comp Date Status Area Number Reason **Priority Action Taken Assigned To** Description Requester Name Riverside ES Location: 164840 Main Building Custodial 11/16/2016 54 \$0.00 11/16/2016 8:09:35 AM Medium Work In Progress La aspiradora no esta levantando basura y el handle no Villalobos, Jose se detiene. Gracias. #0103 Miguel Sonora 151 \$0.00 158492 8/11/2016 Medium Work In Progress 8/11/2016 11:50:53 AM Lara, Ralph Exit back door is not locking. Need to slam the door for the door to be able to close. Mrs. Martinez Norma Martinez 7/22/2016 171 \$0.00 156928 7/22/2016 11:32:51 AM Medium Work In Progress Science Lab -Lara, Ralph Unable to open portable main entrance door. keydoes not go through all the way it seems like something is stock in the cylinder. (Mrs. Peterson) Norma Martinez 11/28/2016 42 \$0.00 165042 Medium Work In Progress 11/28/2016 10:52:03 Flores, Pete Need to tag Tractor (TR-RS-0532) will be used at RS/DV/SP. Guadalupe Ontiveros 8/31/2016 131 \$0.00 159843 8/31/2016 9:07:15 AM Medium Work In Progress Cafeteria Please install door bell for cafeteria back doors for Castillo, Carlos vendors. (Mrs. Nava) Norma Martinez 9/14/2016 117 \$0.00 160798 Medium Work In Progress 9/14/2016 9:18:06 AM BACK DOOR TO KITCHEN NEEDS A FLY BLOWER. Lara, Ralph SNP MANAGER SANTA N. 589.2550 Maritza Gonzalez 11/6/2016 11/27/2016 64 \$0.00 164185 Medium Work In Progress 11/6/2016 12:40:44 AM Monthly - Riverside ES Fire Suppression Insp. - Refer to Medina, Eric PMschedule details.

1/9/2017 3:07:22 PM Page 87 of 122

Margret Villalobos

Total Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID **Deferred By Request Date Target Comp Date Days** Labor Area Until Aged Hours Area Number Reason Created Date/Time Actual Comp Date Status **Priority Action Taken Assigned To** Description Requester Name Riverside ES Location: 158184 8/8/2016 154 \$0.00 Work In Progress 8/8/2016 10:58:30 AM Medium Room 114 Need assistance opening filing cabinet. May need to Lara, Ralph replace key. (Ms. Barraza) Norma Martinez \$0.00 164136 11/6/2016 64 Medium Work In Progress 11/6/2016 12:40:10 AM Medina, Eric Yearly - Riverside ES - Grease Trap - Refer to PM schedule details. Margret Villalobos 11/27/2016 11/6/2016 64 \$0.00 164163 Medium Work In Progress 11/6/2016 12:40:29 AM Medina, Eric Monthly - Riverside ES Range Hood Cleaning - Refer to PMschedule details. Margret Villalobos 11/30/2016 40 \$0.00 165234 Medium Work In Progress 11/30/2016 10:04:44 Castillo, Carlos Need Carlos C. to install electricity for electrical plugs and a lighting fixture at custodial morgan building. Mario Martinez 11/30/2016 \$0.00 165235 Medium Work In Progress 11/30/2016 10:07:53 Castillo, Carlos Need lift at Riverside Elementary for flag pole rope install. Need to to rerope new flag pole. Mario Martinez 166210 12/15/2016 25 \$0.00 12/15/2016 8:57:31 AM Medium Work In Progress Ontiveros, Joe Need Joe O. to fix leaky drain line at boys restroom lavatory. Mario Martinez 12/8/2016 32 \$0.00 165868 Work In Progress 12/8/2016 2:02:26 PM Medium Ontiveros, Joe Need plumber Joe O. to assist with replacing 7 new faucets in boys and girls restrooms at south wing, Mario Martinez

1/9/2017 3:07:22 PM Page 88 of 122

Total Selected Date Range for Request Dates:7/1/2016 - 12/31/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Area Number Reason Created Date/Time Actual Comp Date Status **Priority Description Action Taken Assigned To Requester Name** Location: Riverside ES 163541 10/27/2016 74 \$0.00 Work In Progress 10/27/2016 3:12:00 PM Medium Ontiveros, Joe Need Joe O. to replace bad drinking faucet at nurses office. Mario Martinez 70 10/31/2016 \$0.00 163711 Medium Work In Progress 10/31/2016 12:47:49 Ontiveros. Joe Need assistance replacing 7 lavatory faucets at South wing. But first need to purchase faucets. Mario Martinez 8/22/2016 140 \$0.00 159203 Medium Work In Progress 8/22/2016 3:25:02 PM Martinez, Mario Need to replace 24 I-25 sprinkler heads that have been broken or are not working. Mario Martinez Count: 24 Work Orders Total for Riverside ES 0 \$0.00 Avg. Age of WO's 70

1/9/2017 3:07:22 PM Page 89 of 122

Total Selected Date Range for Request Dates:7/1/2016 - 12/31/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Area Until **Days** Labor **Deferred By** Aged Hours Area Number Reason Status Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description Requester Name Location: RTC - Alliance 160638 9/12/2016 119 \$0.00 Medium Work In Progress 9/12/2016 8:46:15 AM In Mr. Hawkins 2nd class room the light fixer is flickering Moncayo, Fernando and is affecting some students. In Mr. Hawkins first class room some lights are out also in the back office some lights are out Gloria Delgado 9/15/2016 116 \$0.00 160893 Medium Work In Progress 9/15/2016 10:51:09 AM need campus cleaned / also I need vents outside of the Moncayo, Fernando portables replaced or covered animals are going in under the portables dying and it smells Gloria Delgado 9/21/2016 110 \$0.00 161262 Medium Work In Progress 9/21/2016 9:02:20 AM Moncayo, Fernando Need the ceiling panels in the office replaced some are broken, falling and water stains Gloria Delgado Count: 3 Work Orders Total for RTC - Alliance 0 \$0.00 Avg. Age of WO's 115

1/9/2017 3:07:22 PM Page 90 of 122

Total Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Created Date/Time Actual Comp Date **Priority Status** Area Number Reason **Assigned To Description Action Taken** Requester Name Location: San Miguel ES 165215 11/30/2016 40 \$0.00 Medium Work In Progress 11/30/2016 12:47:37 Monthly - San Miguel ES - Grounds Service (Monthly) -Ontiveros, Guadalupe Refer to PMs chedule details. Margret Villalobos Count: 1 Work Orders Avg. Age of WO's 40 0 \$0.00 **Total for San Miguel ES**

1/9/2017 3:07:22 PM Page 91 of 122

WOID Priority Assigned Requester		Area Number Description	Deferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa ES						
162802				10/17/2016		84		\$0.00
Medium	Work In Progress			10/17/2016 7:59:38 AM				
Ambriz, Ju	an	Need to replace	e 18 volt dewalt drill					
Juan Amb	riz							
163029	Main Building			10/19/2016		82		\$0.00
Medium	Work In Progress	Vehicle #166		10/19/2016 3:00:04 PM				
Flores, Pe	te	need to repair i	gnitionswitch					
Juan Amb	riz							
164349		Kitchen		11/7/2016		63		\$0.00
High	Work In Progress			11/7/2016 11:05:55 AM				
Medina, Eı	ric	Freezer temp w R. (575) 589-34	as rising notholdin 139	g. SNP Mgr. Marina				
Dino Facio)							
164693				11/14/2016		56		\$0.00
Medium	Work In Progress			11/14/2016 1:55:36 PM				
Villalobos,	Jose	desk dolly need	ds to be repair ASAI	P I need it by thursday				
Maria Gab	aldon							
165142				11/29/2016		41		\$0.00
Medium	Work In Progress			11/29/2016 1:11:57 PM				
Villalobos,	Jose	good afternoon fixed the desk have a nice da	mover thank you					
Maria Gab	aldon							
157673		Kitchen		8/1/2016		161		\$0.00
High	Work In Progress			8/1/2016 2:21:37 PM				
Medina, Eı	ric	Oven not heating	ng up. SP Mgr. Marir	na R. (575) 589-3439				
Dino Facio)							
164009				11/3/2016		67		\$0.00
Medium	Work In Progress			11/3/2016 3:36:44 PM				
Medina, Eı	ric	FREEZER IS A MARINA R. 589	13 DEGREES. SNF 0.3439	PMANAGER				
Maritza Go	nzalez							
164912		Kitchen		11/17/2016		53		\$0.00
High	Work In Progress			11/17/2016 3:03:17 PM				
Medina, Eı			thru warmers need t (575) 589-3439	o be adjusted SNP				
Dino Facio)							
1/9/2017 3	3:07:22 PM						Da 1	92 of 122

1/9/2017 3:07:22 PM Page 92 of 122

WOID Priority Assigned	Building Status To	Area Deferred By Area Number Reason Description	Until Request Date Created Date/Time	_	•	∟abor Hours	
Requester	Name						
Location:	Santa Te	resa ES					
164910		Kitchen	11/17/2016		53		\$0.00
High	Work In Progress		11/17/2016 2:54:35 PM	I			
Medina, E	ric	Top left oven not reaching proper t Mgr. Marina R. (575) 589-3439	emperature. SNP				
Maritza Go	onzalez						
166212			12/15/2016		25		\$0.00
Medium	Work In Progress		12/15/2016 9:12:51 AM	1			
Ronquillo,	, Ruben	Need to borrow the Extension pole	esaw				
Juan Amb	riz						
161282			9/21/2016		110		\$0.00
Medium	Work In Progress		9/21/2016 2:40:49 PM	1			
Medina, E	ric	HAND SINK IS LEAKING. SNP MA 589-3439	ANAGER MARINA R.				
Maritza Go	onzalez						
165718			12/6/2016		34		\$0.00
Medium	Work In Progress		12/6/2016 1:49:47 PM	1			
Villalobos	, David	SERVING STAND ON LEFT SIDE WATER. SNP MANAGER MARINA					
Maritza Go	onzalez						
163431			10/26/2016		75		\$0.00
Medium	Work In Progress		10/26/2016 11:14:43	}			
Gonzalez,	Salvador	Build a screen panel, 3ft from elec Ambriz.	trical panel, see Juan	reference wo's 1517	752, 151753		
Albert Vall	ejo		-//				
157136			7/26/2016		167		\$0.00
Medium	Work In Progress		7/26/2016 1:07:19 PN	1			
Medina, E		HAND SINK LEAKING- SNP MAN 589-3439	AGER MARINA R.				
Maritza Go		Restroom	12/13/2016		27		\$0.00
166093	Main Building				4 1		φυ.υυ
Medium	Work In Progress	Room #104	12/13/2016 3:30:04 PM	I			
Ambriz, Ju		Need to replace light switch					
Juan Amb		F.4. den	100000				Фо оо
165843	Main Building	Exterior	12/8/2016		32		\$0.00
Medium	Work In Progress		12/8/2016 9:32:34 AM	1			
Ambriz, Ju		Need to paint over graffiti done ye 12/07/16 with afternoon snack (blue					
Juan Amb	riz						

Total

730 - Work Orders In Progress (Fiscal Year)

Selected Da WOID	te Range for Request Building	Dates:7/1/2016 - 1 Area	2/31/2016 Order By L Deferred By	ocation, Status Until	Paguest Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•		=	Actual Comp Date	Aged	Hours	
Assigned [*]		Description	noucon	0.00		Action Taken			
Requester		•							
Location:	Santa Te	resa ES							
165219	Main Building	Exterior			11/30/2016		40		\$0.00
Medium	Work In Progress			11/30/2	016 7:53:36 AM	1			
Ambriz, Ju	an	Need to replac	e all broken electric	al outlet covers					
Juan Amb	riz								
165242	Main Building	Exterior			11/30/2016		40		\$0.00
Medium	Work In Progress			11/3	0/2016 11:09:52	2			
Ambriz, Ju	an	need to cock cr	acks on all exterior v	walls					
Juan Amb	riz								
164708	Main Building	Classroom			11/14/2016		56		\$0.00
Medium	Work In Progress	Portable B-052	!	11/14/2	0163:41:21 PM	1			
Ambriz, Ju	an	Need to paint re	oom, ramp and doo	r					
Juan Amb	riz	•	•						
165240	Main Building	Kitchen			11/30/2016		40		\$0.00
Medium	Work In Progress			11/3)/2016 11:04:22	2			
Ontiveros,	Joe		hot water coming ou the mixing valve	ut in cold water	supply				
Juan Amb	riz								
164705					11/14/2016		56		\$0.00
Medium	Work In Progress			11/14/2	016 3:38:40 PM	1			
Ambriz, Ju	an	need to replace	e tools						
Juan Amb	riz								
164132					11/6/2016		64		\$0.00
Medium	Work In Progress			11/6/20	16 12:40:06 AM	1			
Medina, E	ric	Yearly - Santa schedule detai	Teresa ES - Grease ls.	e Trap - Refer	to PM				
Margret Vil	lalobos								
164164					11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress			11/6/20	16 12:40:29 AM	1			
Medina, E	ric	Monthly-Santa Refer to PMsch	Teresa ES Range l nedule details.	Hood Cleaning	j -				
Margret Vil	lalobos								
164187					11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress			11/6/20	16 12:40:45 AM	1			
Medina, E	ric	Monthly-Santa Refer to PMsch	ı Teresa ES Fire Sup nedule details.	opression Insp). -				
Margret Vil	lalobos								

1/9/2017 3:07:22 PM Page 94 of 122

Selected Da WOID	ate Range for Request Building	Dates:7/1/2016 - 1 Area	2/31/2016 Order By I Deferred By		Target Comp Date	Davs	Labor	Costs
Priority	Status	Area Number	•	•	Actual Comp Date	Aged	Hours	
Assigned		Description			Action Taken			
Requeste	r Name	-						
Location:	Santa Te	resa ES						
165791				12/7/2016	j	33		\$0.00
Medium	Work In Progress	Vehicle 140		12/7/2016 2:22:41 PM	M			
Carrasco	, Danny	need fuel for ve	hicle #140, weed e	ater, and blowers				
Juan Amb	oriz							
165152	Main Building	Hallway/Corric	lor	11/29/2016	i	41		\$0.00
Medium	Work In Progress	all wings		11/29/2016 2:47:15 PN	Л			
Lara, Ralp	bh	Need to replac	e all locks in all wall	bulletin boards on				
Juan Amb	oriz							
163879	Main Building	Exterior		11/2/2016	;	68		\$0.00
Medium	Work In Progress	Playground		11/2/2016 12:32:10 PM	Л			
Ronquillo	, Ruben	Need a sign fo	r playground ages	3 to 6 YRS				
Juan Amb	oriz							
163880		Exterior		11/2/2016	j	68		\$0.00
Medium	Work In Progress	Playground		11/2/2016 12:33:20 PN	Л			
Ronquillo	, Ruben	need a sign for	playground ages 7	to 11 YRS				
Juan Amb	oriz							
162835	Main Building	Foyer		10/17/2016	}	84		\$0.00
Medium	Work In Progress	Main Front		10/17/2016 1:42:54 PN	Л			
Castillo, C	Carlos	Need to Install banner	new electrical outle	t for new electric				
Juan Amb	oriz							
Count: 29	Work Orders	Δ	vg. Age of WO's	64 T	otal for Santa Teres	sa ES	0	\$0.00

1/9/2017 3:07:22 PM Page 95 of 122

Total

730 - Work Orders In Progress (Fiscal Year)

Selected Da	ate Range for Request Building	Dates:7/1/2016 - 1 Area	12/31/2016 Order By I Deferred By	Location, Status Until	Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Crea	ted Date/Time	Actual Comp Date	Aged	Hours	
Assigned		Description				Action Taken			
Requester	r Name								
Location:	Santa Te	resa HS							
163788	AnnexBuilding	Kitchen			11/1/2016		69		\$0.00
Medium	Work In Progress			11/1/20	16 12:33:09 PM	1			
Lara, Ralp	oh .	Bar between d key cylinder.	oors to entrance int	o room 707 is n	nissing				
Jesus Avil	a								
165427					12/2/2016		38		\$0.00
Medium	Work In Progress			12/2/20	16 12:26:21 PM	1			
Castillo, C	carlos	Welding Room unprotected ju	n-Place a proper co nction box.	veroverthe					
Albert Vall	ejo								
165428					12/2/2016		38		\$0.00
Medium	Work In Progress			12/2/20	16 12:28:05 PM	1			
Castillo, C	carlos	Welding Room down cords.	n-need to replace w	riring on welder	drop				
Albert Vall	ejo								
165429					12/2/2016		38		\$0.00
Medium	Work In Progress			12/2/20	16 12:30:16 PM	1			
Castillo, C	carlos		s - several "daisych trical components.	naining" need to	install				
Albert Vall	ejo								
165430					12/2/2016		38		\$0.00
Medium	Work In Progress			12/2/20	16 12:32:11 PM	1			
Castillo, C	arlos	Wood Shop - re	epair power cords o	n (2) hand held	saws.	rerouted to Cali 12/8	3/16		
Albert Vall	ejo								
157625	Locker Room	Dressing Roor	n		7/31/2016		162		\$0.00
Medium	Work In Progress	PE Locker		7/31/2	016 7:23:31 PN	1			
Carbajal,	Jimmy	Lay proper loc this time	ker room flooring.	Only concrete 6	exists at				
Nicholas \	Wohlgemuth								
161740		Kitchen			9/29/2016		102		\$0.00
High	Work In Progress			9/29/20	16 10:01:34 AM	1			
Facio, Din	0	Refrigerator or (575) 589-5332	n serving line at 45° 2	° SNP Mgr. Olg	а В.				
Dino Facio	0								

1/9/2017 3:07:22 PM Page 96 of 122

WOID Priority Assigned		Area Area Number Description	Deferred By Reason	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	
Requeste Location:	Santa Te	roop UC						
	Santa re			- ((
161742		Kitchen		9/29/2016		102		\$0.00
High	Work In Progress			9/29/2016 10:15:59 AM	l			
Facio, Din	0	lce machine do 589-5332	own not working. SN	P Mgr. Olga B. (575)				
Dino Faci	0							
163992				11/3/2016		67		\$0.00
Medium	Work In Progress			11/3/2016 12:35:32 PM				
Ambriz, Jo	ose	need to replace	e beilmo valves to uni	ts café area				
Carlos He	ernandez							
163803	Main Building	Athletic Field		11/1/2016		69		\$0.00
Medium	Work In Progress	tennis courts		11/1/2016 3:00:26 PM	1			
Ontiveros	, Guadalupe	Windscreensn	need to be repaired a	nd tied down				
Lorraine [Dominguez							
161418	-	Custodial		9/23/2016		108		\$0.00
Medium	Work In Progress			9/23/2016 10:12:04 AM	I			
Gonzalez,		the custodial s it would provide	equesta sun shade f taff. It would be very cover from the rain a sun, which at times o	useful in the way that and more				
Jesus Avi 166007	ia Main Building	Custodial		12/12/2016		28		\$0.00
Medium	Work In Progress	Castoaiai		12/12/2016 10:24:30		20		ψ0.00
Flores, Pe	-	Front passenge constantly goes	er tire on gator appea s flat.					
Jesus Avi	la	7.5						
157626		Exterior		7/31/2016		162		\$0.00
Medium	Work In Progress	Front fo Campu	us	7/31/2016 7:25:50 PM	1			
Llanez, Ri	ck		ose of pine needles a along fence line.	and other debris in				
Nicholas	Wohlgemuth							
165241		Kitchen		11/30/2016		40		\$0.00
High	Work In Progress			11/30/2016 11:08:30				
Medina, E	ric		n the Italian Line and rly. SNP Mgr. Olga B.	On The Bun line not (575) 589-5332				
Dino Faci	0	J. 1						

1/9/2017 3:07:22 PM Page 97 of 122

Septemble Sept	WOID	Building	Dates:7/1/2016 - 12/31/2016 Order By Location Area Deferred By Un	ntil Request Date	Target Comp Date	Days Aged	Labor Hours	Costs
Sequestry Seq	Priority	Status	Area Number Reason	Created Date/Time	-	Ageu	i loui s	
Santa San	_		Description		Action Taken			
158574 8/12/2016 150 \$0.00	-							
Medium Mork In Progress Mork In Progress Need to anchor small bleachers with ties. Routed to BM 11/28/16	Location:	Santa Te	resa HS					
Diaz, David Need to anchor small bleachers with ties. Routed to BM 11/28/16 Alfredo Holguin 156085 7/7/2016 186 \$0.0 156086 7/7/2016 8:56:06 AM \$0.0 \$0.0 Medium Work In Progress Requested by Jesus Awila back exterior doors handles not working cannot be locked \$0.0 \$0.0 Cora Ramirez Tis6847 7/12/2016 181 \$0.0 Medium Work In Progress 7/12/16 \$0.0 \$0.0 Medium Work In Progress 10/26/2016 10:04:10 75 \$0.0 David Diazer Several light bulbs need to be replaced. Main entrance area directly in front of library doors. \$0.0 \$0.0 \$0.0 Medium Work In Progress Several light bulbs need to be replaced. Main entrance area directly in front of library doors. \$0.11/10/2016 - asp David, electrician needs to change ballast Jesus Awil \$0.0 \$0.0 \$0.0 \$0.0 Medium Work In Progress \$0.0 \$0.0 \$0.0 \$0.0 \$0.0 \$0.0 \$0.0	158574			8/12/2016		150		\$0.00
Alfredo Holguin 156085	Medium	Work In Progress		8/12/2016 8:02:55 AN	Л			
156085	Diaz, Davi	d	Need to anchor small bleachers with ties		Routed to BM 11/28	3/16		
Medium Work In Progress 77/2016 8:58:06 AM Marquez, Gerardo Requested by Jesus Avila back exterior doors handles not working cannot be locked Cora Ramirez 156:347 7/12/2016 181 \$0.0 Medium Work In Progress 7/12/2016 2:31:20 PM 181 \$0.0 Marquez, Gerardo 7/12/16 Need to install two keylocks to two cabinets in room 313. Need to install two keylocks to two cabinets in room 313. To \$0.0 Need to install two keylocks to two cabinets in room 313. To \$0.0 Need to 10/26/2016 10:04:10 To \$0.0 Need to 10/26/2016 10:04:10 To \$0.0 Need to 11/16/2016 10:04:10 To \$0.0 Need to 11/16/2016 10:04:10 Need to 11/16/2016 10:04:10 Need to \$0.0 \$0.0 Need to 41/16/2016 10:04:10 Need to \$0.0 \$0.0 <t< td=""><td>Alfredo Ho</td><td>olguin</td><td></td><td></td><td></td><td></td><td></td><td></td></t<>	Alfredo Ho	olguin						
Marquez, Gerardo Requested by Jesus Akila back exterior doors handles not working cannot be locked Cora Ramirez 156347 7/12/2016 2:31:20 PM Medium Work In Progress 7/12/16 Need to install two keylocks to two cabinets in room 313. David Diaz 163427 Main Building Library 10/26/2016 10:04:10 75 \$0.0 Medium Work In Progress Several light bulbs need to be replaced. Main entrance area directly in front of library doors. 11/10/2016 1:03+04 11/10/2016 2:57:57 PM Castillo, Carlos Need to determine what part of campus will be affected by by over outage to be conducted due to 1600 amp switch replacement. Need to determine what part of campus will be affected by over outage to be conducted due to 1600 amp switch replacement. Need to determine what part of campus will be affected by over outage to be conducted due to 1600 amp switch replacement. Need to determine what part of campus will be affected by over outage to be conducted due to 1600 amp switch replacement. Need to determine what part of campus will be affected by over outage to be conducted for the backstop (calf Albert) for questions. (Pain	156085			7/7/2016		186		\$0.00
Back exterior doors handles not working cannot be locked	Medium	Work In Progress		7/7/2016 8:58:06 AM	1			
Cora Ramirez Cor	Marquez, 0	Gerardo	Requested by Jesus Avila					
156347 Nedium Work In Progress 7/12/2016 2:31:20 PM 181 \$0.00 Medium Work In Progress 7/12/16 Need to install two keylocks to two cabinets in room 313. Need to install two keylocks to two cabinets in room 313. Need to install two keylocks to two cabinets in room 313. Need to install two keylocks to two cabinets in room 313. To suppose the control of the control of 10/26/2016 10:04:10 75 \$0.00 Medium Work In Progress Several light bulbs need to be replaced. Main entrance area directly in front of library doors. 11/10/2016 - asp David, electrician needs to change ballast 60 \$0.00 Jesus Avila 11/10/2016 2:57:57 PM 60 \$0.00 Medium Work In Progress 11/10/2016 2:57:57 PM 60 \$0.00 Castillo, Carlos Need to determine what part of campus will be affected bypower outage to be conducted due to 1600 amp switch replacement. 8/22/2016 140 \$0.00 Carlos Castillo 159161 8/22/2016 140 \$0.00 Medium Work In Progress 8/22/2016 10:10:04 AM Need to clean coils Carlos Hermandez 11/10/2016 60 \$0.00 Medium Work In Progress								
Medium Work In Progress 7/12/2016 2:31:20 PM Marquez, Gerardo 7/12/16 Need to install two keylocks to two cabinets in room 313. David Diaz 163427 Main Building Library 10/26/2016 10:04:10 75 \$0.0 Medium Work In Progress 10/26/2016 10:04:10 11/15/16 - asp David, electrician needs to change ballast Castillo, Carlos Several light bulbs need to be replaced. Main entrance area directly in front of library doors. 11/10/2016 - asp David, electrician needs to change ballast Jesus Avila 164611 11/10/2016 - asp David, electrician needs to change ballast 11/10/2016 2:57:57 PM Castillo, Carlos Need to determine what part of campus will be affected bypower outage to be conducted due to 1600 amp switch replacement. Carlos Castillo 159161 8/22/2016 10:10:04 AM 159161 8/22/2016 10:10:04 AM Need to determine what part of campus will be affected bypower outage to be conducted due to 1600 amp switch replacement. Carlos Sullow Need to Main Progress Need to determine what part of campus will be affected by acceptable to the part o	Cora Ram	nirez						
Marquez, Gerardo 7/12/16 Need to install two keylocks to two cabinets in room 313.	156347			7/12/2016		181		\$0.00
Need to install two keylocks to two cabinets in room 313.	Medium	Work In Progress		7/12/2016 2:31:20 PM	Л			
163427 Main Building Library 10/26/2016 75 \$0.0 Medium Work In Progress 10/26/2016 10:04:10 Castillo, Carlos Several light bulbs need to be replaced. Main entrance area directly in front of library doors. 11/15/16 - asp David, electrician needs to change ballast Jesus Avila 164611 11/10/2016 60 \$0.0 Medium Work In Progress 11/10/2016 2:57:57 PM Carlos Carlos Need to determine what part of campus will be affected by power outage to be conducted due to 1600 amp switch replacement Carlos Castillo 159161 8/22/2016 140 \$0.0 Medium Work In Progress 8/22/2016 10:10:04 AM Ontiveros, Joe need hose bib installed on roof top to café to clean coils Carlos Hernandez 164568 11/10/2016 8:30:31 AM Ontiveros, Guadalupe Paint field side of the backstop (call Albert) for questions. (Paint-Gloss Black)	Marquez, (Gerardo	Need to install two keylocks to two cabine	ets in room				
Medium Work In Progress Several light bulbs need to be replaced. Main entrance area directly in front of library doors. Several light bulbs need to be replaced. Main entrance area directly in front of library doors. Jesus Avila 11/10/2016 60 \$0.0 Medium Work In Progress 11/10/2016 2:57:57 PM Castillo, Carlos Need to determine what part of campus will be affected by power outage to be conducted due to 1600 amp switch replacement. Carlos Castillo 159161 8/22/2016 140 \$0.0 Medium Work In Progress 8/22/2016 10:10:04 AM Ontiveros, Joe need hose bib installed on roof top to café to clean coils Carlos Hernandez 11/10/2016 8:30:31 AM Ontiveros, Guadalupe Paint field side of the backstop (call Albert) for questions. (Paint- Gloss Black)	David Dia:	Z						
Castillo, Carlos Several lightbulbs need to be replaced. Main entrance area directly in front of library doors. Jesus Avila 164611 11/10/2016 60 \$0.0 Medium Work In Progress 11/10/2016 2:57:57 PM Castillo, Carlos Need to determine what part of campus will be affected by power outage to be conducted due to 1600 amp switch replacement Carlos Castillo 159161 8/22/2016 140 \$0.0 Medium Work In Progress 8/22/2016 10:10:04 AM Ontiveros, Joe need hose bib installed on roof top to café to clean coils Carlos Hernandez 164568 11/10/2016 8:30:31 AM Ontiveros, Guadalupe Paint field side of the backstop (call Albert) for questions. (Paint-Gloss Black)	163427	Main Building	Library	10/26/2016		75		\$0.00
Jesus Avila Jesus Avila 164611	Medium	Work In Progress		10/26/2016 10:04:10)			
164611 11/10/2016 60 \$0.0 Medium Work In Progress 11/10/2016 2:57:57 PM Castillo, Carlos Need to determine what part of campus will be affected by power outage to be conducted due to 1600 amp switch replacement. Carlos Castillo 159161 8/22/2016 140 \$0.0 Medium Work In Progress 8/22/2016 10:10:04 AM Ontiveros, Joe need hose bib installed on roof top to café to clean coils Carlos Hernandez 11/10/2016 60 \$0.0 Medium Work In Progress 11/10/2016 8:30:31 AM 60 \$0.0 Ontiveros, Guadalupe Paint field side of the backstop (call Albert) for questions. (Paint - Gloss Black) (Paint - Gloss Black) Call Albert) for questions.				Main entrance		d, electric	ian needs	to
Medium Work In Progress 11/10/2016 2:57:57 PM Castillo, Carlos Need to determine what part of campus will be affected by power outage to be conducted due to 1600 amp switch replacement Carlos Castillo 159161 8/22/2016 140 \$0.0 Medium Work In Progress 8/22/2016 10:10:04 AM Ontiveros, Joe need hose bib installed on roof top to café to clean coils Carlos Hernandez 164568 11/10/2016 60 \$0.0 Medium Work In Progress 11/10/2016 8:30:31 AM Ontiveros, Guadalupe Paint field side of the backstop (call Albert) for questions. (Paint-Gloss Black)		a		44/40/0040				Φο οο
Castillo, Carlos Need to determine what part of campus will be affected by power outage to be conducted due to 1600 amp switch replacement. Carlos Castillo 159161 8/22/2016 Medium Work In Progress 8/22/2016 10:10:04 AM Ontiveros, Joe need hose bib installed on roof top to café to clean coils Carlos Hernandez 164568 11/10/2016 Medium Work In Progress 11/10/2016 8:30:31 AM Ontiveros, Guadalupe Paint field side of the backstop (call Albert) for questions. (Paint- Gloss Black)						60		\$0.00
bypower outage to be conducted due to 1600 amp switch replacement. Carlos Castillo 159161 8/22/2016 140 \$0.0 Medium Work In Progress 8/22/2016 10:10:04 AM Ontiveros, Joe need hose bib installed on roof top to café to clean coils Carlos Hernandez 164568 11/10/2016 60 \$0.0 Medium Work In Progress 11/10/2016 8:30:31 AM Ontiveros, Guadalupe Paint field side of the backstop (call Albert) for questions. (Paint-Gloss Black)	Medium	Work In Progress		11/10/2016 2:57:57 PM	1			
159161 8/22/2016 140 \$0.0 Medium Work In Progress 8/22/2016 10:10:04 AM Ontiveros, Joe need hose bib installed on roof top to café to clean coils Carlos Hernandez 164568 11/10/2016 60 \$0.0 Medium Work In Progress 11/10/2016 8:30:31 AM Ontiveros, Guadalupe Paint field side of the backstop (call Albert) for questions. (Paint - Gloss Black)	Castillo, C	arlos	bypower outage to be conducted due to 1					
Medium Work In Progress Ontiveros, Joe need hose bib installed on roof top to café to clean coils Carlos Hernandez 164568 11/10/2016 60 \$0.0 Medium Work In Progress 11/10/2016 8:30:31 AM Ontiveros, Guadalupe Paint field side of the backstop (call Albert) for questions. (Paint - Gloss Black)	Carlos Ca	stillo						
Ontiveros, Joe need hose bib installed on roof top to café to clean coils Carlos Hernandez 164568 11/10/2016 60 \$0.0 Medium Work In Progress 11/10/2016 8:30:31 AM Ontiveros, Guadalupe Paint field side of the backstop (call Albert) for questions. (Paint - Gloss Black)	159161			8/22/2016		140		\$0.00
Carlos Hernandez 164568 11/10/2016 60 \$0.0 Medium Work In Progress 11/10/2016 8:30:31 AM Ontiveros, Guadalupe Paint field side of the backstop (call Albert) for questions. (Paint - Gloss Black)	Medium	Work In Progress		8/22/2016 10:10:04 AM	1			
164568 11/10/2016 60 \$0.00 Medium Work In Progress 11/10/2016 8:30:31 AM Ontiveros, Guadalupe Paint field side of the backstop (call Albert) for questions. (Paint-Gloss Black)	Ontiveros,	Joe	need hose bib installed on roof top to cafe	é to clean coils				
Medium Work In Progress 11/10/2016 8:30:31 AM Ontiveros, Guadalupe Paint field side of the backstop (call Albert) for questions. (Paint - Gloss Black)	Carlos He	ernandez						
Ontiveros, Guadalupe Paint field side of the backstop (call Albert) for questions. (Paint-Gloss Black)	164568			11/10/2016		60		\$0.00
questions. (Paint-Gloss Black)	Medium	Work In Progress		11/10/2016 8:30:31 AM	1			
· · · · · · · · · · · · · · · · · · ·	Ontiveros,	Guadalupe	questions.	ert) for				
	Albert Vall	ejo	(2.2.2 2.00.y					

1/9/2017 3:07:22 PM Page 98 of 122

WOID	Building		erred By	-	Target Comp Date	Days	Labor	
Priority	Status _	Area Number Reas	son	Created Date/Time	•	Aged	Hours	
Assigned		Description			Action Taken			
Requester								
Location:	Santa Te	resa HS						
163863				11/2/2016		68		\$0.00
Medium	Work In Progress			11/2/2016 8:17:32 AN	1			
Diaz, Davi	d	Requesting to order s Tool Bag 32PJ37 \$37 Hex/Torx 4RU39 \$47 Contact Cleaner LPS	7.85 (1) 7.95 (1)	2ea. (2)				
David Diaz	<u>z</u>							
156080				7/7/2016		186		\$0.00
Medium	Work In Progress			7/7/2016 7:47:42 AN	1			
Miranda, E	Danny	7/7/16 Need to repair both s class room. Sheetroo moisture coming out	ck is expanding	from too much				
David Diaz	<u>z</u>							
165882				12/8/2016		32		\$0.00
Medium	Work In Progress			12/8/2016 3:32:51 PM	Л			
Ontiveros,	Joe	water fountain next to	room 610 clog	ged need auger				
Carlos He	rnandez							
162762				10/14/2016		87		\$0.00
Medium	Work In Progress			10/14/2016 3:34:21 PM	1			
Ontiveros,	Joe	need to replace wate	rspigotnextm	ain doors to office				
Carlos He	rnandez							
163252				10/24/2016		77		\$0.00
Medium	Work In Progress			10/24/2016 1:12:52 PM	1			
Ontiveros,	Joe	sink in girls locker roo	om clogged ne	ed augar				
Carlos He	rnandez							
162658	Cafeteria (2005)	Cafeteria		10/13/2016		88		\$0.00
Medium	Work In Progress			10/13/2016 12:21:52	2			
Castillo, C	arlos	Light switches in cafe properly.	eteria lobbyare	a not working				
Jesus Avil	a							
165250				11/30/2016		40		\$0.00
Medium	Work In Progress			11/30/2016 1:48:33 PM	1			
Castillo, C	arlos	Need Bucket truck to	reinstall rope to	o main flag pole.				
David Diaz	_							

1/9/2017 3:07:22 PM Page 99 of 122

WOID	Building	Area Deferred By		Target Comp Date	Days	Labor Hours	
Priority	Status	Area Number Reason	Created Date/Time	•	Aged	nour s	
Assigned Requeste		Description		Action Taken			
-							
Location:	Santa Te	resa no					
165298			11/30/2016		40		\$0.00
Medium	Work In Progress		11/30/2016 4:53:14 PM				
Castillo, C	Carlos	several lights in parking lot are ou	t				
Carlos He	ernandez						
166225			12/15/2016		25		\$0.00
Medium	Work In Progress		12/15/2016 1:49:28 PM				
Castillo, C	Carlos	need to replace light switch in roo	m 301				
Carlos He	ernandez						
161565			9/27/2016		104		\$0.00
Medium	Work In Progress		9/27/2016 8:53:48 AM	1			
Llanez, Ri	ick	I need the clips for the nets at the	softball field				
Rick Llan	ez						
166020			12/12/2016		28		\$0.00
Medium	Work In Progress		12/12/2016 1:59:03 PM	l			
Castillo, C	Carlos	need to replace and check outside several are out	e lights on building				
Carlos He	ernandez						
164749			11/15/2016		55		\$0.00
Medium	Work In Progress		11/15/2016 8:02:09 AM	1			
Flores, Pe	ete	Yearly - Santa Teresa HS - Mowe Refer to PMschedule details.	r 0425 - Grounds -				
Margret V	illalobos						
164165			11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress		11/6/2016 12:40:30 AM	1			
Medina, E	Eric	Monthly-Santa Teresa HS Range Refer to PMschedule details.	Hood Cleaning -				
Margret V	illalobos		4.4 10 10 04.0				Φο οο
164134			11/6/2016		64		\$0.00
Medium	Work In Progress		11/6/2016 12:40:08 AN	1			
Medina, E		Yearly - Santa Teresa HS - Greas schedule details.	e Trap - Refer to PM				
Margret V			40/40/0040				Φο οο
166274	Main Building	Gym	12/16/2016		24		\$0.00
Medium	Work In Progress	auxillary gym	12/16/2016 11:54:24				
Castillo, C	Carlos	Move reset button for auxiliary gyr location as it is behind the bleach access button.					
Lorraine [Dominguez						
1/9/2017	3:07:22 PM					Page 10	00 of 122

Action Taken Requester Name Coation: Santa Teresa HS	Costs abor	Days	Target Comp Date		6 - 12/31/2016 Order By Deferred By	st Dates://1/2016 - 7 Area	te Range for Request I Building	Selected Da WOID
Requester Name Location: Santa Teresa HS	ours	Aged	Actual Comp Date	Created Date/Time	per Reason	Area Number	Status	Priority
Location: Santa Teresa HS 164188			Action Taken		n	Description	Го	Assigned '
11/6/2016 11/27/2016 64 Medium Work In Progress 11/6/2016 12:40:46 AM Medium Work In Progress 11/6/2016 12:40:46 AM Medium Work In Progress 11/6/2016 12:40:46 AM Medium Work In Progress Athletic Field 8/5/2016 157 Medium Work In Progress 8/5/2016 1:37:15 PM Llanez, Rick Water spigot needs to be relocated so cement can be poured for seating area behind the new back stop at the baseball field. Rick Llanez 159662 Main Building Classroom 8/29/2016 133 Medium Work In Progress 805, cafeteria 8/29/2016 12:20:37 PM Lara, Ralph We have several work orders that need to be completed so that we can lock the school class rooms and or building properly. Areas are as follows Room 805 front door Hallway at the end of locker rooms door going out to football field does not lock properly Cafeteria door towards softball field is still notworking several work orders have been submitted Lorraine Dominguez 12/4/2016 12:43:43 AM Diaz, David Monthly - Santa Teresa HS Bleacher Inspection - Refer							Name	Requester
Medium Work In Progress 11/6/2016 12:40:46 AM Medina, Eric Monthly- Santa Teresa HS Fire Suppression Insp Refer to PM schedule details. Margret Villalobos 158076 Athletic Field 8/5/2016 1:37:15 PM Medium Work In Progress 8/5/2016 1:37:15 PM Llanez, Rick Water spigot needs to be relocated so cement can be poured for seating area behind the new back stop at the bas eball field. Rick Llanez 159662 Main Building Classroom 8/29/2016 13:33 Medium Work In Progress 805, cafeteria 8/29/2016 12:20:37 PM Lara, Ralph We have several work orders that need to be completed so that we can lock the school classrooms and or building properly. Areas are as follows Room 805 front door Hallway at the end of locker rooms door going out to football field does not lock properly Cafeteria door towards softball field is still not working several work orders have been submitted Lorraine Dominguez 165551 12/4/2016 12:43:43 AM Diaz, David Monthly - Santa Teresa HS Bleacher Inspection - Refer						Teresa HS	Santa Te	Location:
Medina, Eric Monthly-Santa Teresa HS Fire Suppression Insp Refer to PMschedule details. Margret Villalobos 158076 Athletic Field 8/5/2016 1:37:15 PM Medium Work In Progress 8/5/2016 1:37:15 PM Llanez, Rick Water spigot needs to be relocated so cement can be poured for seating area behind the new back stop at the baseball field. Rick Llanez 159662 Main Building Classroom 8/29/2016 133 Medium Work In Progress 805, cafeteria 8/29/2016 12:20:37 PM Lara, Ralph We have several work orders that need to be completed so that we can lock the school classrooms and or building properly. Areas are as follows Room 805 front door Hallway at the end of locker rooms door going out to football field does not lock properly Cafeteria door towards softball field is still not working several work orders have been submitted Lorraine Dominguez 165561 12/4/2016 12:43:43 AM Diaz, David Monthly - Santa Teresa HS Bleacher Inspection - Refer	\$0.00	64	11/27/2016	11/6/2016				164188
Refer to PMschedule details. Margret Villalobos Athletic Field 8/5/2016 1:37:15 PM Medium Work In Progress 8/5/2016 1:37:15 PM Llanez, Rick Water spigot needs to be relocated so cement can be poured for seating area behind the new back stop at the baseball field. Rick Llanez Tispec Main Building Classroom 8/29/2016 1:33 Medium Work In Progress 805, cafeteria 8/29/2016 12:20:37 PM Lara, Ralph We have several work orders that need to be completed so that we can lock the school classrooms and or building properly. Areas are as follows Room 805 front door Hallway at the end of locker rooms door going out to football field does not lock properly Cafeteria door towards softball field is still not working several work orders have been submitted Lorraine Dominguez Lorraine Work In Progress 12/4/2016 12:43:43 AM Diaz, David Monthly - Santa Teresa HS Bleacher Inspection - Refer			l	11/6/2016 12:40:46 AM		5	Work In Progress	Medium
Athletic Field 8/5/2016 1:37:15 PM Medium Work In Progress 8/5/2016 1:37:15 PM Llanez, Rick Water spigot needs to be relocated so cement can be poured for seating area behind the new back stop at the baseball field. Rick Llanez 159662 Main Building Classroom 8/29/2016 133 Medium Work In Progress 805, cafeteria 8/29/2016 12:20:37 PM Lara, Ralph We have several work orders that need to be completed so that we can lock the school classrooms and or building properly. Areas are as follows Room 805 front door Hallway at the end of locker rooms door going out to football field does not lock properly Cafeteria door towards softball field is still not working several work orders have been submitted Lorraine Dominguez 12/4/2016 12:43:43 AM Diaz, David Monthly- Santa Teresa HS Bleacher Inspection - Refer				ppression Insp			ic	Medina, E
Medium Work In Progress 8/5/2016 1:37:15 PM Llanez, Rick Water spigot needs to be relocated so cement can be poured for seating area behind the new back stop at the baseball field. Rick Llanez 159662 Main Building Classroom 8/29/2016 133 Medium Work In Progress 805, cafeteria 8/29/2016 12:20:37 PM Lara, Ralph We have several work orders that need to be completed so that we can lock the school classrooms and or building properly. Areas are as follows Room 805 front door Hallway at the end of locker rooms door going out to football field does not lock properly Cafeteria door towards softball field is still not working several work orders have been submitted Lorraine Dominguez 165551 12/4/2016 12:43:43 AM Diaz, David Monthly - Santa Teresa HS Bleacher Inspection - Refer							lalobos	Margret Vil
Llanez, Rick Water spigot needs to be relocated so cement can be poured for seating area behind the new back stop at the baseball field. Rick Llanez 159662 Main Building Classroom 8/29/2016 133 Medium Work In Progress 805, cafeteria 8/29/2016 12:20:37 PM Lara, Ralph We have several work orders that need to be completed so that we can lock the school classrooms and or building properly. Areas are as follows Room 805 front door Hallway at the end of locker rooms door going out to football field does not lock properly Cafeteria door towards softball field is still not working several work orders have been submitted Lorraine Dominguez 12/4/2016 12:43:43 AM Diaz, David Monthly - Santa Teresa HS Bleacher Inspection - Refer	\$0.00	157		8/5/2016	ld	Athletic Field		158076
poured for seating area behind the new back stop at the baseball field. Rick Llanez 159662 Main Building Classroom 8/29/2016 133 Medium Work In Progress 805, cafeteria 8/29/2016 12:20:37 PM Lara, Ralph We have several work orders that need to be completed so that we can lock the school classrooms and or building properly. Areas are as follows Room 805 front door Hallway at the end of locker rooms door going out to football field does not lock properly Cafeteria door towards softball field is still not working several work orders have been submitted Lorraine Dominguez 165551 12/4/2016 12:43:43 AM Diaz, David Monthly - Santa Teresa HS Bleacher Inspection - Refer			1	8/5/2016 1:37:15 PM		3	Work In Progress	Medium
159662 Main Building Classroom 8/29/2016 133 Medium Work In Progress 805, cafeteria 8/29/2016 12:20:37 PM Lara, Ralph We have several work orders that need to be completed so that we can lock the school class rooms and or building properly. Areas are as follows Room 805 front door Hallway at the end of locker rooms door going out to football field does not lock properly Cafeteria door towards softball field is still not working several work orders have been submitted Lorraine Dominguez 12/4/2016 12:43:43 AM Diaz, David Monthly - Santa Teresa HS Bleacher Inspection - Refer					seating area behind th	poured for sea	ck	Llanez, Ric
Medium Work In Progress 805, cafeteria 8/29/2016 12:20:37 PM Lara, Ralph We have several work orders that need to be completed so that we can lock the school class rooms and or building properly. Areas are as follows Room 805 front door Hallway at the end of locker rooms door going out to football field does not lock properly Cafeteria door towards softball field is still not working several work orders have been submitted Lorraine Dominguez 12/4/2016 12:43:43 AM Diaz, David Monthly - Santa Teresa HS Bleacher Inspection - Refer							z	Rick Llane
Lara, Ralph We have several work orders that need to be completed so that we can lock the school classrooms and or building properly. Areas are as follows Room 805 front door Hallway at the end of locker rooms door going out to football field does not lock properly Cafeteria door towards softball field is still not working several work orders have been submitted Lorraine Dominguez 165551 12/4/2016 1/4/2017 36 Medium Work In Progress 12/4/2016 12:43:43 AM Diaz, David Monthly - Santa Teresa HS Bleacher Inspection - Refer	\$0.00	133		8/29/2016		Classroom	Main Building	159662
so that we can lock the school class rooms and or building properly. Areas are as follows Room 805 front door Hallway at the end of locker rooms door going out to football field does not lock properly Cafeteria door towards softball field is still not working several work orders have been submitted Lorraine Dominguez 165551 12/4/2016 1/4/2017 36 Medium Work In Progress 12/4/2016 12:43:43 AM Diaz, David Monthly - Santa Teresa HS Bleacher Inspection - Refer				8/29/2016 12:20:37 PM	ria	s 805, cafeteria	Work In Progress	Medium
165551 12/4/2016 1/4/2017 36 Medium Work In Progress 12/4/2016 12:43:43 AM Diaz, David Monthly - Santa Teresa HS Bleacher Inspection - Refer				ssrooms and or lows door going out to y Id is still not working	can lock the school cla operly. Areas are as fo front door he end of locker room d does not lock proper oor towards softball fie	so that we can building prope Room 805 fror Hallway at the football field do Cafeteria door	n	Lara, Ralp
Medium Work In Progress 12/4/2016 12:43:43 AM Diaz, David Monthly - Santa Teresa HS Bleacher Inspection - Refer							ominguez	Lorraine D
Diaz, David Monthly - Santa Teresa HS Bleacher Inspection - Refer	\$0.00	36	1/4/2017	12/4/2016				165551
·			l	12/4/2016 12:43:43 AM		3	Work In Progress	Medium
to PMschedule details.				her Inspection - Refer			b	Diaz, Davi
Margret Villalobos							lalobos	Margret Vil

1/9/2017 3:07:22 PM Page 101 of 122

WOID	ate Range for Request Building		Deferred By		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Aged	Hours	
Assigned	То	Description			Action Taken			
Requeste	r Name							
Location:	Santa Te	resa MS						
166312				12/31/2016		9		\$0.00
Medium	Work In Progress			12/31/2016 12:57:59)			
Mijarez, Ja	aime	Yearly - Santa T Refer to PMsch		of Furnace)(Yearly) -				
Margret Vi	illalobos							
164166				11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress			11/6/2016 12:40:31 AN	1			
Medina, E	ric	Monthly - Santa Refer to PMsch		e Hood Cleaning -				
Margret Vi	illalobos							
164189				11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress			11/6/2016 12:40:47 AN	И			
Medina, E	Eric	Monthly - Santa Refer to PM sch		Suppression Insp				
Margret Vi								
161111	Gym (1997)	Gym		9/19/2016		112		\$0.00
Medium	Work In Progress			9/19/2016 3:23:16 PM	Л			
Prospero	, Manuel	9/19/16. NEED PAINT G	YM DOORS AND	FRAMES.				
Manuel P	rospero							
164148				11/6/2016		64		\$0.00
Medium	Work In Progress			11/6/2016 12:40:18 AN	Л			
Medina, E	Eric	Yearly - Santa T schedule details		se Trap - Refer to PM				
Margret Vi	illalobos							
164748				11/15/2016		55		\$0.00
Medium	Work In Progress			11/15/2016 8:02:08 AM	Л			
Flores, Pe	ete	Yearly - Santa T Refer to PMsch		er 0416 - Grounds -				
Margret Vi	illalobos							
165155				11/29/2016		41		\$0.00
Medium	Work In Progress			11/29/2016 2:50:28 PM	1			
Flores, Pe	ete	Gator #0527 ne	eds to get service					

1/9/2017 3:07:23 PM Page 102 of 122

Guadalupe Ontiveros

Total Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID Until **Request Date Target Comp Date Davs** Labor Area **Deferred By** Aged Hours Area Number Reason Created Date/Time Actual Comp Date Status **Priority Action Taken Assigned To** Description Requester Name Santa Teresa MS Location: 165832 12/7/2016 33 \$0.00 Medium Work In Progress 12/7/2016 3:57:05 PM Lara, Ralph Attn: Ralph Lara Gym boys locker restroom partition door needs to be replaced as soon as possible. Mr. Wells will have parents of student payfor the damage. Please contact him so that we can take care of this vandalism. Jaime Mijarez 12/5/2016 35 \$0.00 165624 Medium Work In Progress 12/5/2016 10:14:09 AM Lara, Ralph Gym boys locker room. Partition door to restroom was broken off and needs to be replaced. Will need a cost of everything so that I can add to the vandalism report. Jaime Mijarez North Building Office 10/11/2016 90 \$0.00 162451 10/11/2016 10:36:39 Medium Work In Progress Prospero, Manuel 10/11/16. NEED TO ADJUSTED DOOR FROM HITTING DOOR FRAME AND INSTALLED DOOR CLOSER ALSO. Manuel Prospero North Building Classroom 8/2/2016 160 \$0.00 157751 Medium Work In Progress 8/2/2016 7:31:37 AM A.C water leak in class room 17-2 floor north building. Prospero, Manuel Ismael Rodriguez 160348 South Building Restroom 9/7/2016 124 \$0.00 **SOUTH OFFICE** 9/7/2016 8:11:14 AM Work In Progress Medium REPAIR EXHAUST FANS IN THE RESTROOMS Prospero, Manuel Laura Parra South Building Restroom 8/26/2016 136 \$0.00 159558 SOUTH OFFICE 8/26/2016 11:26:26 AM Work In Progress Medium Prospero, Manuel EXHAUST FANS IN THE RESTROOMS DO NOT WORK. Laura Parra

1/9/2017 3:07:23 PM Page 103 of 122

WOID	Building	Area Deferred By	-	Target Comp Date	Days	Labor	
Priority	Status	Area Number Reason	Created Date/Time	-	Aged	Hours	
Assigned		Description		Action Taken			
Requeste	r Name						
Location:	Santa Te	resa MS					
161672			9/28/2016		103		\$0.00
Medium	Work In Progress		9/28/2016 3:14:43 PM	Л			
Medina, E	ric	May I submit a work order for the exhaworking correctly, there is too much so kitchen area. Manny(Building Mechanisaid it was running slow.	noke in the				
Maritza Go	onzalez						
160815			9/14/2016		117		\$0.00
Medium	Work In Progress		9/14/2016 10:18:14 AN	Л			
Medina, E	ric	3 COMPARTMENT SINK NEEDS NEV MANAGER GESSICA M. 589.9836	V PLUGS. SNP				
Maritza Go	onzalez						
163624			10/28/2016		73		\$0.00
Medium	Work In Progress		10/28/2016 1:57:26 PM	1			
Villalobos	, David	ICE MACHINE- FILTER NEEDS TO BI ICE IS COMING OUT DIRTY. SNP MA GESSICA M. 589.9836	-				
Maritza Go	onzalez						
165055			11/28/2016		42		\$0.00
Medium	Work In Progress		11/28/2016 2:49:37 PM	1			
Villalobos	, David	BATHROOM SINK IS LEAKING FROM MANAGER GESSICA M.589.9836	BOTTOM. SNP				
Maritza Go	onzalez						
159403	North Building	Kitchen	8/24/2016		138		\$0.00
Medium	Work In Progress		8/24/2016 2:32:25 PM	Л			
Ontiveros	, Joe	PUMP TO RAYPACK IS LEAKING AND REPLACED	NEEDS TO BE				
Manuel Pr	rospero						
158575			8/12/2016		150		\$0.00
Medium	Work In Progress		8/12/2016 8:03:28 AM	Л			
Mijarez, Ja	aime	Need to anchor small bleachers with t	es.	Routed to BM 11/28	3/16		
Alfredo Ho	olguin						
160810			9/14/2016		117		\$0.00
Medium	Work In Progress		9/14/2016 10:13:01 AM	1			
Mijarez, Ja	aime	VENTS IN KITCHEN NEED TO BE CL MANAGER GESSICA M. 589.9836	EANED. SNP				
Maritza Go		MANAGER GESSICA M. 589.9836					

1/9/2017 3:07:23 PM Page 104 of 122

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2016 - 12/3/ Area De Area Number Re Description	eferred By		Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa MS						
160811				9/14/2016		117		\$0.00
Medium	Work In Progress			9/14/2016 10:14:09 AM	1			
Mijarez, Jaime		KITCHEN-SOME (REPLACED SNP I		_				
Maritza Go	nzalez							
160813				9/14/2016		117		\$0.00
Medium	Work In Progress			9/14/2016 10:15:05 AM	1			
Mijarez, Jaime		SIDING IN WASH UNDONE. SNP M						
Maritza Go	nzalez							
158066	South Building	Kitchen		8/5/2016		157		\$0.00
Medium	Work In Progress			8/5/2016 12:35:35 PM	1			
Prospero, Manuel		Fix the hole in the building office area		to water leak south				
Ismael Ro	driguez							
161269	North Building	Office		9/21/2016		110		\$0.00
Medium	Work In Progress	JOE ACOSTA-		9/21/2016 12:52:58 PM	l			
Gonzalez,	Salvador	WELD HANDLE O	N GATOR. SEE N	MR ACOSTA				
Laura Pari	a							
166087				12/13/2016		27		\$0.00
Medium	Work In Progress			12/13/2016 1:23:41 PM				
Carrasco, Danny		Attn: Danny C. I ne so that I can insula bldg before we go	ite a water line out	per pipe insulation side of the south				
Jaime Mija								
156776	North Building	Classroom		7/20/2016		173		\$0.00
Medium	Work In Progress	20-Hernandez		7/20/2016 3:23:07 PM	1			
Lara, Ralph		DOOR TO COUNT REPLACE OR RE SCIENCE EQUIPM	PAIR. NEEDED T					
Laura Parı	ra							
160809				9/14/2016		117		\$0.00
Medium	Work In Progress			9/14/2016 10:12:04 AM	1			
Mijarez, Jaime		INCOMPLETE PAI DOORS ARE PAIN 589.9836						
Maritza Go	nzalez							

1/9/2017 3:07:23 PM Page 105 of 122

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2016 - 12/31/2016 Order By L Area Deferred By Area Number Reason Description	Until Request Date Created Date/Time	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Santa Te	resa MS					
163082			10/20/2016		81		\$0.00
Medium	Work In Progress		10/20/2016 8:34:21 AV	I			
Mijarez, Jaime		KITCHEN BATHROOM - MOLD UI CRACKED WALLS.	NDER BASEBOARD,				
Maritza Go							
158065	South Building	Office	8/5/2016		157		\$0.00
Medium	Work In Progress		8/5/2016 12:33:17 PM	1			
Lara, Ralph		Replace doors in south building of there in bad shape.	ffice as per principle				
Ismael Ro							
165632	North Building	Custodial	12/5/2016		35		\$0.00
Medium	Work In Progress		12/5/2016 11:23:09 AM	I			
Villalobos,	, Jose	Service air blower STIHL Serial #9	978 tune up thank you.				
Ismael Ro	driguez						
161437	North Building	Classroom	9/23/2016		108		\$0.00
Medium	Work In Progress		9/23/2016 2:26:19 PM	1			
Prospero,	Manuel	9/23/16. NEED REPLACE 12 V CONTACTO	OR A/C ROOM 15.				
Manuel Pr	ospero						
159381			8/24/2016		138		\$0.00
Medium	Work In Progress		8/24/2016 9:45:11 AM	I			
Prospero, Manuel		8/24/16. REQUEST FOR PL-36 BOOSTEF 115V/60HRZ XL11 BEARING SYS					
Manuel Pr	ospero						
158805			8/16/2016		146		\$0.00
Medium	Work In Progress		8/16/2016 2:44:59 PM	1			
Prospero, Manuel		8/16/16. NEED CHANGED AIR FILTERS N BUILDINGS AND PORTABLES.	IORTH ,SOUTH				
Manuel Pr	ospero						
157966			8/4/2016		158		\$0.00
Medium	Work In Progress		8/4/2016 9:40:23 AM	I			
Prospero, Manuel		8/4/16. HAVE PROBLEM WITH THE LAP TOMMUNICATING WITH THE SO NEED TO REPLACE LAP TAP A.S	UTH BUILDING.				

1/9/2017 3:07:23 PM Page 106 of 122

Manuel Prospero

Total Selected Date Range for Request Dates:7/1/2016 - 12/31/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Area Number Reason **Created Date/Time Actual Comp Date Status Priority Assigned To Description Action Taken** Requester Name Location: Santa Teresa MS 164398 11/7/2016 63 \$0.00 Work In Progress 11/7/2016 3:51:48 PM Medium Ambriz, Jose Please order motor for north bldg upper level storage static inducer exhaust system. Jaime Mijarez 132 North Building Custodial 8/30/2016 \$0.00 159722 Medium Work In Progress 8/30/2016 7:40:59 AM Flores, Pete Ad a roof top to the Gator every time it rains we get wet specially when we travel north to south building thank you. Ismael Rodriguez Count: 36 Work Orders **Total for Santa Teresa MS** 0 Avg. Age of WO's 99 \$0.00

1/9/2017 3:07:23 PM Page 107 of 122

WOID	Building	Dates:7/1/2016 - 12/31/2016 Order By Lo Area Deferred By	Until Request Date	Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number Reason	Created Date/Time	•	Aged	Hours	
Assigned To		Description		Action Taken			
Requester							
Location:	Sunland	Park ES					
164167			11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress		11/6/2016 12:40:31 AM	1			
Medina, Eric		Monthly-Sunland Park ES Range H Refer to PMschedule details.	ood Cleaning -				
Margret Vi	llalobos						
165542			12/4/2016	12/12/2016	36		\$0.00
Medium	Work In Progress		12/4/2016 12:43:36 AM	1			
Prospero, Manuel		Monthly - Sunland Park ES Exit Sign Refer to PMschedule details.	n Insp: Monthly-				
Margret Vi	llalobos						
165543			12/4/2016	12/12/2016	36		\$0.00
Medium	Work In Progress		12/4/2016 12:43:36 AM	1			
Prospero, Manuel		Monthly - Sunland Park ES Emer Li Refer to PMschedule details.	ght Test: Monthly-				
Margret Vi	llalobos						
165593			12/4/2016	12/10/2016	36		\$0.00
Medium	Work In Progress		12/4/2016 12:44:13 AM	1			
Prospero,	Manuel	Monthly - Sunland Park ES Monthly Refer to PMschedule details.	FE Inspection -				
Margret Vi	llalobos						
165976			12/11/2016	12/27/2016	29		\$0.00
Medium	Work In Progress		12/11/2016 12:38:10)			
Prospero,	Manuel	Monthly - Sunland Park ES Playgro PMschedule details.	und Insp - Refer to				
Margret Vi	llalobos						
164190			11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress		11/6/2016 12:40:47 AM	1			
Medina, Eric		Monthly-Sunland Park ES Fire Supplements to PMschedule details.	oression Insp				
Margret Vi	llalobos						
164138			11/6/2016		64		\$0.00
Medium	Work In Progress		11/6/2016 12:40:11 AM	1			
Medina, Eric		Yearly - Sunland Park ES - Grease schedule details.	Trap - Refer to PM				
Margret Vi	llalobos						

1/9/2017 3:07:23 PM Page 108 of 122

Total Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID **Request Date Target Comp Date Days** Labor Deferred By Until Aged Hours Area Number Reason Created Date/Time Actual Comp Date Status **Priority Assigned To** Description **Action Taken** Requester Name Sunland Park ES Location: 163328 Classroom 10/25/2016 76 \$0.00 10/25/2016 9:46:25 AM Work In Progress Medium Teachers Ontiveros, Joe Please check the faucet in the teachers lounge is leaking, please check. Angie Flores 75 163460 Classroom 10/26/2016 \$0.00 Teachers Loune 10/26/2016 3:36:06 PM Medium Work In Progress Ontiveros, Joe Please fixwater faucet in the teachers lounge, its constantlydripping Angie Flores 112 9/19/2016 \$0.00 161078 Medium Work In Progress Main Hallway 9/19/2016 9:41:36 AM Need blinds for the Main Hallway Windows and also for Mijarez, Jaime the Hallwaythat leads to the Cafeteria, please measure windows, order blinds and install, we need these as soon as possible, thank you! **Angie Flores** Classroom 8/22/2016 140 \$0.00 159179 Medium Work In Progress 8/22/2016 12:32:51 PM Mijarez, Jaime Quitan el calenton del bano. Angie Flores 159503 Classroom 8/25/2016 137 \$0.00 Work In Progress Room 40 8/25/2016 2:51:43 PM Medium Mijarez, Jaime Classroom does not have flags, please check to see if you have extras and if so please set them up in classroom. Thank you! **Angie Flores** 166138 Main Building Classroom 12/14/2016 \$0.00 Medium Work In Progress 12/14/2016 9:04:05 AM Prospero, Manuel Please assemble the computer tables that where delivered since 11/10/16, we need the computer tables assembled immediately. Angie Flores 12/1/2016 \$0.00 165328 Library 12/1/2016 11:06:37 AM Work In Progress Medium Library Prospero, Manuel Need to have pictures hung on the walls before the board meeting. Angie Flores

1/9/2017 3:07:23 PM Page 109 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Da	ate Range for Request Building	Dates:7/1/2016 - 1 Area	2/31/2016 Order By L		Target Comp Date	Days	Labor	Costs	
Priority	Status	Area Number	•	Created Date/Time	•	Aged	Hours		
Assigned		Description	reason	Groatou Bato, Filino	Action Taken				
Requeste		2000			7.0				
Location:	Sunland	Park ES							
165817		Gym		12/7/2016		33		\$0.00	
Medium	Work In Progress	Gym		12/7/2016 3:49:52 PM	1				
Prospero,	Manuel	on Tuesday De	set up infront of the ec 13th by 12 pm. T Dec 14th after conc	hey can be taken					
Angie Flor	res								
165813		Gym		12/7/2016		33		\$0.00	
Medium	Work In Progress	Gym		12/7/2016 3:48:17 PM	1				
Prospero,	Manuel	coaches office	set up for board mee bythe outside door. during set up of boa	Need them on					
Angie Flor	res								
163197		Parking Lot		10/21/2016		80		\$0.00	
Medium	Work In Progress			10/21/2016 3:40:43 PM					
Prospero,	, Manuel		D PAINT PARKING I ELOW AND BLUE						
Manuel Pr	rospero								
163093	Main Building	Restroom		10/20/2016		81		\$0.00	
Medium	Work In Progress			10/20/2016 12:17:44					
Prospero,	, Manuel	10/20/16. REQUESTING ROOM 38 THA	A NEW SEAT FOR NKS.	THE TOILET IN					
Manuel Pr	rospero								
163888		Office		11/2/2016		68		\$0.00	
Medium	Work In Progress	From Office to		11/2/2016 1:49:10 PM	1				
Prospero,	Manuel	area of the offic and the other 3	e the blinds on the si ce and set them up set them up in the w see Angie if you have	in Mrs. Kahoes Office vindows across the					
Angie Flor	res								
161077		Mechanical		9/19/2016		112		\$0.00	
Medium	Work In Progress	Principals Office	œ	9/19/2016 9:35:47 AV	1				
Mijarez, Ja	aime	windows, orde	Need blinds for Principals Office, please measure windows, order blinds and set up blinds. We need them as soon as possible, thank you!						
Angie Flor	res	•	-						

1/9/2017 3:07:23 PM Page 110 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Da WOID Priority	ate Range for Request Building Status	Dates:7/1/2016 - 1 Area Area Number	2/31/2016 Order By Loc Deferred By Reason		Target Comp Date Actual Comp Date	Days Aged	Labor Hours	Costs
Assigned		Description	11040011	0.00.00	Action Taken			
Requeste	r Name	-						
Location:	Sunland	Park ES						
157335		Office		7/28/2016		165		\$0.00
Medium	Work In Progress	Outside New		7/28/2016 3:33:58 PN	1			
Mijarez, Ja	aime		he main office sign the ocate it next to the ne					
Angie Flo	res							
160817				9/14/2016		117		\$0.00
Medium	Work In Progress			9/14/2016 10:20:41 AM	1			
Castillo, C	Carlos	-	DS BACK DOOR BEI IACIA C.589-2545	LL INSTALED. SNP				
Maritza G	onzalez							
165438				12/2/2016		38		\$0.00
Medium	Work In Progress			12/2/2016 12:56:04 PM	1			
Villalobos	s, David	_	2 OVENS NOT TURN IACIA C. 589.2545	ING ON. SNP				
Maritza G	onzalez							
160797				9/14/2016		117		\$0.00
Medium	Work In Progress			9/14/2016 9:12:23 AM	1			
Lara, Ralp	oh		O KITCHEN NEEDS R IGNACIA C.589-254					
Maritza G	onzalez							
163692	Main Building	Office		10/31/2016		70		\$0.00
Medium	Work In Progress			10/31/2016 8:46:02 AM	1			
Prospero	, Manuel		new signs for the ma trance) that would be lding thanks.					
Manuel P	rospero							
156598				7/18/2016		175		\$0.00
Medium	Work In Progress			7/18/2016 9:18:12 AM	1			
Mijarez, Ja	aime	Blinds for for th	e hallways and the pri	ncipal's office.				
Rosa Kal	noe							
163234				10/24/2016		77		\$0.00
Medium	Work In Progress	Enterance by		10/24/2016 9:34:34 AM	1			
Prospero	, Manuel		he roof over the back e le from the water it ret					
Angie Flo	res	-						

1/9/2017 3:07:23 PM Page 111 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Da	ite Range for Request Building	Dates:7/1/2016 - 1 Area	2/31/2016 Order By L		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Aged	Hours	
Assigned	То	Description			Action Taken			
Requester	Name							
Location:	Sunland	Park ES						
159939		Cafeteria		9/1/2016		130		\$0.00
Medium	Work In Progress	Cafeteria		9/1/2016 8:59:07 AM	1			
Mijarez, Ja	ime	Roof is leaking	g, please fix, ASAP					
Angie Flor	es							
157043				7/25/2016		168		\$0.00
Medium	Work In Progress			7/25/2016 12:53:36 PM	I			
Mijarez, Ja	ime	Paint portable :	south of school.					
Albert Vall	ejo							
166063	Main Building	Custodial		12/13/2016		27		\$0.00
Medium	Work In Progress			12/13/2016 7:23:41 AM	1			
Villalobos	, Jose	VACUUMS I BE	D PLEASE CHECK (ELIEVE THERE IS A ON CORD IT DOES	PROBLEM WITH				
Jesus Luc	cero							
159486				8/25/2016		137		\$0.00
Medium	Work In Progress	Main		8/25/2016 12:26:24 PM	l			
Lucero, Je	sus	Hallway that le Board meeting	e following floors - N ads to the gym. We on Dec 8 2016 so p ek so that can be dr	will be having a				
Angie Flor	es							
159487				8/25/2016		137		\$0.00
Medium	Work In Progress	All Windows		8/25/2016 12:29:58 PM	I			
Lucero, Je	sus	ones infront of hallway, we wil December 8 20		ne office area and				
Angie Flor	es							
160821				9/14/2016		117		\$0.00
Medium	Work In Progress	Playground Are	ea	9/14/2016 11:02:10 AM	1			
Lucero, Je	sus	Please clean the playground, the	ne graffiti in the shad ank you!	e area in the				
Angie Flor	es							

1/9/2017 3:07:23 PM Page 112 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Da	ate Range for Request Building	Dates:7/1/2016 - 1 Area	12/31/2016 Order By Lo Deferred By		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number	•	Created Date/Time	•	Aged	Hours	
Assigned	То	Description			Action Taken			
Requeste		•						
Location:	Sunland	Park ES						
165936	Main Building	Classroom		12/9/2016		31		\$0.00
Medium	Work In Progress			12/9/2016 12:46:23 PM	I			
Prospero,	, Manuel	12/9/16. HAVIN TROUE	LE SHOOTER HEA	TER ROOM 40.				
Manuel Pr	rospero							
165370				12/1/2016		39		\$0.00
Medium	Work In Progress			12/1/2016 3:44:54 PM	1			
Vallejo, Al	bert	Playground - W	ood-chip upgrade					
Albert Vall	ejo							
164530				11/9/2016		61		\$0.00
Medium	Work In Progress			11/9/2016 3:45:17 PM	1			
Prospero,	, Manuel	11/9/16. STARTED WA	TER HEATERS FOR	R WINTER STATION.				
Manuel Pr	rospero							
165714		Computer Lab		12/6/2016		34		\$0.00
Medium	Work In Progress	Computer Lab	-	12/6/2016 1:27:33 PM	1			
Castillo, C	Carlos		outlets on the pole as e need this done imr					
Angie Flor	res							
Count: 37	Work Orders	A	vg. Age of WO's 8	31 T	otal for Sunland Par	k ES	0	\$0.00

1/9/2017 3:07:23 PM Page 113 of 122

Hector Tellez

WOID	Building	Dates:7/1/2016 - 12/31/2016 Order By Area Deferred By		Target Comp Date	Days	Labor	Costs
Priority	Status	Area Number Reason	Created Date/Time	-	Aged	Hours	
Assigned	То	Description		Action Taken			
Requester	r Name						
Location:	Sunrise I	ES					
164191			11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress		11/6/2016 12:40:48 AM	I			
Medina, E	ric	Monthly-Sunrise ES Fire Suppre PMschedule details.	ession Insp Refer to				
Margret Vi	llalobos						
164168			11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress		11/6/2016 12:40:32 AM	I			
Medina, E	ric	Monthly-Sunrise ES Range Hoo PMschedule details.	od Cleaning - Refer to				
Margret Vi	llalobos						
165986			12/11/2016	12/27/2016	29		\$0.00
Medium	Work In Progress		12/11/2016 12:38:19				
Tellez, He	ctor	Monthly - Sunrise ES Playgroun schedule details.	d Insp - Refer to PM				
Margret Vi	llalobos						
165486			12/4/2016		36		\$0.00
Medium	Work In Progress		12/4/2016 12:42:55 AM	I			
Tellez, He	ctor	Monthly - Sunrise ES A-11 Quar schedule details.	terly ERV - Refer to PM				
Margret Vi	llalobos						
165487			12/4/2016		36		\$0.00
Medium	Work In Progress		12/4/2016 12:42:55 AM				
Tellez, He	ctor	Monthly - Sunrise ES C-6 Quart schedule details.	erly HP - Refer to PM				
Margret Vi	llalobos						
165488			12/4/2016		36		\$0.00
Medium	Work In Progress		12/4/2016 12:42:56 AM	I			
Tellez, He	ctor	Monthly - Sunrise ES C-4 Quart schedule details.	erly SS - Refer to PM				
Margret Vi	llalobos						
164907			11/17/2016		53		\$0.00
Medium	Work In Progress		11/17/2016 2:07:35 PM				
Tellez, He	ctor	need 6-4 lamp ballast for lights	@ sunrise portables				

1/9/2017 3:07:23 PM Page 114 of 122

Gerardo Marquez

Total Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID Area Until **Request Date Target Comp Date Days** Labor **Deferred By** Aged Hours Area Number Reason Status Created Date/Time Actual Comp Date **Priority Action Taken Assigned To** Description Requester Name Sunrise ES Location: 164145 11/6/2016 64 \$0.00 Medium Work In Progress 11/6/2016 12:40:16 AM Medina, Eric Yearly - Sunrise ES - Grease Trap - Refer to PM schedule details. Margret Villalobos 9/1/2016 130 \$0.00 159964 Medium Work In Progress 9/1/2016 1:18:00 PM Tellez. Hector 9/01/16 requesting a push button automatic door unlock for the secretaries at front desk **Hector Tellez** 12/1/2016 39 \$0.00 165341 12/1/2016 2:38:15 PM Medium Work In Progress Tellez, Hector need nuts and bolts for playground climbing equipment, and bracket for guard on slides **Hector Tellez** 11/2/2016 68 \$0.00 163889 Medium Work In Progress 11/2/2016 1:53:32 PM Tellez, Hector Need bucket truck for installation of lights/ballast at chaparral HS..WO 163350 need the truck Nov 3 2016 or when available **Hector Tellez** 12/12/2016 165999 28 \$0.00 Medium Work In Progress 12/12/2016 9:08:47 AM ICE MACHINE NOT MAKING ICE. SNP MANAGER Villalobos, David GLENDA G. 824.3194 Maritza Gonzalez 10/4/2016 97 \$0.00 162192 Medium Work In Progress 10/4/2016 7:47:03 AM NEED A GATE KEY FOR CHAPARRAL HIGH SCHOOL Marquez, Gerardo ISSUED TO C.D. MECHANICAL.

1/9/2017 3:07:23 PM Page 115 of 122

730 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2016 - 12/31/2016 Order By Location, Status Costs Building WOID **Deferred By Request Date Target Comp Date Davs** Labor Area Until Aged Hours Created Date/Time Actual Comp Date Status Area Number Reason **Priority Action Taken Assigned To** Description Requester Name Sunrise ES Location: 158678 8/15/2016 147 \$0.00 Medium Work In Progress 8/15/2016 10:00:17 AM Medina, Eric ONE FOR THE HAND SINK ON THE EAST SIDE OF Resigned to Eric Medina SNP Equip. KITCHEN. THE HOT WATER IS ONLY AT 85* AND Tech. THE STATE ENVIRONMENTAL SAYS IT NEEDS TO BE AT 100*. THEY WROTE ME UP FOR THIS AND IT NEEDS TO BE FIXED WITHIN TEN DAYS. SNP MANAGER GLENDA G. 824.3194 Maritza Gonzalez 158401 Classroom 8/10/2016 152 \$0.00 Medium Work In Progress 212 8/10/2016 12:27:59 PM Marquez, Gerardo NIDIA MORA, 212, BOTH DOORS IN CLASSROOMS WILL NOT CLOSE PROPERLY CLOSET DOORS IN CLASSROOM ARE MISSING LATCH Joanne Munoz Kitchen 11/28/2016 42 \$0.00 165019 High Work In Progress 11/28/2016 8:57:02 AM Reach In temp at 66° SNP Mgr. Glenda G. (575) 824-Medina, Eric 3194 Dino Facio Main Building Classroom 8/5/2016 157 \$0.00 158095 Medium Work In Progress 303 8/5/2016 3:39:11 PM JOANNE MUNOZ, FRONT OFFICE, NEED Marquez, Gerardo REPLACEMENT KEYS FOR 303 CLASSROOM, CAN NOT FIND. 1C18, TS109, 142E, 105E Joanne Munoz 166010 12/12/2016 28 \$0.00 12/12/2016 12:46:04 Medium Work In Progress Villalobos, Jose Stihl Blower Ser. #38539 is not working properly. Can't start at all. Please repair and tune up. Thank you. Felipe Gallegos 12/8/2016 32 \$0.00 165860 Medium Work In Progress 12/8/2016 12:06:53 PM Need spades and fork terminals for heater/cooler Tellez, Hector connections Hector Tellez

1/9/2017 3:07:23 PM Page 116 of 122

Total Selected Date Range for Request Dates:7/1/2016 - 12/31/2016 Order By Location, Status Costs WOID Building **Request Date Target Comp Date** Labor Area **Deferred By** Until **Days** Hours Aged Area Number Reason **Created Date/Time Actual Comp Date Status Priority Assigned To Description Action Taken** Requester Name Location: Sunrise ES 158203 Classroom 8/8/2016 10 \$0.00 Medium Work In Progress 302 8/8/2016 2:31:11 PM 8/18/2016 I need a 8 ft ladder and flashlight as per hector tellez Tellez, Hector **Hector Tellez** 165844 12/8/2016 32 \$0.00 Medium Work In Progress 12/8/2016 9:41:03 AM Please refill propane tank to Propane Burnishing Unit-Herrera, Marin Ser # 122550. Thank you. Felipe Gallegos **Count: 21 Work Orders** Avg. Age of WO's 64 Total for Sunrise ES 0 \$0.00

1/9/2017 3:07:23 PM Page 117 of 122

Requester N Location: 157763 Medium \ , Maritza Gonz 164374	Vado ES Work In Progress	8/2/2016 8/2/2016 9:03:16 AM WALK IN IS AT 51 DEGREES. SNP MANAGER ELIZABETH M. 233-2945	160	\$0.00
Medium \ , Maritza Gonz	-	8/2/2016 9:03:16 AM WALK IN IS AT 51 DEGREES. SNP MANAGER	160	\$0.00
, Maritza Gonz	-	WALK IN IS AT 51 DEGREES. SNP MANAGER		
, Maritza Gonz	-			
	zalez			
16/27/				
104374		11/7/2016	63	\$0.00
Medium \	Work In Progress	11/7/2016 3:25:37 PM		
Medina, Eric	;	SLICER IS NOT WORKING. SNP MANAGER ELIZABETH M. 233.2945		
Maritza Gonz	zalez			
165148		11/29/2016	41	\$0.00
Medium \	Work In Progress	11/29/2016 2:10:44 PM		
Ronquillo, R	uben	need sign to read (ADULT SUPERVISION REQUIRED)		
Danny Miran	nda			
165149		11/29/2016	41	\$0.00
Medium \	Work In Progress	11/29/2016 2:15:01 PM		
Ronquillo, R	uben	NEED SIGNS FOR PLAYGROUND AGE RANGE		
Danny Miran	nda			
165228		11/30/2016	40	\$0.00
Medium \	Work In Progress	11/30/2016 8:42:21 AM		
Gonzalez, Sa	alvador	need 5 post and 4 31 ft. long of chain to block off front part of entranc		
Danny Miran	nda			
165420		12/2/2016	38	\$0.00
Medium \	Work In Progress	12/2/2016 11:26:28 AM		
Carrasco, Da	anny	need two 16 ft. of cable - eight flag hooks - two signs reading (GADSDEN VEHICLES ONLY)		
Danny Miran	nda			
165780		12/7/2016	33	\$0.00
Medium \	Work In Progress	12/7/2016 10:13:48 AM		
Appelzoller,		need to replace faucets in teachers lounge and room 101 SP/ED		
Danny Miran	nda	*******	0.4	
165698		12/6/2016	34	\$0.00
Medium \	Work In Progress	12/6/2016 9:06:38 AM		
Appelzoller, Danny Miran		need new faucet in teachers lounge replaced		

1/9/2017 3:07:23 PM Page 118 of 122

WOID Priority Assigned			rred By	Until Re	=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Location:	Vado ES								
164141					11/6/2016		64		\$0.00
Medium	Work In Progress			11/6/2016	12:40:13 AM				
Medina, Er	ic	Yearly - Vado ES - Gr details.	ease Trap - Re	efer to PM sched	dule				
Margret Vil	lalobos								
165548					12/4/2016	12/12/2016	36		\$0.00
Medium	Work In Progress			12/4/2016	12:43:40 AM				
Miranda, D	anny	Monthly - Vado ES En PMschedule details.	ner. Light Test:	Monthly - Refer	to				
Margret Vil	lalobos								
164169					11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress			11/6/2016	12:40:33 AM				
Medina, Er	ic	Monthly - Vado ES Ra schedule details.	ange Hood Clea	aning - Refer to	PM				
Margret Vil	lalobos								
164192					11/6/2016	11/27/2016	64		\$0.00
Medium	Work In Progress			11/6/2016	12:40:49 AM				
Medina, Er	ic	Monthly - Vado ES Fir schedule details.	e Suppression	Insp Refer to	PM				
Margret Vil	lalobos								
166142	Main Building	Custodial			12/14/2016		26		\$0.00
Medium	Work In Progress			12/14/20)16 10:28:20				
Herrera, M	arin	Need propane tank to	b refill. Thank	you!					
Armando [Diaz								
166002					12/12/2016		28		\$0.00
Medium	Work In Progress			12/12/2016	9:11:38 AM				
Villalobos,	Margret	AS PER ENVIRONME REPORT- KITCHEN/ FOGGED FOR FLIES	CAFETERIA NE			Em Waiver 12/12/16			
Maritza Go	nzalez								
156593					7/18/2016		175		\$0.00
Medium	Work In Progress			7/18/2016	8:57:55 AM				
Carbajal, J	immy	need to replace carpe carpet strips in front e were door was remov	ntrance and by						
Danny Mira	nda								

1/9/2017 3:07:23 PM Page 119 of 122

WOID Priority Assigned Requester	Building Status To	Dates:7/1/2016 - 12/31/2016 Order By Loca Area Deferred By Area Number Reason Description	Days Aged	Labor Hours			
Location:	Yucca He	eights ES					
164125			11/6/2016		64		\$0.00
Medium	Work In Progress		11/6/2016 12:40:01 AM				
Medina, E	ric	Monthly - Yucca Heights ES - Fire Su Refer to PMschedule details.	ppression Insp -				
Margret Vi	llalobos						
164127			11/6/2016		64		\$0.00
Medium	Work In Progress		11/6/2016 12:40:02 AM				
Medina, E	ric	Yearly - Yucca Heights ES - Grease 1 schedule details.	Frap - Refer to PM				
Margret Vi	llalobos						
164126			11/6/2016		64		\$0.00
Medium	Work In Progress		11/6/2016 12:40:02 AM				
Medina, E		Monthly - Yucca Heights ES - Range Refer to PMschedule details.	Hood Cleaning -				
Margret Vi	llalobos		40/44/0040				ФО 00
165974			12/11/2016		29		\$0.00
Medium	Work In Progress		12/11/2016 12:38:08				
Vargas, Ju		Monthly - Yucca Heights ES - Playgro Refer to PMschedule details.	und Insp (M) -				
Margret Vi	llalobos		7/05/0040		4.00		ФО 00
157062			7/25/2016		168		\$0.00
Medium	Work In Progress		7/25/2016 3:19:45 PM				
Marquez, (Gerardo	Please cut three (3) keys for pump hor Heights. Keys to be given to school pri Should you have any questions or nee information, please contact Mr. Ralph 882-6921	incipal. ed more				
Dominiqu	e Esparza						
158694			8/15/2016		147		\$0.00
Medium	Work In Progress		8/15/2016 12:59:11 PM				
Marquez, 0	Gerardo	room 217 need fix core lock the key	not open				
Juan Varg	as						
157774			8/2/2016		160		\$0.00
Medium	Work In Progress		8/2/2016 11:14:09 AM				
Marquez, 0	Gerardo	need four locks for fance gates					
luon Vora							

1/9/2017 3:07:23 PM Page 120 of 122

Juan Vargas

WOID Priority	Building Status	Area Area Number	2/31/2016 Order By Lo Deferred By Reason	Until	=	Target Comp Date Actual Comp Date Action Taken	Days Aged	Labor Hours	Costs
Assigned 1 Requester		Description				Action raken			
Location:	Yucca He	eights FS							
162908					10/18/2016		83		\$0.00
	Work In Broaross			10/10/2		1	0.5		ψ0.00
Medium	Work In Progress				:016 9:56:26 AM	ı			
Esparza, D	ominique	BY WARRANT need fix lights s	Y in main office 110 v switch	women restr	oom				
Juan Varga	as								
163620					10/28/2016		73		\$0.00
Medium	Work In Progress			10/2	8/2016 12:53:41				
Gallegos, I	Rafael	BY WARRANT' work	Y split system a/c in 3	308 room ID	Fnot				
Juan Varga	as								
160459					9/8/2016		123		\$0.00
Medium	Work In Progress			9/8/20	16 12:09:03 PN	1			
Vargas, Ju	an		19- 1/4 x19-14x3 1/2 3/4 111/4x23 1/4 3 1/		3				
Juan Varga	as								
160460					9/8/2016		123		\$0.00
Medium	Work In Progress			9/8/20	16 12:13:48 PM	1			
Vargas, Ju	an		19- 1/4 x19-14x3 1/2 3/4 111/4x23 1/4 3 1/		3				
Juan Varga	as								
163618					10/28/2016		73		\$0.00
Medium	Work In Progress			10/2	8/2016 12:40:18	}			
Gallegos, I	Rafael	BY WARRANT' equipment	Y need check and fix	play ground					
Juan Varga	as								
163619					10/28/2016		73		\$0.00
Medium	Work In Progress			10/2	8/2016 12:46:24	l .			
Gallegos, I	Rafael	BY WARRANT' panel is have lo	Y in 200 wing need on	check electri	cal				
Juan Varga	as								
163693					10/31/2016		70		\$0.00
Medium	Work In Progress			10/31/2	:016 8:49:17 AM	1			
Gallegos, I	Rafael	BY WARRANT	Y the outside fire drill	l speakers n	ot work				
Juan Varga			i ille outside life dfill	i speakers n	UL WUIK				

1/9/2017 3:07:23 PM Page 121 of 122

130 - Work Orders in Frogress (Fiscal Teal)									Tota
Selected Da WOID	ate Range for Request Building	Dates:7/1/2016 - 1 Area	2/31/2016 Order By Lo Deferred By	ocation, Status Until				Labor	Costs
Priority	Status	Area Number	Reason	Crea	ted Date/Time	Actual Comp Date	Aged	Hours	
Assigned	То	Description				Action Taken			
Requester	r Name								
Location:	Yucca He	ights ES							
161335					9/22/2016		-1		\$0.00
Medium	Work In Progress			9/22/2	016 7:32:56 AM	9/21/2016			
Diaz, Erne	sto	Room 322 the	soap dispenser is le	aking soap					
Juan Varg	as								
166226		Custodial			12/15/2016		25		\$0.00
Medium	Work In Progress			12/15/2	016 2:37:31 PM				
Herrera, M	Marin	Need propane	please, thank you!						
Ernesto D	iaz								
Count: 16	Work Orders	A	vg. Age of WO's 8	4	To	tal for Yucca Height	s ES	0	\$0.00
Count: 73	30 Work Orders	A	/g. Age of WO's 7	9		Grand Total		0	\$0.00

1/9/2017 3:07:23 PM Page 122 of 122