

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Alta Vista ECHS</b>									
227145					12/18/2019		208		\$0.00
Medium	Work In Progress	17			12/18/2019 8:29:44 AM				
Marquez, Gerardo		For student safety it has been recommended that the boys bathroom stalls be replaced as well as the divider next to the urinal. Current are unsafe and located too close to the urinal.				Pending asp report 5/7/20			
Melanie Beegle									
230031					3/4/2020		131		\$0.00
Medium	Work In Progress	11			3/4/2020 8:50:03 AM				
Marquez, Gerardo		Please fix the door in P11. The door is hard to open.				Pending asp report 5/7/20			
Melanie Beegle									
<b>Count: 2 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>170</b>		<b>Total for Alta Vista ECHS</b>	<b>0</b>		<b>\$0.00</b>

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Anthony - On Track Pre-K (Village)</b>										
232246		Parking Lot			6/2/2020		41		\$0.00	
Medium	Work In Progress	the pre-k parent			6/2/2020 2:41:51 PM					
Gonzalez, Salvador		Please set pole for marquee. It will be located on the corner of the prek parent entrance parking lot. Next to the light pole. Please contact David Soriano for more details on how we want the sign. He can be reached at 915-731-1957.								
Michelle Soto										
232247		Parking Lot			6/2/2020		41		\$0.00	
Medium	Work In Progress	the prek parent			6/2/2020 2:44:48 PM					
Gonzalez, Salvador		Please set pole for marquee. It will be located on the corner of the prek parent entrance parking lot. Next to the light pole. Please contact David Soriano for more details on how we want the sign. He can be reached at 915-731-1957								
Michelle Soto										
228412					1/23/2020		172		\$0.00	
Medium	Work In Progress				1/23/2020 8:28:01 AM					
Gonzalez, Salvador		Sal please install marquee and Hector will install electrical.								
Jessica Herrera										
<b>Count: 3 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>85</b>	<b>Total for Anthony - On Track Pre-K (Village)</b>			<b>0</b>	<b>\$0.00</b>	

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Anthony ES</b>									
230962					4/9/2020		95		\$0.00
Medium	Work In Progress				4/9/2020 8:40:43 AM				
Escobar, David		As Per Silver							
		troubles showing on the Fire Alarm panel for the AHU are for the M2 unit Controller install on the Lennox Units these troubles needs to be addressed by the AC technicians							
228612					1/28/2020		167		\$583.60
Medium	Work In Progress	305			1/28/2020 9:02:34 AM				
Escobar, David		We're still having issues with the flow sensor in room # 305 please check							
Jessica Lopez									
231917		Kitchen			5/19/2020		55		\$0.00
High	Work In Progress				5/19/2020 9:42:49 AM				
Ontiveros, Joe		No hot water in kitchen area							
Dino Facio									
226632					12/6/2019		220		\$0.00
Medium	Work In Progress	305			12/6/2019 9:14:54 AM				
Escobar, David		Please fix it is very cold 61° in this room and it is showing an alarm. Room #305 thank you							
Jessica Lopez									
227139					12/18/2019		208		\$0.00
Medium	Work In Progress	303,305 & 309			12/18/2019 7:54:12 AM				
Escobar, David		Please adjust temperature it is extremely cold. thank you							
Jessica Lopez									
227997					1/13/2020		182		\$0.00
Medium	Work In Progress	107			1/13/2020 11:18:40 AM				
Escobar, David		Classroom is very hot please adjust temperature in room 107 thank you							
Jessica Lopez									

# 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Anthony ES</b>										
221654					8/22/2019		326		\$0.00	
Medium	Work In Progress	109			8/22/2019 12:04:38 PM					
Escobar, David		Please adjust temperature in room 109 room is extremely hot thank you								
Jessica Lopez										
231059					4/13/2020		91		\$3,502.97	
Medium	Work In Progress				4/13/2020 1:39:02 PM					
Escobar, David		David at the Alamo AE the rubber hose for the Heating unit burst and there was damage done to the area. Please check all other units and order all the hoses that you need to replace the rubber ones with metal. As per the text. Thank you								
Guillermo Hernandez										
<b>Count: 8 Work Orders</b>		<b>Avg. Age of WO's 168</b>			<b>Total for Anthony ES</b>			<b>0</b>	<b>\$4,086.57</b>	

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Berino ES</b>									
222432	Main Building	Classroom			9/5/2019		312		\$95.00
Medium	Work In Progress	teachers lounge			9/5/2019 10:51:37 AM				
Escobar, David		teachers state the room is hot							
Michelle Guerra									
223307					9/23/2019		294		\$0.00
Medium	Work In Progress				9/23/2019 2:56:26 PM				
Escobar, David		filter swap out at Berino Elementary Site.							
David Escobar									
225439	Main Building				11/5/2019		251		\$0.00
Medium	Work In Progress	playground			11/5/2019 12:03:38 PM				
Gonzalez, Salvador		as per OCR report this infractions need to be corrected Bench outside, fix coding on the picnic table and other issues please contact Mrs. Arnold or Michelle Guerra				2/13/20 - Asp Ms. Jessica, route to Joaquin 5/28/20 - Route to welder - J. Romero			
Michelle Guerra									
<b>Count: 3 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>286</b>		<b>Total for Berino ES</b>	<b>0</b>	<b>\$95.00</b>	

# 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral ES</b>									
231953	Main Building	Foyer			5/20/2020		54		\$0.00
Medium	Work In Progress	Entrance			5/20/2020 1:36:48 PM				
Marquez, Gerardo		Door in the foyer is still not closing. switch was installed but the door remains open. This may be an issue with programming please see admin Shannon Davis for further explanation.							
Jennifer Corral									
223523					9/27/2019		290		\$0.00
Medium	Work In Progress				9/27/2019 7:29:14 AM				
Vallejo, Albert		Need chain link fence repair at chaparral elementary in front of ponding area next to Lisa St. and McCombs street.							
Johnny Acuna									
<b>Count: 2 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>172</b>	<b>Total for Chaparral ES</b>			<b>0</b>	<b>\$0.00</b>

# 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

<b>Location:</b>		<b>Chaparral High - Pre-K</b>							
232720		Exterior			6/30/2020		13		\$219.00
Medium	Work In Progress			6/30/2020 4:06:27 PM					
Marquez, Gerardo	New Fence installation has been completed at Chaparral On Track. I am requesting locks that can be opened with my Master Key to be placed in the two small access gates located in the back of the building as well as the large access gate located on the field that splits CHS and On Track. Locks should also be able to be opened by CHS Custodial staff.				Approved by EC Director- Estrella Burciaga and Coordinator Silvia Lorenzo.				

Nathalie Urbina

<b>Count: 1 Work Orders</b>	<b>Avg. Age of WO's</b>	<b>13</b>	<b>Total for Chaparral High - Pre-K</b>	<b>0</b>	<b>\$219.00</b>
-----------------------------	-------------------------	-----------	---	----------	-----------------

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral HS</b>									
228309					1/21/2020		174		\$0.00
Medium	Work In Progress	Science Rms.			1/21/2020 1:03:20 PM				
Acuna, Johnny		Need Bradley eyewash station replacement parts for main building science rooms and the 3 shops in the Q-Building.				Parts on order			
Johnny Acuna									
228416	Field House	Athletic Field			1/23/2020		172		\$0.00
Medium	Work In Progress	Softball field			1/23/2020 8:58:37 AM				
Ontiveros, Guadalupe		Torn screening around the fenced softball field. Can it be replaced with plastic slats. (coach Soltero, softball field)				Asp report 5/13/20 - Need to order			
Mireya Meza									
232647	Field House	Athletic Field			6/25/2020		18		\$0.00
Medium	Work In Progress	Girls practice			6/25/2020 4:37:25 PM				
Ontiveros, Guadalupe		Please remove the fence for softball/baseball that is at the west side of girls practice soccer field. It takes space away from our practice area. (coach Leal)							
Mireya Meza									
224800	A-Wing	Classroom			10/23/2019		264		\$0.00
Medium	Work In Progress				10/23/2019 2:14:05 PM				
Ambriz, Jose		Not communicating on vav boxes rooms A106m,A106S,A108,A109,A110 as per Jessica Herrera.							
Jose Ambriz									
230253		Kitchen			3/10/2020		125		\$0.00
High	Work In Progress				3/10/2020 1:48:27 PM				
Ontiveros, Joe		Hand sink leaking water on to the floor							
Dino Facio									
222715					9/10/2019		307		\$56.05
Medium	Work In Progress	Maintenance			9/10/2019 3:53:07 PM				
Ontiveros, Joe		Need possible domestic water line install inside Maintenance office at CHS for lce-maker.							
Johnny Acuna									
232449	A-Wing	Foyer			6/16/2020		27		\$0.00
Medium	Work In Progress	Front Lobby			6/16/2020 3:50:03 PM				
Tellez, Hector		We need 2 connections for TV's that were placed in the lobby. (Ms. Lopez, principal)							
Mireya Meza									



# 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral HS</b>									
223533					9/27/2019		290		\$0.00
Medium	Work In Progress				9/27/2019 7:43:29 AM				
Vallejo, Albert		Need fence repair (back outdoor fence) in bus entrance area in back of Q-Bldg.							
Johnny Acuna									
229572					2/18/2020		146		\$0.00
Medium	Work In Progress				2/18/2020 9:08:48 PM				
Villalobos, Jose		Extension pole Chainsaw not turning on.							
Johnny Acuna									
<b>Count: 9 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>169</b>		<b>Total for Chaparral HS</b>	<b>0</b>		<b>\$56.05</b>

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral MS</b>									
231951					5/20/2020		54		\$0.00
Medium	Work In Progress				5/20/2020 10:43:45 AM				
Marquez, Gerardo		Please fix Door Hinge Jam to main doors hallway going from Main office towards portable area. 100 Hall							
Johnny Acuna									
223643					9/30/2019		287		\$0.00
Medium	Work In Progress				9/30/2019 3:31:26 PM				
Vallejo, Albert		according to the Annual Fire Inspection Report							
		Maintenance							
		1. Fire pump discharge side valve tamper....Control valve was replaced and wiring was not reconnected to new control							
		2. Fire pump by pass valve 2 tamper Control valve was replaced and wiring was not reconnected to new control							
<b>Cora Ramirez</b>									
231675					5/6/2020		68		\$0.00
Medium	Work In Progress				5/6/2020 8:41:35 AM				
Ontiveros, Joe		faucet in custodial storage (100 hallway) is leaking and faucet is very hot. needs to please be checked and repaired.							
M. Carmen Perez									
226437					12/3/2019		223		\$0.00
High	Work In Progress				12/3/2019 8:47:18 AM				
Ontiveros, Guadalupe		need to remove pine tree.				50% Completed asp report 5/13/20			
Guadalupe Ontiveros									
228652	Main Building	Gym			1/28/2020		167		\$783.18
Medium	Work In Progress	Gym			1/28/2020 2:32:37 PM				
Acuna, Johnny		Please replace backboard cushions in gym							
Maria Garcia									
232491					6/18/2020		25		\$0.00
Medium	Work In Progress				6/18/2020 4:23:27 PM				
Acuna, Johnny		need boys & girls locker room floor painted							
Jimmy Carbajal									
<b>Count: 6 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>137</b>		<b>Total for Chaparral MS</b>	<b>0</b>	<b>\$783.18</b>	

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Pride HS</b>							
231713		Athletic Field			5/7/2020		67		\$0.00
Medium	Work In Progress			5/7/2020 12:53:33 PM					
Romero, Joaquin	El ring que pusieron afuera con el aire se trozaron los cordones y se volaron los hules. Gracias		memo looking into matter 6-24-20						
Miguel Sonora									
232436					6/15/2020		28		\$0.00
Medium	Work In Progress			6/15/2020 8:32:25 AM					
Ontiveros, Guadalupe	Parking Lot. Remove weeds from parking islands, curbs								
Alfredo Holguin									
231104					4/15/2020		89		\$0.00
Medium	Work In Progress			4/15/2020 8:30:20 AM					
Marquez, Gerardo	Need to order Cores for new construction.		pending asp report 5/7/20						
Gerardo Marquez									
230521					3/19/2020		116		\$5,717.92
High	Work In Progress			3/19/2020 3:05:21 PM					
Pacheco, Hector	Please see water heater in boxing gym Mechanical Room #411 pan is full of old stale water. Please address as soon as possible, high hazard. Picture will be included in e-mail. For questions please see Mr. Gallegos in the Construction office. Thank you		3/20/20 Asp Jessica, route to Hector Pacheco Asp Joaquin, water heater needs to be replaced, bottom is all rusted out.						
Rafael Gallegos									
<b>Count: 4 Work Orders</b>		<b>Avg. Age of WO's 75</b>			<b>Total for Desert Pride HS</b>			<b>0</b>	<b>\$5,717.92</b>

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert Trail ES</b>									
231818	Main Building	Restroom			5/12/2020		62		\$0.00
Medium	Work In Progress				5/12/2020 11:33:25 AM				
Tellez, Hector		The restroom located in the office is supposed to be sensor yet a switch was installed. The light turns on and off as the restroom is in use				6/11/20 - Asp Mr. Gallegos, not a warranty issue, GSD needs to address 5/13/20 Asp Electrician, building under warranty			
Elizabeth Hernandez									
219834	Main Building				8/1/2019		347		\$0.00
Medium	Work In Progress	lounge room			8/1/2019 1:47:56 PM				
Ontiveros, Joe		We need ice machine connected.							
Elizabeth Hernandez									
224360		Kitchen			10/15/2019		230	3	\$165.06
High	Work In Progress				10/15/2019 7:17:43 AM	6/1/2020			
Tellez, Hector		Oven will not turn on wont work				6/29/20 - Hector please check on this - mkv			
Dino Facio						Checked oven including operating system checked out ok. Something going on with power outlet where oven is connected to assigned work order to electrician. 6/1/20 dvf			
232569		Classroom			6/23/2020		20		\$0.00
Medium	Work In Progress				6/23/2020 2:48:29 PM				
Marquez, Gerardo		el cuarto num 302 mi llave se atora por favor de revisarla gracias							
Laura Sandoval									
232570		Storage			6/23/2020		20		\$0.00
Medium	Work In Progress				6/23/2020 2:55:06 PM				
Marquez, Gerardo		Las puertas del storage no habre por favor de revisarla gracias							
Laura Sandoval									
229141	Main Building	Office			2/6/2020		158		\$0.00
Medium	Work In Progress				2/6/2020 10:19:29 AM				
Marquez, Gerardo		Recommendation from Mr. Joseph Milliner, Security Hardware Solutions Co.: Repair of exterior entry pairs is to hang pairs of doors on continuous hinges to allow a long lasting result as the remaining pair of doors which was not replaced needs significant readjustment.				Pending asp report 5/7/20			
Elizabeth Hernandez									

# 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert Trail ES</b>									
231950					5/20/2020		54		\$0.00
Medium	Work In Progress				5/20/2020 10:40:55 AM				
Marquez, Gerardo		Please check with Kitchen manager. Her Key does not open up one set of gates in bus turnaround for Lunch Program							
Johnny Acuna									
228679					1/29/2020		166		\$0.00
Medium	Work In Progress				1/29/2020 8:01:24 AM				
Marquez, Gerardo		NEED O ORDER NEW DOOR AND HARDWARE FOR RM. 215.				Pending asp report 5/7/20			
Gerardo Marquez									
<b>Count: 8 Work Orders</b>		<b>Avg. Age of WO's 132</b>		<b>Total for Desert Trail ES</b>				<b>3</b>	<b>\$165.06</b>

# 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert View ES</b>									
232263	Main Building				6/3/2020		40		\$0.00
Medium	Work In Progress				6/3/2020 8:12:27 AM				
Ontiveros, Guadalupe		need wood chips in playground area low on wood chips							
Javier Hernandez									
227887		Exterior			1/10/2020		185		\$0.00
Medium	Work In Progress				1/10/2020 1:16:58 PM				
Ontiveros, Guadalupe		In the outside drain next to the upper level hallway, every time it rains the screening flushes down the drain.				forward to grounds area by drain needs more screen mesh			
Israel Ortega									
232469					6/17/2020		26		\$0.00
Medium	Work In Progress				6/17/2020 8:00:15 AM				
Hernandez, Javier		Need a couple of tiles replaced in the multi-purpose room that are warped and may cause a trip hazard.							
<b>Count: 3 Work Orders</b>									
				<b>Avg. Age of WO's</b>	<b>84</b>	<b>Total for Desert View ES</b>		<b>0</b>	<b>\$0.00</b>

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>GAC</b>							
224447		Electrical Room			10/16/2019		271		\$0.00
Medium	Work In Progress				10/16/2019 10:20:36				
Lara, Ralph		Replace door from electrical room							
Abby Oliva									
232357					6/8/2020		35		\$0.00
Medium	Work In Progress	CONFERENCE			6/8/2020 4:36:09 PM				
Castillo, Carlos		REPLACE LIGHT FIXTURES IN CONFERENCE ROOM #1							
Marylou Delgado									
232473					6/17/2020		26		\$110.45
Medium	Work In Progress				6/17/2020 3:40:33 PM				
Ambriz, Jose		Need to check unit for Crua.							
232358					6/8/2020		35		\$0.00
Medium	Work In Progress	CONFERENCE			6/8/2020 4:38:05 PM				
Hernandez, Javier		PAINT CONFERENCE ROOM #1 (VANILLA BEAN) AND REPLACE SOME CEILING TILES							
Marylou Delgado									
232725		Office			6/30/2020		13		\$0.00
Medium	Work In Progress	TECHNOLOGY			6/30/2020 11:20:02 PM				
Hernandez, Javier		PAINT OFFICES IN CORA'S, SAM'S, AND MR. SNODDY'S							
Marylou Delgado									
223483					9/26/2019		291		\$0.00
Medium	Work In Progress				9/26/2019 9:06:01 AM				
Cortez, Felipa		Per Felipa, Head GAC Custodian, requested I place this request. Floor tiles need to be replaced in the following finance offices: Room #309-3 tiles, #312-3 tiles, #315-1 tile, #316-7 tiles, #317-1 tile, #318-2 tiles. Thank you.				floor tile can be done by custodial			
Anne De Los Santos									
223489					9/26/2019		291		\$0.00
Medium	Work In Progress	Office #110			9/26/2019 9:50:14 AM				
Cortez, Felipa		Please replace light bulbs in Office #110 and Storage Closet				custodians can now change light bulbs			
Abby Oliva									

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>GAC</b>							
229142		Office			2/6/2020		158		\$0.00
Medium	Work In Progress	C-WING			2/6/2020 10:21:54 AM				
Hernandez, Javier		PLEASE REPAIR A HOLE ON THE WALL BEHIND THE DOOR AND PROVIDE A DOOR STOPPER SPRING TO AVOID FUTURE INCIDENTS. THANK YOU.							
Karla Quesada									
232467					6/17/2020		26		\$0.00
Medium	Work In Progress				6/17/2020 7:57:49 AM				
Hernandez, Javier		Need a couple of tiles replaced in the new store room by HR							
229122					2/6/2020		158		\$0.00
Medium	Work In Progress				2/6/2020 8:06:30 AM				
Hernandez, Javier		Please replace a door stopper in office room 320 and install a tack board on the wall in office room 313. Thank you.							
Anne De Los Santos									
232726		Office			6/30/2020		13		\$0.00
Medium	Work In Progress	TECHNOLOGY			6/30/2020 11:21:25 PM				
Hernandez, Javier		REPLACE STAINED CEILING TILES AND MOLDING AROUND TECHNOLOGY DEPT.							
Marylou Delgado									
<b>Count: 11 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>120</b>	<b>Total for GAC</b>			<b>0</b>	<b>\$110.45</b>



## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>GAC - Pre-K</b>							
231964					5/21/2020		53		\$0.00
Medium	Work In Progress				5/21/2020 9:05:21 AM				
Ontiveros, Guadalupe		purchase and install trees. Felipa is asking for fruit trees. We typically do not plant fruit trees because of concern with bees during pollination and mess created when ripened fruit falls on ground. Verify with Pre- k if in agreement							
Alfredo Holguin									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>			<b>53</b>	<b>Total for GAC - Pre-K</b>		<b>0</b>	<b>\$0.00</b>

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden ES</b>									
228752					1/30/2020		165		\$0.00
Medium	Work In Progress				1/30/2020 8:26:21 AM				
Escobar, David		According to Joaquin Romero, the rooftop ERVs are not working. David, if you need help with these talk to Jose Ambriz. Thank you.							
Jessica Herrera									
230295					3/11/2020		124		\$0.00
Medium	Work In Progress				3/11/2020 1:51:52 PM				
Escobar, David		AIR CONDITIONER SYSTEM IS OFF IN COMPUTER LAB ROOM IS VERY HOT RM, 404							
Patty Madrid									
228496		Foyer			1/24/2020		171		\$983.60
Medium	Work In Progress				1/24/2020 10:29:22 AM				
Tellez, Hector		need assistance with foyer light ... they do not turn on...thank you greatly...							
Loraine Gandara									
232228					6/2/2020		41		\$99.67
Medium	Work In Progress				6/2/2020 6:35:28 AM				
Ontiveros, Joe		Need to install air vent for grease trap.							
<b>Count: 4 Work Orders</b>									
<b>Avg. Age of WO's 125</b>									
<b>Total for Gadsden ES 0 \$1,083.27</b>									

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
230252					3/10/2020		125		\$0.00
Medium	Work In Progress			3/10/2020 1:03:47 PM					
Appelzoller, Fred	Requested by Ms. Lisa Roth Rm. 617 Science Building- Has no running water in the classroom sinks-solenoid not working.		Forward to plumber asp J. Romero 3/11/20						
Velia Alarcon									
232597		Restroom (Girls)			6/24/2020		19		\$0.00
Medium	Work In Progress			6/24/2020 1:15:51 PM					
Tellez, Hector	Wrestling building girls restroom - light is LED not working		Route to Hector 7/1/20						
Liliana Acosta									
232598	North Building	Custodial			6/24/2020		19		\$0.00
Medium	Work In Progress			6/24/2020 1:17:44 PM					
Tellez, Hector	custodial closet N Building- light switch not working		Route to Hector - 7/1/20						
Liliana Acosta									
232599	Vocational	Hallway/Corridor			6/24/2020		19		\$176.86
Medium	Work In Progress			6/24/2020 1:20:47 PM					
Tellez, Hector	Light hallway switches not working there are no keys to turn on hallways need them changed out								
Liliana Acosta									
230566		Restroom (Girls)			3/23/2020		112		\$0.00
Medium	Work In Progress			3/23/2020 3:37:05 PM					
Tellez, Hector	Wrestling Building girls restroom light fixture not working		Transfer to Electrician -JR						
Liliana Acosta									
230116					3/5/2020		130		\$0.00
Medium	Work In Progress			3/5/2020 1:30:35 PM					
Tellez, Hector	Requested by Coach Fransisco Velez for Wrestling Room-Lights in girls restroom are not working.								
Velia Alarcon									
230645	Pool Pump	Exterior			3/31/2020		104		\$0.00
Medium	Work In Progress			3/31/2020 7:50:23 AM					
Romero, Joaquin	The metal canopy trim around the pool needs to be painted. Also the poles for the umbrellas. let Mario know so he can explain.								
Alfredo Ortiz									

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden HS</b>									
220945					8/12/2019		336		\$75.90
Medium	Work In Progress				8/12/2019 3:47:50 PM				
Escobar, David		Requested by Ms. Dolores Nanez-The water fountain in the GHS Library pours out hot and tastes salty.							
Velia Alarcon									
220980					8/13/2019		335		\$75.90
Medium	Work In Progress				8/13/2019 10:18:09 AM				
Escobar, David		Requested by Mrs. Virginia Lerma-The students have mentioned to her that the water in the fountains in the North Building is coming out hot, please check.							
Velia Alarcon									
229701					2/21/2020		143		\$0.00
Medium	Work In Progress				2/21/2020 12:50:03 PM				
Escobar, David		We went in to this data room 114D main bldg and the mini split isn't working, I don't know if the filter has been cleaned, etc. can you check it out please.							
Jessica Herrera									
219169					7/23/2019		356		\$0.00
Medium	Work In Progress				7/23/2019 1:51:30 PM				
Escobar, David		repair 3 Big Air fans for GHS site. replace motors, bearings and Propeller.							
David Escobar									
232583					6/24/2020		19		\$0.00
Medium	Work In Progress				6/24/2020 7:15:34 AM				
Villalobos, Jose		weed eater needs to be serviced Doesn't want to start Thank you							
Joaquin Romero									
231405					4/30/2020		74		\$0.00
Medium	Work In Progress				4/30/2020 6:29:17 AM				
Villalobos, Jose		The pull cord from the weed eater broke can some check it out Thank you							
Joaquin Romero									
<b>Count: 13 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>138</b>		<b>Total for Gadsden HS</b>	<b>0</b>	<b>\$328.66</b>	

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden MS</b>									
227980	Annex	Hallway/Corridor			1/13/2020		182		\$0.00
High	Work In Progress	Main entrance to			1/13/2020 9:41:45 AM				
Marquez, Gerardo		Handle on main entrance door to annex building has fallen off (screws are stripped). Adjacent door does not open. Students are not able to enter and this is the main entrance for students and teachers to the building. Please fix/replace asap.				Pending asp report 5/7/20			
Hilda Adler									
232041	C-Wing	Office			5/28/2020		46		\$0.00
Medium	Work In Progress	Nursing			5/28/2020 9:23:34 AM				
Lara, Ralph		Please provide the Nursing Department with a key to the East Gate of Support Services.							
Priscilla Martinez									
228485					1/24/2020		171		\$9.36
Medium	Work In Progress				1/24/2020 8:37:39 AM				
Escobar, David		trouble at GMS kitchen area							
David Escobar									
228585					1/27/2020		168		\$0.00
Medium	Work In Progress	A-wing exit			1/27/2020 3:39:05 PM				
Marquez, Gerardo		Door exiting towards the gym by room 161 in Awing. Handicap access door button was pulled /removed /damaged. Need to fix/replace for handicap access (wheel chair). See Connie for parts that were damaged.				Pending asp report 5/7/20			
Hilda Adler									
228635	Main Building	Restroom			1/28/2020		167		\$9.99
Medium	Work In Progress				1/28/2020 11:47:39 AM				
Marquez, Gerardo		Requesting for doors to be put in the restrooms in the b wing. Due to the fact the restrooms are being vandalized and convert them into staff restrooms. As per principal.				Pending asp report 5/7/20			
Martin Soria									
232270	Main Building	Restroom			6/3/2020		40		\$0.00
Medium	Work In Progress				6/3/2020 3:10:20 PM				
Marquez, Gerardo		Need a key for staff restrooms. Thank you							
Martin Soria									
229263		Library			2/10/2020		154		\$0.00
Medium	Work In Progress	Library/Maldona			2/10/2020 1:33:29 PM				
Marquez, Gerardo		Front Library door does not stay open.				Pending asp report 5/7/20			
Hilda Adler									

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden MS</b>									
222637	Vocational	Classroom			9/9/2019		308		\$0.00
Medium	Work In Progress	RM#301/Home			9/9/2019 3:53:39 PM				
Escobar, David		Refrigerator in kitchen is not working. No sign of power. Please repair or replace. Thank you							
Hilda Adler									
221783	Gym				8/26/2019		322		\$0.00
Medium	Work In Progress	Boys locker			8/26/2019 9:09:01 AM				
Escobar, David		Replace pads for small portable air conditioner in boys locker room. (David Escobar)							
Hilda Adler									
226637	Vocational	Classroom			12/6/2019		220		\$136.64
Medium	Work In Progress	RM#308/Kuehn			12/6/2019 10:24:19 AM				
Escobar, David		Air conditioner is shut down however, cold air is coming through the classrooms vents. Heater does not work, hardly any air is felt through vents. There is no thermostat or on/off switch for heater. Thank you, Mrs. Quinonez							
Hilda Adler									
221492	Annex	Classroom			8/20/2019		328		\$0.00
Medium	Work In Progress	RM#414/F.Marti			8/20/2019 10:43:34 AM				
Escobar, David		Ac is not working, room is very hot.							
Hilda Adler									
230344	Annex	Classroom			3/12/2020		123		\$0.00
Medium	Work In Progress	RM#403/Clawso			3/12/2020 11:26:20 AM				
Ambriz, Jose		Vent is blowing out a lot of cold air. Class is very cold, please fix asap. Thank you							
Hilda Adler									
221244	Vocational	Classroom			8/15/2019		333		\$0.00
Medium	Work In Progress	RM#301/Home			8/15/2019 3:10:09 PM				
Ambriz, Jose		Air conditioner stopped working again. It made some sound as it did the last 2 times when it stopped working. The last time it was worked on, about 2 weeks ago, the districts electrician said he did what he could.							
Hilda Adler									
221320	Vocational	Classroom			8/16/2019		332		\$0.00
Medium	Work In Progress	RM#307& 308			8/16/2019 12:46:39 PM				
Ambriz, Jose		No air conditioner in RM 307 art Room & RM301 home ec, students and teachers are hot.							
Hilda Adler									

# 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Gadsden MS</b>										
219840	Annex	Classroom			8/1/2019		347		\$0.00	
Medium	Work In Progress	RM#411/Mr.			8/1/2019 3:11:15 PM					
Ambriz, Jose The left side of the hallways is blowing hot air.										
Hilda Adler										
219925	Main Building	Classroom			8/2/2019		346		\$0.00	
Medium	Work In Progress				8/2/2019 12:21:40 PM					
Ambriz, Jose AC not working in room 130. checked wiring and switch and all seemed in place, thank you.										
Jesus Avila										
228781		Kitchen			1/30/2020		165		\$0.00	
High	Work In Progress				1/30/2020 2:44:27 PM					
Appelzoller, Fred Gas solenoid on main gas line into kitchen gets very hot needs to be checked (concern)										
Dino Facio										
229646	Annex	Restroom			2/20/2020		144		\$598.40	
Medium	Work In Progress				2/20/2020 10:03:45 AM					
Appelzoller, Fred Sink is coming off the wall in the staff restroom. Sink is very old requesting a new one if possible Located in the Avila hall. Thank you										
Martin Soria										
<b>Count: 18 Work Orders</b>		<b>Avg. Age of WO's 216</b>			<b>Total for Gadsden MS</b>			<b>0</b>	<b>\$754.39</b>	

# 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>GSAC - Alamo</b>							
224970					10/28/2019		259		\$0.00
Medium	Work In Progress				10/28/2019 10:52:22				
Escobar, David		Need to replace the circulating pump in the boiler room Thank you							
Joaquin Romero									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>259</b>			<b>Total for GSAC - Alamo</b>	<b>0</b>		<b>\$0.00</b>



## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: La Union ES</b>									
231335		Kitchen			4/28/2020		76		\$0.00
High	Work In Progress				4/28/2020 1:19:07 PM				
Ambriz, Jose		Fly fan on back door not working							
Dino Facio									
231634		Library			5/5/2020		69		\$80.51
Medium	Work In Progress				5/5/2020 1:45:59 PM				
Castillo, Carlos		Please remove power from circulation desk so they can replace with new circulation desk. Contact is Philip Medina, 915-637-0141. Power will need to be reconnected when new desk comes in.							
232048		Kitchen			5/28/2020		46		\$0.00
High	Work In Progress				5/28/2020 12:28:29 PM				
Lara, Ralph		Need one (1) key for Kitchen doors. Request for key has been approved by Ms. Guerra. Key will be issued to ESA Construction for the LA Security Door Project. Key is needed in the construction office by Tuesday June 2. For questions please contact Mr. Gallegos.							
Dominique Esparza									
230643					3/31/2020		104		\$306.00
Medium	Work In Progress				3/31/2020 7:39:55 AM				
Escobar, David		Need to order T-stat for classroom #307 and #307 restroom.							
Guillermo Hernandez									
231616					5/5/2020		69		\$3.59
Medium	Work In Progress				5/5/2020 6:37:41 AM				
Escobar, David		Need 5 swamp coolers replaced in LAUNION elementary, found five that I have marked at warehouse							
Javier Hernandez									
229596	Main Building	Office			2/19/2020		145		\$0.00
Medium	Work In Progress	FRONT OFFICE			2/19/2020 10:45:00 AM				
Hernandez, Javier		REPLACE CEILING TILE IN SECRETARY'S OFFICE DURING SPRING BREAK							
Joanne Munoz									
232566					6/23/2020		20		\$0.00
Medium	Work In Progress				6/23/2020 2:11:26 PM				
Hernandez, Javier		The ac in room 306 is not working.							
Guadalupe Parada									

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: La Union ES</b>									
232567					6/23/2020		20		\$0.00
Medium	Work In Progress				6/23/2020 2:13:43 PM				
Hernandez, Javier		The ac in room 302 is blowing hot air.							
Guadalupe Parada									
232626					6/25/2020		18		\$0.00
Medium	Work In Progress				6/25/2020 11:05:38 AM				
Hernandez, Javier		There's some ceiling tiles that need to be change in rooms 101,103,104,106,109,110,300,301,302,303,305,308,311 , upper grade hallway and lounge room.							
Guadalupe Parada									
232627					6/25/2020		18		\$0.00
Medium	Work In Progress				6/25/2020 11:06:24 AM				
Hernandez, Javier		There is a water leak in Mr. Moreno's office.							
Guadalupe Parada									
<b>Count: 10 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>59</b>		<b>Total for La Union ES</b>	<b>0</b>	<b>\$390.10</b>	

# 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Loma Linda ES</b>									
232214	Main Building	Parking Lot			6/1/2020		42		\$0.00
Medium	Work In Progress	westside			6/1/2020 1:48:07 PM				
Ontiveros, Guadalupe		As per Mr. Cardona he is requesting crusher- fine grey and red around trees. Crusher-fine (grey) between sidewalk and building.							
Crystalee Heredia									
229417	Main Building	Classroom			2/13/2020		151		\$0.00
Medium	Work In Progress	105/Crowley			2/13/2020 9:20:27 AM				
Escobar, David		Refrigerator is leaking.							
Crystalee Heredia									
<b>Count: 2 Work Orders</b>		<b>Avg. Age of WO's</b>			<b>97</b>	<b>Total for Loma Linda ES</b>		<b>0</b>	<b>\$0.00</b>

# 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Mesquite ES</b>									
228249					1/17/2020		178	\$2,579.28	
Medium	Work In Progress				1/17/2020 3:40:44 PM				
Tellez, Hector		Need to replace all wall packs on building (school)							
Hector Tellez									
231648					5/5/2020		69	\$0.00	
Medium	Work In Progress				5/5/2020 4:01:42 PM				
Tellez, Hector		Need 11 lights for portables behind school							
Hector Tellez									
<b>Count: 2 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>124</b>		<b>Total for Mesquite ES</b>	<b>0</b>	<b>\$2,579.28</b>	

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Physical Plant Complex</b>									
230220					3/9/2020		126		\$4.78
Low	Work In Progress				3/9/2020 3:15:11 PM				
Tellez, Hector		install light dimmer in office. TY							
Ruben Ronquillo									
231419					4/30/2020		74		\$6.20
Medium	Work In Progress				4/30/2020 3:04:41 PM				
Tellez, Hector		At the Lift Station area please do locates. Area will be marked with white paint. Should you have any questions please see Mr. Gallegos in the Construction Office. Thank You							
Dominique Esparza									
228255					1/17/2020		178		\$0.00
Medium	Work In Progress				1/17/2020 3:45:40 PM				
Tellez, Hector		Need emergency fixture in Ms Irmias office (directors office)							
Hector Tellez									
230961					4/9/2020		95		\$748.11
Medium	Work In Progress				4/9/2020 8:30:37 AM				
Escobar, David		Need to replace filters to ice maker in PPD lounge.							
Guillermo Hernandez									
230440					3/16/2020		119		\$0.00
Medium	Work In Progress				3/16/2020 11:00:29 AM				
Marquez, Gerardo		Records Office - Please check key or lock , having a hard time unlocking door.				Pending asp report 5/7/20			
Margret Villalobos									
229353					2/12/2020		152		\$0.00
Medium	Work In Progress				2/12/2020 10:11:33 AM				
Lara, Ralph		NEED TO ORDER LOCKSMITH SUPPLIES, PADLOCKS- CORES -KEY BLANKS-FOR DIST. WIDE							
Ralph Lara									
230078					3/5/2020		130		\$0.00
High	Work In Progress				3/5/2020 9:21:40 AM				
Romero, Joaquin		Roof leaks in the SNP Food Warehouse				6/11/20 - Asp Mr. Gallegos, not a warranty issue, GISD needs to address			
Dino Facio									

# 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>Physical Plant Complex</b>							
231842					5/13/2020		61		\$1,431.18
Medium	Work In Progress				5/13/2020 4:27:28 PM				
Escobar, David	requesting tools from grainger for HVAC dept.								
David Escobar									
<b>Count: 8 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>117</b>	<b>Total for Physical Plant Complex</b>				<b>0</b>	<b>\$2,190.27</b>

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Riverside ES</b>									
231268					4/23/2020		81		\$0.00
Medium	Work In Progress	Office		4/23/2020 6:21:32 PM					
Castillo, Carlos	Please relocate power outlet box that is by the main school entrance office door to the bottom area where a cancel power box is located. Power outlet box is located on the top right side of the door. Plan B will be installing a camera door buzzer and needs area cleared to drill in camera. Please call Mrs. Martinez at 575-386-5741 for any questions. (Mrs. Martinez)								
Norma Martinez									
229243					2/10/2020		154		\$0.00
Medium	Work In Progress			2/10/2020 8:47:43 AM					
Hernandez, Javier	Multiple ceiling tiles need to be replaced. Please check all classrooms and hallways to replace ceiling tiles as needed. (Mrs. Martinez)								
Norma Martinez									
229244					2/10/2020		154		\$0.00
Medium	Work In Progress			2/10/2020 8:50:31 AM					
Hernandez, Javier	Several classrooms and all three computer labs need flag holder for the NM and USA flag. Please check classrooms and computers labs. (Mrs. Martinez)								
Norma Martinez									
228377					1/22/2020		173		\$0.00
Medium	Work In Progress	Kinder Hallway		1/22/2020 12:13:57 PM					
Hernandez, Javier	Please replace ceiling tiles with student hands. Total of 4 down the hallway. (Mrs. Martinez)								
Norma Martinez									
230726					4/2/2020		102		\$0.00
Medium	Work In Progress			4/2/2020 2:13:26 PM					
Gonzalez, Salvador	Need flasher crosswalk light installed behind riverside elementary								
Javier Hernandez									
<b>Count: 5 Work Orders</b>	<b>Avg. Age of WO's 133</b>			<b>Total for Riverside ES</b>			<b>0</b>	<b>\$0.00</b>	

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: RTC - Alliance</b>									
228308					1/21/2020		174		\$0.00
Medium	Work In Progress				1/21/2020 12:21:20 PM				
Hernandez, Javier		we need for our ramps to have anti-skid tread tape on all three portables I had several students today almost skid down the ramps. For safety reason we need it as soon as possible. Thank you greatly appreciated							
Gloria Delgado									
232450		Classroom			6/16/2020		27		\$0.00
Medium	Work In Progress				6/16/2020 4:06:45 PM				
Hernandez, Javier		The air conditioner in Mr. Hawkins Social Studies room at the RTC is not cooling.							
Gloria Delgado									
<b>Count: 2 Work Orders</b>		<b>Avg. Age of WO's 101</b>			<b>Total for RTC - Alliance</b>			<b>0</b>	<b>\$0.00</b>



## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>San Miguel ES</b>							
232476					6/18/2020		25		\$0.00
Medium	Work In Progress				6/18/2020 7:51:00 AM				
Ambriz, Jose		Please check H/C unit Alto De Las Flores portable.							
232472					6/17/2020		26		\$6.43
Medium	Work In Progress				6/17/2020 3:37:26 PM				
Tellez, Hector		Need to identify outlets breakers at SM.							
Guillermo Hernandez									
<b>Count: 2 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>26</b>			<b>Total for San Miguel ES</b>	<b>0</b>		<b>\$6.43</b>

# 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa ES</b>									
232700					6/30/2020		13		\$13.99
Medium	Work In Progress				6/30/2020 6:49:36 AM				
Castillo, Carlos		Rewire and replace booster pump pressure switch.							
Carlos Castillo									
232470					6/17/2020		26		\$0.00
Medium	Work In Progress				6/17/2020 8:01:58 AM				
Hernandez, Javier		Need wall repaired in custodial closet by the multi purpose room it has a hole in it by the baseboard.							
232558	Main Building	Custodial			6/23/2020		20		\$0.00
Medium	Work In Progress				6/23/2020 11:22:56 AM				
Hernandez, Javier		I need door weather strips .around the building doors							
Maria Gabaldon									
<b>Count: 3 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>20</b>		<b>Total for Santa Teresa ES</b>	<b>0</b>		<b>\$13.99</b>

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Santa Teresa HS

232411	Main Building	Football Field			6/11/2020		32		\$0.00
--------	---------------	----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Concession			6/11/2020 1:57:07 PM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Hernandez, Javier Please check that all electrical and air conditioning is functioning in the concession stand as we will use this area for summer workouts. Need the air conditioning due to area used for temperature checks and cooling time for athletes

Lorraine Dominguez

232443	Main Building	Gym			6/15/2020		28		\$0.00
--------	---------------	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Both gyms			6/15/2020 12:52:02 PM				
--------	------------------	-----------	--	--	-----------------------	--	--	--	--

Hernandez, Javier Need air conditioning set for both gyms beginning July 6, 2020 for summer workouts from 4-8:30 pm

Lorraine Dominguez

232329	Main Building	Classroom			6/8/2020		35		\$0.00
--------	---------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	302			6/8/2020 2:47:26 PM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Hernandez, Javier Remove brackets from west wall

Lorraine Dominguez

232330	Main Building	Classroom			6/8/2020		35		\$0.00
--------	---------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	302			6/8/2020 2:48:08 PM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Hernandez, Javier Door and cabinets need to be repaired

Lorraine Dominguez

232332	Vocational	Classroom			6/8/2020		35		\$0.00
--------	------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	807			6/8/2020 2:49:49 PM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Hernandez, Javier Water faucet does not shut off

Lorraine Dominguez

232333	Main Building	Classroom			6/8/2020		35		\$0.00
--------	---------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	303			6/8/2020 2:50:30 PM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Hernandez, Javier Classroom blinds need to be replaced

Lorraine Dominguez

232334	Vocational	Classroom			6/8/2020		35		\$0.00
--------	------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	704			6/8/2020 2:51:20 PM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Hernandez, Javier Floor has missing tiles

Lorraine Dominguez

232336	Vocational	Classroom			6/8/2020		35		\$0.00
--------	------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	707			6/8/2020 3:00:13 PM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Hernandez, Javier Valve for hot water needs to be fixed

Lorraine Dominguez

7/13/2020 12:57:10 PM

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
232337	Vocational	Classroom			6/8/2020		35		\$0.00
Medium	Work In Progress	707			6/8/2020 3:00:51 PM				
Hernandez, Javier		Remove 2 bulletin boards in lobby							
Lorraine Dominguez									
232338	Vocational	Classroom			6/8/2020		35		\$0.00
Medium	Work In Progress	707			6/8/2020 3:01:50 PM				
Hernandez, Javier		Please fix drip in three compartments sink in dish room							
Lorraine Dominguez									
232344	Main Building	Classroom			6/8/2020		35		\$0.00
Medium	Work In Progress	500			6/8/2020 3:06:59 PM				
Hernandez, Javier		Bulletin needs to be hung in classroom							
Lorraine Dominguez									
232346	Main Building	Classroom			6/8/2020		35		\$0.00
Medium	Work In Progress	610			6/8/2020 3:08:24 PM				
Hernandez, Javier		Door needs to be fixed							
Lorraine Dominguez									
232347	Main Building	Classroom			6/8/2020		35		\$0.00
Medium	Work In Progress	203			6/8/2020 3:08:59 PM				
Hernandez, Javier		Re-hang bulletin board							
Lorraine Dominguez									
232348	Main Building	Classroom			6/8/2020		35		\$0.00
Medium	Work In Progress	203			6/8/2020 3:09:54 PM				
Hernandez, Javier		Closet door needs to be fixed							
Lorraine Dominguez									
232349	Main Building	Classroom			6/8/2020		35		\$0.00
Medium	Work In Progress	308			6/8/2020 3:10:41 PM				
Hernandez, Javier		Pipe is leaking in classroom on/off throughout the day							
Lorraine Dominguez									
232353	Main Building	Classroom			6/8/2020		35		\$0.00
Medium	Work In Progress	300			6/8/2020 3:14:16 PM				
Hernandez, Javier		Old pencil sharpner needs to be removed							
Lorraine Dominguez									

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
232355	Main Building	Classroom			6/8/2020		35		\$0.00
Medium	Work In Progress	506			6/8/2020 3:15:50 PM				
Hernandez, Javier		Table has a broken leg							
Lorraine Dominguez									
232356	Main Building	Restroom (Girls)			6/8/2020		35		\$0.00
Medium	Work In Progress	office womens			6/8/2020 3:35:27 PM				
Hernandez, Javier		Lights are not working need bulbs							
Lorraine Dominguez									
228191					1/16/2020		179		\$0.00
Medium	Work In Progress				1/16/2020 2:56:22 PM				
Avila, Jesus		Need to attach or install an skirt around chillers, to prevent trash from going inside the condensers on the chillers. Requested by ESC and approved by Jessica.							
Guillermo Hernandez									
230953					4/8/2020		96		\$308.04
Medium	Work In Progress				4/8/2020 1:09:13 PM				
Avila, Jesus		Please check maintenance office area to install cages for the weed eater and blowers. Thank you							
Guillermo Hernandez									
231711	Main Building	Hallway/Corridor			5/7/2020		67		\$0.00
Medium	Work In Progress	hallway back of			5/7/2020 12:34:39 PM				
Lara, Ralph		Door located on the ramp of the end of 400 has the door handle missing							
Lorraine Dominguez									
230969					4/9/2020		95		\$136.99
Medium	Work In Progress				4/9/2020 11:45:00 AM				
Ontiveros, Guadalupe		Need Arsenal weed killer 5 gallons				Pending approval asp report 5/13/20			
Javier Hernandez									
229423	Main Building	Office			2/13/2020		151		\$0.00
Medium	Work In Progress	Celia office			2/13/2020 9:55:29 AM				
Lara, Ralph		We need keys configured for teacher mailboxes							
Lorraine Dominguez									

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
229511	Main Building	Athletic Field			2/14/2020		150		\$0.00
Medium	Work In Progress	softball field			2/14/2020 3:08:09 PM				
Lara, Ralph		Can we get locks for dugouts and an couple of extra keys for coaches and office							
Lorraine Dominguez									
231945	Cafeteria (2005)	Cafeteria			5/20/2020		54		\$0.00
Medium	Work In Progress	doors			5/20/2020 8:27:53 AM				
Lara, Ralph		Doors underneath stage area need to be fixed as some are not able to be closed							
Lorraine Dominguez									
232441					6/15/2020		28		\$0.00
Medium	Work In Progress	Main Office			6/15/2020 12:19:10 PM				
Lara, Ralph		We need 10 copies of "light key" for admin and contractors as needed.							
Nicholas Wohlgemuth									
232322					6/8/2020		35		\$0.00
Medium	Work In Progress				6/8/2020 2:40:12 PM				
Lara, Ralph		Keys on some of cabinets do not function							
Lorraine Dominguez									
232328	Main Building	Classroom			6/8/2020		35		\$0.00
Medium	Work In Progress	511			6/8/2020 2:46:21 PM				
Lara, Ralph		Some keys do not open up the cabinets							
Lorraine Dominguez									
232342	Main Building	Office			6/8/2020		35		\$0.00
Medium	Work In Progress	nurse office			6/8/2020 3:05:42 PM				
Lara, Ralph		Lock in back room needs to be repaired							
Lorraine Dominguez									
232345	Main Building	Classroom			6/8/2020		35		\$0.00
Medium	Work In Progress	705			6/8/2020 3:07:44 PM				
Lara, Ralph		Fix Door in room 701 to storage							
Lorraine Dominguez									
232352	Main Building	Classroom			6/8/2020		35		\$0.00
Medium	Work In Progress	300			6/8/2020 3:13:26 PM				
Lara, Ralph		Locks on built in storage lockers to store important items							
Lorraine Dominguez									

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
232354	Main Building	Classroom			6/8/2020		35		\$0.00
Medium	Work In Progress	608			6/8/2020 3:15:00 PM				
Lara, Ralph		Difficult time locking and unlocking doors							
Lorraine Dominguez									
232339	Vocational	Classroom			6/8/2020		35		\$0.00
Medium	Work In Progress	707			6/8/2020 3:02:40 PM				
Castillo, Carlos		Change motion sensor switches to regular ones							
Lorraine Dominguez									
227533					1/5/2020		26	2	\$68.32
Medium	Work In Progress	Boys restroom			1/5/2020 5:30:44 PM	1/31/2020			
Pacheco, Hector		Maintenance – replace toilet seat in ADA stall				replaced toilet seat			
Nicholas Wohlgemuth									
227064		Kitchen			12/17/2019		209		\$1,520.00
High	Work In Progress				12/17/2019 8:17:13 AM				
Pacheco, Hector		No hot water in kitchen area							
Dino Facio									
224897	Main Building	Office			10/25/2019		262		\$0.00
Medium	Work In Progress	trainers office			10/25/2019 9:32:46 AM				
Casas, Carlos		Electricity is not working in office							
Lorraine Dominguez									
232541		Mechanical			6/23/2020		20		\$0.00
Medium	Work In Progress				6/23/2020 8:06:42 AM				
Ambriz, Jose		Need to replace water pressure reducing valve to set pressure at 45 psi.							
Jose Ambriz									
<b>Count: 37 Work Orders</b>		<b>Avg. Age of WO's 60</b>		<b>Total for Santa Teresa HS</b>		<b>2</b>		<b>\$2,033.35</b>	

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa MS</b>									
231339		Athletic Field			4/28/2020		76		\$128.91
Medium	Work In Progress				4/28/2020 2:54:19 PM				
Ambriz, Jose		4/28/20. please clean and reset ice maker in gym. Thank you.							
Julio Alvarado									
231927	South Building				5/19/2020		55		\$0.00
Medium	Work In Progress				5/19/2020 4:11:25 PM				
Ambriz, Jose		Choir Rm Bathroom-S Heat Pump							
Rafael Gallegos									
231100	North Building	Mechanical			4/15/2020		89		\$0.00
Medium	Work In Progress				4/15/2020 7:44:55 AM				
Pacheco, Hector		In need to repair leak in 2 inch union at #2 boiler.							
Hector Pacheco									
230642					3/31/2020		104		\$359.27
Medium	Work In Progress				3/31/2020 7:37:30 AM				
Escobar, David		Need to check MUA for the kitchen.							
Guillermo Hernandez									
228431	Gym (1997)	Gym			1/23/2020		131		\$0.00
Medium	Work In Progress	SNYDER			1/23/2020 10:54:42 AM	6/2/2020			
Hernandez, Javier		BOTTOM SKIDS OF BLEACHERS NEED TO BE REPAIRED-- BLEACHERS ARE FALLING APART. NEED APPX 70 FT OF 2X8 WOOD CUT INTO 4.5 SECTION. PLEASE SEE JULIAN ALVARADO				material ordered 6-2-20			
Laura Parra									
<b>Count: 5 Work Orders</b>		<b>Avg. Age of WO's 91</b>		<b>Total for Santa Teresa MS</b>		<b>0</b>	<b>\$488.18</b>		



## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>SNP Complex</b>							
225893		Parking Lot			11/15/2019		241		\$0.00
High	Work In Progress				11/15/2019 11:14:33				
Vallejo, Albert		Need a cement slab in front entrance to snp complex so gate will be easier to roll open and close							
Dino Facio									
231199		Portables			4/22/2020		82		\$86.77
Medium	Work In Progress				4/22/2020 9:39:11 AM				
Diaz, David		Need painting supplies to paint portable Doors and Rails							
David Diaz									
225853					11/14/2019		242		\$93.72
Medium	Work In Progress				11/14/2019 1:37:08 PM				
Diaz, David		Need 1 gallon Handy cap Blue, 1 gallon safety Yellow							
David Diaz									
229606					2/19/2020		145		\$28.84
High	Work In Progress				2/19/2020 1:33:23 PM				
Castillo, Carlos		Need two electrical outlets outside the SNP Equip Shop							
Dino Facio									
<b>Count: 4 Work Orders</b>		<b>Avg. Age of WO's 178</b>			<b>Total for SNP Complex</b>			<b>0</b>	<b>\$209.33</b>

# 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Sunland Park ES</b>									
231860					5/14/2020		60		\$0.00
Medium	Work In Progress				5/14/2020 8:53:39 AM				
Escobar, David		A/C is not working in front office.							
Maria Barraza									
232046		Library			5/28/2020		46		\$0.00
Medium	Work In Progress				5/28/2020 11:19:59 AM				
Lara, Ralph		THE EMERGENCY DOORS NEED FIXING DUST AND WEEDS ARE GETTING THROUGH THE BOTTOM AND SIDE OF DOORS							
Ivette Rios									
232264					6/3/2020		40		\$0.00
Medium	Work In Progress				6/3/2020 8:14:19 AM				
Ontiveros, Guadalupe		need more wood chips in playground area low on wood chips							
Javier Hernandez									
232018		Classroom			5/27/2020		47		\$0.00
Medium	Work In Progress	16			5/27/2020 1:25:43 PM				
Lara, Ralph		OUTSIDE DOOR NEEDS WEATHER STRIPPING TOO MUCH DIRT AND BUGS COME IN							
Ivette Rios									
232019		Portables			5/27/2020		47		\$0.00
Medium	Work In Progress	E			5/27/2020 1:28:30 PM				
Lara, Ralph		VENTS FALLING OFF. DOOR NEEDS TO BE SEALED THERE ARE TOO MANY GAPS WHERE AIR COME IN FROM.							
Ivette Rios									
<b>Count: 5 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>48</b>		<b>Total for Sunland Park ES</b>	<b>0</b>		<b>\$0.00</b>

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunrise ES</b>							
231938					5/20/2020		54		\$0.00
Medium	Work In Progress			5/20/2020 6:52:13 AM					
Ontiveros, Guadalupe	Please check Irrigation System pressure pump to Grass area. changed out some sprinklers where there is yellowing grass, but not enough water pressure.								
Johnny Acuna									
231939					5/20/2020		54		\$15.98
Medium	Work In Progress			5/20/2020 6:53:57 AM					
Ontiveros, Guadalupe	Need landscaping screening for front parking lot area.								
Johnny Acuna									
231940					5/20/2020		54		\$0.00
Medium	Work In Progress			5/20/2020 6:55:31 AM					
Ontiveros, Guadalupe	Need wood chips for both playground areas.								
Johnny Acuna									
229611		Kitchen			2/19/2020		145		\$18.24
High	Work In Progress			2/19/2020 2:37:17 PM					
Acuna, Johnny	New baseboard is needed where the lockers are located								
Dino Facio									
229612		Kitchen			2/19/2020		145		\$6.58
High	Work In Progress			2/19/2020 2:38:55 PM					
Acuna, Johnny	Chemical room needs new baseboard rust is causing holes in baseboard areas								
Dino Facio									
229579		Restroom (Girls)			2/19/2020		145		\$0.00
Medium	Work In Progress			2/19/2020 7:36:41 AM					
Acuna, Johnny	Hola,Buenos dias. El fan de el bano de ninas pasillo luna no esta funcionando es necesario que sea reparado por favor , gracias buen dia.								
Maritxa Vasquez									
232619		Cafeteria			6/25/2020		18		\$0.00
Medium	Work In Progress			6/25/2020 7:36:02 AM					
Acuna, Johnny	Buenos dias, se necesita y requiere cambiar piso quebrado de cafeteria son 20 piezas gracias.								
Maritxa Vasquez									

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunrise ES</b>							
231918	Main Building	Office			5/19/2020		55		\$0.00
Medium	Work In Progress			5/19/2020 9:54:32 AM					
Acuna, Johnny		Mrs. Williams, Office, Will need to paint office walls. Change color from Turquoise to White.							
Monica Narez									
228765		Kitchen			1/30/2020		165		\$0.00
High	Work In Progress			1/30/2020 9:59:40 AM					
Ontiveros, Joe		Need water spigot on back wall to back door to kitchen need water access when servicing grease trap							
Dino Facio									
229528					2/18/2020		146		\$0.00
Medium	Work In Progress	Rm. 304		2/18/2020 8:16:15 AM					
Ontiveros, Joe		(Rm. #304) Need to replace classroom faucet.							
Johnny Acuna									
229715					2/21/2020		3	4	\$142.33
Medium	Work In Progress			2/21/2020 3:42:53 PM		2/24/2020			
Ontiveros, Joe		Need to unclogged Two urinals in las luna Hallway boys RRM. pour drain cleaner and ran cable to unclog							
Joe Ontiveros									
224444	Main Building	Custodial			10/16/2019		271		\$0.00
Medium	Work In Progress	Closet		10/16/2019 9:43:44 AM					
Ontiveros, Joe		Marixta Vazquez, hot water is not coming out from the Custodial closet next to the Cafeteria							
Monica Narez									
<b>Count: 12 Work Orders</b>		<b>Avg. Age of WO's 105</b>		<b>Total for Sunrise ES</b>			<b>4</b>	<b>\$183.13</b>	

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Support Services</b>							
228097					1/15/2020		180		\$1.83
Medium	Work In Progress	support services			1/15/2020 8:16:02 AM				
Tellez, Hector		The outside lights in front of this building and the light where we park "support services" are not working. After Saturday's training, January 11, 2020 it was really dark after the training.							
Lisa Sanchez									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>180</b>			<b>Total for Support Services</b>	<b>0</b>		<b>\$1.83</b>

## 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Vado ES</b>									
232364	Main Building	Classroom			6/9/2020		34		\$0.00
Medium	Work In Progress	Room # 106 Ms.			6/9/2020 9:54:29 AM				
Pacheco, Hector		install sink							
Sylvia Cary									
232594		Kitchen			6/24/2020		19		\$0.00
High	Work In Progress				6/24/2020 12:57:31 PM				
Appelzoller, Fred		Floor drain in dish room clogged							
Dino Facio									
232275	Main Building	Classroom			6/4/2020		39		\$0.00
Medium	Work In Progress	Room #104 Ms.			6/4/2020 9:22:52 AM				
Pacheco, Hector		Sink is not in place							
Sylvia Cary									
231223					4/23/2020		81		\$0.00
Medium	Work In Progress				4/23/2020 6:41:04 AM				
Escobar, David		The HVAC unit in room 303 is leaking from the valve. Valve is off and unit is off. Thank you							
Joaquin Romero									
223997	Main Building	Classroom			10/7/2019		280		\$0.00
Medium	Work In Progress	Room # 106 Ms.			10/7/2019 2:15:56 PM				
Escobar, David		Temperature is too high, please check thermostat.							
Sylvia Cary									
232362	Main Building	Classroom			6/9/2020		34		\$0.00
Medium	Work In Progress	Room #309 Ms.			6/9/2020 9:40:55 AM				
Marquez, Gerardo		Back door doesn't close on it's own, have to force it close.							
Sylvia Cary									
<b>Count: 6 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>81</b>		<b>Total for Vado ES</b>	<b>0</b>		<b>\$0.00</b>

# 203 - Work Orders In Progress (FY Ending 2020)

Selected Date Range for Request Dates: 7/1/2019 - 6/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Yucca Heights ES</b>							
232437		Classroom			6/15/2020		28		\$0.00
Medium	Work In Progress				6/15/2020 9:21:02 AM				
Acuna, Johnny	Need to paint the wall in room #302.								
Ernesto Diaz									
231942					5/20/2020		54		\$0.00
Medium	Work In Progress				5/20/2020 7:00:05 AM				
Ontiveros, Guadalupe	Need wood chips for all playground equipment areas.								
Johnny Acuna									
<b>Count: 2 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>41</b>	<b>Total for Yucca Heights ES</b>			<b>0</b>	<b>\$0.00</b>	
<b>Count: 203 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>116</b>	<b>Grand Total</b>			<b>9</b>	<b>\$21,495.44</b>	