

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location: Alta Vista ECHS</b>										
233356					7/15/2020		36	11	\$649.38	
Medium	Work In Progress			7/15/2020 11:35:35 AM	8/20/2020					
Tellez, Hector	Replaced bulbs in girls restrooms and 2 fixtures did not work needs ballast		Light fixtures need to be replaced with modern fixtures. T-12 light bulbs are no longer ordered or carried by warehouse. Please forwarded to Electrician							
Maria Davila										
233863					7/28/2020		72		\$0.00	
Medium	Work In Progress	11 & 13		7/28/2020 2:05:26 PM						
Marquez, Gerardo	Classroom doors for portables 11 & 13 are hard to close.									
Melanie Beegle										
234001					7/30/2020		70		\$0.00	
Medium	Work In Progress	13		7/30/2020 9:14:16 AM						
Romero, Joaquin	Replace 3 pink colored blinds with white or cream colored blinds.		Ordered on 8-7-20							
Melanie Beegle										
<b>Count: 3 Work Orders</b>		<b>Avg. Age of WO's 59</b>		<b>Total for Alta Vista ECHS</b>			<b>11</b>	<b>\$649.38</b>		

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Anthony - On Track Pre-K (Village)</b>									
236317					9/17/2020		21		\$403.81
Medium	Work In Progress				9/17/2020 7:45:24 AM				
Appelzoller, Fred		need to test gas line at pre-k							
Fred Appelzoller									
<b>Count: 1 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>21</b>		<b>Total for Anthony - On Track Pre-K (Village)</b>	<b>0</b>		<b>\$403.81</b>

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Anthony ES</b>									
236271					9/15/2020		23		\$0.00
Medium	Work In Progress				9/15/2020 3:50:03 PM				
Appelzoller, Fred		need faucets to replace the last of the old office							
Fred Appelzoller									
235946		Kitchen			9/8/2020		30		\$0.00
High	Work In Progress				9/8/2020 9:20:29 AM				
Appelzoller, Fred		Need the three compartment sink faucet replaced (corroded)							
Dino Facio									
234460					8/5/2020		64		\$4,950.00
Medium	Work In Progress				8/5/2020 3:51:19 PM				
Tellez, Hector		replace light fixtures with 2x4 flat panels in classrooms							
Hector Tellez									
233082					7/7/2020		93		\$0.00
High	Work In Progress				7/7/2020 3:03:09 PM				
Ontiveros, Guadalupe		irrigation system needs to be rewire and replace control to be able to water soccer field.							
Guadalupe Ontiveros									
<b>Count: 4 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>53</b>	<b>Total for Anthony ES</b>			<b>0</b>	<b>\$4,950.00</b>

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Berino ES</b>							
233539					7/21/2020		79		\$0.00
Medium	Work In Progress			7/21/2020 2:49:16 PM					
Marquez, Gerardo	LOCK SETS AT FACULTY RESTROOMS ARE LOOSE AND HARD TO OPEN. PLEASE FIX.								
Gerardo Marquez									
233561					7/22/2020		78		\$50.50
Medium	Work In Progress			7/22/2020 7:45:16 AM					
Escobar, David	trouble at room 109,109a, 110, 131, and 133.								
David Escobar									
234706	Main Building	Office			8/11/2020		58		\$235.85
Medium	Work In Progress	Front		8/11/2020 8:21:28 AM					
Romero, Joaquin	Paint the door frames on all the doors of the school can you please close work order 234658 please		paint is on order						
Michelle Guerra									
234346	Main Building	Office			8/4/2020		65		\$0.00
Medium	Work In Progress	Front		8/4/2020 9:18:56 AM					
Romero, Joaquin	Paint the side door frames in the front entrance		duplicate						
Michelle Guerra									
234823	Main Building	Classroom			8/13/2020		56		\$0.00
Medium	Work In Progress	114		8/13/2020 10:38:21 AM					
Escobar, David	classroom is too cold								
Michelle Guerra									
233768	Main Building	Classroom			7/27/2020		73		\$0.00
Medium	Work In Progress	144		7/27/2020 1:57:16 PM					
Escobar, David	Classroom is hot								
Michelle Guerra									
233769	Main Building	Classroom			7/27/2020		73		\$0.00
Medium	Work In Progress	142		7/27/2020 1:57:58 PM					
Escobar, David	classroom is hot								
Michelle Guerra									
233770	Main Building	Classroom			7/27/2020		73		\$0.00
Medium	Work In Progress	140		7/27/2020 1:58:49 PM					
Escobar, David	classroom is hot								
Michelle Guerra									

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Berino ES</b>									
233771	Main Building	Classroom			7/27/2020		73		\$0.00
Medium	Work In Progress	137			7/27/2020 2:00:06 PM				
Escobar, David		classroom is hot							
Michelle Guerra									
233773	Main Building	Classroom			7/27/2020		73		\$0.00
Medium	Work In Progress	114			7/27/2020 2:01:42 PM				
Escobar, David		classroom is hot							
Michelle Guerra									
233774	Main Building	Classroom			7/27/2020		73		\$0.00
Medium	Work In Progress	117			7/27/2020 2:02:30 PM				
Escobar, David		classroom is hot							
Michelle Guerra									
233775	Main Building	Classroom			7/27/2020		73		\$0.00
Medium	Work In Progress	116			7/27/2020 2:03:14 PM				
Escobar, David		classroom is hot							
Michelle Guerra									
233780	Main Building	Classroom			7/27/2020		73		\$0.00
Medium	Work In Progress	115			7/27/2020 2:16:40 PM				
Escobar, David		classroom is hot							
Michelle Guerra									
233781	Main Building	Classroom			7/27/2020		73		\$0.00
Medium	Work In Progress	128			7/27/2020 2:17:57 PM				
Escobar, David		classroom is hot							
Michelle Guerra									
233782	Main Building	Classroom			7/27/2020		73		\$0.00
Medium	Work In Progress	131			7/27/2020 2:18:51 PM				
Escobar, David		classroom is hot							
Michelle Guerra									
233783	Main Building	Classroom			7/27/2020		73		\$0.00
Medium	Work In Progress	133			7/27/2020 2:19:22 PM				
Escobar, David		classroom is hot							
Michelle Guerra									

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Berino ES</b>							
233785	Main Building	Classroom			7/27/2020		73		\$0.00
Medium	Work In Progress	133			7/27/2020 2:19:50 PM				
Escobar, David		classroom is hot							
Michelle Guerra									
<b>Count: 17 Work Orders</b>		<b>Avg. Age of WO's</b>			<b>71</b>	<b>Total for Berino ES</b>		<b>0</b>	<b>\$286.35</b>

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral ES</b>									
233526	Main Building	Office			7/21/2020		79		\$0.00
Medium	Work In Progress	office			7/21/2020 1:13:12 PM				
Marquez, Gerardo		need room across from vault to have same key as vault (rekey) See front office.							
Jennifer Corral									
233165	Main Building	Office			7/9/2020		91		\$0.00
Medium	Work In Progress	Vault and extra			7/9/2020 3:41:05 PM				
Marquez, Gerardo		Administration would like locks to be redone and keyed with different key for vault and extra utility room located in the front office. Please see Jennifer or Duque/Davis							
Jennifer Corral									
235319		Kitchen			8/25/2020		44		\$0.00
High	Work In Progress				8/25/2020 9:40:53 AM				
Chavez, Santos		Light out in bathroom							
Dino Facio									
235082					8/19/2020		50		\$0.00
Medium	Work In Progress				8/19/2020 10:15:11 AM				
Chavez, Santos		Need doorbells upgraded							
Jimmy Carbajal									
234544	Main Building	Classroom			8/7/2020		62		\$0.00
Medium	Work In Progress				8/7/2020 9:25:14 AM				
Acuna, Johnny		Room #326 doesn't have window blinds				Reassign to Memo - 8/12/20			
Adrian Flores									
<b>Count: 5 Work Orders</b>		<b>Avg. Age of WO's 65</b>		<b>Total for Chaparral ES</b>				<b>0</b>	<b>\$0.00</b>

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
235128		Kitchen			8/20/2020		49		\$0.00
High	Work In Progress			8/20/2020 11:46:46 AM					
Acuna, Johnny	Need to replace the mop holders in the mop room broken dont hold the mops anymore								
Dino Facio									
233093					7/7/2020		93		\$39.80
Medium	Work In Progress	AUX. GYM		7/7/2020 5:19:51 PM					
Acuna, Johnny	Need (8) Emergency light batteries for New Aux. Gym. (Hubbell: Part #93012372)								
Johnny Acuna									
236459					9/21/2020		17		\$0.00
Medium	Work In Progress			9/21/2020 3:37:49 PM					
Carrasco, Danny	Need tools for Juan Carlos Vargas.								
Johnny Acuna									
233734					7/24/2020		76		\$0.00
Medium	Work In Progress			7/27/2020 8:48:32 AM					
Flores, Pete	JD Gator # 0500 needs to be service.								
Guadalupe Ontiveros									
233107					7/8/2020		92		\$0.00
Medium	Work In Progress			7/8/2020 10:15:04 AM					
Ontiveros, Joe	check water faucets in all restroom sinks alot of them are loose.								
Jesus Urquidi									
235184	D-Wing	Restroom			8/21/2020		48		\$0.00
Medium	Work In Progress	Staff restroom		8/21/2020 9:12:00 AM					
Villalobos, Margret	Need to fumigate D wing staff restroom. Has ants. (Custodial)					8/24/20 - Approved and EM Waiver			
Mireya Meza									
235185	Field House	Athletic Field			8/21/2020		48		\$0.00
Medium	Work In Progress	Concession		8/21/2020 9:14:39 AM					
Villalobos, Margret	Need to fumigate concession stand field house. Has black widows in it. (Custodial)					8/24/20 - Approved and EM Waiver			
Mireya Meza									
235186	Q-Wing	Classroom			8/21/2020		48		\$0.00
Medium	Work In Progress	All of Q & R		8/21/2020 9:17:16 AM					
Villalobos, Margret	Need to fumigate Q & R buildings have lots of spiders. Black widows and other type of spiders. (Custodial)					8/24/20 - Approved and EM Waiver			
Mireya Meza									



## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral HS</b>									
235931	B-Wing	Classroom			9/8/2020		30		\$6.99
Medium	Work In Progress				9/8/2020 7:57:40 AM				
Ontiveros, Joe		sink in B science classroom by the window shoots water from on top of water faucet.							
Jesus Urquidi									
236012	B-Wing	Restroom			9/9/2020		29		\$2.19
Medium	Work In Progress				9/9/2020 10:51:44 AM				
Ontiveros, Joe		staff restroom leaks down the shaft when flushed.							
Jesus Urquidi									
236043	G-Wing	Custodial			9/10/2020		28		\$0.00
Medium	Work In Progress				9/10/2020 7:58:27 AM				
Ontiveros, Joe		custodial closet sink faucet leaking.							
Jesus Urquidi									
236044		Gym			9/10/2020		28		\$0.00
Medium	Work In Progress				9/10/2020 7:59:56 AM				
Ontiveros, Joe		new gym custodial closet sink faucet leaking.							
Jesus Urquidi									
236324	B-Wing	Classroom			9/17/2020		21		\$0.00
Medium	Work In Progress				9/17/2020 9:04:31 AM				
Ontiveros, Joe		B-wing eye wash shower part is leaking on top B-3 science room.							
Jesus Urquidi									
236388	Field House	Restroom			9/18/2020		20		\$141.80
Medium	Work In Progress				9/18/2020 1:23:34 PM				
Ontiveros, Joe		boys restroom outside by consession 6 toilets and 4 urinals need batteries.							
Jesus Urquidi									
235131	Q-Wing	Restroom			8/20/2020		49		\$14.97
Medium	Work In Progress				8/20/2020 12:24:05 PM				
Ontiveros, Joe		2nd urinal leaking from bottom.							
Jesus Urquidi									

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Chaparral HS

233076	E-Wing	Classroom			7/7/2020		93		\$0.00
--------	--------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	E4			7/7/2020 2:00:39 PM				
--------	------------------	----	--	--	---------------------	--	--	--	--

Chavez, Santos  
Please fix outlets. Only the one by the front of class works. All the others don't. This has been an on going problem in my room. This is not the first time I ask for them to be fixed. (Ms. Gonzalez, E4)

Mireya Meza

235196					8/21/2020		48		\$2.25
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/21/2020 10:36:18 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Chavez, Santos  
Fluorescent light cover missing main hallway in front of old gym.

Jesus Urquidi

233275	G-Wing	Classroom			7/13/2020		87		\$0.00
--------	--------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	G1			7/13/2020 3:18:20 PM				
--------	------------------	----	--	--	----------------------	--	--	--	--

Marquez, Gerardo  
Wall cabinet on the right side does not lock. (Ms. Montelongo, G1)

Mireya Meza

233347	G-Wing	Classroom			7/15/2020		85		\$0.00
--------	--------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	G4			7/15/2020 10:23:27 AM				
--------	------------------	----	--	--	-----------------------	--	--	--	--

Marquez, Gerardo  
Lock on this door is hard to open and close. When you insert key it turns several times and key gets stuck. (Mireya Meza0)

Mireya Meza

233348	F-Wing	Classroom			7/15/2020		85		\$0.00
--------	--------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	F5			7/15/2020 10:26:19 AM				
--------	------------------	----	--	--	-----------------------	--	--	--	--

Marquez, Gerardo  
We do not have a key number for wall cabinet in F5. The core is blank. We don't know if it works. (Mireya Meza)

Mireya Meza

234391		Kitchen			8/4/2020		65		\$0.00
--------	--	---------	--	--	----------	--	----	--	--------

High	Work In Progress				8/4/2020 3:13:23 PM				
------	------------------	--	--	--	---------------------	--	--	--	--

Marquez, Gerardo  
North side door that leads from the kitchen to the dining area will open with master key

Dino Facio

233569	A-Wing	Office			7/22/2020		78		\$0.00
--------	--------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Counselor area			7/22/2020 9:33:59 AM				
--------	------------------	----------------	--	--	----------------------	--	--	--	--

Marquez, Gerardo  
Please make me 2 copies of key CH21 & 1 of CH17. (Mireya Meza)

Mireya Meza

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
233504	A-Wing	Office			7/21/2020		79		\$0.00
Medium	Work In Progress	Mireya's office			7/21/2020 11:04:37 AM				
Marquez, Gerardo		Need copy of key to Mireya's office. (Victoria Lopez, principal)							
Mireya Meza									
233512	B-Wing	Classroom			7/21/2020		79		\$0.00
Medium	Work In Progress	B4			7/21/2020 11:40:34 AM				
Marquez, Gerardo		Please make me 2 copies of key CH37. (Mireya Meza)							
Mireya Meza									
234549	A-Wing	Classroom			8/7/2020		62		\$0.00
Medium	Work In Progress	A110			8/7/2020 10:01:39 AM				
Marquez, Gerardo		May I have 3 copies of key 194E. (Mireya Meza)							
Mireya Meza									
234505	B-Wing	Classroom			8/6/2020		63		\$0.00
Medium	Work In Progress	B3			8/6/2020 1:53:35 PM				
Marquez, Gerardo		Door is off balance and will not close all the way. (custodian, B3)							
Mireya Meza									
234506	B-Wing	Restroom (Girls)			8/6/2020		63		\$0.00
Medium	Work In Progress	Girls restroom			8/6/2020 1:55:20 PM				
Marquez, Gerardo		The 5th stall in the girls bathroom in B hall is missing part of the locking latch. (custodian, B wing girls bathroom)							
Mireya Meza									
234672					8/10/2020		59		\$0.00
Medium	Work In Progress				8/10/2020 12:14:59 PM				
Marquez, Gerardo		Please replace missing lock cylinder to lock on back of football bleachers gate.							
Johnny Acuna									
236473					9/21/2020		17		\$0.00
Medium	Work In Progress				9/21/2020 4:22:48 PM				
Acuna, Johnny		Need to paint outer beam under roof to main building in Front Courtyard.							
Johnny Acuna									
<b>Count: 29 Work Orders</b>		<b>Avg. Age of WO's 57</b>		<b>Total for Chaparral HS</b>			<b>0</b>	<b>\$208.00</b>	

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral MS</b>									
235405	Main Building	Classroom			8/27/2020		42		\$0.00
Medium	Work In Progress	Entire building			8/27/2020 9:33:14 AM				
Acuna, Johnny		Need touch up of paint on all walls and door frames from inside classrooms and outside classrooms				9/29/20 - Route back to Johnny asp Memo -mkv			
Maria Garcia									
233344	Main Building	Classroom			7/15/2020		85		\$0.00
Medium	Work In Progress	102			7/15/2020 9:04:07 AM				
Marquez, Gerardo		Door will not open							
Maria Garcia									
236438	Main Building	Foyer			9/21/2020		17		\$0.00
Medium	Work In Progress	Entrance Doors			9/21/2020 11:10:17 AM				
Marquez, Gerardo		Entrance Doors that lead to fields do not shut properly hinges and door frame are rusted out need to be replaced.							
Maria Garcia									
235034					8/18/2020		51		\$900.51
Medium	Work In Progress				8/18/2020 1:12:12 PM				
Chavez, Santos		Need to repair Emergency lighting and Exit lighting. Please see Johnny Acuña for list. ThankYou.....							
Johnny Acuna									
235039					8/18/2020		51		\$0.00
Medium	Work In Progress				8/18/2020 1:24:17 PM				
Chavez, Santos		Band Room Lobby: Need to replace missing light cover w/frame to light fixture.							
Johnny Acuna									
234954					8/17/2020		52		\$30.98
Medium	Work In Progress				8/17/2020 10:20:31 AM				
Ontiveros, Joe		Need to replace leaking water supply valve on wall to ice -machine located inside the back Boy's Locker Room.							
Johnny Acuna									
235667					9/2/2020		36		\$0.00
Medium	Work In Progress				9/2/2020 4:15:24 PM				
Chavez, Santos		Need to replace burned out light ballasts to light fixtures in portable #6							
Johnny Acuna									

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Chaparral MS</b>										
234364	Main Building	Classroom			8/4/2020		65		\$0.00	
Medium	Work In Progress	203			8/4/2020 10:33:00 AM					
Ontiveros, Joe		sink clogged								
Maria Garcia										
235687	Main Building	Exterior			9/3/2020		35		\$0.00	
Medium	Work In Progress	field			9/3/2020 10:12:49 AM					
Ontiveros, Guadalupe		west side tree line irrigation valves leaking								
Maria Garcia										
235004		Custodial			8/18/2020		51		\$0.00	
Medium	Work In Progress				8/18/2020 9:16:20 AM					
Acuna, Johnny		I needs windo screens throughout the whoule school								
		Gracias								
M. Carmen Perez										
<b>Count: 10 Work Orders</b>		<b>Avg. Age of WO's 49</b>		<b>Total for Chaparral MS</b>				<b>0</b>	<b>\$931.49</b>	

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Desert Pride HS</b>							
236446		Parking Lot			9/21/2020		17		\$0.00
Medium	Work In Progress	Main Gate			9/21/2020 1:35:11 PM				
Avila, Jesus		The fence pole to the main gate doors was bent and needs repair							
Maria Carbajal									
236151		Kitchen			9/11/2020		27		\$0.00
High	Work In Progress				9/11/2020 2:27:27 PM				
Appelzoller, Fred		Hand sink at front serving line not reaching 100° temp as per Health Insp.							
Dino Facio									
234998					8/18/2020		51		\$0.00
Medium	Work In Progress				8/18/2020 8:10:21 AM				
Appelzoller, Fred		Need to replace circulating pump for new boiler at DP.							
Guillermo Hernandez									
<b>Count: 3 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>32</b>	<b>Total for Desert Pride HS</b>			<b>0</b>	<b>\$0.00</b>

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail ES</b>							
236475		Kitchen			9/22/2020		16		\$0.00
High	Work In Progress			9/22/2020 7:03:30 AM					
Ontiveros, Joe	Three compartment sink drain clogged								
Dino Facio									
236628		Portables			9/24/2020		14		\$0.00
Medium	Work In Progress			9/24/2020 10:42:07 AM					
Chavez, Santos	Buenos dias el portable num.413 le puse focos nuevos y no prenden por favor de revisarlo gracias								
Laura Sandoval									
236804		Portables			9/30/2020		8		\$0.00
Medium	Work In Progress			9/30/2020 9:45:42 AM					
Chavez, Santos	Buenos dias .La luz del portable 401 de afuera no prende por favor de revisarla gracias								
Laura Sandoval									
235741	Main Building	Classroom			9/4/2020		34		\$0.00
Medium	Work In Progress	308		9/4/2020 10:24:03 AM					
Chavez, Santos	there is a constant flashing\blinking of a ceiling light (emergency light) possibly under warranty Attention: Gallegos								
Elizabeth Hernandez									
234106	Main Building	Office			7/31/2020		69		\$0.00
Medium	Work In Progress	front office		7/31/2020 2:48:55 PM					
Marquez, Gerardo	Secretary office door is hard to unlock and lock.								
Elizabeth Hernandez									
234470		Kitchen			8/6/2020		63		\$0.00
High	Work In Progress			8/6/2020 7:57:46 AM					
Ambriz, Jose	AC unit not working in kitchen area (hot)								
Dino Facio									
233009		Custodial			7/6/2020		94		\$0.00
Medium	Work In Progress			7/6/2020 11:30:33 AM					
,	WALK IN GATE AT BUS TURN AROUND NEEDS TO BE FIXED.								
Laura Sandoval									
236483	Main Building	Classroom			9/22/2020		16		\$0.00
Medium	Work In Progress			9/22/2020 9:04:34 AM					
Acuna, Johnny	Put up the white dry erase board in classrooms, see Ms. Barajas upon arrival								
Elizabeth Hernandez									
10/8/2020 11:24:21 AM									

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Desert Trail ES</b>							
236481	Main Building	Exterior			9/22/2020		16		\$17.57
Medium	Work In Progress				9/22/2020 9:03:24 AM				
Ontiveros, Guadalupe		Sacar con raiz el zacata de las posas de los arboles							
Elizabeth Hernandez									
<b>Count: 9 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>37</b>	<b>Total for Desert Trail ES</b>			<b>0</b>	<b>\$17.57</b>



# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert View ES</b>									
236445	Main Building	Hallway/Corridor			9/21/2020		17		\$0.00
Medium	Work In Progress				9/21/2020 1:26:19 PM				
Lara, Ralph		On the handicap entrance that goes to the Multi-Purpose room the the lock that is on top of the removable steel mullion needs to be repaired. When I use my key it just twist with no stop and it does not open.							
Israel Ortega									
234756					8/11/2020		58		\$0.00
Medium	Work In Progress				8/11/2020 9:08:19 PM				
Gonzalez, Salvador		please need homemade drags							
Luis Saucedo									
236247	Main Building	Hallway/Corridor			9/15/2020		23		\$0.00
Medium	Work In Progress				9/15/2020 1:16:34 PM				
Guardado, Sergio		The hallway wall by the Multi-Purpose room needs to be repainted because the paint that was used for touch-up did not match. I did the touch-up because there was a lot of staples that left a lot of white mark but the paint is off and didn't match.							
Israel Ortega									
236573					9/23/2020		15		\$0.00
Medium	Work In Progress				9/23/2020 2:26:26 PM				
Guardado, Sergio		Cut grass through out campus and pounding area. Thank u							
Sergio Guardado									
236383					9/18/2020		20		\$0.00
Medium	Work In Progress	Front of the			9/18/2020 10:20:20 AM				
Guardado, Sergio		Paint the blue rails from the front of the school.							
Guadalupe Gonzalez									
<b>Count: 5 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>27</b>		<b>Total for Desert View ES</b>	<b>0</b>		<b>\$0.00</b>

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: GAC

236440 9/21/2020 17 \$230.00

Medium Work In Progress 9/21/2020 11:31:32 AM

Ambriz, Jose Felipa, our head custodian, asked me to place this work order. Please place an extractor in the bathroom located close to the pre-k center (Finance area). There has been a terrible smell in recent days coming out from that room. Maybe the plumbing should be looked at also. Thank you.

Anne De Los Santos

236645 9/24/2020 14 \$225.00

Medium Work In Progress 9/24/2020 12:25:45 PM

Castillo, Carlos GAC - MICHAEL VEGA OFFICE (TECHNOLOGY DEPT) PLEASE NEEDING NEW LIGHTING.  
THANK YOU

Cora Ramirez

236294 Kitchen 9/16/2020 22 \$0.00

High Work In Progress 9/16/2020 1:19:17 PM

Castillo, Carlos Need baseline electrical cord removed from GAC Kitchen office and re-installed at Desert Pride Kitchen office (modular furniture)

Dino Facio

236424 9/21/2020 17 \$0.00

Medium Work In Progress 9/21/2020 10:29:31 AM

Pacheco, Hector Need to go check water line on the ceiling that is it leaking thru the ceiling tile see felipa for more info. Thank u

Sergio Guardado

236550 Restroom 9/23/2020 15 \$178.09

Medium Work In Progress C-WING BY 9/23/2020 9:12:12 AM

Pacheco, Hector AS PER FELIPA CORTEZ, BATHROOM SINK IN C-WING ACROSS KITCHENETTE IS CLOGGED UP. PLEASE FIX. THANK YOU!

Karla Quesada

236644 9/24/2020 14 \$0.00

Medium Work In Progress 9/24/2020 12:24:20 PM

Guardado, Sergio AT GAC, MICHAEL VEGA OFFICE (TECHNOLOGY DEPT) VENT HAS NO COVERING. PLEASE CHECK AND FIX  
THANK YOU

Cora Ramirez

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: GAC</b>									
236601					9/24/2020		14		\$0.00
Medium	Work In Progress			9/24/2020 7:04:51 AM					
Carbajal, Jimmy	Need the asphalt planner for today and friday. Ill go and get it. Thank u								
Sergio Guardado									
236764					9/29/2020		9		\$0.00
Medium	Work In Progress			9/29/2020 10:57:06 AM					
Solis, Aaron	Need a small snake to unclogged sink. Thank u								
Sergio Guardado									
235075					8/19/2020		50		\$0.00
Medium	Work In Progress			8/19/2020 7:57:35 AM					
Lara, Ralph	Please remove all doors and material that was on the back of the building after renovation was completed for the old front desk.								
Guillermo Hernandez									
<b>Count: 9 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>19</b>		<b>Total for GAC</b>	<b>0</b>	<b>\$633.09</b>	

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>GAC - Pre-K</b>							
235701		Classroom			9/3/2020		35		\$0.00
Medium	Work In Progress	202			9/3/2020 12:19:25 PM				
Lara, Ralph		The door going outside is getting stuck.							
Micaela Paniagua									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>35</b>	<b>Total for GAC - Pre-K</b>			<b>0</b>	<b>\$0.00</b>

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Gadsden ES</b>										
236439		Office			9/21/2020		17		\$0.00	
Medium	Work In Progress				9/21/2020 11:19:32 AM					
Ontiveros, Guadalupe		GES-Requesting for stepping stones to be placed in the front of the school, plus complete stepping stones in the back of the school. GES has purchased stepping stones and are on campus.								
Patty Madrid										
236686		Classroom			9/25/2020		13		\$0.00	
Medium	Work In Progress	308/304			9/25/2020 8:21:42 AM					
Romero, Joaquin		I want to let you know that the pounding is still happening. I have not seen anyone come by since I mentioned it to you last and you put a work order for it. Not sure how serious this problem is but I just want to bring it to your attention....again. (sorry)								
Patty Madrid										
235523		Office			8/31/2020		38		\$0.00	
Medium	Work In Progress	101			8/31/2020 7:55:10 AM					
,		GES-Classroom 101 Temperature in the classroom is very hot								
Patty Madrid										
234329		Office			8/4/2020		65		\$0.00	
Medium	Work In Progress	402			8/4/2020 7:35:47 AM					
Romero, Joaquin		Good Morning Ms. Herrera per our conversation here is the work order for the following. Requesting blinds for the PTO, side office, counselors window for privacy.				waiting for blinds ordered on 8-4-20				
		Greatly Appreciated,								
Patty Madrid										
236683		Parking Lot			9/25/2020		13		\$0.00	
Medium	Work In Progress				9/25/2020 8:14:29 AM					
Tellez, Hector		GES-Requesting lightbulbs that have burnt out in the parking light and the perimeter of the school to be replaced. Thank you								
Patty Madrid										
235682		Restroom			9/3/2020		35		\$0.00	
Medium	Work In Progress				9/3/2020 9:22:57 AM					
Chavez, Santos		boys restroom emergency lights not working hallway Washington 100								
Jose Pinon										

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Gadsden ES</b>							
234937		Custodial			8/17/2020		52		\$0.00
Medium	Work In Progress				8/17/2020 7:10:05 AM				
Ambriz, Jose		Maine Communications room in front of computer lab 404 air conditioner not working real hot in there							
Jose Pinon									
<b>Count: 7 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>33</b>			<b>Total for Gadsden ES</b>	<b>0</b>		<b>\$0.00</b>

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
234773					8/12/2020		57		\$393.41
Medium	Work In Progress			8/12/2020 12:14:04 PM					
Escobar, David	Portable 150 computer tech room unit is not working. trouble shoot unit and it might be the contractor need to order parts								
Joaquin Romero									
236249					9/15/2020		23		\$210.27
Medium	Work In Progress			9/15/2020 2:10:27 PM					
Romero, Joaquin	Requested by Mr. David Martinez for Rm. 715 in Admin. Building-Please paint one wall, opposite of the door inside the office # 715. PLEASE CONTACT MR. MARTINEZ ABOUT REQUEST BEFORE PAINTING BEGINS.				Ordered paint on 10-7-20				
Velia Alarcon									
236250					9/15/2020		23		\$309.07
Medium	Work In Progress			9/15/2020 2:13:41 PM					
Romero, Joaquin	Requested by Mr. David Martinez for Wall Outside of Office # 712 in Admin. Building-Please paint the wall outside of Mrs. Rodriguez's Office, closest to her door. PLEASE CONTACT MR. MARTINEZ AND/OR MRS. RODRIGUEZ ABOUT REQUEST BEFORE PAINTING BEGINS.				Ordered paint on 10-7-20				
Velia Alarcon									
236231					9/15/2020		23		\$0.00
Medium	Work In Progress			9/15/2020 8:20:00 AM					
Escobar, David	replace AC system at portable 10 GHS.								
David Escobar									
236488					9/22/2020		16		\$0.00
Medium	Work In Progress			9/22/2020 9:27:31 AM					
Tellez, Hector	lite fixer needs to be replaced in grounds storage. replaced lite bulbs, still not working.								
Guadalupe Ontiveros									
236186					9/14/2020		24		\$60.03
Medium	Work In Progress			9/14/2020 7:46:50 AM					
Tellez, Hector	Wire up ticket booth for football								
Hector Tellez									

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
234924					8/14/2020		55		\$0.00
Medium	Work In Progress			8/14/2020 3:53:18 PM					
Tellez, Hector	Requested by Mr. Ramon Quiroga Rm. 516 CTE Building Flower Shop-Wants to see if an electrical outlet can be placed in the flower shop where teacher has no electricity. MR. QUIROGA IS ON CAMPUS ON MONDAY, TUESDAY, THURSDAY AND FRIDAY. IF MAINTENANCE HAVE ANY QUESTIONS.		8/19/20 - asp Joaquin, outlets need to be moved						
Velia Alarcon									
234122					7/31/2020		69		\$82.81
Medium	Work In Progress			7/31/2020 4:04:55 PM					
Tellez, Hector	Requested by Chef Anthony Sapien Rm. 515/517 CTE Building-Replace silver receptacles outlets located in the kitchen with purchases Electrical Rooftop Cord Reels (total of 3). FOR FURTHER INFORMATION OR INSTRUCTION PLEASE CHEF SAPIEN. HE HAS CHOSEN THE OPTION OF ONLY BEING ON THE SCHOOL CAMPUS ON MONDAYS AND TUESDAY, PLEASE SEE HIM THEN.								
Velia Alarcon									
233845	Academic Bldg				7/28/2020		72		\$259.45
Medium	Work In Progress			7/28/2020 11:22:50 AM					
Tellez, Hector	2 light fixtures in hallways Balast out in both. first light fixture outside classroom 330 the other by room 322								
Liliana Acosta									
235423					8/27/2020		42		\$0.00
High	Work In Progress			8/27/2020 12:16:43 PM					
Appelzoller, Fred	Culinary kitchen (Panther Hut) needs a new gas connection for an additional stove. Also needs the quick-disconnect gas lines that were not purchased with the stove.								
Danielle Rodriguez									
235947					9/8/2020		30		\$0.00
Medium	Work In Progress			9/8/2020 9:32:03 AM					
Flores, Pete	M-GHS-0436 mower needs blade bearing replaced and belt.this mower is being used at ghs-gms-								
Guadalupe Ontiveros									
236616					9/24/2020		14		\$0.00
High	Work In Progress			9/24/2020 9:12:19 AM					
Gonzalez, Salvador	TR-GHS-#0752 repair gate on trailer.								
Guadalupe Ontiveros									



## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Gadsden HS

235603		Restroom			9/1/2020		37		\$0.00
--------	--	----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				9/1/2020 10:55:46 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Hernandez, Guillemo  
 OLD MAIN BOYS RESTROOMS STALLS- restroom stalls need to be sanded they have GRAFFITI carved on all the stalls, they were not sanded during the summer

Liliana Acosta

233070					7/7/2020		93		\$0.00
--------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				7/7/2020 1:24:36 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe  
 Requested by Mrs. Danielle Rodriguez for Landscape Outside of the Science Building on the South Side-Rock needs to be added to the landscape outside of the Science Building on the south side.

Velia Alarcon

233071					7/7/2020		93		\$0.00
--------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				7/7/2020 1:26:06 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe  
 Requested by Mrs. Danielle Rodriguez Landscape Outside of the Cafeteria-Rock needs to be added to the landscape outside of the Cafeteria.

Velia Alarcon

233590	Cafeteria (1998)				7/22/2020		78		\$0.00
--------	------------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/22/2020 2:06:53 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe  
 Requested by the G.H.S. Admin. Team-Leaves in front of the Cafeteria and on the rocks need to be swept up and picked up.

Velia Alarcon

233598					7/22/2020		78		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/22/2020 2:25:33 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe  
 Requested by the G.H.S. Admin. Team-The weeds inside the courtyard of the Old Main Building need to be pulled/cleaned up.

Velia Alarcon

233600					7/22/2020		78		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/22/2020 2:40:05 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe  
 Requested by the G.H.S. Admin. Team-Rocks needs to be filled on the north side of the Theater Building.

Velia Alarcon

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
233602					7/22/2020		78		\$0.00
Medium	Work In Progress			7/22/2020 2:42:23 PM					
Ontiveros, Guadalupe	Requested by the G.H.S. Admin. Team-Rock needs to be filled on the south side of the North Building between the North Building and Theater.								
Velia Alarcon									
233603					7/22/2020		78		\$0.00
Medium	Work In Progress			7/22/2020 2:44:14 PM					
Ontiveros, Guadalupe	Requested by the G.H.S. Admin. Team-Sweep rocks off the sidewalk on the north side of the North Building by ROTC.								
Velia Alarcon									
233605					7/22/2020		78		\$0.00
Medium	Work In Progress			7/22/2020 2:47:03 PM					
Ontiveros, Guadalupe	Requested by the G.H.S. Admin. Team-Rock needs to be filled outside of the Academic Building on the north side.								
Velia Alarcon									
233616					7/22/2020		78		\$0.00
Medium	Work In Progress			7/22/2020 3:28:40 PM					
Ontiveros, Guadalupe	Requested by the G.H.S. Admin. Team-Trim tree outside of Mr. Mora's (Athletic Training Room) by the Panther Gym.								
Velia Alarcon									
233622					7/22/2020		78		\$0.00
Medium	Work In Progress			7/22/2020 3:39:17 PM					
Ontiveros, Guadalupe	Requested by the G.H.S. Admin. Team-Rocks need to be filled on the north side of the Weight Room.								
Velia Alarcon									
235359					8/25/2020		44		\$0.00
Medium	Work In Progress			8/25/2020 3:47:17 PM					
Lara, Ralph	Requested by Ms. Juana Santamaria Rm. 805 Annex Building-Need door knob to lock the door from inside of the classroom restroom.								
Velia Alarcon									

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden HS</b>									
233252					7/13/2020		87		\$0.00
Medium	Work In Progress				7/13/2020 8:05:02 AM				
Lara, Ralph		The boys gym is going to get the gym floor re-done and need to change the locks so no one may enter except the the company that is doing the gym floor.							
233493					7/21/2020		79		\$0.00
Medium	Work In Progress				7/21/2020 9:10:58 AM				
Lara, Ralph		Requested by Frank Marin for Rm. 504 CTE Building- Bay door is not working and needs to be re-set, bay door does not go up.							
Velia Alarcon									
235122					8/20/2020		49		\$0.00
Medium	Work In Progress				8/20/2020 11:07:00 AM				
Lara, Ralph		Requested by Mr. David Martinez-Please provide a key that will open the Varsity Gym entrance doors only, 8 keys will be needed.							
Velia Alarcon									
235711					9/3/2020		35		\$0.00
Medium	Work In Progress				9/3/2020 2:27:51 PM				
Lara, Ralph		Requested by Mr. David Martinez for Varsity Gym-The Varsity Gym doors that lead to the basketball court need to be repaired or replaced because they are not working properly when trying to secure the Varsity Gym.							
Velia Alarcon									
236484					9/22/2020		16		\$0.00
Medium	Work In Progress				9/22/2020 9:08:04 AM				
Lara, Ralph		Requested by Velia for New Panther Gym (Boys Gym)- Six (6) additional HE200 keys are needed for the entrance doors into the New Panther Gym (Boys Gym).							
Velia Alarcon									
236695					9/25/2020		13		\$0.00
Medium	Work In Progress				9/25/2020 10:07:01 AM				
Lara, Ralph		Requested by Mr. David Martinez for Varsity Gym- Please check the Varsity Gym doors that lead to the basketball court. These doors are difficult to secure and appear to be out of alignment.							
Velia Alarcon									

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Gadsden HS</b>										
236500		Custodial			9/22/2020		16		\$0.00	
Medium	Work In Progress				9/22/2020 10:33:24 AM					
Lara, Ralph		Need metal screw on pegs for Varsity doors to prop doors open/spoke with Daniel Carrasco told me request them from lock smith								
Liliana Acosta										
236638	Boys Gym	Custodial			9/24/2020		14		\$0.00	
Medium	Work In Progress				9/24/2020 11:28:58 AM					
Lara, Ralph		Boys Gym -Training room custodial closet- need custodial doors both in and outside keys changed one to M200 inside training room the other top lock door outside to HE-1.								
Liliana Acosta										
233708					7/24/2020		76		\$0.00	
Medium	Work In Progress				7/24/2020 11:09:30 AM					
Lara, Ralph		Requested by the Admin. Team-Three keys are need to open the storage room # 208S in the North Building.								
Velia Alarcon										
<b>Count: 33 Work Orders</b>		<b>Avg. Age of WO's 52</b>		<b>Total for Gadsden HS</b>				<b>0</b>	<b>\$1,315.04</b>	

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden MS</b>									
233006					7/6/2020		94		\$0.00
Medium	Work In Progress	Garden by			7/6/2020 10:41:01 AM				
Ontiveros, Guadalupe		Please remove weeds from garden ground as per Mrs. Quinonez. Thank you							
Hilda Adler									
233184					7/10/2020		90		\$0.00
Medium	Work In Progress	Mrs. Quinonez			7/10/2020 1:29:55 PM				
Villalobos, Jose		Please fix Pallet Jack, we need it. Its not working, leaking hydraulic oil. Thank you Mrs. Quinonez				Please forward to Joe - J. Romero 8/4/20			
Hilda Adler									
236641	Main Building	Restroom			9/24/2020		14		\$54.51
Medium	Work In Progress				9/24/2020 12:07:50 PM				
Appelzoller, Fred		Clogged urinal in the boys restroom. on the mid corridor. Thank you							
Martin Soria									
235267	C-Wing	Office			8/24/2020		45		\$0.00
Medium	Work In Progress	Nursing			8/24/2020 1:29:00 PM				
Marquez, Gerardo		Please send Locksmith, I have lost a set of keys to my storage portable. Nursing Department. Thank you, Priscilla							
Priscilla Martinez									
234594	Cafeteria	Cafeteria			8/7/2020		62		\$4.68
Medium	Work In Progress	Cafeteria / Mr.			8/7/2020 3:41:35 PM				
Escobar, David		One AC unit in the cafeteria is not working.							
Hilda Adler									
<b>Count: 5 Work Orders</b>			<b>Avg. Age of WO's 61</b>			<b>Total for Gadsden MS</b>	<b>0</b>		<b>\$59.19</b>

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: La Union ES</b>									
234446					8/5/2020		64		\$44.99
Medium	Work In Progress				8/5/2020 2:39:05 PM				
Pacheco, Hector		Hose bid is leaking outside the cafeteria.							
Guadalupe Parada									
236560					9/23/2020		15		\$194.80
Medium	Work In Progress				9/23/2020 11:57:51 AM				
Pacheco, Hector		Requesting to have the toilet in room 201 to be replaced due to is not flushing to well.							
Guadalupe Parada									
235669		Kitchen			9/3/2020		35		\$0.00
High	Work In Progress				9/3/2020 7:26:20 AM				
Castillo, Carlos		Electrical power pole source not functioning properly							
Dino Facio									
235190	Main Building	Athletic Field			8/21/2020		48		\$0.00
Medium	Work In Progress				8/21/2020 9:33:50 AM				
Ontiveros, Guadalupe		Poor drainage near PreK playground. Rain water flows toward building instead of drain. Need to re-slope area so that water will run towards drain. Discussed with Mr. Ontiveros last school year. Also, look into installing gutters on middle wing roof that will empty into drain.							
Arthur Moreno									
236323					9/17/2020		21		\$0.00
Medium	Work In Progress				9/17/2020 8:44:21 AM				
Lara, Ralph		As per Mr. Sanchez to installed door sweeps in all the inside school doors.				This work order was reroute to locksmith. Thank u			
Guadalupe Parada									
236498					9/22/2020		16		\$0.00
Medium	Work In Progress				9/22/2020 9:59:41 AM				
Lara, Ralph		As per Mr. Sanchez requesting door stoppers to be installed in all classrooms doors including offices and library.							
Guadalupe Parada									
<b>Count: 6 Work Orders</b>		<b>Avg. Age of WO's 33</b>		<b>Total for La Union ES</b>		<b>0</b>		<b>\$239.79</b>	

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Loma Linda ES</b>									
236486		Kitchen			9/22/2020		16		\$0.00
High	Work In Progress				9/22/2020 9:21:34 AM				
Romero, Joaquin		Exhaust fan not working in kitchen restroom				Ordered exhaust fan on 9-24-20			
Dino Facio									
236150		Kitchen			9/11/2020		27		\$0.00
High	Work In Progress				9/11/2020 2:07:29 PM				
Romero, Joaquin		Exhaust fan in kitchen restroom not working				duplicate			
Dino Facio									
235446					8/28/2020		41		\$0.00
Medium	Work In Progress				8/28/2020 6:13:57 AM				
Carrasco, Danny		need plasti-coat paint that turns into a rubber to repair broken cafeteria tables the rubber on the sides of the seats are being peeled off.				8/28/20 - as per Danny, this needs to be routed to maintenance.			
236740					9/28/2020		10		\$54.51
Medium	Work In Progress				9/28/2020 10:46:34 AM				
Appelzoller, Fred		el drenage esta tapado de los baños de las niñas del pasillo 200. es urgente							
Joe Munoz									
236509		Kitchen			9/22/2020		16		\$0.00
High	Work In Progress				9/22/2020 12:05:26 PM				
Ontiveros, Joe		Need water source to Skillet open no water comes out from sprayer							
Dino Facio									
236564		Kitchen			9/23/2020		15		\$0.00
High	Work In Progress				9/23/2020 1:16:36 PM				
Ontiveros, Joe		Toilet leaking from the bottom							
Dino Facio									
236802		Restroom			9/30/2020		8		\$0.00
Medium	Work In Progress				9/30/2020 9:07:46 AM				
Ontiveros, Joe		EL DRENAGE DE LOS BAÑOS DE LOS NINOS DEL PASILLO 200 SE ENCUENTRA TAPADO.							
Joe Munoz									

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Loma Linda ES</b>									
235178	Main Building	Exterior			8/21/2020		48		\$0.00
Medium	Work In Progress	Outside of main			8/21/2020 8:26:52 AM				
Romero, Joaquin		Mr. Cardona is requesting for the tables and benches outside to be retouched.				ordered paint 9-9-20			
Crystalee Heredia									
235182	Main Building	Restroom			8/21/2020		48		\$0.00
Medium	Work In Progress	All boy/girl			8/21/2020 8:43:34 AM				
Romero, Joaquin		Mr. Cardona is requesting for all bathroom partitions to be painted.				Ordered paint on 9-20-20			
Crystalee Heredia									
<b>Count: 9 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>25</b>	<b>Total for Loma Linda ES</b>			<b>0</b>	<b>\$54.51</b>



## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Mesquite ES</b>							
234967	Main Building	Office			8/17/2020		52		\$0.00
Medium	Work In Progress	Room # 203/205			8/17/2020 12:44:01 PM				
Escobar, David		In room 203/205 A/C not working please fix. Thank you.							
Sandra Mora									
233763	Army Building	Portables			7/27/2020		73	0.5	\$43.10
Medium	Work In Progress	Portable # 505			7/27/2020 1:36:14 PM				
Escobar, David		Portable A/C is not working we have staff in it please make it cool thank you.				Troubleshoot unit. Compressor did not start Forward to Hvac 7-28-20			
Sandra Mora									
235022					8/18/2020		51		\$0.00
Medium	Work In Progress				8/18/2020 12:00:06 PM				
Marquez, Gerardo		Front door hinge							
Branden Jaquemai									
236676		Kitchen			9/25/2020		13		\$90.85
High	Work In Progress				9/25/2020 7:07:01 AM				
Appelzoller, Fred		Floor drain in the middle of kitchen floor clogged							
Dino Facio									
233715		Kitchen			7/24/2020		76		\$0.00
High	Work In Progress				7/24/2020 1:34:13 PM				
Tellez, Hector		Need new electrical plug for new cutter/mixture							
Dino Facio									
235330	Main Building				8/25/2020		44		\$0.00
Medium	Work In Progress	Room # 107			8/25/2020 11:33:33 AM				
Tellez, Hector		Lina Flores requesting electrical work done in book room plugs installed please and thank you.							
Sandra Mora									
236089	Main Building	Office			9/10/2020		28		\$0.00
Medium	Work In Progress	Lobby			9/10/2020 2:30:25 PM				
Tellez, Hector		Noise in main office due to light fixture ballast.. please help and thank you.							
Sandra Mora									
<b>Count: 7 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>48</b>	<b>Total for Mesquite ES</b>			<b>0.5</b>	<b>\$133.95</b>

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: North Valley ES</b>									
233648		Kitchen			7/23/2020		77		\$913.23
High	Work In Progress				7/23/2020 8:59:27 AM				
Appelzoller, Fred		No hot water in kitchen area							
Dino Facio									
235023					8/18/2020		51		\$21.16
Medium	Work In Progress	playground			8/18/2020 12:36:48 PM				
Ontiveros, Guadalupe		Please refill the bark in playground areas. Thank you.							
Ruth Gomez									
<b>Count: 2 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>64</b>		<b>Total for North Valley ES</b>	<b>0</b>	<b>\$934.39</b>	

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Northern On-Track Pre-K (LM)</b>										
235450					8/28/2020		41		\$0.00	
Medium	Work In Progress				8/28/2020 8:05:26 AM					
		The door handle in classroom 108 is loose and not locking correctly. Please check it out. Thanks!								
Viola Ramos										
<b>Count: 1 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>41</b>	<b>Total for Northern On-Track Pre-K (LM)</b>			<b>0</b>	<b>\$0.00</b>	

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Physical Plant Complex</b>									
236713	Main Warehouse				9/25/2020		13		\$0.00
Medium	Work In Progress				9/25/2020 1:22:29 PM				
Carrasco, Danny		REQUESTING 2" STRAPS FOR TRUCK # 64							
Danny Carrasco									
236651					9/24/2020		14		\$0.00
Medium	Work In Progress				9/24/2020 12:49:23 PM				
Appelzoller, Fred		needing bay drains cleaned out please							
Pete Flores									
236737					9/28/2020		10		\$0.00
Medium	Work In Progress	Instructional			9/28/2020 10:10:22 AM				
Marquez, Gerardo		Install small window on door to Instructional Materials main entrance.							
Ray Lara									
236739					9/28/2020		10		\$0.00
Medium	Work In Progress				9/28/2020 10:42:25 AM				
Guardado, Sergio		Need to order material and order a pre hung solid wood door with window for the Hvac office/shop. Thank you							
Sergio Guardado									
235140					8/20/2020		49		\$224.00
Medium	Work In Progress				8/20/2020 12:47:31 PM				
Gonzalez, Salvador		Need to repair damaged chain link fence in back of Riverside elementary							
Salvador Gonzalez									
236229					9/15/2020		23		\$0.00
Medium	Work In Progress	Truck #246			9/15/2020 8:00:36 AM				
Gonzalez, Salvador		As per conversation with Pete and Memo in need to weld side hooks on truck rack for ladders..							
Hector Pacheco									
236348					9/17/2020		21		\$0.00
Medium	Work In Progress				9/17/2020 2:00:29 PM				
Gonzalez, Salvador		9-17-2020 Requesting some chemicals for shop Rust remover and prime coat Penetrating oil Grease remover							
Salvador Gonzalez									

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Physical Plant Complex</b>									
236448					9/21/2020		17		\$0.00
Medium	Work In Progress				9/21/2020 1:45:06 PM				
Avila, Jesus		Requesting tools for welding shop.							
Jesus Avila									
236608					9/24/2020		14		\$0.00
Medium	Work In Progress				9/24/2020 8:19:22 AM				
Avila, Jesus		we need to be replaced damaged ac motor in welding shop, not working properly.							
Jesus Avila									
234799					8/13/2020		56		\$746.32
Medium	Work In Progress				8/13/2020 7:52:10 AM				
Pacheco, Hector		In need of sewer cable for machine 1/2 inch x 50 feet and a 1/2 inch x 75 feet cable.							
Hector Pacheco									
236566		Electrical Room			9/23/2020		15		\$0.00
Medium	Work In Progress				9/23/2020 1:29:25 PM				
Castillo, Carlos		Check ,service,clean,lubricate all S.District electrical equipment							
Carlos Castillo									
235370					8/26/2020		43		\$0.00
Medium	Work In Progress				8/26/2020 8:41:42 AM				
Marquez, Gerardo		NEED TO ORDER FANS FOR LOCKSMITH VANS.							
Gerardo Marquez									
236126					9/11/2020		27		\$0.00
Medium	Work In Progress				9/11/2020 9:35:37 AM				
Marquez, Gerardo		PLEASE ORDER UNIVERSAL PINNING KITS AND NEEDED LOCKSMITHING TOOLS AND SUPPLIES FROM CLK COMPANY.							
Gerardo Marquez									
235999					9/9/2020		29		\$0.00
Medium	Work In Progress				9/9/2020 8:09:06 AM				
Marquez, Gerardo		NEED TO ORDER CARBIDE BUR SETS FOR LOCKSMITH USE DISTRICT WIDE USE.							
Gerardo Marquez									

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Physical Plant Complex</b>										
236414					9/21/2020		17		\$0.00	
Medium	Work In Progress				9/21/2020 9:10:25 AM					
Marquez, Gerardo		AS PER MEMO, PLEASE INVENTORY KEYS TO BE ISSUED TO AARON SOLIZ, AND ISSUE NEEDED KEYS.								
Gerardo Marquez										
233474					7/20/2020		80		\$0.00	
Medium	Work In Progress				7/20/2020 3:22:44 PM					
Marquez, Gerardo		Please change cores from DC-1 to something different, (see Memo first thing in the morning) Total of (5) - Offices Memo, Margret, Ruben, Maintenance Storage Area front and back door.								
Guillermo Hernandez										
233310					7/14/2020		86		\$0.00	
Medium	Work In Progress				7/14/2020 11:54:17 AM					
Marquez, Gerardo		Needed in the construction office preferably by Friday afternoon or Monday Morning at the latest one (1) GM #6 and one (1) GM #7. Keys will be check out to Aliene O'Bryne. Should you have any questions please seemr. Gallegos in the Construction Office.								
Dominique Esparza										
<b>Count: 17 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>31</b>	<b>Total for Physical Plant Complex</b>			<b>0</b>	<b>\$970.32</b>	

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Riverside ES</b>							
234696					8/10/2020		59		\$32.01
Medium	Work In Progress			8/10/2020 3:45:46 PM					
Castillo, Carlos	Pick up at warehouse and install flashing light by bus turnaround.								
Guillermo Hernandez									
235707					9/3/2020		35		\$0.00
Medium	Work In Progress	Main Hallway		9/3/2020 2:01:26 PM					
Ambriz, Jose	Main hallway is very hot please adjust temperature. ((Mrs. Martinez)								
Norma Martinez									
234757					8/11/2020		58		\$0.00
Medium	Work In Progress			8/11/2020 9:11:09 PM					
Gonzalez, Salvador	please need homemade drags								
Luis Saucedo									
234035					7/30/2020		70		\$0.00
Medium	Work In Progress			7/30/2020 2:48:42 PM					
Hernandez, Guillemo	Re-stencil parking lot located behind the school. Principal, Assistant Principal, Secretary, Nurse, and SNP Manager. (Mrs. Martinez)								
Norma Martinez									
236508					9/22/2020		16		\$18.13
Medium	Work In Progress	Ramp by the		9/22/2020 11:44:08 AM					
Guardado, Sergio	Ramp going to the cafeteria/gym is peeling off on the bottom area due to the water licks we used to have before roof was replaced. Expose cinder block looks like it has mold. (Mr. Damian)								
Norma Martinez									
233704					7/24/2020		76		\$140.57
Medium	Work In Progress	Exit doors		7/24/2020 10:26:52 AM					
Guardado, Sergio	Bird spikes need to be re-secure. Pigeons moved bird spikes. (Mrs. Martinez)		Asp report 8/3/20 - pending supplies have been ordered - R. Ortiz						
Norma Martinez									
235708					9/3/2020		35		\$132.75
Medium	Work In Progress			9/3/2020 2:02:30 PM					
Guardado, Sergio	Please paint playground canopy's poles brown to match school building. (Mr. Damian)								
Norma Martinez									

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Riverside ES</b>							
236613					9/24/2020		14		\$26.22
Medium	Work In Progress			9/24/2020 8:52:21 AM					
Guardado, Sergio	Drop off(OUT) zone sign on Rio Grande Dr. street sprayed with graffiti. Please clean graffiti off the sign. (Mrs. Martinez)								
Norma Martinez									
236121					9/11/2020		27		\$0.00
Medium	Work In Progress	Outside		9/11/2020 8:54:39 AM					
Guardado, Sergio	Please paint all three portables to remove the turquoise color. Paint portable trim and ramp brown to match the trim color of the school building. (Mrs. Martinez)								
Norma Martinez									
236124					9/11/2020		27		\$884.13
Medium	Work In Progress	Office		9/11/2020 9:13:58 AM					
Guardado, Sergio	Please replace pvc vinyl wall base in office hallway, offices and restroom to brown to match the front office trim. (Mrs. Martinez)								
Norma Martinez									
236583					9/23/2020		15		\$0.00
Medium	Work In Progress			9/23/2020 2:50:53 PM					
Guardado, Sergio	Need to clean and pick up trash on the drop zone area. Thank u								
Sergio Guardado									
236712					9/25/2020		13		\$0.00
Medium	Work In Progress			9/25/2020 1:04:21 PM					
Lara, Ralph	Door located behind school that takes you to parking lot behind school between cafeteria and gym gets stuck and its very hard to open. (Mrs. Martinez)								
Norma Martinez									
235942					9/8/2020		30	56	\$1,502.96
High	Work In Progress			9/8/2020 9:07:23 AM					
Vasquez, Jose	need to check irrigation . replace broken sprinklers and fix leaks around school site.								
Guadalupe Ontiveros									
<b>Count: 13 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>37</b>	<b>Total for Riverside ES</b>		<b>56</b>	<b>\$2,736.77</b>	



# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>RTC - Alliance</b>							
236605		Portables			9/24/2020		14		\$0.00
Medium	Work In Progress				9/24/2020 8:01:32 AM				
Guardado, Sergio		If possible need window rails and doors painted. Haven't been painted since about 10 yrs.							
Gloria Delgado									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>14</b>			<b>Total for RTC - Alliance</b>	<b>0</b>	<b>0</b>	<b>\$0.00</b>

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description					Action Taken			
Requester Name									
<b>Location:</b>		<b>San Miguel ES</b>							
236526					9/22/2020		2	4.5	\$112.50
Medium	Work In Progress				9/22/2020 3:33:35 PM	9/24/2020			
Appelzoller, Fred	shut off gas for the whole school and disconnect gas line from kitchen					undid gas line, went back to close all the gas at school			
Fred Appelzoller									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>2</b>		<b>Total for San Miguel ES</b>		<b>4.5</b>	<b>\$112.50</b>

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa ES</b>							
236630	Main Building	Custodial			9/24/2020		14		\$97.58
Medium	Work In Progress			9/24/2020 11:02:58 AM					
Pacheco, Hector		Can you replace broken faucet from restroom sink on portable (K).							
		thank you ..							
Maria Gabaldon									
236631	Main Building	Custodial			9/24/2020		14		\$0.00
Medium	Work In Progress			9/24/2020 11:05:50 AM					
Pacheco, Hector		can you replace faucet from restroom sink on portable (C-053.)							
		thank you..							
Maria Gabaldon									
236161					9/11/2020		27		\$27.60
Medium	Work In Progress			9/11/2020 4:06:07 PM					
Castillo, Carlos		Need to change light bulbs on two light poles. First is west pole located in the student pick up area. Second is the north west pole furthest in the parking lot. Should you have any questions please see Mr. Gallegos in the Construction office. Thank You							
Dominique Esparza									
236722	Main Building	Portables			9/25/2020		13		\$557.57
Medium	Work In Progress	Portable J - Art		9/25/2020 3:36:55 PM					
Guardado, Sergio		Please paint the interior of Portable J. Thank you.							
Rita Mendez									
236723		Portables			9/25/2020		13		\$571.55
Medium	Work In Progress	Portable K		9/25/2020 3:39:20 PM					
Guardado, Sergio		Please paint interior of Portable K. Thank you.							
Rita Mendez									
236360	Main Building	Exterior			9/17/2020		21		\$0.00
Medium	Work In Progress	Area under the		9/17/2020 3:41:20 PM					
Ontiveros, Guadalupe		The area under the marquee needs landscape rock and stepping stones. This would eliminate the abundance of thorny weeds in that area. Also, we need to walk under the marquee to input information manually in the marquee. Thank you.							
Rita Mendez									

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Santa Teresa ES</b>							
236131					9/11/2020		27		\$0.00
Medium	Work In Progress				9/11/2020 10:38:48 AM				
Lara, Ralph		Need gate for for El Paso Disposal; please give to Mary Sitters so that she can issue out to them							
Jessica Herrera									
<b>Count: 7 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>18</b>	<b>Total for Santa Teresa ES</b>				<b>0</b>	<b>\$1,254.30</b>

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
233985	Annex Building	Classroom			7/30/2020		70		\$0.00
Medium	Work In Progress	Dinning Room			7/30/2020 7:56:52 AM				
Lara, Ralph		Install Door Top on Dinning rooms door							
Gema Suggs									
233829					7/28/2020		72		\$7.18
Medium	Work In Progress	Campuswide			7/28/2020 9:50:25 AM				
Lara, Ralph		Remove several lock from current off master status. Please see Mr. W and Mrs. Soriano for discussion about which locks and how they would like them keyed.							
Nicholas Wohlgemuth									
236099	Main Building	Office			9/10/2020		28		\$0.00
Medium	Work In Progress	Grounds office			9/10/2020 3:41:20 PM				
Lara, Ralph		Door in grounds office is broken							
Lorraine Dominguez									
236234					9/15/2020		23		\$0.00
Medium	Work In Progress				9/15/2020 8:34:48 AM				
Lara, Ralph		Need to do spare keys of each bldg mechanic trucks. Juan Ambris # 138, Luis Saucedo # 153, Manuel Prospero # 191, Ruben Ortiz # 107. Thank u							
Sergio Guardado									
236200	Main Building	Classroom			9/14/2020		24		\$0.00
Medium	Work In Progress				9/14/2020 10:55:35 AM				
Lara, Ralph		Teacher in C2 misplaced her key, can we have another key for teacher							
Lorraine Dominguez									
236107	Main Building	Classroom			9/10/2020		28		\$6.99
Medium	Work In Progress	Outside 800			9/10/2020 3:52:14 PM				
Ontiveros, Guadalupe		clean all areas outside of 800 area inside fence area							
Lorraine Dominguez									
234664	Main Building	Classroom			8/10/2020		59		\$0.00
Medium	Work In Progress	509			8/10/2020 10:55:25 AM				
Lara, Ralph		Teacher classroom is accessible to all teachers, please make her key for classroom only for her key.							
Lorraine Dominguez									

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
235148	Main Building	Gym			8/20/2020		49		\$0.00
Medium	Work In Progress	Varsity gym area			8/20/2020 3:06:51 PM				
Lara, Ralph		Door is missing screws							
Lorraine Dominguez									
235149	Main Building	Classroom			8/20/2020		49		\$0.00
Medium	Work In Progress	610			8/20/2020 3:07:46 PM				
Lara, Ralph		Classroom door does not open with master key							
Lorraine Dominguez									
232735					7/1/2020		99		\$0.00
Medium	Work In Progress	Tech Portable			7/1/2020 10:03:00 AM				
,		AC not working. Please check and service ASAP.							
Nicholas Wohlgemuth									
235032					8/18/2020		51		\$0.00
Medium	Work In Progress				8/18/2020 1:08:17 PM				
Ontiveros, Guadalupe		enclosed courtyard area - remove trash including pieces of walk mats blown of roof							
Alfredo Holguin									
233109	Main Building	Athletic Field			7/8/2020		92		\$130.00
Medium	Work In Progress	Outdoor fields			7/8/2020 11:07:23 AM				
Ontiveros, Guadalupe		Grounds is in need of tractor with scraper as well as round up for weeds							
Lorraine Dominguez									
234422	Main Building	Athletic Field			8/5/2020		64		\$0.00
Medium	Work In Progress	all outdoor			8/5/2020 9:53:02 AM				
Ontiveros, Guadalupe		Need more round up to clear up weeds around all athletic fields Round up sprayer one on campus broke In need a Kubota tractor with scraper							
Lorraine Dominguez									
234735	Main Building	Hallway/Corridor			8/11/2020		58		\$0.00
Medium	Work In Progress	corridor in			8/11/2020 2:15:31 PM				
Ontiveros, Guadalupe		Please clear up all weeds, grass and debris from corridors right outside admin offices							
Lorraine Dominguez									

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
234814	Main Building	Portables			8/13/2020		56		\$0.00
Medium	Work In Progress	Nurse Portable			8/13/2020 9:32:13 AM				
Ramos, Rudy		Nurse has reported that both AC's in her portable are not working. 8/13/2020 at 9:31am							
Gema Suggs									
235044	Main Building	Classroom			8/18/2020		51		\$0.00
Medium	Work In Progress	801			8/18/2020 1:28:06 PM				
Ramos, Rudy		Ceiling tiles need replacement							
Lorraine Dominguez									
235046	Vocational	Classroom			8/18/2020		51		\$0.00
Medium	Work In Progress	803			8/18/2020 1:28:50 PM				
Ramos, Rudy		Ceiling tiles need replacing							
Lorraine Dominguez									
235047	Vocational	Classroom			8/18/2020		51		\$0.00
Medium	Work In Progress	805			8/18/2020 1:29:27 PM				
Ramos, Rudy		Ceiling tiles need replacing							
Lorraine Dominguez									
235048	Vocational	Restroom			8/18/2020		51		\$0.00
Medium	Work In Progress	restroom			8/18/2020 1:30:19 PM				
Ramos, Rudy		Lights need to be looked at not sure if its light bulbs or not functioning							
Lorraine Dominguez									
235051	Main Building	Hallway/Corridor			8/18/2020		51		\$0.00
Medium	Work In Progress	500 hallway			8/18/2020 1:32:58 PM				
Ramos, Rudy		Need lights in the hallway replaced as there is about 6 out.							
Lorraine Dominguez									
235615	Main Building	Hallway/Corridor			9/1/2020		37		\$0.00
Medium	Work In Progress	Hallway by			9/1/2020 2:38:53 PM				
Ramos, Rudy		Ceiling tile in hallway needs to be replaced							
Lorraine Dominguez									
236102	Vocational	Classroom			9/10/2020		28		\$0.00
Medium	Work In Progress	803			9/10/2020 3:48:11 PM				
Guardado, Sergio		Remove all equipment and desks from top storage area of the classroom							
Lorraine Dominguez									

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Santa Teresa HS</b>									
236769					9/29/2020		9		\$11.94
Medium	Work In Progress			9/29/2020 1:41:43 PM					
Guardado, Sergio	Need to change bad ac motor to a new ac motor on the auxililary gym. Thank u								
Sergio Guardado									
233102		Athletic Field			7/8/2020		92		\$0.00
Medium	Work In Progress			7/8/2020 8:28:44 AM					
Villalobos, Jose	please check air compressor, not working. thank you.								
Lauro Jasso									
235383					8/26/2020		43		\$0.00
Medium	Work In Progress			8/26/2020 3:23:54 PM					
Gonzalez, Salvador	Need to fabricate ladders for culinary building in STHS								
Salvador Gonzalez									
235745	Main Building	Football Field			9/4/2020		34		\$0.00
Medium	Work In Progress	Area around		9/4/2020 12:12:25 PM					
Ontiveros, Guadalupe	Please remove weeds around football field								
Lorraine Dominguez									
235984	Main Building	Classroom			9/8/2020		30		\$0.00
Medium	Work In Progress	312		9/8/2020 2:47:16 PM					
Ambriz, Jose	Air conditioner not working and it continues to leak. They came in to look at it back on Aug 3 decided it needed to let it drain. They removed 2 ceiling panels								
Gema Suggs									
234642					8/10/2020		59		\$573.26
Medium	Work In Progress			8/10/2020 7:30:21 AM					
Ambriz, Jose	Unit in culinary kitchen not cooling.								
Jose Ambriz									
233350	Vocational				7/15/2020		85		\$0.00
Medium	Work In Progress			7/15/2020 10:36:26 AM					
Escobar, David	In the Culinary Arts Kitchen, roof top unit showing alarm. Tempature is showing 90.4°. No other information is showing on diagnostic. Please have HVAC look into this. Thank You								
Dominique Esparza									



## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
236655		Electrical Room			9/24/2020		14		\$0.00
Medium	Work In Progress				9/24/2020 1:12:31 PM				
Castillo, Carlos		Install power logger.							
Carlos Castillo									
236349	Main Building	Classroom			9/17/2020		21		\$0.00
Medium	Work In Progress	Workroom/printe			9/17/2020 2:23:22 PM				
Castillo, Carlos		If a power strip can be added to room in order to have the ability to plug in all copiers (please see Margie Computer Tech)							
Lorraine Dominguez									
236350	Main Building	Office			9/17/2020		21		\$0.00
Medium	Work In Progress	Technician office			9/17/2020 2:24:52 PM				
Castillo, Carlos		An power strip is needed for Margie to use in her office (please see Margie for further direction)							
Lorraine Dominguez									
236335					9/17/2020		21		\$0.00
Medium	Work In Progress				9/17/2020 10:49:18 AM				
Castillo, Carlos		Please issue to Ana Perez (Attendance Clerk) 10 light keys that will be checked out to staff and admin.							
Nicholas Wohlgemuth									
235606	Main Building	Gym			9/1/2020		37		\$0.00
Medium	Work In Progress	hallway by gym			9/1/2020 12:29:28 PM				
Castillo, Carlos		Broken light fixture in hallway in gym area. Please see Maria for further direction							
Lorraine Dominguez									
235612	Main Building	Hallway/Corridor			9/1/2020		37		\$0.00
Medium	Work In Progress				9/1/2020 2:13:35 PM				
Castillo, Carlos		As per blog.mech. need assistance w/500 hallway lighting							
Carlos Castillo									
235613	Main Building	Dressing Room			9/1/2020		37		\$0.00
Medium	Work In Progress	locker room			9/1/2020 2:36:12 PM				
Castillo, Carlos		Light fixture in locker room is broken							
Lorraine Dominguez									
235614	Main Building	Dressing Room			9/1/2020		37		\$0.00
Medium	Work In Progress	girls loccker			9/1/2020 2:37:37 PM				
Castillo, Carlos		Light fixtures in girls locker room needs to be replaced							
Lorraine Dominguez									

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
233335	Concession	Restroom			7/14/2020		72	15	\$961.16
Medium	Work In Progress			7/14/2020 3:49:47 PM	9/24/2020				
Pacheco, Hector	s per conversation with Head Custodian to replace 4 toilet flush valves and also 3 urinal flush valves.		troubleshoot main water shut off to replace 3 urinal flush valves and 3 toilet flush valves						
Hector Pacheco									
233305	Main Building	Hallway/Corridor			7/14/2020		86		\$0.00
Medium	Work In Progress	main hallway		7/14/2020 10:52:37 AM					
Pacheco, Hector	Issue with restroom in main hallway please see below En el baño de los hombres, de el pasillo principal, (enfrente de la oficina de Emma) uno de los uriniales no flachea.		waiting on sensors asp report 8/3/20 - R. Ramos						
Lorraine Dominguez									
235596		Kitchen			9/1/2020		37		\$131.48
High	Work In Progress			9/1/2020 10:00:54 AM					
Ontiveros, Joe	Need water pressure regulator valve on water inlet to dish machine								
Dino Facio									
<b>Count: 40 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>48</b>	<b>Total for Santa Teresa HS</b>			<b>15</b>	<b>\$1,822.01</b>	

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
235415	North Building	Office			8/27/2020		42		\$23.33
Medium	Work In Progress	SECURITY			8/27/2020 10:33:51 AM				
Ambriz, Jose	HEATING/COOLING NEEDS TO BE REPAIRED. AS PER BUILDING MECHANIC OFFICE NEEDS NEW DUCT WORK								
Laura Parra									
235524	North Building				8/31/2020		38		\$0.00
Medium	Work In Progress				8/31/2020 7:59:05 AM				
Guardado, Sergio	Need ceiling tiles in rooms #13-14-16-23-22-21-20-18-17 and in hallways on the north building as well.								
Cristian Martinez									
234449		Hallway/Corridor			8/5/2020		64		\$1,072.80
Medium	Work In Progress				8/5/2020 3:22:18 PM				
Guardado, Sergio	I NEED to change the ceiling tiles (not lights) in rooms 13,14,16,23,22,21,20,18,17, and teacher lounge 19, and hallways of the north building please					8/28/20 - work order will be re-routed to maintenance; this is for ceiling tiles to be replaced not lights. Danny will be picking up bulbs from STM and adjusting them back into inventory.			
Cristian Martinez									
234523	North Building	Classroom			8/6/2020		63		\$0.00
Medium	Work In Progress	P3A MIHALICK			8/6/2020 3:25:43 PM				
Lara, Ralph	TEACHER NEEDS KEY TO ENTER BUILDING, IF POSSIBLE SAME AS CLASSROOM KEY								
Laura Parra									
236072	North Building	Portables			9/10/2020		28		\$0.00
Medium	Work In Progress	PORTABLE 2A-			9/10/2020 10:52:09 AM				
Lara, Ralph	NEED KEY FOR DOOR CONNECTING PORTABLES.								
Laura Parra									
<b>Count: 5 Work Orders</b>		<b>Avg. Age of WO's 47</b>		<b>Total for Santa Teresa MS</b>			<b>0</b>	<b>\$1,096.13</b>	

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Sunland Park ES</b>									
236576					9/23/2020		15		\$92.98
Medium	Work In Progress				9/23/2020 2:33:40 PM				
Guardado, Sergio		Patch asphalt at the main entrance. Thank u							
Sergio Guardado									
236578					9/23/2020		15		\$59.48
Medium	Work In Progress				9/23/2020 2:39:12 PM				
Guardado, Sergio		Need to remove rebar from the asphalt at the parking lot. Thank u							
Sergio Guardado									
236581					9/23/2020		15		\$65.00
Medium	Work In Progress				9/23/2020 2:45:43 PM				
Guardado, Sergio		Need to cut grass through out campus and pounding area. Thank u							
Sergio Guardado									
234676					8/10/2020		59		\$0.00
Medium	Work In Progress				8/10/2020 12:40:48 PM				
Gonzalez, Salvador		please need homemade drags please ask luis							
Luis Saucedo									
233309		Kitchen			7/14/2020		86		\$0.00
High	Work In Progress				7/14/2020 11:44:02 AM				
Escobar, David		AC Unit not cooling in kitchen (Hot)							
Dino Facio									
233588					7/22/2020		78		\$75.52
Medium	Work In Progress	76			7/22/2020 2:03:23 PM				
Guardado, Sergio		computer lab to painted the doors and wall that has a brown stain on it by the blue cabinet. doors also need to be painted.				Pending asp report 8/3/20 - waiting on supplies have been ordered			
Ivette Rios									
236691					9/25/2020		13		\$0.00
Medium	Work In Progress				9/25/2020 9:54:50 AM				
Castillo, Carlos		NO LIGHTING IN THE OFFICE LOUNGE RESTROOM							
Ivette Rios									
<b>Count: 7 Work Orders</b>			<b>Avg. Age of WO's 40</b>			<b>Total for Sunland Park ES</b>	<b>0</b>		<b>\$292.98</b>

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Sunrise ES</b>									
236762					9/29/2020		9		\$114.07
Medium	Work In Progress			9/29/2020 10:36:38 AM					
Chavez, Santos	Install two 40A 3 pole circuits for two new 12 ton refrigeration units for multi purpose room.								
Santos Chavez									
233266					7/13/2020		87		\$0.00
Medium	Work In Progress			7/13/2020 1:45:19 PM					
Chavez, Santos	Entrada de escuela 2 balastras estan descompuestas y necesitan focos gracias buen dia.								
Maritxa Vasquez									
236196	Main Building	Restroom (Girls)			9/14/2020		24		\$0.00
Medium	Work In Progress			9/14/2020 9:45:40 AM					
Ontiveros, Joe	Hola, buenos dias. El bano de ninas pasillo luna la primera tasa tiene una fuga de agua la yabe podria arreglarla por favor.								
Maritxa Vasquez									
235270	Main Building				8/24/2020		45		\$0.00
Medium	Work In Progress			8/24/2020 2:06:20 PM					
Marquez, Gerardo	Need new pad lock west bus turn around gate.								
Monica Narez									
235272					8/24/2020		45		\$0.00
Medium	Work In Progress			8/24/2020 2:07:08 PM					
Marquez, Gerardo	Cathie Williams, Office, Key gets stuck to open the Isolation Room.								
Monica Narez									
236046	Main Building	Office			9/10/2020		28		\$0.00
Medium	Work In Progress			9/10/2020 8:14:15 AM					
Marquez, Gerardo	Cathie Williams, Office, Need 7 dogging keys (L & Wrenches?								
Monica Narez									
233288					7/13/2020		87		\$0.00
Medium	Work In Progress	playground		7/13/2020 5:24:35 PM					
Ontiveros, Guadalupe	please repair stuck irrigation valve solenoid to grass irrigation sprinkler system. water is constantly on. Thank You...								
Johnny Acuna									

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Sunrise ES</b>									
233826	Main Building	Classroom			7/28/2020		72		\$0.00
Medium	Work In Progress				7/28/2020 8:53:37 AM				
Acuna, Johnny		Rocio Nieto, Classroom 103, Needs blinds on her windows and side window.							
Monica Narez									
236512	Main Building	Office			9/22/2020		16		\$0.00
Medium	Work In Progress				9/22/2020 1:09:47 PM				
Acuna, Johnny		Cathie Williams, Office, Need to remove dead weeds, remove dead shrubs.							
Monica Narez									
236436	Main Building	Office			9/21/2020		17		\$0.00
Medium	Work In Progress				9/21/2020 11:03:08 AM				
Acuna, Johnny		As per Mrs. Williams, Office, The bats moved to the front entrance of the office and bats came back to nest. Will need to put covering in the front and through the back right side corner by the cafeteria.							
Monica Narez									
<b>Count: 10 Work Orders</b>		<b>Avg. Age of WO's 43</b>		<b>Total for Sunrise ES</b>		<b>0</b>	<b>\$114.07</b>		

# 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Vado ES</b>							
235671		Gym			9/3/2020		35		\$0.00
Medium	Work In Progress	Cafeteria/Gym			9/3/2020 7:40:20 AM				
Escobar, David		Gymnasium is very hot. Mr. Armando Diaz (Head Custodian) already tried to change temperature manually and it didn't work.							
Sylvia Cary									
235661					9/2/2020		36		\$0.00
Medium	Work In Progress				9/2/2020 3:42:11 PM				
Escobar, David		trouble at Vado kitchen.							
David Escobar									
234333		Kitchen			8/4/2020		65		\$0.00
High	Work In Progress				8/4/2020 7:58:13 AM				
Escobar, David		AC units not working very hot in kitchen area							
Dino Facio									
<b>Count: 3 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>45</b>	<b>Total for Vado ES</b>			<b>0</b>	<b>\$0.00</b>

## 274 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 9/30/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Yucca Heights ES</b>									
233475		Classroom			7/20/2020		80		\$0.00
Medium	Work In Progress				7/20/2020 3:25:55 PM				
Ambriz, Jose		Need to check units that are not working properly.							
Jose Ambriz									
236203					9/14/2020		24		\$0.00
Medium	Work In Progress				9/14/2020 12:34:30 PM				
Marquez, Gerardo		Need to repair lock to maintenance storage shed as soon as possible. Lock not staying locked.							
Johnny Acuna									
236198					9/14/2020		24		\$0.00
Medium	Work In Progress				9/14/2020 9:58:59 AM				
Ontiveros, Guadalupe		Put rock under fence to avoid coyotes coming in. They have been digging.							
Rocio Rodriguez									
236411					9/21/2020		17		\$0.00
Medium	Work In Progress	Playground area			9/21/2020 8:40:06 AM				
Hernandez, Guillermo		Circle area needs to be filled with concrete.							
Rocio Rodriguez									
<b>Count: 4 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>36</b>	<b>Total for Yucca Heights ES</b>			<b>0</b>	<b>\$0.00</b>
<b>Count: 274 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>45</b>	<b>Grand Total</b>			<b>87</b>	<b>\$19,215.64</b>