

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Alta Vista ECHS							
247108		Exterior			7/7/2021		222		\$6.99
Medium	Work In Progress				7/7/2021 10:40:43 AM				
Vasquez, Jose		Please pick up pine needles and level the area behind portables 10-20. Also, please fill in any holes under portables.							
Isaac Grijalva									
254394					11/19/2021		87		\$0.00
Medium	Work In Progress	21			11/19/2021 4:07:45 PM				
Marquez, Gerardo		Door is not locking correctly.							
Melanie Beegle									
Count: 2 Work Orders		Avg. Age of WO's		155	Total for Alta Vista ECHS			0	\$6.99

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony - On Track Pre-K (Village)									
246750		Office			7/1/2021		6	7	\$190.33
Medium	Work In Progress	104			7/1/2021 11:14:21 AM	7/7/2021			
Tellez, Hector		electrical outlet needed by clerk's desk				Done			
Michelle Soto									
Count: 1 Work Orders		Avg. Age of WO's		6	Total for Anthony - On Track Pre-K (Village)			7	\$190.33

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
249795					8/18/2021		180		\$0.00
Medium	Work In Progress	262			8/18/2021 2:12:32 PM				
Ambriz, Jose		Teacher is saying that room is very hot, please adjust temperature room# 262							
Jessica Lopez									
249625					8/17/2021		181		\$0.00
Medium	Work In Progress	115			8/17/2021 9:11:41 AM				
Ambriz, Jose		Please check data clerk's office, room gets very hot in the afternoons thank you							
Jessica Lopez									
254210					11/16/2021		90		\$0.00
Medium	Work In Progress	243			11/16/2021 12:08:49				
Ambriz, Jose		Please adjust temperature, room is extremely hot room # 243							
Jessica Lopez									
253742		Kitchen			11/4/2021		102		\$0.00
High	Work In Progress				11/4/2021 7:51:59 AM				
Appelzoller, Fred		Water line from wall to disposal leaking							
Dino Facio									
255657					1/4/2022		41		\$0.00
Medium	Work In Progress	403			1/4/2022 8:40:05 AM				
Marquez, Gerardo		Please repair/replace broken door (vandalism) room# 403							
Jessica Lopez									
255659					1/4/2022		41		\$0.00
Medium	Work In Progress	411			1/4/2022 8:41:21 AM				
Marquez, Gerardo		Please replace/repair broken door due to vandalism. room # 411							
Jessica Lopez									
255656					1/4/2022		41		\$0.00
Medium	Work In Progress	405			1/4/2022 8:38:01 AM				
Hernandez, Guillermo		Please replace/repair broken door (vandalism) room # 405							
Jessica Lopez									

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Anthony ES							
255660					1/4/2022		41		\$0.00
Medium	Work In Progress	principal's office			1/4/2022 8:43:30 AM				
Hernandez, Guillermo		Please repair/replace broken door due to vandalism. Principal's office							
Jessica Lopez									
Count: 8 Work Orders		Avg. Age of WO's	90			Total for Anthony ES	0		\$0.00

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Berino ES									
250130					8/24/2021		174		\$7.96
Medium	Work In Progress				8/24/2021 10:14:24 AM				
Vasquez, Jose	Please trim & remove tree branches from the roof, and trim & remove tree branches from fence. Pease refer to e-mail with pictures. Should you have any questions please see Mr. Gallegos in the Construction Office (575) 882-6921.Thank You								
Dominique Esparza									
253554		Kitchen			11/1/2021		105		\$0.00
High	Work In Progress				11/1/2021 8:23:18 AM				
Appelzoller, Fred	Faucet on three compartment sink leak corrosion is starting to form								
Dino Facio									
250489	Main Building	Classroom			8/31/2021		167		\$0.00
Medium	Work In Progress	102			8/31/2021 7:51:13 AM				
Ambriz, Jose	The heater in the classroom turned on								
Michelle Guerra									
249292	Main Building	Classroom			8/11/2021		187		\$0.00
Medium	Work In Progress	137			8/11/2021 12:32:43 PM				
Ambriz, Jose	Classroom is very hot								
Michelle Guerra									
Count: 4 Work Orders			Avg. Age of WO's	158	Total for Berino ES			0	\$7.96

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral ES									
249178	Main Building	Classroom			8/10/2021		188		\$0.00
Medium	Work In Progress	101		8/10/2021 11:58:06 AM					
Ambriz, Jose	Nurse office is hot. See Priscilla or Violeta								
Jennifer Corral									
250527	Main Building				8/31/2021		167		\$0.00
Medium	Work In Progress	207		8/31/2021 11:24:31 AM					
Ambriz, Jose	second request for room. Room is hot teacher says they worked on it last week and it was fine and this week it's not working anymore. See Saldana								
Jennifer Corral									
255793					1/5/2022		40		\$28.50
Medium	Work In Progress			1/5/2022 12:42:11 PM					
Ambriz, Jose	Refrigeration Water Fountain not cooling. Water Fountain next to Nurse's Office.								
Johnny Acuna									
256502	Main Building	Office			1/24/2022		21		\$9.16
Medium	Work In Progress	Nurse office		1/24/2022 12:37:14 PM					
Appelzoller, Fred	Do not have access to hot water. Sink gives cold water only. Please see Nurse Zapata or Nurse assistant Ms. Lugo								
Jennifer Corral									
251829					9/23/2021		144		\$32.87
Medium	Work In Progress			9/23/2021 3:37:30 PM					
Ontiveros, Joe	Need to fix water leak under sink in Porable 3 .								
Joe Ontiveros									
253797	Main Building	Office			11/4/2021		102		\$0.00
Medium	Work In Progress	office		11/4/2021 2:33:07 PM					
Hernandez, Guillermo	need to order reorder key cards. As per Guillermo Hernandez 20 key cards will be ordered and distributed to designated person. See Administration Ms. Duque or Mrs. White								
Jennifer Corral									
249630	Main Building	Classroom			8/17/2021		181		\$0.00
Medium	Work In Progress			8/17/2021 9:47:03 AM					
Marquez, Gerardo	room 331 need core for closet door				Pending asp report 9/13/21 - 281				
Adrian Flores					Transfer to Locksmith				

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral ES									
248094	Main Building	Office			7/28/2021		201		\$0.00
Medium	Work In Progress	office			7/28/2021 9:35:45 AM				
Marquez, Gerardo		front door not latching see office				? asp report 9/13/21 - 281 Transfer to Locksmith			
Jennifer Corral									
254435		Restroom			11/29/2021		77		\$0.00
Medium	Work In Progress				11/29/2021 8:23:08 AM				
Marquez, Gerardo		Staff restroom not Locking in 2 grade.thanks							
Saul Chavez									
254532	Main Building	Foyer			11/30/2021		76		\$0.00
Medium	Work In Progress	foyer area			11/30/2021 10:28:16				
Marquez, Gerardo		Door bell is no longer working in the front. We do not know when parents are there. This is through Plan B not sure if they take care of that issue as well. We are also having trouble with parents listening to us. See front office							
Jennifer Corral									
256330	P.E. Building	Classroom			1/19/2022		26		\$0.00
Medium	Work In Progress	Classroom/gym			1/19/2022 7:55:30 AM				
Marquez, Gerardo		Cannot tell what the number is on the core on the doorknob to this room. Looking for a key to give to coaches since it is now the gym and cannot locate because there are two numbers listed on the core. May need a key. See Jennifer							
Jennifer Corral									
Count: 11 Work Orders			Avg. Age of WO's	111	Total for Chaparral ES			0	\$70.53

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Chaparral High - Pre-K							
253001		Exterior			10/19/2021		118		\$0.00
Medium	Work In Progress				10/19/2021 3:42:11 PM				
Vasquez, Jose		Prek playground is in need of wood chips for fall zones as well as sand for the students sand box.							
Nathalie Urbina									
Count: 1 Work Orders		Avg. Age of WO's	118	Total for Chaparral High - Pre-K				0	\$0.00

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
254325					11/18/2021		88		\$0.00
Medium	Work In Progress				11/18/2021 3:18:50 PM				
Vasquez, Jose		Possible water leak in Boy's Baseball field on home plate area.							
Johnny Acuna									
253364		Athletic Field			10/29/2021		108		\$0.00
Medium	Work In Progress				10/29/2021 8:06:27 AM				
Vasquez, Jose		We need 460' of privacy slats in the softball field.							
Jose Vasquez									
252463	H-Wing	Auditorium			10/8/2021		129		\$197.96
Medium	Work In Progress	Main gym			10/8/2021 11:02:24 AM				
Acuna, Johnny		Replace Basketball Rim. (Coach Padilla, main gym)				Basketball rim on order.			
Mireya Meza									
253956					11/8/2021		98		\$64.84
Medium	Work In Progress				11/8/2021 3:54:35 PM				
Ambriz, Jose		Please repair 2 refrigerated water fountains. (1) Old Gym: (Drain) Water leaks on the bottom when used. (1) Culinary arts room (R Bldg.) water fountain water stays on. Stuck open.							
Johnny Acuna									
255302	A-Wing	Restroom			12/16/2021		60		\$0.00
Medium	Work In Progress	Boys restroom			12/16/2021 12:44:46				
Vargas, Juan		Stall in boys restroom by concession is clogged. (custodian, Christina)							
Mireya Meza									
254219					11/16/2021		90		\$0.00
Medium	Work In Progress				11/16/2021 1:04:10 PM				
Acuna, Johnny		Need (3) Hand Truck Dollies				On order			
Johnny Acuna									
254242	G-Wing	Classroom			11/16/2021		90		\$0.00
Medium	Work In Progress	G6			11/16/2021 5:07:45 PM				
Acuna, Johnny		Please fix the circulation vent that is in the greenhouse in G6. (Vicki Lopez, principal)							
Mireya Meza									

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
254204					11/16/2021		90		\$0.00
Medium	Work In Progress				11/16/2021 11:25:44				
Acuna, Johnny	Need heavy duty replacement bolt cutter Jaws.		On order						
Johnny Acuna									
256799					1/31/2022		14		\$1,330.50
Medium	Work In Progress				1/31/2022 8:57:27 AM				
Acuna, Johnny	Need to fix lighting to old gym locker rooms.								
Johnny Acuna									
256871					1/31/2022		14		\$0.00
Medium	Work In Progress				1/31/2022 4:09:35 PM				
Hernandez, Guillermo	Need to fix or replace window in C-Wing cyber-Cafe. Window builds up condensation.								
Johnny Acuna									
253090					10/21/2021		116		\$0.00
Medium	Work In Progress				10/21/2021 3:34:39 PM				
Avila, Jesus	Please fabricate saddle Roof pulley to lift filter boxes and materials to roof tops.								
Johnny Acuna									
255611	Field House	Athletic Field			1/3/2022		42		\$0.00
Medium	Work In Progress	Football field			1/3/2022 11:42:33 AM				
Avila, Jesus	During the break one side of the goal post broke off because of strong winds. Please weld or replace. Pictures were sent to Shane Smith. (Mr. Tullius, AP)		Transfer to Welding Dept.						
Mireya Meza									
250098	A-Wing	Foyer			8/23/2021		175		\$0.00
Medium	Work In Progress	Front Lobby			8/23/2021 4:26:49 PM				
Marquez, Gerardo	The bar of the double doors on the east side of the front lobby stays pushed in when someone leaves thru that door. Which leaves the doors unlocked a the end of the day. (security Zuniga)		Pending asp report 9/13/21 - 281						
Mireya Meza									
248612	G-Wing	Foyer			8/3/2021		195		\$0.00
Medium	Work In Progress	G wing			8/3/2021 9:22:22 AM				
Marquez, Gerardo	"G hallway door to main hallway handle is broken Security and Mr. Martinez couldn't open it after lunch. (security Quinones)		Pending asp report 9/13/21 - 281						
Mireya Meza									

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Chaparral HS							
254358	G-Wing	Classroom			11/19/2021		87		\$0.00
Medium	Work In Progress	G6 & F3			11/19/2021 10:44:38				
Marquez, Gerardo		Please make me 3 keys that open the back door to the green houses in G6 & F3. (Mireya Meza)							
Mireya Meza									
255197	H-Wing	Auditorium			12/14/2021		62		\$0.00
Medium	Work In Progress	Main gym			12/14/2021 8:53:25 AM				
Marquez, Gerardo		Broken latch to the door entering the main gym (Coach Y)				Duplicate of WO#255828			
Mireya Meza									
251112	Field House	Athletic Field			9/10/2021		157		\$0.00
Medium	Work In Progress	Ticket booth			9/10/2021 10:29:25 AM				
Marquez, Gerardo		Please re-place the door knob at the ticket booth out by the football field. It is broken. (Mr. Mata, AP)				Pending asp report 9/13/21 - 281			
Mireya Meza									
248977	A-Wing	Foyer			8/6/2021		192		\$0.00
Medium	Work In Progress	All doors to			8/6/2021 5:09:47 PM				
Marquez, Gerardo		We had trouble with G wing, and E wing not opening during fire drill this morning. I would like for Jerry to check all our doors at the entrance of each wing but specially those two. (Mr. Martinez, AP)				Pending asp report 9/13/21 - 281			
Mireya Meza									
256372					1/19/2022		26		\$0.00
Medium	Work In Progress				1/19/2022 3:52:15 PM				
Appelzoller, Fred		need circulating pump for water heater B-wing							
Fred Appelzoller									
254029	D-Wing	Classroom			11/10/2021		96		\$0.00
Medium	Work In Progress	D7			11/10/2021 1:07:48 PM				
Ontiveros, Joe		I have two faucets with problems on the lab tables. One on the far left of the room leaks and the other is the 3rd lab table back on the right side (window side) and it is really loose. Also the 1st faucet on the left side there is an outlet without a face plate on the table. (Mr. King, D7)							
Mireya Meza									
254009	F-Wing	Restroom			11/10/2021		96		\$0.00
Medium	Work In Progress	F boys restroom			11/10/2021 8:58:58 AM				
Ontiveros, Joe		First stall in boys restroom is clogged in F wing. (Rosalva, custodian)							
Mireya Meza									

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
253932	B-Wing	Classroom			11/8/2021		98		\$0.00
Medium	Work In Progress	B2			11/8/2021 1:59:44 PM				
Ontiveros, Joe		Spout on kitchen sink valve has come off. (Mr. Perez, B2)							
Mireya Meza									
253935	F-Wing	Restroom (Girls)			11/8/2021		98		\$0.00
Medium	Work In Progress	F girls restroom			11/8/2021 2:08:07 PM				
Ontiveros, Joe		Last stall in girls restroom is clogged. (Rosalba, custodian)							
Mireya Meza									
254374	G-Wing	Classroom			11/19/2021		87		\$0.00
Medium	Work In Progress	G6 & F3			11/19/2021 12:38:09				
Ontiveros, Joe		Please check the water lines in the greenhouse in G6 & F3. We will start using them and we want to make sure they are working properly. (Miss Montelongo)							
Mireya Meza									
256086		Cafeteria			1/11/2022		34		\$0.00
Medium	Work In Progress				1/11/2022 12:27:23 PM				
Moreno, Mario		Led lighting retrofit in cafeteria seating area.							
Mario Moreno									
256280	Q-Wing				1/18/2022		27		\$0.00
Medium	Work In Progress				1/18/2022 7:52:42 AM				
Moreno, Mario		Exterior wallpack lighting led retrofit for building -Q and building- R							
Mario Moreno									
256611	Field House	Athletic Field			1/26/2022		19		\$0.00
Medium	Work In Progress	Baseball field			1/26/2022 11:58:03 AM				
Vasquez, Jose		Foul poles to be repainted yellow (Coach Jimenez)							
Mireya Meza									
256551	Field House	Athletic Field			1/25/2022		20		\$0.00
Medium	Work In Progress	Softball field			1/25/2022 11:00:26 AM				
Vasquez, Jose		Slats in the softball field that were removed a while back need to be replaced. (Mr. Tullius, AP)							
Mireya Meza									

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Chaparral HS							
254082	E-Wing	Classroom			11/12/2021		94		\$0.00
Medium	Work In Progress	E sped			11/12/2021 3:25:09 PM				
Ambriz, Jose		Please re-set temperature in E-spiced room. It is really hot in the room. (Mr. Seanez, tech)							
Mireya Meza									
251231		Mechanical			9/13/2021		154		\$0.00
Medium	Work In Progress				9/13/2021 3:28:21 PM				
Ambriz, Jose		Will request a new armstrong pump for back up, STHS mechanical room.							
Jose Ambriz									
250151	G-Wing	Foyer			8/24/2021		174		\$106.74
Medium	Work In Progress	Entrance to G			8/24/2021 1:07:06 PM				
Acuna, Johnny		Please paint double doors to entrance of G wing. (Mireya Meza)				Paint on order.			
Mireya Meza									
252466	A-Wing	Cafeteria			10/8/2021		129		\$261.85
Medium	Work In Progress	Cafeteria			10/8/2021 11:19:19 AM				
Acuna, Johnny		Please paint the doors that leave the cafeteria towards the auxiliary gym. The outside part of the doors look really bad. Please paint with CHS gray not maroon. (Mireya Meza)				Paint on order			
Mireya Meza									
251914					9/27/2021		140		\$0.00
Medium	Work In Progress				9/27/2021 4:58:07 PM				
Acuna, Johnny		Need to replace Make up air motor to culinary art kitchen's Rooftop unit (Hood) in the R Bldg.				Motor and Pulley on order.			
Johnny Acuna									
254066	H-Wing				11/12/2021		94		\$0.00
Medium	Work In Progress	Main gym			11/12/2021 8:45:19 AM				
Ambriz, Jose		Coach Y.P.E. locker room has a water fountain that is missing the middle bar. (Badillo, custodian)							
Mireya Meza									
253665		Classroom			11/2/2021		104		\$0.00
Medium	Work In Progress	all buildings			11/2/2021 3:08:10 PM				
Ambriz, Jose		Need to order Freon, v-belts, contactors for R/R controls doing PM's on all equipment in chaparral high school.							
Jose Ambriz									
Count: 35 Work Orders		Avg. Age of WO's		94	Total for Chaparral HS			0	\$1,961.89

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
254158		Hallway/Corridor			11/15/2021		91		\$0.00
Medium	Work In Progress				11/15/2021 2:48:31 PM				
Ambriz, Jose		Need to replace (2) refrigerated water fountains. One in the middle hallway next to Boy's Restroom (Left One) (Has an electrical short and is tripping the breaker, The other one is in the cafeteria on the left side of the main stage next to custodial closet.							
Johnny Acuna									
255830	Main Building	Exterior			1/6/2022		39		\$0.00
Medium	Work In Progress	softball/baseball			1/6/2022 8:03:36 AM				
Vasquez, Jose		Fix bases and pitchers mound on both baseball and softball fields							
Maria Garcia									
256447	Main Building	Exterior			1/21/2022		24		\$0.00
Medium	Work In Progress	softball/baseball			1/21/2022 10:21:11 AM				
Vasquez, Jose		line softball and baseball fields for games on 1/22, 2/5, 2/19, 3/5							
Maria Garcia									
254538		Custodial			11/30/2021		76		\$0.00
Medium	Work In Progress				11/30/2021 12:23:23				
Marquez, Gerardo		Buenas tardes senesecita areglar candado storage de custodian de 100-hallway Gracias							
M. Carmen Perez									
254207	Main Building	Restroom			11/16/2021		90		\$0.00
Medium	Work In Progress	300 Halls			11/16/2021 12:05:07				
Acuna, Johnny		2 doors in 300 hall boys restroom broken							
Maria Garcia									
250129	Main Building	Portables			8/24/2021		174		\$2,167.20
Medium	Work In Progress	Portables			8/24/2021 10:10:27 AM				
Acuna, Johnny		Ramps on portables get slippery				Paint on order			
Maria Garcia									
253134	Main Building				10/22/2021		115		\$0.00
Medium	Work In Progress				10/22/2021 3:47:03 PM				
Vasquez, Jose		empty trash cans around field							
Maria Garcia									

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Chaparral MS							
252192	Main Building	Athletic Field			10/4/2021		133		\$0.00
Medium	Work In Progress				10/4/2021 11:39:17 AM				
Vasquez, Jose		Line Field for payoff games saturday 10/9							
Maria Garcia									
Count: 8 Work Orders		Avg. Age of WO's		93	Total for Chaparral MS			0	\$2,167.20

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Trail ES									
253228					10/26/2021		111		\$0.00
Medium	Work In Progress				10/26/2021 3:28:52 PM				
Acuna, Johnny		Need to replace all swing seats, s-hooks, chain, main swivel brackets. (Playground Equipment)				On order			
Johnny Acuna									
256293	Main Building	Football Field			1/18/2022		27		\$0.00
Medium	Work In Progress	Soccer goals on			1/18/2022 9:57:57 AM				
Gonzalez, Salvador		Soccer goals on field need anchors to hold them into ground. Need to be secured.				Re-route to Welding Dept.			
Elizabeth Hernandez									
250460	Main Building	Classroom			8/30/2021		168		\$22.46
Medium	Work In Progress	417			8/30/2021 3:55:40 PM				
Marquez, Gerardo		the door for portable 417 keeps getting stuck. It is really hard to open. It's the door itself that is getting stuck.				Pending asp report 9/13/21 - 281 waiting on APCO quote Transfer to Locksmith			
Elizabeth Hernandez									
256693					1/27/2022		18		\$0.00
Medium	Work In Progress	elihernandez@g			1/27/2022 12:01:29 PM				
Marquez, Gerardo		the hydraulic arm closure on the main entrance door needs to be replaced, it appears to be leaking oil							
Elizabeth Hernandez									
254339	Main Building	Classroom			11/18/2021		88		\$0.00
Medium	Work In Progress	307			11/18/2021 4:22:19 PM				
Marquez, Gerardo		Ms. Marques is having trouble with doorknob, it keeps getting jammed.							
Elizabeth Hernandez									
249889		Classroom			8/19/2021		179		\$0.00
Medium	Work In Progress				8/19/2021 11:55:53 AM				
Marquez, Gerardo		la clase 107 la puerta se atora por favor de revisarla gracias				Pending asp report 9/13/21 - 281 Transfer to Locksmith			
Laura Sandoval									
250725	Main Building	Office			9/3/2021		164		\$0.00
Medium	Work In Progress	elihernandez@g			9/3/2021 1:01:37 PM				
Marquez, Gerardo		Align the front entrance door as it is not hinging correctly and at times is open therefore we have issues with safety and the automatic door opener				Pending asp report 9/13/21 - 281			
Elizabeth Hernandez									

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Trail ES

248532 Main Building Classroom 8/2/2021 196 \$0.00

Medium Work In Progress 416 8/2/2021 1:16:44 PM

Marquez, Gerardo Door handle keeps getting stuck. Pending asp report 9/13/21 - 281

Elizabeth Hernandez

254309 Custodial 11/18/2021 88 \$0.00

Medium Work In Progress 11/18/2021 12:29:47

Marquez, Gerardo La puerta de la clase 307 el gendel esta suelto por favor de revisarla gracias

Laura Sandoval

254892 12/6/2021 70 \$0.00

Medium Work In Progress 12/6/2021 6:52:26 AM

Vasquez, Jose Please dig up and remove stump/exposed roots to old tree at Chaparral Elementary Grass area. Leaves sprouting up and section is a safety hazard.

Johnny Acuna

253720 Main Building Classroom 11/3/2021 103 \$0.00

Medium Work In Progress 101 11/3/2021 3:33:34 PM

Moreno, Mario In room 101 one light keeps flickering.

Elizabeth Hernandez

252459 Main Building Classroom 10/8/2021 129 \$0.00

Medium Work In Progress 1st grade girls 10/8/2021 10:11:50 AM

Moreno, Mario 1st grade girls bathroom ceiling lights are flickering.

Elizabeth Hernandez

252683 Main Building Hallway/Corridor 10/12/2021 125 \$0.00

Medium Work In Progress kinder hall 10/12/2021 4:05:34 PM

Moreno, Mario the ceiling light exiting to the playground keeping flickering.

Elizabeth Hernandez

252735 Main Building Classroom 10/13/2021 124 \$0.00

Medium Work In Progress 103 10/13/2021 3:51:50 PM

Moreno, Mario the light in room 103 keep flickering on and off.

Elizabeth Hernandez

252478 Main Building Classroom 10/8/2021 129 \$0.00

Medium Work In Progress 108 10/8/2021 11:59:01 AM

Moreno, Mario Lights in room 108 are flickering.

Elizabeth Hernandez

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail ES							
252480	Main Building	Classroom			10/8/2021		129		\$0.00
Medium	Work In Progress	301		10/8/2021 12:23:45 PM					
Moreno, Mario		The light in room 301 keep flickering.							
Elizabeth Hernandez									
252481	Main Building	Classroom			10/8/2021		129		\$0.00
Medium	Work In Progress	302		10/8/2021 12:30:04 PM					
Moreno, Mario		The lights in room 302 keep flickering.							
Elizabeth Hernandez									
252487	Main Building	Classroom			10/8/2021		129		\$0.00
Medium	Work In Progress	3rd grade boys		10/8/2021 1:27:12 PM					
Moreno, Mario		the lights in 3rd grade boys bathroom keep flickering							
Elizabeth Hernandez									
252488	Main Building	Classroom			10/8/2021		129		\$0.00
Medium	Work In Progress	2nd grade girls		10/8/2021 1:29:13 PM					
Moreno, Mario		The lights in the 2nd grade girls bathroom keep flickering.							
Elizabeth Hernandez									
254451		Custodial			11/29/2021		77		\$0.00
Medium	Work In Progress			11/29/2021 10:01:21					
Moreno, Mario		Buenos dias la luz del pasillo de kinder esta prendiendo y apagando por favor de revisarla gracias				Transfer to Electrician.			
Laura Sandoval									
254292	Main Building	Classroom			11/18/2021		88		\$0.00
Medium	Work In Progress			11/18/2021 7:38:17 AM					
Moreno, Mario		blinking light Room 311							
Elizabeth Hernandez									
254363		Restroom			11/19/2021		87		\$0.00
Medium	Work In Progress			11/19/2021 11:10:37					
Moreno, Mario		Buenos dias el bano de los ninos de tercer grado la luz esta fayando por favor de revisarla gracias				Transfer to Electrician			
Laura Sandoval									
252183	Main Building	Office			10/4/2021		133		\$0.00
Medium	Work In Progress	elihernandez@g		10/4/2021 10:22:47 AM					
Moreno, Mario		Flashing light at the entrance of the school lobby							
Elizabeth Hernandez									

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Trail ES									
256035	Main Building	Restroom			1/10/2022		35		\$0.00
Medium	Work In Progress	2nd grade			1/10/2022 2:49:54 PM				
Moreno, Mario		Women 2nd grade teacher bathroom ceiling light is flickering.							
Elizabeth Hernandez									
256036	Main Building	Classroom			1/10/2022		35		\$0.00
Medium	Work In Progress	110			1/10/2022 2:54:59 PM				
Moreno, Mario		In room 110 bathroom light keeps flickering.							
Elizabeth Hernandez									
248141					7/28/2021		201		\$0.00
Medium	Work In Progress				7/28/2021 3:37:27 PM				
Tellez, Hector		In room 102 the ceiling light keeps flickering.							
Elizabeth Hernandez									
254553					11/30/2021		76		\$0.00
Medium	Work In Progress				11/30/2021 3:08:05 PM				
Moreno, Mario		Light fixture blinking to 300 Hall Faculty Restroom.							
Johnny Acuna									
255142	Main Building	Classroom			12/13/2021		63		\$0.00
Medium	Work In Progress				12/13/2021 9:04:43 AM				
Moreno, Mario		Flashing light in Ms. Herrera's classroom room 313							
Elizabeth Hernandez									
255144	Main Building	Hallway/Corridor			12/13/2021		63		\$0.00
Medium	Work In Progress				12/13/2021 9:05:20 AM				
Moreno, Mario		flashing light in the third/fourth hallway							
Elizabeth Hernandez									
255178		Kitchen			12/13/2021		63		\$0.00
Medium	Work In Progress				12/13/2021 3:53:55 PM				
Moreno, Mario		Kitchen fire suppression not interlocked with fire alarm system.							
Mario Moreno									
255897	Main Building	Hallway/Corridor			1/7/2022		38		\$0.00
Medium	Work In Progress	elihernandez@g			1/7/2022 11:41:17 AM				
Moreno, Mario		a ceiling light is flashing constantly at the kinder/first grade hallway.							
Elizabeth Hernandez									

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Desert Trail ES								
255196	Main Building	Classroom			12/14/2021		62		\$0.00	
Medium	Work In Progress			12/14/2021 8:37:29 AM						
Moreno, Mario	flickering light in the entrance of Ms. Marquez classroom, very distracting Room 307									
Elizabeth Hernandez										
253285	Main Building	Mechanical			10/27/2021		110		\$44.99	
Medium	Work In Progress	outside		10/27/2021 2:04:00 PM						
Appelzoller, Fred	the water valve outside mechanical rooms keeps leaking.									
Elizabeth Hernandez										
252182		Classroom			10/4/2021		133		\$0.00	
Medium	Work In Progress			10/4/2021 10:17:04 AM						
Ontiveros, Joe	Buenos dias el bano de la clase 111 se esta cerrando el candado por favor de revisarlo gracias									
Laura Sandoval										
250162					8/24/2021		174		\$0.00	
Medium	Work In Progress			8/24/2021 2:15:22 PM						
Ontiveros, Joe	Need to fix or replace sink faucet to men's staff restroom in front of main teacher's lounge. Leaking when in use.									
Johnny Acuna										
Count: 35 Work Orders			Avg. Age of WO's	105	Total for Desert Trail ES			0	\$67.45	

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert View ES									
256290		Kitchen			1/18/2022		27		\$11.98
High	Work In Progress				1/18/2022 9:35:14 AM				
Pacheco, Hector		No hot water in kitchen area							
Dino Facio									
249948	Main Building	Classroom			8/20/2021		178		\$0.00
Medium	Work In Progress				8/20/2021 9:39:24 AM				
Ambriz, Jose		Classroom 217 the AC is not working properly							
Israel Ortega									
256846		Classroom			1/31/2022		14		\$0.00
Medium	Work In Progress				1/31/2022 12:45:53 PM				
Ambriz, Jose		Classroom 217 the heater is not working							
Israel Ortega									
256616	Main Building	Exterior			1/26/2022		19		\$0.00
Medium	Work In Progress				1/26/2022 1:15:03 PM				
Deveau, David		The wall that is facing the pump room just outside of the 6th grade wing needs to be painted. The graffiti there was only removed with graffiti remover but it was never painted and the lettering from the graffiti still stands out.							
Israel Ortega									
Count: 4 Work Orders			Avg. Age of WO's	60		Total for Desert View ES	0		\$11.98

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
254305					11/18/2021		13		\$554.07
Medium	Work In Progress				11/18/2021 10:32:05	12/1/2021			
Deveau, David	Selma Sepulveda needs a light bulb replaced in her office		Reroute electrical - SANTOS						
Maria Ruiz									
255781	The Pointe	Office			1/5/2022		1		\$0.00
Medium	Work In Progress				1/5/2022 10:42:38 AM	1/6/2022			
Ambriz, Jose	CRUA Office vent came out the office is the one on the left side back needs to be replaced ASAP. Is complete out and hanging.		REROUTE - HVAC Vent is completely out/damage. Duct is hanging below ceiling grid.						
Martha Ortega									
256599	The Pointe	Office			1/26/2022		19		\$0.00
Medium	Work In Progress				1/26/2022 10:35:57 AM				
Ambriz, Jose	Ms. Rios room #203 heater is not working if you may please send someone to check out the heater system.								
Martha Ortega									
252359		Custodial			10/6/2021		131		\$0.00
Medium	Work In Progress				10/6/2021 1:14:32 PM				
Chavez, Santos	La oficina 205 tiene un probelma electrico no esta funcionando, un una de las lamparas y parte de la coneccion de la pared. Se le cambiaron los focos y no prendieron, ademas tiene problemas al conectar su computadora.								
Yolanda Martinez									
255782	The Pointe	Computer Lab			1/5/2022		40		\$0.00
Medium	Work In Progress				1/5/2022 10:44:18 AM				
Chavez, Santos	Computer lab all light fixtures need to be all replaced.								
Martha Ortega									
Count: 5 Work Orders		Avg. Age of WO's 41			Total for GAC			0	\$554.07

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden ES									
256661					1/27/2022		18		\$0.00
Medium	Work In Progress				1/27/2022 9:39:43 AM				
Tellez, Hector		emergency ballast in room 106 near entrance Washington hallway needs replacing							
Federico Montoya									
256245		Classroom			1/14/2022		31		\$0.00
Medium	Work In Progress	100 area			1/14/2022 9:55:16 AM				
,		Need to replace Thermal Expansion Tank model XT-18 leaking water. Thank you							
Jose Ambriz									
256371					1/19/2022		26		\$14.77
Medium	Work In Progress				1/19/2022 3:50:39 PM				
Appelzoller, Fred		expansion Tank leaking need new one							
Fred Appelzoller									
249789		Computer Lab			8/18/2021		180		\$0.00
Medium	Work In Progress	pamadrid			8/18/2021 1:35:26 PM				
Ambriz, Jose		GES-Please check temperature in Computer Lab Room 404 its extremely warm. Thank you,							
Patty Madrid									
256699		Classroom			1/27/2022		18		\$0.00
Medium	Work In Progress	pamadrid@gisd.			1/27/2022 1:31:33 PM				
Marquez, Gerardo		Requesting a window to a classroom door, Room 100. This room will now be the Sensory Retreat room for SPED students. Thank you,							
Patty Madrid									
Count: 5 Work Orders			Avg. Age of WO's	55		Total for Gadsden ES	0		\$14.77

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

253831 11/5/2021 101 \$0.00

Medium Work In Progress 11/5/2021 9:15:52 AM

Hernandez, Guillermo Requested by Velia-Please issue G.H.S. through Velia Alarcon 20 additional key cards.

Velia Alarcon

248062 Grounds Shop Athletic Field 7/27/2021 202 \$0.00

Medium Work In Progress 7/27/2021 3:48:19 PM

Vasquez, Jose Need to cut weeds around softball field, JV softball field and baseball.

Jose Vasquez

248751 8/4/2021 194 \$0.00

Medium Work In Progress 8/4/2021 11:32:00 AM

Vasquez, Jose Requested by Mr. David Martinez for Football Field- Please fix the seams on the Football field. There was information provided by Hellas Construction Maintenance Summary Report. The report is attached to this work order and it does states "Seams are coming loose in several places of field. Base appears to be rough on outside edge by track and some spots in play area/d-zone."

Velia Alarcon

253658 11/2/2021 104 \$0.00

Medium Work In Progress 11/2/2021 2:17:29 PM

Vasquez, Jose Requested by Ms. Taylor Brooke Provencio for Bus Turn Around-The water pump inside of the bus turn-around needs to be fixed and/or probably replaced as soon as the Ag. Farm is complete with the flood irrigation for the Alfalfa crop. That is currently growing.

Velia Alarcon

256576 1/25/2022 20 \$0.00

Medium Work In Progress 1/25/2022 4:21:09 PM

Hernandez, Carlos Requested by Mr. David Martinez-Please place two room identification plaques for room #'s 228 and 228S in the North Building. These room are across from Mr. Mora's classroom. ordered plaques

Velia Alarcon

256830 1/31/2022 14 \$0.00

Medium Work In Progress 1/31/2022 10:12:34 AM

Hernandez, Carlos Requested by Ms. Juana Santamaria Rm. 805 Annex Building-Door threshold between classroom and restroom is broken and needs to be repaired. ordered threshold 2-9-22

Velia Alarcon

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

254663 12/2/2021 74 \$0.00

Medium Work In Progress 12/2/2021 12:56:26 PM

Hernandez, Carlos Requested by Campus Security for Varsity Gym-Varsity Gym boys restroom (Lobby Area) vandalism to restroom stall door (detached) needing repair (12/01/2021) sharp edge posing safety issue. ordered replacement parts.

Velia Alarcon

255219 12/14/2021 62 \$825.00

Medium Work In Progress 12/14/2021 11:18:10

Hernandez, Carlos Requested by Campus Security for Rm. 335 Boy's Restroom in Academic Building-On 12/10/2021 the Custodian (evening shift) reported to G.H.S. Security vandalism of Academic Building Boys Restroom, light switch damage due to attempt of removal. ordered switches

Velia Alarcon

249038 8/9/2021 189 \$0.00

Medium Work In Progress 8/9/2021 9:54:02 AM

Hernandez, Carlos Requested by Mr. David Martinez for Student Restrooms in the Cafeteria-Please add signs to the Boy's and Girl's Restrooms located at the G.H.S. Cafeteria. ordered signs

Velia Alarcon

256097 1/11/2022 34 \$0.00

Medium Work In Progress 1/11/2022 2:01:18 PM

Vasquez, Jose Requested by Coach Sergio Quintero for Visiting Team's Bullpen Area for Baseball Field-Opposing team members throw bullpen 3 feet away from a passerby and there is no barricade to keep the Athlete and fans safe from each other. There is no enclosure or fence to stop a ball from hitting a spectator passing by on the sidewalk. As the opposing pitcher and catcher are warming up in the bullpen. The bullpen is currently on the side of the visiting team's dugout, right beside the sidewalk used for fans to walk on to access the field and Tennis Court area. A fence could be very helpful in ensuring a safe environment

Velia Alarcon

253378 10/29/2021 108 \$0.00

Medium Work In Progress 10/29/2021 11:28:21

Ambriz, Jose Requested by Mr. Anthony Sapien Rm. 515 & 517 CTE Building-Update on refrigerator units that were left "testing" after David's visit. Update on refrigerator units in the dinning room area.

Velia Alarcon

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
Location: Gadsden HS										
250971					9/8/2021		159		\$623.77	
Medium	Work In Progress				9/8/2021 11:13:49 AM					
Tellez, Hector		Requested by Mr. Carlos Enriquez Rm. 500 CTE Building-Vehicle lift on west side of Auto Shop needs to be connected to shop power.								
Velia Alarcon										
255608					1/3/2022		42		\$0.00	
Medium	Work In Progress				1/3/2022 10:56:43 AM					
Ambriz, Jose		Computer Tech Office Heater not working please check...THANK YOU								
Cora Ramirez										
255218					12/14/2021		62		\$0.00	
Medium	Work In Progress				12/14/2021 11:17:04					
Tellez, Hector		Requested by Campus Security for Rm. 310 Boy's Restroom in Academic Building-On 12/10/2021 the Custodian (evening shift) reported to G.H.S. Security vandalism of Academic Building Boys Restroom, light switch was pushed in and cover is missing.								
Velia Alarcon										
Count: 14 Work Orders		Avg. Age of WO's		98	Total for Gadsden HS			0	\$1,448.77	

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
254471		Kitchen			11/29/2021		77		\$0.00
High	Work In Progress				11/29/2021 12:22:57				
Tellez, Hector		Lights flicker when there off in kitchen area							
Dino Facio									
253354					10/28/2021		109		\$777.24
Medium	Work In Progress				10/28/2021 3:55:00 PM				
Tellez, Hector		Need 4 four foot wrap lighting for kitchen Emergency backup							
Hector Tellez									
256004		Cafeteria			1/10/2022		35		\$0.00
Medium	Work In Progress	Cafeteria / S.			1/10/2022 10:18:58 AM				
Ambriz, Jose		Heater is not working in the cafeteria work area. Its blowing out cold air instead of warm. Please fix, is cold.							
Hilda Adler									
254439	Annex	Classroom			11/29/2021		77		\$37.95
Medium	Work In Progress	RM 409, Norris			11/29/2021 8:51:47 AM				
Ambriz, Jose		There's no heat in my room, Its cold. Need the heater to work or portable heater please.							
Hilda Adler									
250310		Office			8/26/2021		172		\$0.00
Medium	Work In Progress	Terry Urbina			8/26/2021 12:04:37 PM				
Marquez, Gerardo		Door to her office is off the hinges. Please adjust, its messing up the floor. Thank you, Mr. Mora				Pending asp report 9/13/21 - 281			
Hilda Adler									
248085					7/28/2021		201		\$0.00
Medium	Work In Progress	Gardens			7/28/2021 8:44:56 AM				
Vasquez, Jose		Cut grass and weeds from both gardens by the canopy and by the annex. Please dispose of weeds and grass. thank you.							
Hilda Adler									
254548					11/30/2021		76		\$0.00
Medium	Work In Progress	entire school			11/30/2021 2:30:03 PM				
Apodaca, Mario		Water is coming our yellow in all the water fountains, sinks and toilets.							
Hilda Adler									

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Gadsden MS							
248516	Annex	Classroom			8/2/2021		196		\$6.79
Medium	Work In Progress	RM# 407/ Durr			8/2/2021 11:41:14 AM				
Marquez, Gerardo		Green Room , inside door seal is broken and sand/dirt gets into the classroom . Please fix, thank you Mr. Mora				Forward to Jerry- Rafa			
Hilda Adler									
Count: 8 Work Orders		Avg. Age of WO's 118			Total for Gadsden MS			0	\$821.98

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: La Union ES									
256149					1/12/2022		33		\$0.00
Medium	Work In Progress			1/12/2022 11:14:43 AM					
Hernandez, Guillermo	Asp PM 255975 inspection plastic is cracked on slide and blue paint is chipped.								
Javier Villalva									
254063	Main Building	Classroom			11/12/2021		94		\$0.00
Medium	Work In Progress	111		11/12/2021 8:39:53 AM					
Ambriz, Jose	BEATRIZ PANDO, 111, CLASSROOM IS SUPER COLD PLEASE TURN ON HEAT.								
Joanne Munoz									
252175	Main Building	Computer Lab			10/4/2021		133		\$0.00
Medium	Work In Progress	200		10/4/2021 8:46:33 AM					
Ambriz, Jose	JOANNE MUNOZ, RECP., MAIN COMPUTER LAB IS VERY HOT ROOM 200 PLEASE TURN ON AIR CONDI								
Joanne Munoz									
250142	Main Building	Office			8/24/2021		174	0.5	\$12.50
Medium	Work In Progress	FRONT OFFICE		8/24/2021 11:35:28 AM					
Gallegos, Rafael	JOANNE MUNOZ, RECEPTIONIST, CHECK TEMP IN OFFICE STILL VERY WARM. PLEASE CHECK THE ACTUAL TEMP IN MAIN OFFICE.					Re-Route to Mr. Gallegos - New units construction. -Jose Ambriz			
Joanne Munoz									
256270	Main Building	Cafeteria			1/17/2022		28		\$0.00
Medium	Work In Progress			1/17/2022 2:39:29 PM					
Chavez, Santos	2 each ceiling lights are out								
Joe Munoz									
Count: 5 Work Orders		Avg. Age of WO's 92		Total for La Union ES			0.5	\$12.50	

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Loma Linda ES							
250878		Classroom			9/7/2021		160		\$0.00
Medium	Work In Progress	Room#217			9/7/2021 8:15:23 AM				
Ontiveros, Joe	Favor de remplazar la llave del agua del zinc del salon #217 de la clase de arte .								
Sol Suarez									
250879		Classroom			9/7/2021		160		\$0.00
Medium	Work In Progress	Room#222			9/7/2021 8:17:34 AM				
Ontiveros, Joe	Favor de eregrar la llave del zinc del cuarto #222 se queda abierta en todo momento.								
Sol Suarez									
254036		Kitchen			11/10/2021		96		\$0.00
High	Work In Progress				11/10/2021 2:40:38 PM				
Ontiveros, Joe	Water pipe from wall to dish machine is leaking causing a puddle in the tray room								
Dino Facio									
256729					1/28/2022		17		\$0.00
Medium	Work In Progress				1/28/2022 7:54:08 AM				
Avila, Jesus	Need pole welded on canopy at bus turn around first on out of the building. installation of IMC pole 8 ft off the pitch								
Hector Tellez									
254228		Exterior			11/16/2021		1	1.5	\$127.19
Medium	Work In Progress				11/16/2021 3:35:13 PM	11/17/2021			
Vasquez, Jose	Need to repair leak on the water pump by the Morgan.					Repaired leak and replaced parts.			
Jose Vasquez									
Count: 5 Work Orders		Avg. Age of WO's		87	Total for Loma Linda ES		1.5	\$127.19	

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Mesquite ES									
250053	Main Building				8/23/2021		175		\$0.00
Medium	Work In Progress	Outside Storm			8/23/2021 11:26:10 AM				
Hernandez, Guillemo		As per Michael Reyes/Assistant Principal, storm drain outside next to main building the cement looks like it is caving in can someone come look at it please and thank you.							
Sandra Mora									
252644					10/12/2021		125		\$0.00
Medium	Work In Progress				10/12/2021 10:42:22				
Marquez, Gerardo		Need key made for box in vault.							
Sandra Mora									
249049	Army Building				8/9/2021		189		\$0.00
High	Work In Progress	Portable # 609			8/9/2021 10:47:13 AM				
Marquez, Gerardo		Socorro Lerma/PE Teacher, needs classroom door hinge and stopper put on asap teacher had accident on finger.. please and thank you.				Transfer to Jerry - Rafa			
Sandra Mora									
249309	Army Building				8/11/2021		187		\$0.00
Medium	Work In Progress	Portable # 609			8/11/2021 2:33:31 PM				
Marquez, Gerardo		Inside door in portable # 609 door needs closer replacement please and thank you.				Pending asp report 9/13/21 - 281			
Sandra Mora									
255850	Main Building	Hallway/Corridor			1/6/2022		39		\$0.00
Medium	Work In Progress	Main Lobby			1/6/2022 11:24:52 AM				
Marquez, Gerardo		Our front doors when parent/visitor rings the bell and we in front office press button to open it door doesn't unlock so visitor can come in we have to go to the door and open manually.... please help and thank you.							
Sandra Mora									
251255		Kitchen			9/14/2021		153		\$0.00
High	Work In Progress				9/14/2021 7:24:15 AM				
Tellez, Hector		Power surge ovens and warmers on than they completely all turned off now wont turn back on							
Dino Facio									
Count: 6 Work Orders			Avg. Age of WO's	145			Total for Mesquite ES	0	\$0.00

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		North Valley ES							
253072					10/21/2021		116		\$0.00
Medium	Work In Progress				10/21/2021 10:34:31				
Hernandez, Carlos		If possible we need some holes covered up and painted in rooms where the Smart Boards were removed. Rooms: 101,103,104,105,106,107,108,201,202,203,204,205,206,207,208,209,210,212,300,301,302,303,304,305,306,307,308,309,310. Thank You.				summer project			
Gloria Reyes									
256190		Classroom			1/13/2022		32		\$286.20
Medium	Work In Progress	101			1/13/2022 7:54:46 AM				
Ambriz, Jose		Need to check heat pump tripping breaker.							
Jose Ambriz									
254012		Mechanical			11/10/2021		96		\$0.00
Medium	Work In Progress				11/10/2021 9:21:40 AM				
Ambriz, Jose		The Communications Room is not working.							
Gloria Reyes									
251254		Athletic Field			9/14/2021		153		\$0.00
Medium	Work In Progress				9/14/2021 7:19:57 AM				
Vasquez, Jose		We have a tree near the staff parking lot that a large branch broke off.							
Gloria Reyes									
Count: 4 Work Orders		Avg. Age of WO's 99			Total for North Valley ES			0	\$286.20

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
Location: Northern On-Track Pre-K (LM)										
254508					11/30/2021		13	11	\$275.00	
Medium	Work In Progress				11/30/2021 6:57:54 AM	12/13/2021				
Ambriz, Jose		The heaters from all the rooms on one side of the building are not working				cleared alarms and set temp at 72				
Viola Ramos										
Count: 1 Work Orders			Avg. Age of WO's	13	Total for Northern On-Track Pre-K (LM)			11	\$275.00	

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
251949	Main Warehouse				9/29/2021		138		\$846.68
Medium	Work In Progress				9/29/2021 3:13:39 PM				
Tellez, Hector		Please adjust lights on the warehouse the are to be on from dusk to dawn and are currently running 24/7. Also please replace light to the left of the warehouse sign that is brunt out. Please see email for picture. For questions please see Mr. Gallegos in the Construction Office. Thank You							
Dominique Esparza									
256796					1/31/2022		14		\$0.00
Medium	Work In Progress	Instructional			1/31/2022 8:47:58 AM				
Ambriz, Jose		Heater is not working in Rudy's office in IM							
Rosa Gamon									
256650		Athletic Field			1/27/2022		18		\$0.00
Medium	Work In Progress				1/27/2022 8:17:56 AM				
Vasquez, Jose		Need fertilizer for CHS,GHS,STH, CMS, STMS, GMS							
Jose Vasquez									
255747					1/5/2022		40		\$0.00
Medium	Work In Progress	Instructional			1/5/2022 8:35:21 AM				
Ambriz, Jose		Heater in Rudy's office is not working at IM warehouse							
Rosa Gamon									
255252	Main Warehouse	Athletic Field			12/15/2021		61		\$0.00
Medium	Work In Progress				12/15/2021 9:02:21 AM				
Vasquez, Jose		Need white and black paint for STH, GHS, CHS, STM, CMS. and GMS.							
Jose Vasquez									
256259					1/14/2022		31		\$0.00
Medium	Work In Progress				1/14/2022 3:38:07 PM				
Appelzoller, Fred		ware house sew line clogged							
Fred Appelzoller									
256222					1/13/2022		32		\$345.24
Medium	Work In Progress				1/13/2022 3:50:19 PM				
Appelzoller, Fred		Need cutters for Gen wire Machines							
Fred Appelzoller									

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
253794					11/4/2021		102		\$0.00
Medium	Work In Progress				11/4/2021 2:05:43 PM				
Hernandez, Guillermo		Need to order proximity cards.							
Guillermo Hernandez									
256096	Motor Vehicle	Exterior			1/11/2022		34		\$0.00
Medium	Work In Progress				1/11/2022 1:34:48 PM				
Gonzalez, Salvador		Would you please make 6 keys to open and close 2" ball valves							
Jose Vasquez									
253598	Motor Vehicle				11/1/2021		105		\$0.00
Medium	Work In Progress				11/1/2021 3:48:42 PM				
Villalobos, Jose		Tractor # 0506 front tire needs to be repaired							
Ramiro Holguin									
252855					10/15/2021		95	0.3	\$750.25
Medium	Work In Progress				10/15/2021 12:48:07	1/18/2022			
Carrasco, Danny		10/15/2021 Requesting replacement of ladders. Replacement of hammer drill. Thank you				issue			
Federico Flores									
254970					12/7/2021		69		\$0.00
Medium	Work In Progress				12/7/2021 1:19:36 PM				
Lara, Ralph		Need 10 PAD LOCKS KEYED FOR 7GM KEY. FOR ELECTRICAL LOAD CENTERS LOCATED OUTSIDE. FOR STUDENT SAFETY.							
Santos Chavez									
254301					11/18/2021		88		\$0.00
Medium	Work In Progress	Instructional			11/18/2021 8:42:51 AM				
Marquez, Gerardo		Please adjust door handle for entrance door at IM							
Rosa Gamon									
254352					11/19/2021		87		\$0.00
Medium	Work In Progress	Instructional			11/19/2021 9:06:23 AM				
Marquez, Gerardo		Please change door handle for it to be locked from the inside of main entrance of IM							
Rosa Gamon									
Count: 14 Work Orders			Avg. Age of WO's	65		Total for Physical Plant Complex	0.30000	\$1,942.17	

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Riverside ES							
253752					11/4/2021		102		\$0.00
High	Work In Progress	6th grade boys			11/4/2021 9:58:39 AM				
Deveau, David		Please replace bracket/bar that holds handicap restroom dividers due to student hanging on bar to break it intentionally. Bar was removed and needs to be replaced to secure restroom dividers. Sunland Park PD requesting estimate on damages please provide estimate via email to namartinez@gisd.k12.nm.us (Mrs. Martinez)				Pending asp report 11/18/21			
Norma Martinez									
256498					1/24/2022		21		\$0.00
Medium	Work In Progress	Room 116			1/24/2022 11:09:36 AM				
Ambriz, Jose		Nurses office is very cold please adjust temperature by 2 degree. (Mrs. Perez)							
Norma Martinez									
Count: 2 Work Orders		Avg. Age of WO's		62	Total for Riverside ES			0	\$0.00

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: RTC - Alliance									
256375		Exterior			1/19/2022		26		\$0.00
Medium	Work In Progress				1/19/2022 3:56:30 PM				
Deveau, David		we had placed a worker order to paint window rails and back metal ramps never completed 236605 and 240594 please look into it Thank you							
Gloria Delgado									
256376		Office			1/19/2022		5		\$0.00
Medium	Work In Progress				1/19/2022 3:59:21 PM	1/24/2022			
Ambriz, Jose		please replace ceiling panels and inspect portable roof for leaks 2nd time to replace panels came already and applied tar				1/27/22 REROUTE HVAC - Missing cap on top of vent			
Gloria Delgado									
247446					7/14/2021		215		\$21.74
Medium	Work In Progress				7/14/2021 2:57:48 PM				
Vasquez, Jose		need our campus clean before students start on Aug 2,2021							
Gloria Delgado									
Count: 3 Work Orders		Avg. Age of WO's		82	Total for RTC - Alliance			0	\$21.74

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: San Miguel Special Services									
247757					7/22/2021		207		\$20.81
Medium	Work In Progress				7/22/2021 9:19:39 AM				
Vasquez, Jose	Please trim all dead branches from all trees. Should you have any questions please see Mr. Gallegos in the Construction Office. Thank You.								
Dominique Esparza									
248548					8/2/2021		7	32	\$840.08
Medium	Work In Progress				8/2/2021 2:29:41 PM	8/9/2021			
Vasquez, Jose	Please send a crew to install 3 poles with cables to the gravel area so that people will stop parking in there. Thank you.		installed ballards						
Susie Ramos Lara									
254031	Main Building	Hallway/Corridor			11/10/2021		96		\$0.00
Medium	Work In Progress				11/10/2021 1:27:35 PM				
Ambriz, Jose	Water fountain needs to be fixed or replaced, makes extremely loud noises and leaks water periodically.								
Delilah Appelzoller									
Count: 3 Work Orders			Avg. Age of WO's	103	Total for San Miguel Special Services			32	\$860.89

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa ES									
251338		Classroom			9/15/2021		152		\$0.00
Medium	Work In Progress				9/15/2021 9:49:58 AM				
Ambriz, Jose		Need to repair pvc condensation line							
Jose Ambriz									
256469	Main Building	Classroom			1/21/2022		24		\$0.00
Medium	Work In Progress	room 107 Ms. J.			1/21/2022 5:50:44 PM				
Pacheco, Hector		Please check sink in the classroom-clogged. Thank you.							
Rita Mendez									
254733					12/3/2021		73		\$82.68
Medium	Work In Progress				12/3/2021 1:39:18 PM				
Chavez, Santos		2 lights at STE Entrance Lobby, they are out & need to be fixed. Please see e-mail with picture of lights. Should you have any questions please see Mr. Gallegos in the Construction Office Thank You							
Dominique Esparza									
248252	Main Building	Portables			7/30/2021		199		\$0.00
Medium	Work In Progress	portable F Mrs.			7/30/2021 1:07:17 PM				
Lara, Ralph		Door to portable F unable to be opened-bottom part gets stuck. Please check. Thank you.							
Rita Mendez									
Count: 4 Work Orders			Avg. Age of WO's	112		Total for Santa Teresa ES	0		\$82.68

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
256813		Classroom			1/31/2022		14		\$0.00
Medium	Work In Progress	311			1/31/2022 9:41:19 AM				
Lara, Ralph		Need: File Cabinet Lock and Storage Cabinet Lock							
Aida Gentzler									
255767		Classroom			1/5/2022		40		\$0.00
Medium	Work In Progress	311			1/5/2022 10:22:11 AM				
Lara, Ralph		Locks: 1 cabinet & 1 storage cabinet							
Aida Gentzler									
255769		Classroom			1/5/2022		40		\$0.00
Medium	Work In Progress	805			1/5/2022 10:23:19 AM				
Lara, Ralph		Door closer is leaking oil							
Aida Gentzler									
254729		Kitchen			12/3/2021		73		\$0.00
Medium	Work In Progress				12/3/2021 12:17:08 PM				
Lara, Ralph		Curtain to stand 3 does not go up.							
Maritza Gonzalez									
254715					12/3/2021		73		\$0.00
Medium	Work In Progress	Exterior Doors			12/3/2021 11:08:18 AM				
Lara, Ralph		Handicap door button still not working. main entrance and 200 hall entrance.							
Aida Gentzler									
251453		Classroom			9/17/2021		150		\$0.00
Medium	Work In Progress	505			9/17/2021 10:56:53 AM				
Lara, Ralph		"Various locks on cabinets do not work. Various handles on cabinets are loose"							
Aida Gentzler									
256822					1/31/2022		1		\$0.00
Medium	Work In Progress	707			1/31/2022 9:47:48 AM	2/1/2022			
Deveau, David		Water flow to the chemical machine that injects degreaser chemicals for dishwasher the drainage is leaking water all over the floor in the kitchen.							
Aida Gentzler						2/1/22 Asp email from Mrs. Gentzler, wrong area was checked, this is a culinary classroom 707, not the cafeteria kitchen. David please check a/s/a/p - mkv DM is functioning properly 2/1/22 - Asp Foreman, chemical is to dishwasher in Kitchen/Cafeteria, need to route to Food Services - mkv			

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To		Description							
Requester Name									
Location:		Santa Teresa HS							
256143		Classroom			1/12/2022		2	1	\$25.00
Medium	Work In Progress	600		1/12/2022 10:32:43 AM	1/14/2022				
Lara, Ralph		Need a door between Mr. Lawrence and the next classroom. (The classroom across Mr. Avila's classroom)				REROUTE - LOCKSMITH		Need to have complete door installed	
Aida Gentzler									
256403					1/20/2022		25		\$0.00
Medium	Work In Progress			1/20/2022 12:43:20 PM					
Carrasco, Danny		Push broom (1), Sweeping broom with dust pan (1), Wet/Dry Shop Vac - 5gal (1), Full size Squeegee (1), Flatshovel, Pointed shovel (1 of each), Large rake (1), Large black trash bags (3 boxes). THESE ITEMS ARE FOR MAINTENANCE SHOP							
David Deveau									
249433	Main Building	Classroom			8/13/2021		185		\$590.00
Medium	Work In Progress	Different Areas		8/13/2021 10:00:37 AM					
Deveau, David		8/12 due to all the rain there are several areas in the school that have water damage. Ceiling tiles need to be replaced around the school. This includes classrooms in the 500, main back hallway, classrooms in the 400							
Gema Suggs									
256387					1/20/2022		25		\$0.00
Medium	Work In Progress			1/20/2022 10:16:08 AM					
Villalobos, Jose		Need to repair Mower #M-STHS-0425. Will not stay running.							
Jose Villalobos									
255770		Classroom			1/5/2022		40		\$0.00
Medium	Work In Progress	506		1/5/2022 10:25:29 AM					
Chavez, Santos		no power on outlets between two exit doors. These outlets are adjacent to the countertops							
Aida Gentzler									
254721		Classroom			12/3/2021		73		\$0.00
Medium	Work In Progress	306		12/3/2021 11:21:15 AM					
Chavez, Santos		All but 2 of the electrical outlets in my room are not working.							
Aida Gentzler									

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
256624					1/26/2022		19		\$0.00
Medium	Work In Progress	Softball Field			1/26/2022 2:24:11 PM				
Chavez, Santos		Requesting lights by the softball batting cages if possible. Thank you!							
Aida Gentzler									
256144		Classroom			1/12/2022		33		\$179.67
Medium	Work In Progress	Choir room			1/12/2022 10:33:55 AM				
Chavez, Santos		Need a 240v outlet installed (NEMA16-30p outlet)							
Aida Gentzler									
255194	Cafeteria (2005)	Auditorium			12/14/2021		62		\$0.00
Medium	Work In Progress	Stage			12/14/2021 8:26:39 AM				
Chavez, Santos		Replace the non working outlets							
Gema Suggs									
250377	Vocational	Classroom			8/27/2021		171		\$0.00
Medium	Work In Progress	707			8/27/2021 11:25:56 AM				
Chavez, Santos		need two light bulbs in Rm. 707; and to replace light covers							
Aida Gentzler									
251017	GYM (2009)	Gym			9/9/2021		158		\$0.00
Medium	Work In Progress	New Gym			9/9/2021 7:59:51 AM				
Chavez, Santos		Need 2 light bulbs replaced in the new gym. Thank you!							
Aida Gentzler									
256470	Main Building	Gym			1/22/2022		2		\$0.00
Medium	Work In Progress	Girls Restrooms			1/22/2022 3:55:24 PM	1/24/2022			
Pacheco, Hector		Toilet is broken.				1/27/22 REROUTE PLUMBING - Toilet is completely broken. Needs new toilet			
Raul Villagrana									
256377	GYM (2009)	Restroom			1/20/2022		25		\$118.59
Medium	Work In Progress	Locker Room			1/20/2022 5:49:56 AM				
Pacheco, Hector		Water coming out from toilet.							
Raul Villagrana									

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

256820 Classroom 1/31/2022 14 \$0.00

Medium Work In Progress 707 1/31/2022 9:47:05 AM

Pacheco, Hector The gas valve/ regulator doesn't work on the (stove 6 burners). It makes a popping sounds when I turn the gas valve on and turn all six pilot lights and in a few seconds to a minute the pilot light goes off by making a loud popping sound.

Aida Gentzler

250451 Classroom 8/30/2021 168 \$0.00

Medium Work In Progress 205 8/30/2021 3:13:16 PM

Ambriz, Jose Air conditioner was fixed but then it broke or something. Hot air is still coming out. It only worked for a few hours.

Aida Gentzler

255957 Storage (Tennis) Football Field 1/9/2022 36 \$0.00

Medium Work In Progress Football Field 1/9/2022 1:15:35 PM

Vasquez, Jose Grooming of the Turf--Please speak with Ms. Gentzler, Athletic Administrator when it gets done.

Gema Suggs

256623 1/26/2022 19 \$0.00

Medium Work In Progress Softball Field 1/26/2022 2:23:22 PM

Vasquez, Jose Grass needs to be watered. Outfield needs to be leveled. Holes are causing injuries. Sprinkler to water infield is requested.

Thank you!

Aida Gentzler

256482 Athletic Field 1/24/2022 21 \$0.00

Medium Work In Progress 1/24/2022 8:47:04 AM

Vasquez, Jose Need compost topsoil to level practice soccer field at STHS

Jose Vasquez

252229 Cafeteria (2005) Choral 10/4/2021 2 3 \$121.00

Medium Work In Progress gsuggs@gisd.k1 10/4/2021 4:58:58 PM 10/6/2021

Ambriz, Jose AC reinstalled belts

Gema Suggs

252324 Kitchen 10/6/2021 131 \$0.00

Medium Work In Progress culinary kitchen 10/6/2021 7:49:47 AM

Ambriz, Jose Need to replace a temperature control to beverage freezer in culinary kitchen.

Jose Ambriz

2/14/2022 1:29:46 PM

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
248442					8/1/2021		197		\$0.00
Medium	Work In Progress	JTP Portable			8/1/2021 6:13:08 PM				
Ambriz, Jose		AC Unit is not Cooling							
Aida Gentzler									
248028	Vocational	Classroom			7/27/2021		202		\$0.00
High	Work In Progress	707			7/27/2021 11:13:37 AM				
Ambriz, Jose		Fix air conditioning							
Aida Gentzler						need to re-route to Sergio Guardado swamp a/c. Theres no swamp a/c need to re route to joe ambriz. Thank u by sergio guardado			
256740	Main Building	Classroom			1/28/2022		17		\$12.66
Medium	Work In Progress	303/305			1/28/2022 9:45:30 AM				
Ambriz, Jose		Temperature 76							
Gema Suggs									
Count: 30 Work Orders			Avg. Age of WO's	67		Total for Santa Teresa HS	4	\$1,046.92	

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
256862	Gym (1997)	Gym			1/31/2022		14		\$0.00
Medium	Work In Progress	GIRLS/BOYS			1/31/2022 3:38:36 PM				
Ambriz, Jose		WATER FOUNTAIN IN BOYS LOCKER ROOM SENDS ELECTRICAL SHOCKS WHEN PRESSED- SAFETY HAZARD							
		Asp Santos, route to HVAC water fountain has been disconnected- 1/31/22							
Laura Parra									
254656		Electrical Room			12/2/2021		74		\$0.00
Medium	Work In Progress				12/2/2021 11:53:28 AM				
Ambriz, Jose		12/2/21. Air is not working in electrical room very hot inside, need to check.							
Julio Alvarado									
247178	South Building	Classroom			7/8/2021		0	6	\$150.00
Medium	Work In Progress				7/8/2021 1:34:26 PM	7/8/2021			
Ambriz, Jose		Need to check office unit and room 21 .				problems with the condensation line, relocated			
Jose Ambriz									
249261	Gym (1997)	Gym			8/11/2021		187		\$0.00
Medium	Work In Progress	BOYS LOCKER			8/11/2021 9:52:12 AM				
Ambriz, Jose		LEAVE AC ON UNTIL 6 PM DAILY. STUDENTS ARE STAYING AFTER SCHOOL TO PRACTICE AND LOCKER ROOMS GET TOO HOT IN THE AFTERNOONS							
Laura Parra									
256062	North Building	Restroom			1/11/2022		34		\$81.83
Medium	Work In Progress	Lower Level			1/11/2022 7:44:27 AM				
Pacheco, Hector		Need to install a 24 inch access door in boys restroom to repair a leak in a top level floor drain that's leaking on a light fixture.							
Hector Pacheco									
251290					9/14/2021		153		\$0.00
Medium	Work In Progress				9/14/2021 2:04:59 PM				
Chavez, Santos		Classroom S49 needs a replacement 2x4 light							
Santos Chavez									

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

254011	North Building	Restroom			11/10/2021		96		\$0.00
--------	----------------	----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/10/2021 9:07:08 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Chavez, Santos PORFAVOR DE CHECAR LAS LUCES DEL BOYS RESTROOM SE APAGARON Y SOLO ESTA PRENDIDA LA LUZ DE EMERGENCIA GRACIAS

Cristian Martinez

255158	Gym (1997)	Storage			12/13/2021		2	1	\$25.00
--------	------------	---------	--	--	------------	--	---	---	---------

Medium	Work In Progress	JANITORS			12/13/2021 11:19:21	12/15/2021			
--------	------------------	----------	--	--	---------------------	------------	--	--	--

Chavez, Santos REPLACE LIGHTS IN JANITOR'S CLOSET Re-route to Electrician as per B.M.

Laura Parra

252828		Kitchen			10/15/2021		122		\$0.00
--------	--	---------	--	--	------------	--	-----	--	--------

High	Work In Progress				10/15/2021 7:16:50 AM				
------	------------------	--	--	--	-----------------------	--	--	--	--

Chavez, Santos Two ceiling lights in kitchen area are out

Dino Facio

256305	North Building	Cafeteria			1/18/2022		27		\$0.00
--------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/18/2022 11:53:02 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Chavez, Santos PORFAVOR DE REVISAR UNA LAMPARA DE LA CAFETERIA QUE NO QUISO PRENDER GRACIAS

Cristian Martinez

256554	South Building	Restroom			1/25/2022		20		\$0.00
--------	----------------	----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/25/2022 11:56:17 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Deveau, David PORFAVOR DE CAMBIAS LOS ESPEJOS DE LOS BOYS RESTROOM DEL EDIFICIO SUR, Y UN BASE BORD ,1 DEL RESTROOM PRIMERO UPPER LEVEL Y 2 DEL RESTROOM DEL MEDIO Y 1 EN EL RESTROOM PRIMERO DEL DOWN LEVEL ,Y OTRO DE EL RESTROOM DEL MEDIO Need to replace 5 mirrors including all hardware (2 missing, 3 damaged). Sent material request 1/27/22

Cristian Martinez

256357	Gym (1997)	Gym			1/19/2022		26		\$0.00
--------	------------	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress	EXTERIOR			1/19/2022 3:08:43 PM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Deveau, David STMS SIGNAGE GYM MISSING BLACK COVER ON THE LETTER "M" AND THE LETTER "S"

Laura Parra

250918	North Building	Exterior			9/7/2021		160		\$0.00
--------	----------------	----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	JULIO			9/7/2021 2:09:51 PM				
--------	------------------	-------	--	--	---------------------	--	--	--	--

Vasquez, Jose NEED 4 LOADS OF FILL DIRT

Laura Parra

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Santa Teresa MS							
256725	South Building	Restroom			1/28/2022		17		\$0.00
Medium	Work In Progress	lower level			1/28/2022 6:27:27 AM				
Lara, Ralph		Please secure with a lock the plumbing access panel door students are accessing. Please see Mr. Delgado or Ms. Davis							
Shannon Davis									
Count: 14 Work Orders		Avg. Age of WO's		67	Total for Santa Teresa MS			7	\$256.83

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
Location: SNP Complex										
254972					12/7/2021		69		\$0.00	
High	Work In Progress				12/7/2021 2:11:34 PM					
Chavez, Santos		Need to check power inverter on safety light in vault								
Dino Facio										
252991		Office			10/19/2021		118		\$0.00	
High	Work In Progress				10/19/2021 1:30:49 PM					
Chavez, Santos		Need electrical plugs installed in copy room for copier and one on hallway wall of main office								
Dino Facio										
252750		Office			10/14/2021		123		\$2,805.35	
High	Work In Progress				10/14/2021 7:59:14 AM					
Ambriz, Jose		AC unit in server room not working properly Hot								
Dino Facio										
Count: 3 Work Orders		Avg. Age of WO's 103		Total for SNP Complex				0	\$2,805.35	

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunland Park ES									
248181					7/29/2021		200		\$0.00
Medium	Work In Progress	40			7/29/2021 9:57:59 AM				
Ambriz, Jose		A/C NOT WORKING							
Ivette Rios									
255680		Kitchen			1/4/2022		41		\$0.00
High	Work In Progress				1/4/2022 9:52:49 AM				
Chavez, Santos		Check LED lighting in hood							
Dino Facio									
254163					11/15/2021		91		\$319.06
Medium	Work In Progress				11/15/2021 3:27:15 PM				
Chavez, Santos		Need to order support for feeder for portable E							
Santos Chavez									
256215	Main Building	Restroom			1/13/2022		32		\$409.86
Medium	Work In Progress				1/13/2022 2:04:46 PM				
Pacheco, Hector		The faucet on the second sink in the boys bathroom is not working properly. It does not turn off by itself and we constantly have the water flowing on the floor.							
Maria Barraza									
256219	Main Building	Custodial			1/13/2022		32		\$0.00
Medium	Work In Progress	Custodial Room			1/13/2022 3:37:20 PM				
Pacheco, Hector		Drain in custodial room on Hallway 20-25 does not drain. The water just sits there. Problem has been going on for a long time, has been looked at before but not resolved.				Refer to WO#255042			
Maria Barraza									
250034	Main Building	Hallway/Corridor			8/23/2021		175		\$0.00
Medium	Work In Progress	Hallway Doors			8/23/2021 9:34:24 AM				
Lara, Ralph		Please provide a key for PE coach that opens the side doors to the playground the side door to the portables, the storage room in the gym and Portable E.				RE-ROUTE TO LOCKSMITH			
Maria Barraza									
255835		Restroom (Girls)			1/6/2022		39		\$0.00
Medium	Work In Progress				1/6/2022 9:22:26 AM				
Lara, Ralph		Girls Restroom - Stall door damaged, needs to be replaced, including all hardware. 57.5 inches tall - 35.5 inches wide							
David Deveau									

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Sunland Park ES							
255696	Main Building	Restroom (Girls)			1/4/2022		41		\$0.00
Medium	Work In Progress				1/4/2022 11:20:34 AM				
Lara, Ralph		stall door was removed from girls bathroom and hasn't been installed please and thank you				Reroute to Locksmith - DD 1/4/22			
Vanessa Davila									
247903		Exterior			7/26/2021		203		\$0.00
Medium	Work In Progress				7/26/2021 9:14:33 AM				
Vasquez, Jose		please trim tree branches in teachers parking lot.							
Ivette Rios									
255297	Main Building	Restroom (Girls)			12/16/2021		60		\$0.00
Medium	Work In Progress				12/16/2021 11:24:11				
Deveau, David		a door hinge of one of the bathroom stalls is jammed. please check and thank you				Door is completely broke, hinge is broke and door is broke where hinge connects to door. Door has been removed - ordered new door and all hardware on 1/6/22.			
Vanessa Davila									
256124	Main Building	Office			1/12/2022		33		\$0.00
Medium	Work In Progress				1/12/2022 7:30:45 AM				
Deveau, David		flag pole chain broken please fix thank you							
Vanessa Davila									
254183					11/16/2021		90		\$124.71
Medium	Work In Progress				11/16/2021 7:48:47 AM				
Avila, Jesus		Need new mast for electrical service							
Santos Chavez									
255694	Main Building	Office			1/4/2022		41		\$0.00
Medium	Work In Progress				1/4/2022 11:16:58 AM				
Gonzalez, Salvador		Please evaluate pigeon problem in front entrance of building by the office thank you				Please install same screen as of Riverside as per Memo			
Vanessa Davila									
Count: 13 Work Orders		Avg. Age of WO's		83	Total for Sunland Park ES			0	\$853.63

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
255867	Main Building	Classroom			1/6/2022		39		\$0.00
Medium	Work In Progress			1/6/2022 3:26:15 PM					
Acuna, Johnny	Please mount New line board TV into Mrs. Williams office								
Joanna Rodriguez									
250571	Main Building	Exterior			9/1/2021		166		\$1,299.70
Medium	Work In Progress			9/1/2021 8:17:15 AM					
Acuna, Johnny	Pavilion poles need to be cleaned, premiered, and painted. They are rusting at the base. Spray for ants					Paint on order.			
Joanna Rodriguez									
247845	Main Building	Classroom			7/23/2021		206		\$0.00
Medium	Work In Progress			7/23/2021 9:11:43 AM					
Acuna, Johnny	As per Mrs. Williams she would like to change the room number that is currently labled as Resource to room 300					On Order			
Joanna Rodriguez									
255849	Main Building	Classroom			1/6/2022		39		\$0.00
Medium	Work In Progress			1/6/2022 11:21:21 AM					
Marquez, Gerardo	Will need locks replacement in the conference room cabinets closet.								
Joanna Rodriguez									
250947	Main Building	Classroom			9/8/2021		159		\$0.00
Medium	Work In Progress	Resourse		9/8/2021 7:48:23 AM					
Marquez, Gerardo	Please change name of room called "Resouce" to room 300. Thank You!								
Joanna Rodriguez									
252962		Kitchen			10/19/2021		118		\$0.00
High	Work In Progress			10/19/2021 7:37:30 AM					
Hernandez, Guillermo	Water sprinklers in chemical room are leaking								
Dino Facio									
256391	Main Building	Classroom			1/20/2022		25		\$212.89
Medium	Work In Progress	307, Sol WR		1/20/2022 11:19:18 AM					
Ambriz, Jose	Sol Work room office is too cold, and room 307 is super cold as well can you please adjust the temperature 70 degrees. Thank You								
Joanna Rodriguez									

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
Location: Sunrise ES										
256739	Main Building	Classroom			1/28/2022		17		\$0.00	
Medium	Work In Progress	305			1/28/2022 9:44:48 AM					
Ambriz, Jose		The temperature in the classroom is off. For the last couple of days, the fan stays on all day long just blowing out air. This does not have anything to do with the exhaust fan because when I turn off there is air coming out of the vents which is not warm enough to be enjoyable								
Joanna Rodriguez										
251216		Classroom			9/13/2021		154		\$369.00	
Medium	Work In Progress	Resource			9/13/2021 1:25:51 PM					
Ambriz, Jose		Counselor's office is very hot, seems like the heater is on Room # Resource								
Joanna Rodriguez										
Count: 9 Work Orders		Avg. Age of WO's 103			Total for Sunrise ES			0	\$1,881.59	

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
Location: Support Services										
255834					1/6/2022		39		\$0.00	
Medium	Work In Progress	support services			1/6/2022 8:54:42 AM					
Ambriz, Jose		I am going to need a space heater for now, the unit in my office is not working. Thank You!								
Lisa Sanchez										
256485		Office			1/24/2022		21		\$0.00	
Medium	Work In Progress	301			1/24/2022 9:10:08 AM					
Ambriz, Jose		Heating/ac unit is rattling loudly when turned on.								
Sylvia Gaeta										
248091		Office			7/28/2021		201		\$0.00	
Medium	Work In Progress				7/28/2021 8:58:32 AM					
Ambriz, Jose		good morning, there is an like oily substance coming out of my ac unit on the wall....would greatly appreciate assistance in this matter... thank you....								
Loraine Gandara										
253664		Portables			11/2/2021		104		\$0.00	
Medium	Work In Progress	athletics			11/2/2021 2:50:23 PM					
Ambriz, Jose		Need to replace a 3 ton package unit.								
Jose Ambriz										
Count: 4 Work Orders		Avg. Age of WO's 91		Total for Support Services			0	\$0.00		

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Vado ES									
256433		Classroom			1/21/2022		24		\$0.00
Medium	Work In Progress				1/21/2022 7:54:30 AM				
Ambriz, Jose		Need to check room 100 not heating.							
Jose Ambriz									
256393	Main Building	Custodial			1/20/2022		25		\$0.00
Medium	Work In Progress				1/20/2022 11:27:37 AM				
Ambriz, Jose		Water fountain in 200 hallway is not working !							
Armando Diaz									
256236	Main Building	Hallway/Corridor			1/14/2022		31		\$0.00
Medium	Work In Progress	Hallway by			1/14/2022 7:49:16 AM				
Tellez, Hector		Need to replace ballast on fluorescent light fixture and parking light need to be fix/replace							
Sylvia Cary									
256455	Main Building	Hallway/Corridor			1/21/2022		24		\$20.94
Medium	Work In Progress	Hallway by			1/21/2022 11:07:22 AM				
Tellez, Hector		Light be the ladies restroom by the main office still not working, parking lights aren't working either. Please come before 12:00 pm so main custodian can show you which lights							
Sylvia Cary									
254638	Main Building	Classroom			12/2/2021		74		\$0.00
Medium	Work In Progress				12/2/2021 7:54:55 AM				
Marquez, Gerardo		Principal request 2 chains one 18' and the other 15' for outside tables !							
Armando Diaz									
Count: 5 Work Orders		Avg. Age of WO's 36		Total for Vado ES		0		\$20.94	

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Yucca Heights ES									
254457					11/29/2021		77		\$0.00
Medium	Work In Progress				11/29/2021 10:37:33				
Marquez, Gerardo		Doors that go to playground area are missing the trim. They also need to be adjusted they slam when they close				Transfer to locksmith			
Rocio Rodriguez									
253245		Parking Lot			10/27/2021		110		\$0.00
Medium	Work In Progress				10/27/2021 5:41:58 AM				
Marquez, Gerardo		Need to lubricate all locks at front gates. Thank you!							
Ernesto Diaz									
254068					11/12/2021		94		\$0.00
Medium	Work In Progress				11/12/2021 9:04:54 AM				
Marquez, Gerardo		Need to check Keys from Yucca Elementary.							
248071		Restroom (Girls)			7/28/2021		201		\$0.00
Medium	Work In Progress				7/28/2021 6:40:39 AM				
Acuna, Johnny		We need some screws for the restroom stalls for the door latches. Johnny Acuna has sample.				On order			
Ernesto Diaz									
248125		Exterior			7/28/2021		201		\$0.00
Medium	Work In Progress				7/28/2021 2:04:56 PM				
Vasquez, Jose		Asper Mrs. Pargas, we need wood chips in the play ground, please				Transfer to Grounds Dept.			
Ernesto Diaz									
252859					10/15/2021		122		\$0.00
Medium	Work In Progress	Playground			10/15/2021 1:33:02 PM				
Vasquez, Jose		Please remove cement footing in playground area. There is an orange cone on top of cement.							
Johnny Acuna									
252860					10/15/2021		122		\$0.00
Medium	Work In Progress	Playground			10/15/2021 1:35:26 PM				
Vasquez, Jose		Need to fill in playground area with more wood chips.							
Johnny Acuna									
255903					1/7/2022		38		\$0.00
Medium	Work In Progress				1/7/2022 1:25:11 PM				
Acuna, Johnny		Need new blinds for portable 402 & 403							
Rocio Rodriguez									

279 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2021 - 1/31/2022 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
Location: Yucca Heights ES										
255904					1/7/2022		38		\$0.00	
Medium	Work In Progress				1/7/2022 1:51:57 PM					
Acuna, Johnny		Need blinds for school entrance area.								
Rocio Rodriguez										
255919		Mechanical			1/7/2022		38		\$0.00	
Medium	Work In Progress				1/7/2022 3:42:44 PM					
Moreno, Mario		Emergency lighting back up inverter batteries in west penthouse bad. Need to replace batteries.								
Mario Moreno										
256079					1/11/2022		34		\$0.00	
Medium	Work In Progress				1/11/2022 11:23:45 AM					
Vasquez, Jose		Need 2 big soccer goals for the field and the lining of the soccer field				Transfer to Grounds Dept.				
Rocio Rodriguez										
254458					11/29/2021		77		\$0.00	
Medium	Work In Progress				11/29/2021 10:39:32					
Vasquez, Jose		Need playground area and front palm tree to get trim.								
Rocio Rodriguez										
255832		Classroom			1/6/2022		39		\$630.00	
Medium	Work In Progress	Room 203			1/6/2022 8:30:21 AM					
Ambriz, Jose		Need to replace expansion valve.								
Jose Ambriz										
Count: 13 Work Orders		Avg. Age of WO's 92		Total for Yucca Heights ES				0	\$630.00	
Count: 279 Work Orders		Avg. Age of WO's 89		Grand Total				63.3000000	\$18,427.55	