

PHYSICAL PLANT SPECIAL PROJECTS/REQUESTS
(Revised 3/13/2023)

Site	WO#	Project Description	Estimated Completion Date	
CHS	277165	Exterior	Need to replace backflow for potable water.	4/15/2023
District Wid	271241	Exterior	Backflow Repairs	4/1/2023
District Wid	270358	Interior	Fire Sprinkler Repairs	Complete
DV	277348	Exterior	Install 4" By Pass at water tank working on the weekend.	Complete
DV	276774	Interior	Need to replace faulty valves, rusted water shutoff and gauges in boiler room.	4/15/2023
GAC	242117	Interior	Finance Dept - Paint offices and hallway.	4/5/2023
GAC	272954	Exterior	Reinforce and paint wooden fence by ramp and Pre-K.	Complete
GAC	277170	Interior	Fire sprinkler repairs as per Fire marshal inspection.	6/15/2023
GE	275997	Exterior	Installation of new playground (Train Toy)	Complete
GES	275609	Exterior	Parking and drop-offs, crack seal, seal coat and striping	5/15/2023
GHS	267150	Exterior	Need to replace failing pump head to fire pump	3/15/2023
GHS	276549	Exterior	Varsity Gym Roof - wind damage.	4/15/2023
LM PRE-K	277166	Exterior	Need to prune trees. Safety concern trees to tall and touching power line.	4/15/2023
NV	275608	Exterior	Bus and parent drop-off, crack seal, seal coat and striping	5/15/2023
NV	275995	Exterior	Removal and installation of new playgrounds 1 & 2.	5/10/2023
PPD	271243	Interior	HVAC Shop - Mildew remediation	4/15/2023
PPD	273690	Interior	Need to install window to doors in the auto shop	5/10/2023
PPD	276773	Interior	Need to patch and paint walls in construction department.	4/15/2023
PPD	277307	Interior	Need to remove and replace the two windows facing west of the building.	5/10/2023
RE	275607	Exterior	Rockwall repair and privacy gates	5/15/2023
RE	275605	Exterior	Install front block wall and chain link fence	5/15/2023
RE	275611	Exterior	Main Parking and drop-offs, crack seal, seal coat and striping	5/15/2023
RS	275994	Exterior	Removal and installation of new playgrounds 1 & 2.	5/10/2023
SR	275996	Exterior	Removal and installation of new playground 1.	Complete
STE	275166	Exterior	The kitchen grease trap need to be replaced do to corrosion at STE .	4/15/2023
STH	271312	Interior	Fixtures in Cafeteria need to be replaced, several are not working	6/10/2023
VE	275613	Exterior	Main Parking and drop-offs, crack seal, seal coat and striping	5/15/2023
VE	275606	Exterior	Basketball courts replacement	5/15/2023
YE	276427	Interior	Several lights out throughout the school	6/10/2023
YHE	264993	Exterior	Relocation of portable from DTE to YHE	4/15/2023
YHE	267465	Exterior	Need to install playground bouncing toys	5/15/2023