

PHYSICAL PLANT SPECIAL PROJECTS/REQUESTS
(Revised 4/18/2023)

Site	WO#	Project Description	Estimated Completion Date	
CE	278688	Exterior	Fence is broken and falling. It is about to come down. Please fix asap. Where the Roadrunner sign is located. See front office	Complete
CHS	277165	Exterior	Need to replace backflow for potable water.	Complete
CHS	277521	Exterior	Need to repair damaged chain link fence. Fence damaged by student and reported by principal.	6/15/2023
District Wide	270358	Interior	Fire Sprinkler Repairs	Complete
District Wide	271241	Exterior	Backflow Repairs	Complete
DV	276774	Interior	Need to replace faulty valves, rusted water shutoff and gauges in boiler room.	5/30/2023
DV	277348	Exterior	Install 4" By Pass at water tank working on the weekend.	Complete
DV	278949	Exterior	Relocate portable from Sunland Park to Desert View Elementary.	6/15/2023
GAC	242117	Interior	Finance Dept - Paint offices and hallway.	5/30/2023
GAC	272954	Exterior	Reinforce and paint wooden fence by ramp and Pre-K.	Complete
GAC	277170	Interior	Fire sprinkler repairs as per Fire marshal inspection.	Complete
GAC	278166	Exterior	Replacement of playground equipment 1.	6/15/2023
GE	275609	Exterior	Parking and drop-offs, crack seal, seal coat and striping	Complete
GE	275997	Exterior	Installation of new playground (Train Toy)	Complete
GE	278168	Exterior	Replacement of playground equipment (two total)	6/15/2023
GHS	267150	Exterior	Need to replace failing pump head to fire pump	6/30/2023
GHS	276549	Exterior	Varsity Gym Roof - wind damage.	Complete
LM PRE-K	261905	Interior	Floor tiles in Rm 114 (daycare) are lifting.	6/15/2023
LM PRE-K	277166	Exterior	Need to prune trees. Safety concern trees too tall and touching power line.	Complete
LM PRE-K	278167	Exterior	Replacement of playground equipment.	6/15/2023
NV	275608	Exterior	Bus and parent drop-off, crack seal, seal coat and striping	Complete
NV	275995	Exterior	Removal and installation of new playgrounds 1 & 2.	5/10/2023
PPD	271243	Interior	HVAC Shop - Mildew remediation	Complete
PPD	273690	Interior	Need to install window to doors in the auto shop	5/10/2023
PPD	273690	Interior	Requesting a (1) mirrored glass door for Supervisor office (door facing auto shop) and add (1) window mirrored to door facing the hallway.	6/15/2023
PPD	276773	Interior	Need to patch and paint walls in construction department.	Complete
PPD	277307	Interior	Need to remove and replace the two windows facing west of the building.	6/15/2023
PPD	278195	Exterior	PPD warehouse metal awning above main roll up deliver doors	6/15/2023
RE	275605	Exterior	Install front block wall and chain link fence.	5/15/2023
RE	275607	Exterior	Rockwall repair and privacy gates	5/15/2023
RE	275611	Exterior	Main Parking and drop-offs, crack seal, seal coat and striping	5/15/2023
RE	275994	Exterior	Removal and installation of new playgrounds 1 & 2.	5/10/2023
RE	277677	Exterior	The rock walls along the walkway towards the school entrance need to be maintained and replaster with concrete.	6/15/2023
SNP	278841	Exterior	Add chain link fence (south side) to enclose the entire SNP Complex grounds	6/15/2023
SNP	278946	Exterior	Need to install chain link fence at SNP on the open area.	6/15/2023
SR	275996	Exterior	Removal and installation of new playground.	Complete

PHYSICAL PLANT SPECIAL PROJECTS/REQUESTS
 (Revised 4/18/2023)

Site	WO#	Project Description	Estimated Completion Date	
STE	275166	Exterior	The kitchen grease trap needs to be replaced due to corrosion.	Complete
STE	277890	Interior	Room 303's exit door has water damage on door and floor.	6/15/2023
STH	271312	Interior	Light fixtures in Cafeteria need to be replaced, several are not working	6/15/2023
VE	258856	Interior	The laminate on the counter top in front office is peeling off and laminate is in a bad shape.	6/15/2023
VE	275606	Exterior	Basketball courts replacement	Complete
VE	275613	Exterior	Main Parking and drop-offs, crack seal, seal coat and striping	Complete
VE	277804	Exterior	Installation of a 4-foot chain link fence in the area outlined in email photo.	Complete
VE	278196	Exterior	Demo existing damage concrete and disposal.	Complete
VE	278951	Exterior	Relocate portable from RTC to Vado Elementary.	6/15/2023
YHE	264993	Exterior	Relocation of portable from DTE to YHE	5/30/2023
YHE	267465	Exterior	Need to install playground components.	Complete
YHE	276427	Interior	Several lights out throughout the school	6/10/2023