

PHYSICAL PLANT SPECIAL PROJECTS/REQUESTS
(Revised 5/17/2023)

Site	WO#	Interior/Exterior	Description	Estimated
CHS	277521	Exterior	Need to repair damaged chain link fence. Fence damaged by student and reported by principal.	Complete
DV	276774	Interior	Need to replace faulty valves, rusted water shutoff and gauges in boiler room.	6/15/2023
DV	278949	Exterior	Relocate portable from Sunland Park to Desert View Elementary.	6/20/2023
GAC	242117	Interior	Finance Dept - Paint offices and hallway.	Complete
GAC	278166	Exterior	Replacement of playground equipment 1.	6/15/2023
GE	278168	Exterior	Replacement of playground equipment (two total)	6/15/2023
GE	280361	Exterior	Basketball Courts striping and repairs	6/30/2023
GHS	267150	Exterior	Need to replace failing pump head to fire pump	6/30/2023
GHS	276549	Exterior	Varsity Gym Roof - wind damage.	Complete
LM PRE-K	261905	Interior	Floor tiles in Rm 114 (daycare) are lifting.	6/15/2023
LM PRE-K	278167	Exterior	Replacement of playground equipment.	6/15/2023
NV	275995	Exterior	Removal and installation of new playgrounds 1 & 2.	6/20/2023
PPD	273690	Interior	Requesting a (1) mirrored glass door for Supervisor office (door facing auto shop) and add (1) window mirrored to door facing the hallway.	Complete
PPD	277307	Interior	Need to remove and replace the two windows facing west of the building.	6/15/2023
PPD	278195	Exterior	PPD warehouse metal awning above main roll up deliver doors	6/15/2023
RE	275605	Exterior	Install front block wall and chain link fence.	6/20/2023
RE	275607	Exterior	Rockwall repair and privacy gates	6/20/2023
RE	275611	Exterior	Main Parking and drop-offs, crack seal, seal coat and striping	Complete
RE	275994	Exterior	Removal and installation of new playgrounds 1 & 2.	Complete
RE	277677	Exterior	The rock walls along the walkway towards the school entrance need to be maintained and replaster with concrete.	6/15/2023
RE	279391	Interior	Patch walls, paint and replace flooring in double portable	6/30/2023
RE	279736	Interior	Portable 3 renovations - paint walls and remove carpet and replace with linoleum part of	6/30/2023
SNP	278946	Exterior	Need to install chain link fence at SNP on the open area.	6/15/2023
STE	277890	Interior	Room 303's exit door has water damage on door and floor.	Complete
STH	271312	Interior	Light fixtures in Cafeteria need to be replaced, several are not working	Complete
VE	258856	Interior	The laminate on the counter top in front office is peeling off and laminate is in a bad shape.	6/15/2023
VE	278951	Exterior	Relocate portable from RTC to Vado Elementary.	6/15/2023
YHE	264993	Exterior	Relocation of portable from DTE to YHE	Complete
YHE	276427	Interior	Several lights out throughout the school	Complete