

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Alta Vista ECHS</b>							
297806					4/24/2024		20		\$0.00
Medium	Work In Progress	parking lot			4/24/2024 9:02:44 AM				
Hernandez, Carlos		Repaint the parking lot lines before the end of the SY. Please see Principal De La Garza before painting any arrows.							
Melanie Beegle									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>20</b>	<b>Total for Alta Vista ECHS</b>			<b>0</b>	<b>\$0.00</b>

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Anthony - On Track Pre-K (Village)</b>									
291124		Classroom			12/4/2023		162		\$0.00
Medium	Work In Progress	109			12/4/2023 2:26:31 PM				
Tellez, Hector		classroom needs more outlets. Please see teacher Ms. Daisy for more information							
Michelle Soto									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>162</b>	<b>Total for Anthony - On Track Pre-K (Village)</b>				<b>0</b>	<b>\$0.00</b>

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Anthony ES</b>									
294512					2/19/2024		85	\$58.25	
Medium	Work In Progress				2/19/2024 11:27:03 AM				
Tellez, Hector		Building: Library Description: Please install 4 Electrical outlets alongside the closet wall. (see Ms. Avalos for exact location) thank you							
Jessica Lopez									
297439					4/17/2024		27	\$0.00	
Medium	Work In Progress				4/17/2024 7:32:20 AM				
Carbajal, Jimmy		Please replace cracked tiles in the cafeteria as soon as possible (see Chemo or office for more information) thank you				as per memo reroute to jimmy			
Jessica Lopez									
297461					4/17/2024		27	\$0.00	
Medium	Work In Progress				4/17/2024 8:20:25 AM				
Tellez, Hector		As per Ms. Lopez (principal) please install hand dryers in all the restrooms thank you							
Jessica Lopez									
297697					4/22/2024		22	\$0.00	
Medium	Work In Progress	224			4/22/2024 3:14:15 PM				
Ruiz, Danny		As per Ms. Lopez, Mirror tint window needed for our new IEP room rom #224 thank you							
Jessica Lopez									
<b>Count: 4 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>40</b>		<b>Total for Anthony ES</b>	<b>0</b>	<b>\$58.25</b>	

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral ES</b>									
298120	Main Building	Office			4/30/2024		14		\$0.00
Medium	Work In Progress	Office			4/30/2024 7:36:19 AM				
Flores, Antonio		Hello, the lights in the middle of the office don't have a switch for us to turn off and due to safety issues when we had a lockdown we are requesting one.							
		Thank you for all your help!							
		Micaela							
Micaela Paniagua									
298122	Main Building	Classroom			4/30/2024		14		\$0.00
Medium	Work In Progress	331			4/30/2024 7:41:44 AM				
Cangas, Kevin		The water in room 331 is too hot according to Ms. Sang & she is afraid the students will get burnt.							
		Thanks for all your help!							
Micaela Paniagua									
289310					10/26/2023		201		\$6.90
Medium	Work In Progress				10/26/2023 8:19:26 AM				
Vela, Nancy		CE need fix roof for warranty. TPO on 321 room area							
Juan Vargas									
295936					3/20/2024		55		\$0.00
Medium	Work In Progress	100A & 100F			3/20/2024 8:41:02 AM				
Flores, Antonio		Please adjust the sensor for both of these lights. The one in my office shuts off automatically within a short period of time even when I'm in the office and the one in the vault never turns off automatically.							
Micaela Paniagua									
<b>Count: 4 Work Orders</b>		<b>Avg. Age of WO's 71</b>			<b>Total for Chaparral ES</b>			<b>0</b>	<b>\$6.90</b>

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral HS</b>									
296094		Athletic Field			3/22/2024		53		\$0.00
Medium	Work In Progress	Softball field			3/22/2024 1:49:15 PM				
Flores, Antonio		Need electrical outlets place inside the dugout to meet NMAA guidelines(to run PA system to announce require sportmanship creed, and to run score board.							
Eli Barrios									
296095		Athletic Field			3/22/2024		53		\$0.00
Medium	Work In Progress	Baseball field			3/22/2024 1:50:42 PM				
Flores, Antonio		Need electrical outlets place inside the dugout to meet NMAA guidelines(to run PA system to announce require sportmanship creed, and to run score board. See Mr Martinez for further details							
Eli Barrios									
297101					4/10/2024		34		\$0.00
Medium	Work In Progress				4/10/2024 9:36:04 AM				
Duenas, Jose		Need scraping front and back school							
Juan Vargas									
284788	Field House	Athletic Field			8/7/2023		281		\$0.00
Medium	Work In Progress	Baseball field			8/7/2023 9:52:49 AM				
Duenas, Jose		Baseball Field needs a flag pole and pitching mound needs dirt. (coach Soria)				Asp report 10/16/23 -Waiting on pole to arrive			
Mireya Meza									
292724					1/16/2024		119		\$29.23
Medium	Work In Progress				1/16/2024 2:54:54 PM				
Duenas, Jose		Flowerbeds to be cleaned and resurface.				Re-route to Jose. Heavy equipment team will do the work.			
Guillermo Hernandez									
289304					10/26/2023		201		\$23.88
Medium	Work In Progress				10/26/2023 7:55:28 AM				
Avila, Jesus		Need extended. Metal canopy nex to Morgan storage							
Juan Vargas									
297754		Restroom (Girls)			4/23/2024		21		\$251.00
Medium	Work In Progress	main office			4/23/2024 12:20:26 PM				
Cangas, Kevin		The faucet in the main office ladies restroom leaks when the valve is pushed down to open water.							
Christina Nares									

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
297873	A-Wing	Gym			4/25/2024		19		\$0.00
Medium	Work In Progress	Weight Room			4/25/2024 8:15:45 AM				
Vargas, Juan		weightlifting machines needs screws. Please see Coach Yturalde for further detail. (Coach Yturalde, Weight Room)							
Eli Barrios									
<b>Count: 8 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>98</b>	<b>Total for Chaparral HS</b>			<b>0</b>	<b>\$304.11</b>

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
297826		Restroom			4/24/2024		20		\$0.00
Medium	Work In Progress			4/24/2024 12:09:49 PM					
Vargas, Juan	El bano de los Maestros. el Exhaust Fan no prende por favor de revisarlo ,Pasillo 300 Gracias								
Laura Sandoval									
297828		Classroom			4/24/2024		20		\$152.44
Medium	Work In Progress			4/24/2024 12:19:59 PM					
Vargas, Juan	En la clase 208 se necesita pintar la pared donde se taparon oyos por favor gracias								
Laura Sandoval									
297833		Custodial			4/24/2024		20		\$0.00
Medium	Work In Progress			4/24/2024 12:46:32 PM					
Vargas, Juan	El Exhaust Fan dela oficina custodial no prende por favor de revisarlo gracias				5/9/24 - As per Juan, waiting on motors				
Laura Sandoval									
297970	Main Building	Classroom			4/26/2024		18		\$0.00
Medium	Work In Progress	202		4/26/2024 11:46:00 AM					
Vargas, Juan	Classroom 202 in the 200 hallways has about 6 pieces of broken vct tile broken, need to be replaced.								
David Hinojosa									
297978		Gym			4/26/2024		18		\$0.00
Medium	Work In Progress			4/26/2024 1:10:56 PM					
Vargas, Juan	En la entrada de Locker Room Boys hay 4 tile quebrados y se pueden trompesar por favor de revisarlos gracias								
Laura Sandoval									
297918		Classroom			4/25/2024		19		\$0.00
Medium	Work In Progress			4/25/2024 3:10:27 PM					
Vargas, Juan	La clase 202 se nesesita remplazar algunos tile del piso por favor gracias								
Laura Sandoval									
297582	Main Building	Classroom			4/18/2024		26		\$1,505.70
Medium	Work In Progress			4/18/2024 3:26:56 PM					
Ambriz, Jose	Need to installed t-stat plastic covers to new mini ductless remote sensors.								
Jose Ambriz									

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Chaparral MS</b>									
297540					4/18/2024		22	6.5	\$162.50
Medium	Work In Progress			4/18/2024 8:35:27 AM	5/10/2024				
Duenas, Jose	Pleaser pick up 7 wrestling mats from the warehouse on May 10 and deliver to Chaparral MS, see Maria Garcia at CMS for placement.		pick up mats from warehouse and deliver to C.M.S cafeteria						
	Thank you								
Priscilla Guterrez									
293458					2/1/2024		103		\$0.00
Medium	Work In Progress			2/1/2024 7:51:15 AM					
Vasquez, Jose	Need paint softball. And baseball. Fields								
Juan Vargas									
293471	Main Building	Classroom			2/1/2024		103		\$0.00
Medium	Work In Progress			2/1/2024 9:37:25 AM					
Flores, Antonio	Need to run electrical to the new 2 ton ductless units in all classrooms for CMS, Thank you								
Jose Ambriz									
297379	Main Building	Gym			4/16/2024		28		\$107.53
Medium	Work In Progress	GYM		4/16/2024 10:07:56 AM					
Vargas, Juan	4 fire extinguishers are missing covers in the gym								
Maria Garcia-Castillo									
<b>Count: 11 Work Orders</b>			<b>Avg. Age of WO's</b>		<b>36</b>	<b>Total for Chaparral MS</b>		<b>6.5</b>	<b>\$1,928.17</b>



# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>Desert Pride HS</b>							
297146					4/10/2024		34		\$0.00
Medium	Work In Progress				4/10/2024 4:20:16 PM				
Vasquez, Jose	Need to add rock to the lands scape around DP.								
Guillermo Hernandez									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>34</b>	<b>Total for Desert Pride HS</b>				<b>0</b>	<b>\$0.00</b>

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert Trail ES</b>									
297389		Classroom			4/16/2024		28		\$40.42
Medium	Work In Progress				4/16/2024 12:22:51 PM				
Cangas, Kevin		Classroom sink leaks room #307							
Ernesto Diaz									
297390		Classroom			4/16/2024		28		\$0.00
Medium	Work In Progress				4/16/2024 12:26:20 PM				
Cangas, Kevin		There is a water leak in the sink of room#202.							
Ernesto Diaz									
297893		Restroom			4/25/2024		19		\$0.00
Medium	Work In Progress				4/25/2024 11:32:43 AM				
Vargas, Juan		Se necesita Reemplazar moldura de la ventana del bano de los Boys del pasillo 200 es para una inspeccion por favor gracias							
Laura Sandoval									
<b>Count: 3 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>25</b>		<b>Total for Desert Trail ES</b>	<b>0</b>		<b>\$40.42</b>

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
298100					4/30/2024		14		\$0.00
Medium	Work In Progress			4/30/2024 1:15:15 AM					
Flores, Pete	Monthly - Desert View ES - Mower M-DV-0522 - Refer to PM schedule details.								
Margret Villalobos									
298101					4/30/2024		14		\$0.00
Medium	Work In Progress			4/30/2024 1:15:15 AM					
Flores, Pete	Monthly - Desert View ES - Mower M-DV-0438 - Refer to PM schedule details.								
Margret Villalobos									
296019		Exterior			3/21/2024		54		\$0.00
Medium	Work In Progress			3/21/2024 11:07:50 AM					
Saenz, Daniel	There are some exterior lights that are staying ON all the day.								
Israel Ortega									
294476					2/19/2024		85		\$2,412.50
Medium	Work In Progress			2/19/2024 12:34:09 AM					
Carrasco, Danny	Monthly - Desert View ES - Quarterly Filter Change - Refer to PM schedule details.								
Margret Villalobos									
<b>Count: 4 Work Orders</b>		<b>Avg. Age of WO's 42</b>			<b>Total for Desert View ES</b>			<b>0</b>	<b>\$2,412.50</b>

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>GAC</b>							
295654					3/12/2024		63		\$0.00
Medium	Work In Progress	IT room			3/12/2024 8:48:46 AM				
Ambriz, Jose		BGAco. is doing the replacement on the blower motor and the labor to.				motor lead time from factory of 8-10 weeks			
Jose Ambriz									
298057		Office			4/29/2024		15		\$79.00
Medium	Work In Progress	C-wing round			4/29/2024 3:00:33 PM				
Saenz, Daniel		Need to run electrical power supply to 2 mirage ductless in C-wing round center office, 200 office, Thank you							
Jose Ambriz									
297986		Custodial			4/26/2024		18		\$0.00
Medium	Work In Progress				4/26/2024 2:27:27 PM				
Herrera, Marin		Buenas Tardes Solicito Door stops de metal para las puertas. Tengo varias que no funcionan adecuadamente. (6)							
Yolanda Martinez									
<b>Count: 3 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>32</b>		<b>Total for GAC</b>		<b>0</b>	<b>\$79.00</b>

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>GAC - Pre-K</b>							
297814		Exterior			4/24/2024		20		\$0.00
Medium	Work In Progress				4/24/2024 9:42:52 AM				
Villalobos, Margret		Our playground toys (little houses, toy box) have spiders under them.				4/24 Approved and EM Lorraine			
Christina Zamora									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>20</b>			<b>Total for GAC - Pre-K</b>	<b>0</b>		<b>\$0.00</b>

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden ES</b>							
297661					4/22/2024		22		\$0.00
Medium	Work In Progress			4/22/2024 12:45:17 AM					
Flores, Pete	Monthly - Gadsden ES - Mower M-GES-0433 - Refer to PM schedule details.								
Margret Villalobos									
294898		Classroom			2/27/2024		77		\$0.00
Medium	Work In Progress	206		2/27/2024 12:27:49 PM					
Tellez, Hector	There is another light in my classroom that seems like it is going out. room 206								
Patty Madrid									
295927		Classroom			3/20/2024		55		\$0.00
Medium	Work In Progress			3/20/2024 7:09:20 AM					
Tellez, Hector	I have a light out in my room (302) that needs to be changed. Please assist. Thank you!		reroute to electrician.						
Patty Madrid									
294639		Classroom			2/21/2024		83		\$0.00
Medium	Work In Progress	206		2/21/2024 8:17:03 AM					
Tellez, Hector	I wanted to see if I could place a work order for the light in my classroom. This particular light has been out, despite all the others being on. room 206								
Patty Madrid									
<b>Count: 4 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>59</b>	<b>Total for Gadsden ES</b>			<b>0</b>	<b>\$0.00</b>

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Gadsden HS

294169	Varsity Gym				2/12/2024		92		\$4.30
--------	-------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Boys Baseball			2/12/2024 8:59:46 AM				
--------	------------------	---------------	--	--	----------------------	--	--	--	--

Hernandez, Carlos Requested per Ms. Perry, the lockers in the BOYS BASEBALL LOCKER RM located in the VARSITY GYM need to be repaired. Photos are attached. They seem to be broken and cannot be locked. ordered handles

Laura Gomez

291496		Exterior			12/12/2023		154		\$0.00
--------	--	----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	Various Areas			12/12/2023 9:36:19 AM				
--------	------------------	---------------	--	--	-----------------------	--	--	--	--

Tellez, Hector Outside building lights need to be replaced in-between CTE and Admin building. Currently none of them are working. Large outdoor light just in front of the entrance to cafeteria is out, needs to be replaced. Lights on shed of the entrance to CTE building, some of the lights need to be replaced, thank you.

Laura Gomez

292164	Business	Classroom			1/5/2024		130		\$0.00
--------	----------	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	619			1/5/2024 3:30:21 PM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Ruiz, Danny Requested per Ms. Perry/Ms. Hernandez, the blinds in CLASSROOM #619 located in the SCIENCE BLDG., are broken and need to be replaced, thank you. reroute to danny ruiz

Laura Gomez

289274	Business	Classroom			10/25/2023		202		\$0.00
--------	----------	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	600			10/25/2023 1:27:41 PM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Pacheco, Hector Requested per Ms. Favela, she has stated that there are several of the sinks in her classroom leaking along with some faucets. She is located in the SCIENCE BLDG (BUSINESS BLDG) ROOM #600. Can this please get repaired as soon as possible, thank you.

Laura Gomez

290238					11/13/2023		183		\$0.00
--------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/13/2023 7:35:37 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Tellez, Hector pole was hit check for integrity

Hector Tellez

295362					3/4/2024		71		\$0.00
--------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/4/2024 3:45:14 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Tellez, Hector need to order a GFCI drop receptacle box for auto shop at GHS shop

Hector Tellez

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

295527	North Building	Restroom			3/7/2024		68		\$0.00
--------	----------------	----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	204B			3/7/2024 9:54:54 AM				
--------	------------------	------	--	--	---------------------	--	--	--	--

Hernandez, Carlos Requested per Mr. Lugo, the BATHROOM STALL DOOR in the BOYS RESTROOM 204B located in the NORTH BLDG., is bent. Can this possibly be looked and and replaced, thank you. Photo had been attached.

Laura Gomez

297017	North Building	Kitchen			4/8/2024		36		\$33.18
--------	----------------	---------	--	--	----------	--	----	--	---------

Medium	Work In Progress	208			4/8/2024 3:01:58 PM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Ambriz, Jose Requested per Ms. Aragon, the FRIDGE the was repaired in her kitchen CLASSROOM #208 located in the NORTH BLDG., is making a LOUD NOISE again and needs to be looked at please, if there is any questions please get in contact with Ms. Aragon, thank you.

Laura Gomez

297709					4/23/2024		21		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/23/2024 12:46:22 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Flores, Pete Monthly - Gadsden HS - Mower M-GHS-0436 - Refer to PM schedule details.

Margret Villalobos

297369	Vocational	Kitchen			4/16/2024		28		\$0.00
--------	------------	---------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	517			4/16/2024 9:01:37 AM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Pacheco, Hector Requested per Frank Marin, the GARBAGE DISPOSAL located in KITCHEN #517 in the CTE/VOCATIONAL BLDG., does not seem to be working, if this can please be looked at and repaired, it would be greatly appreciated, thank you.

Laura Gomez

298029	North Building	Restroom			4/29/2024		15		\$0.00
--------	----------------	----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	216			4/29/2024 8:56:45 AM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Cangas, Kevin Requested per Mr. Lugo, the TOILET and FAUCET located in the BOYS RESTROOM #216 in the NORTH BDLG., is leaking water (photo attached), if this can please be looked at and repaired as soon as possible, thank you.

Laura Gomez



# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden HS</b>									
298036	Main Building				4/29/2024		15		\$0.00
Medium	Work In Progress				4/29/2024 10:27:23 AM				
Cangas, Kevin		Requested per Frank Marin, there are TWO (2) WATER FOUNTAINS located in the OLD MAIN BLDG. do not have any water, if these can please be looked at and repaired, thank you.							
Laura Gomez									
298051					4/29/2024		15		\$0.00
Medium	Work In Progress				4/29/2024 1:27:47 PM				
Tellez, Hector		computer tech portable 151 needs to have led lights and electrical outlet moved.							
		Please see Adrian or Jose							
Cora Ramirez									
298167	North Building	Restroom			4/30/2024		14		\$0.00
Medium	Work In Progress	216M			4/30/2024 2:50:59 PM				
Pacheco, Hector		Requested per Frank Marin, the TOILET and SPOUT in the BOYS RESTROOM #216M located in the NORTH BLDG., does not turn off and when flushed is starts to drip, there currently is bucket being kept their to catch the water. If this can please be looked at and repaired, thank you.							
Laura Gomez									
<b>Count: 14 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>75</b>	<b>Total for Gadsden HS</b>			<b>0</b>	<b>\$37.48</b>

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Gadsden MS</b>							
296894		Kitchen			4/5/2024		39	\$37.48	
High	Work In Progress				4/5/2024 1:33:30 PM				
Cangas, Kevin		Toilet in kitchen area keeps leaking water							
Dino Facio									
296895		Kitchen			4/5/2024		39	\$6.82	
High	Work In Progress				4/5/2024 1:34:53 PM				
Cangas, Kevin		Water valve between three compartment sink and hand sink is leaking							
Dino Facio									
<b>Count: 2 Work Orders</b>		<b>Avg. Age of WO's</b>			<b>39</b>	<b>Total for Gadsden MS</b>		<b>0</b>	<b>\$44.30</b>

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: La Union ES</b>									
296985		Athletic Field			4/8/2024		36		\$0.00
Medium	Work In Progress				4/8/2024 7:53:54 AM				
Herrera, Marin		Woudl you please aerate and fertilize the field				4/10/24 - Asp Memo, route back to Marin			
Jose Vasquez									
297305					4/15/2024		29		\$0.00
Medium	Work In Progress				4/15/2024 9:36:04 AM				
Ruiz, Danny		Need (2) blinds 66.5in w X 40in L tan color please they are for the nurses office							
Marin Herrera									
296081	Main Building				3/22/2024		53		\$0.00
Medium	Work In Progress	RM #112,			3/22/2024 10:33:29 AM				
Herrera, Marin		PLEASE PAINT ALL WALLS IN TEACHER'S LOUNGE AND WORKROOM. THANK YOU.							
Virginia Galindo									
297942	Main Building	Office			4/25/2024		19		\$0.00
Medium	Work In Progress	MR. REYES			4/25/2024 4:48:21 PM				
Ambriz, Jose		CHECK EXHAUST FAN. DIRT IS COMING THROUGH EXHAUST FAN, GETTING ON COMPUTER, PHONE AND DESK. THANK YOU.				Re route to HVAC checked by building mechanics and needs flex ducting thank you			
Virginia Galindo									
<b>Count: 4 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>34</b>		<b>Total for La Union ES</b>	<b>0</b>		<b>\$0.00</b>

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Loma Linda ES</b>									
296637	Main Building	Restroom			4/1/2024		43		\$154.31
Medium	Work In Progress	third grade			4/1/2024 1:08:39 PM				
Cangas, Kevin		Urinal needs new flush handle or tubing.							
Crystalee Heredia									
294111	Main Building	Classroom			2/9/2024		95		\$0.00
Medium	Work In Progress	104/Casiano			2/9/2024 3:48:34 PM				
Tellez, Hector		Lights don't turn off. Concerned about safety for lockdowns or other situations.							
Crystalee Heredia									
<b>Count: 2 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>69</b>	<b>Total for Loma Linda ES</b>			<b>0</b>	<b>\$154.31</b>

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: North Valley ES</b>									
294147					2/12/2024		92		\$2,293.65
Medium	Work In Progress				2/12/2024 12:37:26 AM				
Carrasco, Danny		Monthly - North Valley ES -Quarterly Filter Change - Refer to PM schedule details.							
Margret Villalobos									
294662					2/21/2024		83		\$0.00
Medium	Work In Progress				2/21/2024 1:46:35 PM				
Tellez, Hector		We need to add receptacles to the Assistant Principal's office.							
Gloria Reyes									
<b>Count: 2 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>88</b>		<b>Total for North Valley ES</b>	<b>0</b>		<b>\$2,293.65</b>

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Northern On-Track Pre-K (LM)</b>									
295656					3/12/2024		63	45.5	\$1,569.18
Medium	Work In Progress				3/12/2024 10:13:40 AM				
Duenas, Jose		Remove playground at La Mesa PreK				3/20/24 - Welders have removed Big Toys. As per Memo, Heavy Equip Operator needs to remove poles.			
Guillermo Hernandez									
298023					4/29/2024		15		\$12.61
Medium	Work In Progress				4/29/2024 7:42:49 AM				
Hernandez, Carlos		New water fountain have been replace and need upper area painted. Also panel on the bottom of the new water fountain is now close properly.							
Sandy Silvas									
297479					4/17/2024		27		\$0.00
Medium	Work In Progress				4/17/2024 12:36:53 PM				
Hernandez, Carlos		Need tile replace in the front entry way. Can be done over the summer Break. Thank you							
Sandy Silvas									
298049					4/29/2024		15		\$40.26
Medium	Work In Progress				4/29/2024 12:35:33 PM				
Tellez, Hector		Replace 2 GFI's plugs in room #102				reroute to electrician			
Sandy Silvas									
<b>Count: 4 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>30</b>		<b>Total for Northern On-Track Pre-K (LM)</b>	<b>45.5</b>	<b>\$1,622.05</b>	

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Physical Plant Complex</b>									
297739					4/23/2024		21		\$0.00
Medium	Work In Progress				4/23/2024 9:24:03 AM				
Ambriz, Jose		requesting tools list for sheet metal fabrication shop.							
David Escobar									
297662					4/22/2024		22		\$49.01
Medium	Work In Progress				4/22/2024 7:19:42 AM				
Flores, Antonio		Light is not working in front of office.							
Antonio Flores									
297757					4/23/2024		21		\$0.00
Medium	Work In Progress				4/23/2024 1:42:20 PM				
Tellez, Hector		Need to connect electrical to a/c to custodial							
Carlos Hernandez									
288972	Motor Vehicle				10/19/2023		208		\$0.00
Medium	Work In Progress				10/19/2023 9:43:35 AM				
Flores, Pete		requesting service on Stihl chainsaw #4 (Pete Flores)							
Danny Carrasco									
291586					12/14/2023		97	0.5	\$12.50
Medium	Work In Progress				12/14/2023 7:52:16 AM	3/20/2024			
Pacheco, Hector		Need Cable Snake Cutting Tips for big Cable Services Sanke.				Please chk work order, nothing was ordered.			
Joe Ontiveros									
293047	Motor Vehicle				1/23/2024		112		\$23.62
Medium	Work In Progress				1/23/2024 2:23:05 PM				
Villalobos, Jose		Need to up grade old air compressor system and rusted air lines for auto shop. Too much water/condensation in air lines and air compressor.							
Jose Villalobos									
293134					1/24/2024		111		\$27.96
Medium	Work In Progress	hvac shop			1/24/2024 2:37:25 PM				
Avila, Jesus		NEED TO MAKE A DISPLAY FRAME STAND FOR A MINI DUCTLESS. THANK YOU				04/29/2024 - Per J. Ambriz - waiting for water reservoir container.			
Jose Ambriz									
<b>Count: 7 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>85</b>	<b>Total for Physical Plant Complex</b>			<b>0.5</b>	<b>\$113.09</b>

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Riverside ES</b>							
292614					1/12/2024		123		\$0.00
Medium	Work In Progress			1/12/2024 10:33:02 AM					
Herrera, Marin	The fire truck in lower grade playground the boards are cracked and need to be replaced thank you		Re-route to Marin GH 1/18/24 ON ORDER						
Marin Herrera									
297096		Athletic Field			4/10/2024		34		\$192.48
Medium	Work In Progress			4/10/2024 8:21:00 AM					
Vasquez, Jose	There are a few 1 25s that need to be replace								
Jose Vasquez									
297801		Exterior			4/24/2024		20		\$0.00
Medium	Work In Progress			4/24/2024 8:32:26 AM					
Saenz, Daniel	Would you please find the wire that goes from the mechanical room to the timer, its practically on the floor, I would like to put it higher.								
Jose Vasquez									
298035	New Wing 1/02				4/29/2024		15		\$30.30
Medium	Work In Progress			4/29/2024 10:10:56 AM					
Pacheco, Hector	El salon #144 Checar el bano , remplazar el toilet flapper y la llave de paso gotea.								
Norma Onate									
297683					4/22/2024		22		\$0.00
Medium	Work In Progress			4/22/2024 12:22:36 PM					
Vasquez, Jose	Please check grass irrigation in front of school there is yellow spots.								
Marin Herrera									
<b>Count: 5 Work Orders</b>		<b>Avg. Age of WO's 43</b>		<b>Total for Riverside ES</b>			<b>0</b>	<b>\$222.78</b>	



# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: San Miguel Special Services</b>									
296732					4/3/2024		41		\$13.64
Medium	Work In Progress				4/3/2024 12:35:00 AM				
Duenas, Jose		Monthly - San Miguel ES -Grounds Service (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
293006	Classrooms	Exterior			1/23/2024		112		\$0.00
Medium	Work In Progress				1/23/2024 8:40:58 AM				
Pacheco, Hector		As per Memeo to disconnect water gas and sewer at portable that's going to be moved out.							
Hector Pacheco									
<b>Count: 2 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>77</b>	<b>Total for San Miguel Special Services</b>			<b>0</b>	<b>\$13.64</b>

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Santa Teresa ES</b>							
286920					9/11/2023		246		\$0.00
Medium	Work In Progress	Potable E (Ms.			9/11/2023 11:17:08 AM				
Herrera, Marin		Please install a fiber optic corner shower in portable E with Ms. Diaz. Ms. Diaz has the optic just needs assistance to install it. (Ms. Diaz)				Still waiting on approval spoke with Memo 9/12/23, 10/31/23			
Norma Martinez									
290780					11/29/2023		167		\$0.00
Medium	Work In Progress				11/29/2023 3:15:13 PM				
Lara, Ralph		As per Mr. S. Smythe approval, please install an additional door to the nurse's office for safety purposes. The door will be installed next to the conference room. (Mrs. Word)							
Norma Martinez									
293839					2/6/2024		98		\$0.00
Safety	Work In Progress	Casa Roja			2/6/2024 9:39:27 AM				
Herrera, Marin		The fire extinguisher located by the student restrooms needs a new cover, the cover is broken and needs to be replaced. (Mrs. Martinez)				ON ORDER			
Norma Martinez									
294479					2/19/2024		46	0.15	\$815.17
Medium	Work In Progress				2/19/2024 12:34:11 AM	4/5/2024			
Carrasco, Danny		Monthly - Santa Teresa ES -Quarterly Filter Change - Refer to PM schedule details.				issued			
Margret Villalobos									
294682					2/21/2024		83		\$0.00
Medium	Work In Progress	OFFICE			2/21/2024 4:02:15 PM				
Saenz, Daniel		The top portion of the marquee where the school name is displayed needs a light bulb replacement. The digital message area is working perfectly but it seems like the electrician needs to replace the light bulb for the top area. (Mrs. Martinez)				Re-route to electrician thank you			
Norma Martinez									
<b>Count: 5 Work Orders</b>		<b>Avg. Age of WO's 128</b>			<b>Total for Santa Teresa ES</b>		<b>0.15000</b>	<b>\$815.17</b>	

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Santa Teresa HS

296834	Main Building	Athletic Field			4/4/2024		40		\$0.00
--------	---------------	----------------	--	--	----------	--	----	--	--------

Medium	Work In Progress	Baseball field			4/4/2024 1:41:49 PM				
--------	------------------	----------------	--	--	---------------------	--	--	--	--

Saenz, Daniel In baseball game of foul ball, hit a light and broke it.

Ashley Villalobos-Trujillo

296348		Exterior			3/28/2024		47		\$0.00
--------	--	----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/28/2024 8:20:28 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Pacheco, Hector Please replace hose bib that was discussed with Ed. Located by the mechanical room by softball fields and closest to the new portable restroom trailer. If you have any questions or concerns please call Ed or Clarissa. Thank you!

Clarissa De Leon

297262	Main Building	Parking Lot			4/12/2024		32		\$0.00
--------	---------------	-------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Security Guard			4/12/2024 3:22:46 PM				
--------	------------------	----------------	--	--	----------------------	--	--	--	--

Herrera, Marin Stop sign for the guard check

Blanca Rivera

297405	Main Building	Classroom			4/16/2024		28		\$0.00
--------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	215			4/16/2024 2:21:13 PM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Pacheco, Hector Oven is not working, it is not turning on. There is no hot water in the kitchen sink. The garbage disposal is not working.

Blanca Rivera

291198	Main Building	Classroom			12/5/2023		161		\$0.00
--------	---------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	501			12/5/2023 3:04:14 PM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Ruiz, Danny Please install blinds in classroom Re-route to Danny Ruiz thank you

Ashley Villalobos-Trujillo

297559	GYM (2009)	Gym			4/18/2024		26		\$5.50
--------	------------	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Auxillary Gym			4/18/2024 11:01:15 AM				
--------	------------------	---------------	--	--	-----------------------	--	--	--	--

Herrera, Marin Loose cables hanging from the the aux gym ceiling

Blanca Rivera

297659					4/22/2024		22		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/22/2024 12:45:15 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Flores, Pete Monthly - Santa Teresa HS - STHS-UV-0916 - Refer to PM schedule details.

Margret Villalobos

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
297332	Vocational	Classroom			4/15/2024		29		\$0.00
Medium	Work In Progress	801		4/15/2024 1:55:16 PM					
Lara, Ralph	4th notice Roll up door bottom seal is dry and broken needs to be replaced, lets a lot of dust to enter and can damage students computers and classroom equipment								
Blanca Rivera									
297886	Main Building	Classroom			4/25/2024		19		\$0.00
Medium	Work In Progress	215		4/25/2024 10:37:14 AM					
Pacheco, Hector	The stove is not turning on, sink garbage disposal not working, and there's no hot water in sink.								
Blanca Rivera									
298146	Main Building	Football Field			4/30/2024		14		\$37.50
Medium	Work In Progress	Stadium		4/30/2024 10:53:12 AM					
Herrera, Marin	Spoke with Mr. Marin about the grounds assisting Mr. Champagne in placing the additional dream catchers in the stadium.								
Blanca Rivera									
298147	Vocational	Classroom			4/30/2024		14		\$0.00
Medium	Work In Progress	801		4/30/2024 10:58:02 AM					
Lara, Ralph	4th noticed rollup door need bottom seal replaced,lots of dust is entering the classroom and damage computers ann 3D Printers I requested this since August 2023				Re-route to locksmith thank you				
Blanca Rivera									
<b>Count: 11 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>39</b>	<b>Total for Santa Teresa HS</b>			<b>0</b>	<b>\$43.00</b>

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa MS</b>									
298055	South Building	Classroom			4/29/2024		15		\$0.00
Medium	Work In Progress	54- VACANT			4/29/2024 2:05:47 PM				
Herrera, Marin		1-PLEASE DISASSEMBLE TABLES IN ROOM 54 AND MOVE TO PORTABLE 1-A 2- PLEASE ASSEMBLE TABLES ONCE THEY ARE MOVED TO PORTABLE 1-A							
Laura Parra									
297556	Gym (1997)	Gym			4/18/2024		26		\$0.00
Medium	Work In Progress	BLEACHERS			4/18/2024 10:44:40 AM				
Hernandez, Guillermo		BLEACHERS DO NOT RETRACT CORRECTLY, LOOK LIKE THEY MY BE MISALINGNED.				Re-route to Memo, Norcon did PMs in March			
Laura Parra									
294418	South Building	Classroom			2/16/2024		88		\$0.00
Medium	Work In Progress	UPPER LEVEL			2/16/2024 8:31:32 AM				
Smythe, Shane		1- PLEASE REMOVE STUDENT LOCKERS. 2- PAINT BEHIND THE LOCKERS. 3- INSTALL TILE AND TRIM.				Re-route to Shane S. thank you			
Laura Parra									
294419	North Building	Hallway/Corridor			2/16/2024		88		\$0.00
Medium	Work In Progress	UPPER LEVEL			2/16/2024 8:32:29 AM				
Smythe, Shane		1- PLEASE REMOVE STUDENT LOCKERS. 2- PAINT BEHIND THE LOCKERS. 3- INSTALL TILE AND TRIM.				Re-route to Shane S. thank you			
Laura Parra									
297094		Athletic Field			4/10/2024		34		\$0.00
Medium	Work In Progress				4/10/2024 8:19:35 AM				
Vasquez, Jose		Stations #24, 25, and 31 need attention							
Jose Vasquez									
296104	North Building	Dressing Room			3/22/2024		53		\$0.00
Medium	Work In Progress	BOYS LOCKER			3/22/2024 2:34:52 PM				
Pacheco, Hector		NO WATER - BOYS LOCKER ROOM SINK							
Laura Parra									
<b>Count: 6 Work Orders</b>		<b>Avg. Age of WO's 51</b>		<b>Total for Santa Teresa MS</b>		<b>0</b>		<b>\$0.00</b>	

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>Sunland Park ES</b>							
297002	Main Building	Classroom			4/8/2024		36		\$1.19
Medium	Work In Progress				4/8/2024 12:16:35 PM				
Pacheco, Hector		Please check room 23 sink small faucet leaking. Thank you							
Alma Morales									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>36</b>	<b>Total for Sunland Park ES</b>				<b>0</b>	<b>\$1.19</b>

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Sunrise ES</b>									
297331	Main Building	Hallway/Corridor			4/15/2024		29		\$571.32
Medium	Work In Progress				4/15/2024 1:49:00 PM				
Flores, Antonio		Round light fixture in front of Luna hallway is out							
Adrian Flores									
294835	Main Building	Football Field			2/26/2024		78		\$20.79
Medium	Work In Progress				2/26/2024 11:56:58 AM				
Vargas, Juan		kinder playground green four seats see saw orange cap is missing				Forward. To memo			
Adrian Flores									
294848	Main Building	Exterior			2/26/2024		78		\$0.00
Medium	Work In Progress				2/26/2024 3:03:43 PM				
Vasquez, Jose		We need 4 field goals with nets please thank you							
Joanna Rodriguez									
297600	Main Building	Custodial			4/19/2024		25	1	\$128.49
Medium	Work In Progress				4/19/2024 7:31:23 AM				
Cangas, Kevin		Custodian closet faucet leak went you turn on hot				Forward. To plumbing - faucet needs to be replaced			
Adrian Flores									
298117		Kitchen			4/30/2024		14		\$0.00
High	Work In Progress				4/30/2024 7:33:16 AM				
Vargas, Juan		In and around mop sink room walls/corners possible black mold growing (As per Health Insp.)							
Dino Facio									
<b>Count: 5 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>45</b>		<b>Total for Sunrise ES</b>	<b>1</b>	<b>\$720.60</b>	

# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Vado ES</b>									
297370					4/16/2024		28		\$0.00
Medium	Work In Progress				4/16/2024 9:17:29 AM				
Tellez, Hector		In room 201 in the restroom light is out.							
Guadalupe Parada									
297468	Main Building	Classroom			4/17/2024		27		\$0.00
Medium	Work In Progress				4/17/2024 9:14:35 AM				
Tellez, Hector		The light in the restroom in room 201 doesn't turn on.							
Maribel Villela									
297042		Classroom			4/9/2024		35		\$0.00
Medium	Work In Progress				4/9/2024 9:01:45 AM				
Pacheco, Hector		Mr. Santa Maria is requesting a Deep Utility sink for his classroom. He is the Art teacher.							
Maribel Villela									
294335					2/14/2024		90		\$0.00
Medium	Work In Progress				2/14/2024 1:11:06 PM				
Tellez, Hector		In the boy's restroom on the 200's hallway one of the lights is out.				reroute to electrician.			
Guadalupe Parada									
293544					2/2/2024		102		\$0.00
Medium	Work In Progress				2/2/2024 10:06:39 AM				
Tellez, Hector		In room 204 two lights panels are completely out.							
Guadalupe Parada									
292621					1/12/2024		123		\$0.00
Medium	Work In Progress				1/12/2024 11:28:34 AM				
Tellez, Hector		In room 211 one of the emergency lights is out.				reroute to electrician.			
Guadalupe Parada									
<b>Count: 6 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>68</b>			<b>Total for Vado ES</b>	<b>0</b>	<b>\$0.00</b>



# 124 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2023 - 4/30/2024 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Yucca Heights ES</b>								
293738					2/5/2024		99	\$2,031.75		
Medium	Work In Progress				2/5/2024 1:01:33 AM					
Carrasco, Danny		Monthly - Yucca Heights ES-Quarterly Filter Change - Refer to PM schedule details.								
Margret Villalobos										
294645		Kitchen			2/21/2024		83	\$196.34		
High	Work In Progress				2/21/2024 10:13:51 AM					
Pacheco, Hector		Water spigot right outside kitchen back door leaking wont close completely								
Dino Facio										
298058		Classroom			4/29/2024		15	\$0.00		
Medium	Work In Progress	room 302			4/29/2024 3:03:18 PM					
Ambriz, Jose		Need to replace a switch overflow.								
Jose Ambriz										
<b>Count: 3 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>66</b>	<b>Total for Yucca Heights ES</b>			<b>0</b>	<b>\$2,228.09</b>	
<b>Count: 124 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>59</b>	<b>Grand Total</b>			<b>53.6500000</b>	<b>\$13,138.70</b>	